



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

GST Reg No.: 201718369R

POH HUIHUA

04/10/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPALG.

Jia Le.

Accident date: 20/09/2019

Estimated repair cost for vehicle no: SLU1899P MINI ONE 1.2 A '17

CHASSIS: WMWXS120702G64697

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet <i>Repair</i>		\$1,237.75 +
2	1	Front L/H Fender <i>Dented</i>		\$405.80 ✓
3	1	Front L/H Fender Signal Lamp <i>cut</i>		\$51.70 ✓
4	1	Front L/H Arch Protector <i>cut</i>		\$137.15 ✓
5	8	Front L/H Arch Protector Clip <i>new</i>	\$6.50	\$52.00 20
6	1	Front L/H Side Mirror Assy <i>new</i>		\$823.10 X
7	1	Front L/H Tyre <i>new</i>		\$450.00 X
8	1	Front L/H Rim <i>cut</i>		\$604.50 400(SN)
			614.65	Subtotal:-
			553.18	400(SN)
				\$3,762.00

Labour charges

To check wheel alignment

\$150.00 X

To check wiring

630 \$100.00 30

Tuff kote

\$100.00 X

Panel beating

~~\$800.00~~ 200

Spray painting

~~\$1,000.00~~ 400

Subtotal:- \$2,150.00

Total:- \$5,912.00

1.2K.

total 1583.18
L/S: 1.2K 03 Days