

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: India International Insurance Pte Ltd

Accident Date : 02.10.2019

*Not Authorized
U Sup B?
Running After Paint
1 day*

Third Party

Policy No: _____

07.10.2019

Date: _____

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Honda Jazz" Reg. No. SJY8163K Claiming Against Your Insured Veh. No. SHC8332D			
1pc	Tailgate		<i>R</i> 845.00 ✓
1pc	Tailgate Glass Moulding Top		<i>M</i> 50.00 ✓
1pc	Tailgate Glass Moulding Lower		<i>M</i> 50.00 ✓
1pc	Tailgate Badge "Jazz"		<i>M</i> 28.00 ✓
1pc	Tailgate Lock		<i>M</i> 198.00 ✓
1pc	Tailgate Lock Catch		<i>R</i> 28.50 ✓
1pc	Tailgate Weatherstrip		<i>M</i> 101.00 ✓
1pc	Tailgate Trim Board		<i>M</i> 112.00 ✓
10pcs	Tailgate Trim Board Clips	5.00	<i>M</i> 50.00 ✓
1pc	Tailgate Stopper LH		<i>M</i> 13.00 ✓
1pc	Rear Bumper		<i>R</i> 485.00 ✓
10pcs	Rear Bumper Clips	3.80	<i>M</i> 38.00 ✓
2pcs	Rear Bumper Brackets	18.00	36.00 ✓
2pcs	Rear Bumper Top Retainers	18.00	36.00 ✓
1pc	Rear Bumper Lower Diffuser Cover		<i>D</i> 300.00 ✓
1pc	Rear Bumper Tow Cover		<i>M</i> 18.50 ✓
2pcs	Rear Bumper Corner Retainers	110.00	<i>D</i> 220.00 ✓
2pcs	Taillamps	383.00	766.00 ✓
2pcs	Taillamps Gasket	26.00	52.00 ✓
2pcs	Taillamps Lock Clips	15.00	30.00 ✓
1pc	Taillamps Panel LH		<i>R</i> 146.00 X
1pc	End Panel		<i>R</i> 303.00 ✓
1pc	End Panel Garnish		<i>M</i> 65.00 ✓
1pc	Spare Tyre Panel		<i>R</i> 830.00 ✓
1pc	Spare Tyre Panel Insulation		<i>M</i> 195.00 ✓
1pc	Spare Tyre Top Board		<i>M</i> 209.00 ✓
1pc	Rear Styrofoam Storage Box		<i>C</i> 290.00 ✓
1pc	Rear Fender Inner Trim Boards	255.00	<i>C</i> 510.00 ✓
1pc	Rear Exhaust Silencer		<i>R</i> 533.00 X
1pc	Rear Exhaust Silencer Gasket		<i>S</i> 28.00 X
			6,566.00
	Less 25%		1,641.50
			4,924.50
	Rear Number Plate		<i>S</i> 45.00 SN X
	Tailgate Glass Sealant		<i>M</i> 40.00 SN
	Tailgate Glass Fastener		<i>M</i> 30.00 SN
	Rear Bumper Reverse Sensor		<i>R</i> 280.00 SN
			<i>S</i> 200.00
		C/F	5,349.50

趙源摩托 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: India International Insurance Pte Ltd

Accident Date : 02.10.2019

Third Party
 Policy No: _____

 Date: 07.10.2019

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Honda Jazz" Reg. No. SJY8163K Claiming Against Your Insured Veh. No. SHC8332D		
		B/F	5,349.50
	To Conduct Front Electrical Check, Reverse Sensors, Module, etc		120.00 <i>50c</i>
	To Dismantle / Transfer Tailgate Fitting / Ancillary Accessories		150.00 <i>60c</i>
	To Dismantle / Refit Tailgate Glass / Ancillary Accessories		160.00 <i>120c</i>
	To Dismantle / Refit Trunk Compartment Boards & Trims		80.00 <i>60c</i>
	To Supply Rear Body Panel Sealant		80.00 <i>60c</i>
	To Repair / Replace Exhanst Silencer		150.00 <i>60c</i>
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		150.00 <i>90c</i>
	Labour Charge - Panel Beating, Repairing Of Rear Chassis Member, Inner Panel, Floor Panel, Rear Fender etc. Cnt, Weld End Panel, Spare Tyre Panel and Parts Replacement		1,600.00 <i>1200c</i>
	To Respray Affected Areas		1,500.00 <i>1200c</i>
	Total :		9,339.50

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____