



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

TP China
Version

JSAEZC31360202356

Page No. 1

Vehicle No. SJH6949M SUZUKI SWIFT

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
	PARTS (LIST ITEMS)			
1	REAR BOOTLID Distorted		760.00	628
1	REAR BOOTLID LOCK Damaged		186.70	✓
1	REAR BOOTLID LOCK CATCH xtr		55.00	x
1	REAR BOOTLID CENTRE LOGO Nec		76.00	45
2	REAR BOOTLID HINGE LH & RH @\$80.60 xtr nec		161.20	x
1	REAR BOOTLID ABSORBER Not nec		247.70	x
1	REAR BOOTLID " SWIFT " EMBLEM nec		81.00	42
1	REAR BOOTLID INNER BOARD Deformed		325.00	172
1	REAR BOOTLID RUBBER Lt		261.20	✓
1	REAR BOOTLID OUTER HANDLE curved		85.00	✓
1	REAR BOOTLID WIPER ARM } xtr		110.00	✓
1	REAR BOOTLID WIPER MOTOR } nec		365.50	x
1	REAR BUMPER Distorted		624.30	549
1	REAR BUMPER TOW COVER Deformed		91.00	45
2	REAR BUMPER SIDE RETAINER LH & RH @\$79.50 Nec		159.00	78
2	REAR BUMPER SIDE BRACKET LH & RH @\$92.30 xtr nec		184.60	x
1	REAR BUMPER LOWER GARNISH Deformed		604.50	427
2	REAR BUMPER REVERSE LAMP LH & RH @\$154.20 nec nec		308.40	x
2	REAR BUMPER REINFORCEMENT BRACKET LH & RH @\$135.90 Dented		271.80	96.
2	REAR NUMBER PLATE LAMP LH & RH @\$71.50 curved		143.00	58.
1	REAR END PANEL Distorted		432.50	✓
1	REAR END PANEL TOP GARNISH Deformed		262.00	74
1	REAR END PANEL AIR VENT Not nec		111.00	x
1	REAR SPARE TYRE PANEL Buckled		590.70	x
1	REAR SPARE TYRE PANEL TOP COVER BOARD Deformed		255.00	✓
1	REAR SPARE TYRE PANEL UPPER SPONGE Deformed		311.00	198
2	REAR TAILLAMP LH & RH @\$399.30 curved		798.60	556
2	REAR TAILLAMP PANEL LH & RH @\$298.90 Lt Buckled		596.60	148
2	REAR FENDER LH & RH @\$665.90 Reps		1331.80	x
2	REAR FENDER INNER GARNISH LH & RH @\$291.20 curved		584.20	218.
1	REAR EXHAUST SILENCER Dented		711.00	653
1	REAR EXHAUST SILENCER RUBBER Not nec		98.00	x
			11183.50	
		less 170 (10%)	1118.35	10%
			10065.15	
	SPECIAL NETT ITEMS			
1 SET	REAR BUMPER CLIPS nec		100.00	30
1	REAR FENDER SEALANT nec		80.00	x
1 SET	REAR CAR PLATE WITH HOLDER curved		70.00	50.
1	REAR WINDSCREEN SEALANT nec		100.00	60
1	REAR TAILGATE INNER BOARD CLIPS nec		100.00	30
	Total Parts		10515.15	



ACE AUTOLUTION PTE LTD
13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807
Tel: 6702 4282 Fax: 6702 4202

Page No. 2

Vehicle No. SJH6949M SUZUKI SWIFT

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	OUR ASSESSMENT (\$\$)
1	LABOUR To remove the affected parts & fittings to commence repairs and replace damaged parts	1600.00	1200
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00	1000
3	To remove, re-fix wiring system at accident damage areas and check for proper function	150.00	30
4	To perform anti-rust treatment on affected areas	210.00	60
5	Cavity treatment on New parts	120.00	x
6	To remove and re-fix rear bootlid mechanism	150.00	80
7	To conduct water seepage test	120.00	x
8	To remove and re-fix rear windscreen	120.00	✓
Labour Total :		3670.00	
TOTAL (PARTS & LABOUR):		14185.15	

total 7588.38
c/s 6k

08 Days.

(6k)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: