

1552000

INS. CASE OWNER:

CC3/AIG19017609/Aha3

LKK:

IDAC:

Surveyor:

ADRIAN

DOI:

08/10/2019

Date/Time:

07/10/2019

Registered in Meriton:

07/10/2019

Pre-assign / CCU / FTE



Insured Vehicle No. : SKS 2486M
 Name of Insured : LOW HWEE HWA
 Insured Tel No. : HP: +65-90103567
 Excess Sec II :SS D.O.A : 06/10/2019 08:35
 Is driver the owner? (YES / NO) Nature of Accident :
 Claim No. : 8A39087730G
 Policy No. :
 Make / Model : MAZDA 5 SP-2.0 (A)
 Place of Accident : ALONG AYE TOWARDS TUAS DIRECTION

If NO, Driver Name / Age : LIU SHANYI

Driver Tel No. : +65-97590729

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SFV 8092U



INSRS:
WSP: PREMIUM
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/Time	SFV 8092U - X	SKS 2486M - X	STAGE	DATE / PIC
09/10/19 @ 4:30PM	CALL OI (FATHER), OIB W/LS SON. OI CONFIRMED ACCIDENT DETAILS & OIB RATE-BONDED TP. INFORMED TP CLAIM. AGREED TO SETtle & AWAITS NCB ISSUES. SEND LETTER TO OI.		Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OI: After call ltr to OI:	
12/02/2020	MAIL URGENTLY CLERK TO MINUTE COX MINUTED TP LOD IN BY MAIL		Documentation Check List: Handler Typist	
12/02/2020	TPS REPORT FOR MANDATE APPROVAL REPORT DONE		Notification ltr (if non-pickup): After call ltr to OI: MAIL	
12/02/2020	SEND MANDATE APPROVAL TO AIG AIG APPROVED MANDATE SEND ACCEPTANCE MAIL TO TP ALL DONE IN ORDER TO CLOSE.		Authorisation To Act: Release Voucher: Final Repair Bill: Car Rental Invoice: Towing Invoice: LTA / GIA : Medical Bill: PIR: Mandate/Reject Instruction: LOD Payment Breakdown Form: Post-Repair Photos: Others:	
PRELIMINARY ADVICE Date/Time: Sent By:				
FINALIZATION Date/Time: Confirm with: Confirm by:				
Repair Cost: P/B S\$ 11,995.76 (6 days) Reduction: 60 % Email ☐ Call ☐				
FINAL SETTLEMENT Date/Time: 04/02/2020 Confirm with: NABIA Email ☐ Call ☐				
Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27			If NO or B 28, Ass. Lia: (OIB RATE-BONDED TP)	
Repair Cost: (w/cond) S\$ 12,835.46				
Loss of Rental (LOR): S\$ 1,050.00 (7 days) x \$150.00				
Loss of Use (LOU): S\$ — (5 x days)				
Loss of Income (LOI): S\$ — (5 x days)				
LOR only ☒ LOU only ☐ LOR + LOU ☐ [Tick only one]				
GIA/LTA Search S\$ 7.45				
Medical: S\$ —			1) Claim status: Normal/Reject/Private Settle	
Disbursement: S\$ — (e.g. Tow/ Independent)			2) Report Format:	
Legal Cost S\$ —			3) Survey fee: \$310.00	
Total: S\$ 13,892.91 Global Sum S\$: —				
FINAL PAYMENT Date/Time: Confirm with: Email ☐ Call ☐				
Payee 1: S\$ 13,892.91 Name 1: PREMIUM AUTOMOBILES PTE LTD				
Payee 2: (Strike if N.A.) S\$ — Name 2: —				
Payee 3: (Strike if N.A.) S\$ — Name 3: —				

COPY SENT 4/3/2020

REF: MG

ASSIGNMENT

From: Date: 8/10/2019

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: SFV80924

at Workshop m/s Premium

of 55 ubi Road 1

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: 10am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR. Seen: Consistent? : Yes or No

Est. Repairs: 06/05 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^(up)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SFV80924- Yr Regn: 2019 / August

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A5 cc 1984.

Colour: Black A/C: Insured / Std / NI / NA

Sp Reading: 7146 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WAUZZZF57KA026822

Gen. Cond: Good

Steering: Insured / J

Brake: Insured / J

Modi: Nil / S/R

Tyre Size: F: 255/35 R19.

R: 255/35 R19.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental.

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 08/019

Survey held at Premium.

Des. of Damages: Frt ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AG.

P/P \$ 11,995.76

CRV = \$ 17,677.24 (60%)

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp. (\$)

Survey Fee:

Transportation:

S + RS \$

Photos:

Notes:

(Total)

Report Format:

Lump Sum / L.B.I.:

☐ : Interview (\$)☐ : Tech. Insp. (\$)☐ : Witness (\$)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SFV 8092 U

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00 ✓	
2	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$ 480.00 ✓	
3	To dismantle and renew rear bumper and rear lid. To repair lhs rear fender. To cut out and reweld end panelling. Re-organise rear crash management components. Reinstall all parts removed.	\$ 5,200.00	1,550 1,500.00
4	To respray rear bumper, rear lid, lhs rear fender, end panelling, and spare wheel housing.	\$ 4,900.00	1650
5	To remove and renew lhs rear exhaust silencer. To align to position.	S/N \$ 480.00	2. 280
6	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		\$ 11,612.00	

③ To Reapply Paint Protection Film for rear bumper, rear boot and rear fender.

\$ 2530.00

~~1,550~~ 1,500

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFV 8092 U

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
1	REAR BUMPER <i>Del'd</i>	\$ 2,311.00	✓	1,848.80
2	REAR BUMPER FIXING PARTS <i>ne m</i>	\$ 150.00	+	
3	REAR BUMPER SECURING STRIP <i>Ne</i>	\$ 203.00	✓	162.40
4	REAR BUMPER TRIM <i>enhd</i>	\$ 928.00	✓	742.40
5	REAR LIGHT REFLECTOR - LH <i>enhd</i>	\$ 38.00	✓	29.68
6	REAR BUMPER CARRIER <i>Best</i>	\$ 819.00	✓	655.20
7	REAR BUMPER SEAL <i>ne m</i>	2 \$ 25.00	+	
8	REAR BUMPER GUIDE SECTION - LH / RH <i>ne m</i>	2 \$ 80.00	+	
9	REAR BUMPER GUIDE SECTION - LH / RH <i>ne m</i>	2 \$ 40.00	+	
10	AERIAL RETAINER - LH <i>ne m</i>	\$ 23.00	+	
11	TELEPHONE AERIAL <i>ne m</i>	\$ 164.00	+	
12	REAR PARKING AID SENSOR - INNER / OUTER <i>ne m</i>	2 \$ 462.00	+	
13	REAR PARKING AID SEAL RING <i>ne m</i>	4 \$ 12.00	+	
14	REAR BUMPER WIRING SET <i>ne m</i>	\$ 618.00	+	
15	BOOT LID CONTROL UNIT <i>ne m</i>	\$ 381.00	✓	307.20
16	REAR LID <i>Defted</i>	\$ 2,449.00	✓	1,959.20
17	REAR LID HINGE - LH / RH <i>ne m</i>	2 \$ 762.00	+	
18	REAR LID ATTACHMENT PARTS <i>ne m</i>	\$ 154.00	+	
19	REAR LID LOCK <i>ne m</i>	\$ 210.00	+	
20	LID LOCK PUSH BUTTON <i>ne m</i>	\$ 1,230.00	+	
SUB-TOTAL SPARE PARTS		\$ 11,059.00		

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No SFV 8092 U

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	REAR LID LOCK STRIKER <i>all in</i>	\$ 30.00	+
22	REAR LID ANTI THEFT GUARD COVER - INNER <i>all in</i>	\$ 58.00	+
23	REAR LID FLAP GASKET <i>all in</i>	2 \$ 207.00	+
24	PACKING ADHESIVE <i>all in</i>	2 \$ 18.00	✓ 13.92
25	AUDI EMBLEM <i>2 all in</i>	4 \$ 127.00	✓ 101.60
26	A5 INSCRIPTION <i>all in</i>	\$ 87.00	✓ 69.28
27	REAR CROSS PANEL <i>Repair</i>	3 \$ 329.00	+
28	CROSS PANEL REINFORCEMENT <i>Repair</i>	6 \$ 577.00	+
29	LED LICENCE PLATE LIGHT <i>all in</i>	2 \$ 92.00	+
30	LED TAIL LIGHT - LH <i>all in</i>	\$ 931.00	+
31	TAIL LIGHT TRIM - LH <i>all in</i>	\$ 27.00	+
32	EXHAUST TAILPIPIES TRIM SET <i>all in</i>	\$ 153.00	✓ 122.40
33	REAR SILENCER - LH <i>Not all in</i>	\$ 813.00	+
34	REAR SILENCER DUAL CLIP <i>all in</i>	\$ 45.00	+
35	EXHAUST SILENCER BRACKET <i>Not all in</i>	\$ 38.00	+
36	ACRYLIC SEALANT <i>all in</i>	S/N \$ 180.00	+
37	CAVITY WAX <i>all in</i>	S/N \$ 140.00	+
38	STONE CHIP <i>all in</i>	S/N \$ 180.00	+
39	REAR NO PLATE <i>all in</i>	S/N \$ 40.00	+
40	SUNDRIES <i>New</i>	\$ 400.00	2168.
TOTAL SPARE PARTS		: \$ 15,531.00	
TOTAL LABOUR CHARGES		: \$ 11,612.00	
GRAND TOTAL		: \$ 27,143.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adam King
Surveyed Date : 08/10/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Outlensed, 05 Days (Without End Panel)
08 Days (With End Panel)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 14969

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1204/2019/NS
Date : 7-Oct-19

Vehicle IN workshop. Kindly arrange for survey.

Your insured veh no. : **SKS 2486 M**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ong Kok Kiong
Address : 95 Prince Charles Crescent
#04-09
Singapore 159027
Telephone : (HP) +65 97879653
Type of Claim : Third Party Claims
Policy No. : 1900016808
Vehicle No : **SFV 8092 U**
Model Code : Audi A5 Coupe 2.0 TFSI S Tronic
Model / Year : Feb-19
Engine No : CVK 076379
Chassis No : WAUZZZF57KA026822
Mileage : 7146
Date In : 7-Oct-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Oct-19
Place of Accident : Along AYE Towards Tuas Direction



C. N. N: 201636586N

INVOICE

Bill To:

Name :

Contact Number :

Address :

Mr. Ong

9787 9053

DATE:

7/Mar/19

INVOICE #

5D 19111

Vehicle Make/Model/Colour :

Audi A5 Black

Vehicle Registration Number :

SFV 8092 U

TERM: Nets / Cash / Credit

DESCRIPTION	AMOUNT
STEK Paint Protection Film - Extreme Plus Package (10 Year Warranty)	\$ 5,400.00
De-Chrome -	
* Gloss Black	\$ 150.00
*Carbon	\$ 50.00
Remarks (if any):	
Car Maintenance Tips:	
1. Wash your car regularly with mild car soap (Recommended once a week)	
2. Avoid doing any further polishing and using wax as it will void your warranty	
3. The warranty does not extend coverage cause by misuse, accident, missapplication, normal wear and tear, or dents from road debris impact, collisions and/ or intentional damage of any kind.	
	\$ 5,600.00



Bill To:

Name :

Contact Number :

Address :

Mr. Ong

9787 9053

DATE: _____

7 October, 2019

INVOICE #

Quotation

Vehicle Make/Model/Colour :

Audi A5 Black

TERM:

Vehicle Registration Number :

SFV 8092 U

1550

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 14969

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1204/2019/NS
Date : 7-Oct-19

Vehicle IN workshop. Kindly arrange for survey.

Your insured veh no. : **SKS 2486 M**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

We took 8 days exclude 1 Sunday

jb 15 Jan 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ong Kok Kiong
Address : 95 Prince Charles Crescent
#04-09
Singapore 159027
Telephone : (HP) +65 97879653
Type of Claim : Third Party Claims
Policy No. : 1900016808
Vehicle No : **SFV 8092 U**
Model Code : Audi A5 Coupe 2.0 TFSI S Tronic
Model / Year : Feb-19
Engine No : CVK 076379
Chassis No : WAUZZZF57KA026822
Mileage : 7146
Date In : 7-Oct-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Oct-19
Place of Accident : Along AYE Towards Tuas Direction

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SFV 8092 U

S/N	Nature of Jobs		Estimated Charges	Surveyor's recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$	360.00	\$ 360.00
2	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$	480.00	\$ 480.00
3	To dismantle and renew rear bumper and rear lid. To repair lhs rear fender. To cut out and reweld end panelling. Re-organise rear crash management components. Reinstall all parts removed. (Rear panel repair 0.5 day)	\$	5,200.00	\$ 1,500.00
4	To respray rear bumper, rear lid, lhs rear fender, end panelling, and spare wheel housing.	\$	4,900.00	\$ 1,650.00
5	To remove and renew lhs rear exhaust silencer. To align to position.	S/N \$	480.00	\$ 280.00
6	Added jobs - owner invoice attached	\$	1,500.00	\$ 1,500.00
7	To carry out diagnostic checks.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 13,112.00	\$ 5,962.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFV 8092 U

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER	\$ 2,311.00	\$ 1,848.80
2	REAR BUMPER FIXING PARTS	\$ 150.00	
3	REAR BUMPER SECURING STRIP	\$ 203.00	\$ 162.40
4	REAR BUMPER TRIM	\$ 928.00	\$ 742.40
5	REAR LIGHT REFLECTOR - LH	\$ 38.00	\$ 29.68
6	REAR BUMPER CARRIER	\$ 819.00	\$ 655.20
7	REAR BUMPER SEAL	2 \$ 25.00	
8	REAR BUMPER GUIDE SECTION - LH / RH	2 \$ 80.00	
9	REAR BUMPER GUIDE SECTION - LH / RH	2 \$ 40.00	
10	AERIAL RETAINER - LH	\$ 23.00	
11	TELEPHONE AERIAL	\$ 164.00	
12	REAR PARKING AID SENSOR - INNER / OUTER	2 \$ 462.00	
13	REAR PARKING AID SEAL RING	4 \$ 12.00	
14	REAR BUMPER WIRING SET	\$ 618.00	
15	BOOT LID CONTROL UNIT	\$ 381.00	\$ 307.20
16	REAR LID	\$ 2,449.00	\$ 1,959.20
17	REAR LID HINGE - LH / RH	2 \$ 762.00	
18	REAR LID ATTACHMENT PARTS	\$ 154.00	
19	REAR LID LOCK	\$ 210.00	
20	LID LOCK PUSH BUTTON	\$ 1,230.00	
SUB-TOTAL SPARE PARTS		\$ 11,059.00	\$ 5,704.88

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No SFV 8092 U

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/Nett	Remarks
			\$	5,704.88
21	REAR LID LOCK STRIKER		\$ 30.00	
22	REAR LID ANTI THEFT GUARD COVER - INNER		\$ 58.00	
23	REAR LID FLAP GASKET	2	\$ 207.00	
24	PACKING ADHESIVE	2	\$ 18.00	\$ 13.92
25	AUDI EMBLEM	4	\$ 127.00	\$ 101.60
26	A5 INSCRIPTION		\$ 87.00	\$ 69.28
27	REAR CROSS PANEL	3	\$ 329.00	
28	CROSS PANEL REINFORCEMENT	6	\$ 577.00	
29	LED LICENCE PLATE LIGHT	2	\$ 92.00	
30	LED TAIL LIGHT - LH		\$ 931.00	
31	TAIL LIGHT TRIM - LH		\$ 27.00	
32	EXHAUST TAILPIPES TRIM SET		\$ 153.00	\$ 122.40
33	REAR SILENCER - LH		\$ 813.00	
34	REAR SILENCER DUAL CLIP		\$ 45.00	
35	EXHAUST SILENCER BRACKET		\$ 38.00	
36	ACRYLIC SEALANT	S/N	\$ 180.00	
37	CAVITY WAX	S/N	\$ 140.00	
38	STONE CHIP	S/N	\$ 180.00	
39	REAR NO PLATE	S/N	\$ 40.00	
40	SUNDRIES		\$ 400.00	\$ 21.68
	TOTAL SPARE PARTS	:	\$ 15,531.00	\$ 6,033.76
	TOTAL LABOUR CHARGES	:	\$ 13,112.00	\$ 5,962.00
	GRAND TOTAL	:	\$ 28,643.00	\$ 11,995.76

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant



OCBC Bank

5D SOLUTIONS PTE LTD

7 SOON LEE STREET
#01-26 ISPACE

DATE/TIME: 13/11/19 16:49:27

MID:000000090345771

TID: 92005634

SALE

VISA

***** 4825

ENT TYPE:Chip

STAN:002512 RRN:931716109924

BATCH:000518

TRACE:000931

APPR CODE:008038

AID: A0000000031010

APP: VISA

TC : 649DA85846387423

TOTAL AMOUNT: \$ 1,500.00

SIGN: _____

ONG KOK KIONG

I AGREE TO PAY THE ABOVE TOTAL AMOUNT
ACCORDING TO THE CARD ISSUER AGREEMENT

***** CUSTOMER COPY *****
THANK YOU. HAVE A NICE DAY



BILL TO:

Name :

Contact Number :

Address :

Mr Ong

9787 9653

[illegible]

DATE: _____

DATE:
13-Nov-19

INVOICE #

SD 19763

Vehicle Make/Model/Colour :

Audi A5 / Black

Vehicle Registration Number :

SFV 8092 U

TERM: Nets / Cash / Credit

ADD: 7 Soon Lee Street #01-26 ISPACE Singapore 627608 | T:+65 866807560 | E:info@Sdsolutions.com.sg

Vic (LKKAuto)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Wednesday, 15 January, 2020 6:47 PM
To: Adrian Ling (LKKAuto); CS A Team; Admin A; Vic (LKKAuto); Carrine Leong; jlayee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: FINAL REVISION - SFV8092U - TP AIG - SURVEYED 8 OCT 19
Attachments: OWNER INVOICE - SFV8092U.pdf; PA12042019 - SFV 8092 U - Audi A5 COUPE 2.0 TFSI - REAR - TP (AIG).xls; WhatsApp Image 2019-10-10 at 4.55.42 PM (resize).jpeg; WhatsApp Image 2019-10-10 at 4.55.43 PM (3) (resize).jpeg; WhatsApp Image 2019-10-10 at 4.55.43 PM (1) (resize).jpeg; WhatsApp Image 2019-10-10 at 4.55.43 PM (resize).jpeg; WhatsApp Image 2019-10-10 at 4.55.43 PM (2) (resize).jpeg; WhatsApp Image 2019-10-10 at 4.56.58 PM (resize).jpeg; WhatsApp Image 2019-10-10 at 4.55.36 PM (resize).jpeg; WhatsApp Image 2019-10-10 at 4.55.41 PM (resize).jpeg; WhatsApp Image 2019-10-10 at 4.55.40 PM (resize).jpeg; WhatsApp Image 2019-10-10 at 4.12.51 PM (resize).jpeg; WhatsApp Image 2019-10-10 at 4.55.42 PM (1) (resize).jpeg; WhatsApp Image 2019-10-10 at 4.55.42 PM (2) (resize).jpeg; WhatsApp Image 2019-10-10 at 4.55.42 PM (3) (resize).jpeg; WhatsApp Image 2019-10-11 at 4.25.12 PM (1) (resize).jpeg; WhatsApp Image 2019-10-10 at 5.25.38 PM (resize).jpeg; WhatsApp Image 2019-10-11 at 4.25.13 PM (1) (resize).jpeg; WhatsApp Image 2019-10-11 at 4.25.12 PM (resize).jpeg; WhatsApp Image 2019-10-11 at 4.25.14 PM (1) (resize).jpeg; WhatsApp Image 2019-10-11 at 4.25.14 PM (resize).jpeg; WhatsApp Image 2019-10-11 at 4.25.13 PM (resize).jpeg; WhatsApp Image 2019-10-10 at 4.56.59 PM (resize).jpeg; WhatsApp Image 2019-10-10 at 4.57.00 PM (resize).jpeg; WhatsApp Image 2019-10-10 at 5.08.16 PM (resize).jpeg; WhatsApp Image 2019-10-10 at 5.08.14 PM (resize).jpeg; WhatsApp Image 2019-10-10 at 5.08.17 PM (resize).jpeg

Hi Adrian and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$11,995.76 @ 8 days exclude 1 Sunday.

Your early closure is well appreciated.

Best regards - jb

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Policy No. : 1900016808
Period of Insurance : 25 Feb 2019 to 24 Feb 2020

Endorsement No. : 000000000263266
Issued Date : 07 Mar 2019

ABOUT THE POLICYHOLDER

Name of Policyholder : ONG KOK KIONG
Address : 33A WEST COAST PARK
01-41
SINGAPORE 127727
Occupation/Nature of Business : Doctor/Lawyer/Dentist/Judge

ABOUT THE VEHICLE

Registration No. : SFV8092U	Engine Capacity/Tonnage : 1,984.00 CC
Chassis No. : WAUZZZF57KA026822	Engine No. : CVK 076379
Seating Capacity : 4	First Year of Registration : 2019
Make/Model : AUDI A5 Coupe 2.0 TFSI S tronic (Design)	Body Type : Coupe
Hire Purchase Company/Employer's Loan : DBS BANK LTD	

ABOUT THE COVER

Sum Insured : Market Value	Off Peak Car	No
Driver Restriction : NA	Insuring with COE/PARF	Yes
Person or Classes of Persons Entitled to Drive :		

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

*You have to pay an additional sum of \$1,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 21 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use :

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Other Key Policy Benefits :

Act of God, Stroke, Riots and Civil Commotions, PA to Authorized Driver / Unnamed Passengers- \$10000, Dealer + AIG Authorized Workshops, PA Insured- \$100000, Features and Accessories (Cosmetic)- \$5000, Solar Film- \$1150, New For Old (36 months), Loss of Use 18000cc - 20000cc Optional, In-Car Camera Excess Waiver, Glass Roof/Moon Roof/ Sun Roof/Panoramic Glass Roof, NCO

ENDORSEMENT REMARK

- 1) Driver Details : Update Claims Details
- 2) NCD Details : Update NCD on Policy with AIG

Declared Previous Insurer: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Declared NCD: 50%

Verified NCD: 50%

With the update in Claims/NCD details, premium and/or excess are revised. Refer to details stated above.
Based on the updated NCD, Safe Driver Discount and/or No Claim Discount Protector is/are revised accordingly.

Endorsement effective from:25-Feb-2019. All other terms and conditions remain unchanged.

Summer Lee (LKK Auto)

From: Claims <claims@premiumauto.com.sg>
Sent: Monday, 7 October, 2019 2:33 PM
To: 'Admin-D (LKKAuto)'; 'Admin A'; 'SUR'
Cc: 'Claims'
Subject: ACCIDENT BETWEEN SFV 8092 U AND YOUR INSURED SKS 2486 M ON 6/10/2019
Attachments: SFV 8092 U - 06102019.PDF

Dear all,

Kindly assist in the liability clearance for above mentioned case. We propose for a 100% direct settlement in our client's favour

Please advise who is the officer in-charge we shall liaise with. To avoid dispute during finalisation, we propose for LOU/R at \$100/180 per day.

Attached is the GIA report for your reference and we will send you the estimate once it is ready.

Kindly arrange survey on 8/10/2019, 10AM. Vehicle is in our compound.

Best Regards,
Syafiq
Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

Print Received Message

This mail is associated with :

***SFV8092U (8439087173SG)
[SKS2486M]**

TP

ONG KOK KIONG

Oct 6 2019 9:00PM

[LOW HWEE HWA]

Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 04/03/2020 09:22 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$13892.91) - SFV8092U - Claim Handler: Ler, Bernard-JQ

Approved:13892.91:Cost of Repair : \$12,835.46 As per surveyor finalization Loss of Rental : \$1,050.00 7 days @
S\$ 150/day LTA/ GIA Search Fee : \$7.45 Total : \$13,892.91

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Policy No. : 1900016808
 Period of Insurance : 25 Feb 2019 to 24 Feb 2020

Endorsement No. : 000000000263266
 Issued Date : 07 Mar 2019

ABOUT THE POLICYHOLDER

Name of Policyholder : ONG KOK KIONG
 Address : 33A WEST COAST PARK
 01-41
 SINGAPORE 127727
 Occupation/Nature of Business : Doctor/Lawyer/Dentist/Judge

ABOUT THE VEHICLE

Registration No. : SFV8092U
 Chassis No. : WAUZZZF57KA026822
 Seating Capacity : 4
 Make/Model : AUDI A5 Coupe 2.0 TFSI S tronic (Design)
 Hire Purchase Company/Employer's Loan : DBS BANK LTD

Engine Capacity/Tonnage : 1,984.00 CC
 Engine No. : CVK 076379
 Body Type : Coupe

First Year of Registration : 2019

ABOUT THE COVER

Sum Insured : Market Value
 Driver Restriction : NA
 Person or Classes of Persons Entitled to Drive :

Off Peak Car : No
 Insuring with COE/PAF : Yes

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Other Key Policy Benefits :

Act of God, Strike, Riots and Civil Commotions, PA to Authorised Driver / Unnamed Passengers- \$10000, Dealer + AIG Authorised Workshops, PA Insured- \$100000, Fixture and Accessories (Casualty)- \$5000, Solar Film- \$1150, New For Old (36 months), Loss of Use- 180000 - 200000 Optional, In-Car Camera Excess Waiver, Glass Roof/ Moon Roof/ Sun Roof/ Panoramic Glass Roof, NCD Protection

ENDORSEMENT REMARK

- 1) Driver Details : Update Claims Details
- 2) NCD Details : Update NCD on Policy with AIG

Declared Previous Insurer: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Declared NCD: 50%

Verified NCD: 50%

With the update in Claims/NCD details, premium and/or excess are revised. Refer to details stated above.

Based on the updated NCD, Safe Driver Discount and/or No Claim Discount Protector is/are revised accordingly.

Endorsement effective from: 25-Feb-2019. All other terms and conditions remain unchanged.

BREAKDOWN OF PAYMENT

Vehicle No: SFV 8092 U
Accident on 6/10/2019 at A/E Towards Tuas Praction.
Involving vehicle/s Sks 2486 M.

1) Repair cost \$ 12,835.46 Payable to: Premium Automobiles Pte Ltd

2) GIA/LTA search fee \$ 7.45 Payable to: Premium Automobiles Pte Ltd

3) Loss of Use or Rental Car \$ 1,050.00 Payable to: ong kok kiong

4) Medical fees \$ _____ Payable to: _____

5) Others \$ _____ Payable to: _____

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.
SMD8133Y

Make / Model
SUBARU / XV 2.0I-S EYESIGHT AWD CVT

Vehicle Type :
R11 - Private Hire (Self-Drive) Station Wagon/Jeep/Land Rover

Vehicle Attachment 1 :
No Attachment

Vehicle Scheme :
Normal

Chassis No. :
JF1GT7KL5JG032911

Propellant :
Petrol

Engine No. :
FB20YC96846

Motor No. :
-

Engine Capacity :
1995 cc

Power Rating :
-

Maximum Power Output :
115.0 kW (154 bhp)

Maximum Laden Weight :

1940 kg

Unladen Weight :

1489 kg

Year Of Manufacture :

2018

Original Registration Date :

06 Sep 2018

Lifespan Expiry Date :

-

COE Category :

B - Car above 1600cc or 97kW (130bhp)

Quota Premium :

\$34,381.00

COE Expiry Date :

05 Sep 2028

Road Tax Expiry Date :

05 Mar 2020

PARF Eligibility Expiry Date :

05 Sep 2028

Inspection Due Date :

05 Sep 2021

Intended Transfer Date :

12 Feb 2020

CO2 Emission :

159.00 (g/km)

CEV/VES Rebate Utilised Amount :

-

CO Emission :

0.160590 (g/km)

HC Emission :

0.022240 (g/km)

NOx Emission :

0.012720 (g/km)

PM Emission :

0.150000 (mg/km)

Fees To Be Paid For Transfer

Transfer Fees	\$25.00
Road Tax Renewal - 6 months (06 Mar 2020 to 05 Sep 2020)	\$604.00
Road Tax Renewal - 12 months (06 Mar 2020 to 05 Mar 2021)	\$1,208.00

Message

The fees above do not include any late road tax fees, which apply if road tax or lay-up has expired. You can use the digital service Enquire Road Tax Payable to check if there are any late road tax fees. Any road tax that has been paid for the vehicle will be transferred to the next owner.

Print

OK →

Save as PDF

Copy as Text

RELEASE VOUCHER
(AIG Express Third Party Claim)

We/I, Premium Automobiles Pte Ltd. ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$12,835.96 (Repair Cost), S\$ 1050.00 (Loss of rental/use), S\$ (Disbursement), for vehicle no. SFV 8092 U that was damaged pursuant to the accident which occurred on 6/10/2019 (date) along Air Towards Tuas direction. (location) involving vehicle no/s SLS 2486 M. This is pursuant to the inspection conducted on _____ (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner ong kok kong ("the third party claimant") of vehicle no. SFV 8092 U make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to _____ (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 7 (day) of Feb (month) 2020 (year)

Signed by appointed surveyor



Signed by "the workshop" (with chop)

Premium Automobiles Pte Ltd

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKS 2486 M

Nora Khai From
6768 9828 Telephone +65
6841 1183 Telefax +65
claims@premiumauto.com.sg Email
Body & Paint Dept Our Dept
PA/TP/1204/2019/NH

4th March 2020 Date

Dear Sir/Mdm,

RE: INSURANCE SETTLEMENT OF SFV 8092 U – Audi A5 COUPE 2.0 TFSI

The above matter refers.

Enclose, kindly find a copy of the Final Discharge Voucher duly signed by our client for the settlement of his claim.

We look forward to receiving your cheque soonest possible.

Regards

This is a computer-generated document. No signature is required.

Claims Dept

Encls

Premium Automobiles Pte
Ltd, Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Oct 2019 Edit Reg		08 Oct 2019 00:00 Edit Adj Rpt	\$11,995.76 Edit Estimates	\$11,995.76 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LOW HWEE HWA, ID: S1553724H								
Main Claimant:	ONG KOK KIONG, ID: S6980498E								
Vehicle Reg. No.:	SFV8092U	Date of Loss:	06/10/2019 21:00 - :59 [7 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8439087173SG	Policy/Cover Note No.:	2100409722 (Comprehensive) Coverage: 31/03/2019 - 30/03/2020						
Vehicle Reg. No. (Insured):	SKS2486M	Policy No. (Claimant):	1900016808						
		Excess:							
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 16/10/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG_EXPRESS (04/03/2020): Alert - Adj Mandate Approved (\$13892.91) - SFV8092U - Claim Handler: Ler, Berna...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFV8092U (8439087173SG)
[SKS2486M]

TP

ONG KOK KIONG

Oct 6 2019 9:00PM

[LOW HWEE HWA]

Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Videos			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		☒			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown															Edit			
Photos/Images															3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	22/01/20 12:46	General View															Load JPG ☒			
2	22/01/20 12:46	General View															Load JPG ☒			
3	22/01/20 12:46	General View															Load JPG ☒			
4	22/01/20 12:46	General View															Load JPG ☒			
5	22/01/20 12:46	General View															Load JPG ☒			
6	22/01/20 12:46	General View															Load JPG ☒			
7	22/01/20 12:46	General View															Load JPG ☒			
8	22/01/20 12:46	General View															Load JPG ☒			
9	22/01/20 12:46	General View															Load JPG ☒			
10	22/01/20 12:46	General View															Load JPG ☒			
11	22/01/20 12:46	General View															Load JPG ☒			
12	22/01/20 12:46	General View															Load JPG ☒			
13	22/01/20 12:46	General View															Load JPG ☒			
14	22/01/20 12:46	General View															Load JPG ☒			
15	22/01/20 12:46	General View															Load JPG ☒			
16	22/01/20 12:46	General View															Load JPG ☒			
17	22/01/20 12:46	General View															Load JPG ☒			
18	22/01/20 12:46	General View															Load JPG ☒			
19	22/01/20 12:46	General View															Load JPG ☒			
20	22/01/20 12:46	General View															Load JPG ☒			
21	22/01/20 12:46	General View															Load JPG ☒			
22	22/01/20 12:46	General View															Load JPG ☒			
23	22/01/20 12:46	General View															Load JPG ☒			
24	22/01/20 12:47	Reinspection Photo															Load JPG ☒			
25	22/01/20 12:47	Reinspection Photo															Load JPG ☒			
26	22/01/20 12:47	Reinspection Photo															Load JPG ☒			
27	22/01/20 12:47	Reinspection Photo															Load JPG ☒			
28	22/01/20 12:47	Reinspection Photo															Load JPG ☒			
29	22/01/20 12:47	Reinspection Photo															Load JPG ☒			
30	22/01/20 12:47	Reinspection Photo															Load JPG ☒			
31	22/01/20 12:47	Reinspection Photo															Load JPG ☒			
32	22/01/20 12:47	Reinspection Photo															Load JPG ☒			
33	22/01/20 12:47	Reinspection Photo															Load JPG ☒			
34	22/01/20 12:47	Reinspection Photo															Load JPG ☒			
35	22/01/20 12:47	Reinspection Photo															Load JPG ☒			
36	22/01/20 12:47	Reinspection Photo															Load JPG ☒			
37	22/01/20 12:47	Reinspection Photo															Load JPG ☒			
38	22/01/20 12:47	Reinspection Photo															Load JPG ☒			
39	22/01/20 12:47	Reinspection Photo															Load JPG ☒			
40	22/01/20 12:47	Reinspection Photo															Load JPG ☒			

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
					☒
41	22/01/20 12:47	Reinspection Photo		Load JPG	☒
42	22/01/20 12:47	Reinspection Photo		Load JPG	☒
43	22/01/20 12:47	Reinspection Photo		Load JPG	☒
44	22/01/20 12:47	Reinspection Photo		Load JPG	☒
45	22/01/20 12:47	Reinspection Photo		Load JPG	☒
46	22/01/20 12:47	Reinspection Photo		Load JPG	☒
47	22/01/20 12:47	Reinspection Photo		Load JPG	☒
48	22/01/20 12:47	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/10/19 15:54	TP GIA REPORT		Load PDF	
2	08/10/19 11:45	TP ESTIMATE - MARKED		Load PDF	
3	09/10/19 16:41	EMAIL TO OI		Load PDF	
4	12/02/20 17:02	RENTAL RECEIPT		Load PDF	
5	12/02/20 17:02	LTA SEARCH		Load PDF	
6	12/02/20 17:02	LOD		Load PDF	
7	04/03/20 11:13	EMAIL FROM TP		Load PDF	
8	05/03/20 08:58	WORKSHOP INVOICE		Load PDF	
9	05/03/20 08:58	AUTHORISATION TO ACT FORM		Load PDF	
10	05/03/20 08:58	Release Voucher		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	08/10/19 14:16	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKS2486M (Insd veh)	Model:	AUDI A5 2.0 (A)
	SFV8092U (TP veh)		
Date of Accident:	06/10/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	31,750.11
Final Repair Cost	:	\$	12,835.46
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	1,050.00 7 days
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	13,892.91

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: 27

BOLA Liability: 100_____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Premium Automobiles Pte Ltd	:	\$ 13,892.91
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

05 Mar
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19017609/AHA3Q2

Date: 05/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100409722
 Claimant: SFV8092U Insured Vehicle No: SKS2486M
 Vehicle No: SFV8092U
 Date of Loss: 06/10/2019 Nature of Claim: TP Claim No: 8439087173SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFV8092U
 Make & Model: AUDI A5, 2.0 (A) Engine No: CVK076379
 Reg. Date: 25/02/2019 (Man. Year: 2019) Chassis No: WAUZZZF57KA026822
 Colour: Black Odometer: 7146 km
 Engine Capacity: 1984 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 255/35 R19 Rear Tyre Size: 255/35 R19
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,531.00	6,033.76	9,497.24	61.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,142.00	5,962.00	8,180.00	57.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	29,673.00	11,995.76	17,677.24	59.57
+ GST 7.00/7.00% (S\$)	2,077.11	839.70	1,237.41	59.57
Nett Amount (S\$)	31,750.11	12,835.46	18,914.65	59.57
+ Car Rental (7.0 x S\$150.00/day) (S\$)		1,050.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		13,892.91		

INSPECTION

Date of Assignment: 08/10/2019
 Date Inspected: 08/10/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
 55 Ubi Road 1
 Singapore 408699
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,311.00 FS	*1,848.80 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	150.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Necessary	203.00 FS	*162.40 FS
4	1		*REAR BUMPER TRIM	Cracked	928.00 FS	*742.40 FS
5	1		*REAR LIGHT REFLECTOR -LH	Cracked	38.00 FS	*29.68 FS
6	1		*REAR BUMPER CARRIER	Bent	819.00 FS	*655.20 FS
7	2		*REAR BUMPER SEAL	Not Necessary	25.00 FS	*- FS
8	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	80.00 FS	*- FS
9	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	40.00 FS	*- FS
10	1		*AERIAL RETAINER -LH	Not Necessary	23.00 FS	*- FS
11	1		*TELEPHONE AERIAL	Not Necessary	164.00 FS	*- FS
12	2		*REAR PARKING SENSOR -INNER /OUTER	Not Necessary	462.00 FS	*- FS
13	4		*REAR PARKING AID SEAL RING	Not Necessary	12.00 FS	*- FS
14	1		*SET REAR BUMPER WIRING	Not Necessary	618.00 FS	*- FS
15	1		*BOOT LID CONTROL UNIT	Cracked	381.00 FS	*307.20 FS
16	1		*REAR LID	Dented	2,449.00 FS	*1,959.20 FS
17	2		*REAR LID HINGE -LH/RH	Not Necessary	762.00 FS	*- FS
18	1		*REAR LID ATTACHMENT PARTS	Not Necessary	154.00 FS	*- FS
19	1		*REAR LID LOCK	Not Necessary	210.00 FS	*- FS
20	1		*LID LOCK PUSH BUTTON	Not Necessary	1,230.00 FS	*- FS
21	1		*REAR LID LOCK STRIKER	Not Necessary	30.00 FS	*- FS
22	1		*REAR LID ANTI THEFT GUARD COVER -INNER	Not Necessary	58.00 FS	*- FS
23	2		*REAR LID FLAP GASKET	Not Necessary	207.00 FS	*- FS
24	2		*PACKING ADHESIVE	Necessary	18.00 FS	*13.92 FS
25	4		*AUDI EMBLEM	Necessary	127.00 FS	*101.60 FS
26	1		*A5 INSCRIPTION	Necessary	87.00 FS	*69.28 FS
27	3		*REAR CROSS PANEL	Repair	329.00 FS	*- FS
28	6		*CROSS PANEL REINFORCEMENT	Repair	577.00 FS	*- FS
29	2		*LED LICENCE PLATE LIGHT	Not Necessary	92.00 FS	*- FS
30	1		*LED TAIL LIGHT -LH	Not Necessary	931.00 FS	*- FS
31	1		*TAIL LIGHT TRIM -LH	Not Necessary	27.00 FS	*- FS
32	1		*SET EXHAUST TAILPIPES TRIM	Cut	153.00 FS	*122.40 FS
33	1		*REAR SILENCER -LH	Not Necessary	813.00 FS	*- FS
34	1		*REAR SILENCER DUAL CLIP	Not Necessary	45.00 FS	*- FS
35	1		*EXHAUST SILENCER BRACKET	Not Necessary	38.00 FS	*- FS
36	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
37	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
38	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
39	1		*REAR NO PLATE	Not Necessary	40.00 FS	*- FS
40	1		*SUNDRIES	Necessary	400.00 FS	*21.68 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 15,531.00 6,033.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR .CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS ,BATTERY MANAGER ,FUSE AND RELAY TRAYS ,ELECTRICAL AND AUDIO COMPONENTS	New	480.00	480.00
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID .TO REPAIR LHS REAR FENDER .TO CUT OUT AND REWELD END PANELLING .RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	5,200.00	1,500.00
4	TO RESPRAY REAR BUMPER ,REAR LID ,LHS REAR FENDER ,END PANELLING ,AND SPARE WHEEL HOUSING	New	4,900.00	1,650.00
5	TO REMOVE AND RENEW LHS REAR EXHAUST SILENCER ,TO ALIGN TO POSITION	New	480.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
7	TO DEAPPLY PAINT PROTECTION FILM FOR REAR BUMPER ,REAR BOOT AND REAR FENDER	New	2,530.00	1,500.00
Gross Labour Cost (S\$)			14,142.00	5,962.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >