

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

4-Oct-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8933 A

1 pc	Front bumper emblem	— <i>rec</i>	\$ 44.00
1 pc	Front bumper	— <i>CRG</i>	\$ 531.00
1 pc	Front bumper sponge	X <i>su</i>	\$ 110.00
1 pc	Front bumper reinforcement	X <i>su</i>	\$ 328.00
1 pc	Front bumper n/s fog lamp cover	X <i>su</i>	\$ 66.00
1 pc	Front bumper n/s protector	X <i>su</i>	\$ 51.00
1 pc	Front n/s fender inner shield	X <i>su</i>	\$ 120.00
1 pc	n/s headlamp	— <i>cut</i>	\$ 1,028.00
1 pc	Front bumper n/s side retainer	— <i>CRG</i>	\$ 16.00
1 pc	Bonnet grille	X <i>su</i>	\$ 386.00
1 pc	Front n/s fender	— <i>Painted</i>	\$ 384.00
1 pc	Front n/s wheel cover	X <i>su</i>	\$ 116.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00	X <i>su</i>	\$ 32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00	X <i>su</i>	\$ 32.00
1 pc	Front bumper centre grille	X <i>su</i>	\$ 174.00
1 pc	Front bumper lower stiffer	X <i>su</i>	\$ 134.00
1 pc	Front bumper lip	X <i>su</i>	\$ 52.00
1 pc	Front bumper inner sponge	X <i>su</i>	\$ 110.00
1 pc	Front bumper reinforcement	X <i>su</i>	\$ 328.00
			<u>\$ 4,042.00</u>
Less 10%			\$ 404.20
			<u>\$ 3,637.80</u>

S/NETT

1 pc	Front bumper clips	— <i>rec</i>	\$ 48.00
1 pc	Front n/s fender sticker	X <i>su</i>	\$ 30.00
1 set	Front n/s fender inner shield clips	X <i>su</i>	\$ 28.00
Sundry			\$ 50.00 <i>20</i>
To check front n/s wheel alignment			\$ 80.00 <i>X su</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.			\$ 180.00 <i>X su</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same bonnet, front n/s chassis, front n/s fender			\$ 750.00 <i>400</i>
To putty and spray painting on front bumper, front n/s fender, bonnet			\$ 600.00 <i>360</i>

To apply rustproofing on the repaired and replaced panels.

\$ 120.00 50
\$ 5,523.80

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Kalin May

✓ 4/10/19 1020h

3 Days

4/5

After Repair photo

10/10/19
cal 4/5 \$2100/3 Days

L&K Auto Consultants hence notify
the Rep/Owner of the following:

- The necessary before/after spray painting
- The necessary damaged parts during resurvey
- The necessary parts subject to confirmation
- The quality survey without "Without Prejudice" basis
- No illegal motor vehicle is allowed
- Supplemental work by the Insured and Company is subject to their equipment, a standard Company

Acknowledged by Insurer
Signature:
Date: