

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

4-Oct-19

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8933 A

1 pc	Front bumper emblem ✓	\$	44.00
1 pc	Front bumper ✓	\$	531.00
1 pc	Front bumper sponge ✕	\$	110.00
1 pc	Front bumper reinforcement ✕	\$	328.00
1 pc	Front bumper n/s fog lamp cover ✕	\$	66.00
1 pc	Front bumper n/s protector ✕	\$	51.00
1 pc	Front n/s fender inner shield ✕	\$	120.00
1 pc	n/s headlamp ✓	\$	1,028.00
1 pc	Front bumper n/s side retainer ✓	\$	16.00
1 pc	Bonnet grille ✕	\$	386.00
1 pc	Front n/s fender ✓	\$	384.00
1 pc	Front n/s wheel cover ✕	\$	116.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 ✕	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00 ✕	\$	32.00
1 pc	Front bumper centre grille ✕	\$	174.00
1 pc	Front bumper lower stiffer ✕	\$	134.00
1 pc	Front bumper lip ✕	\$	52.00
1 pc	Front bumper inner sponge ✕	\$	110.00
1 pc	Front bumper reinforcement ✕	\$	328.00
		\$	4,042.00
Less 10%		\$	404.20
		\$	3,637.80

### S/NETT

1 pc	Front bumper clips ✓	\$	48.00
1 pc	Front n/s fender sticker ✕	\$	30.00
1 set	Front n/s fender inner shield clips ✕	\$	28.00
Sundry		\$	<del>50.00</del> 20
To check front n/s wheel alignment		\$	<del>80.00</del> ✕
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	<del>180.00</del> ✕
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same bonnet, front n/s chassis, front n/s fender		\$	<del>750.00</del> 400
To putty and spray painting on front bumper, front n/s fender, bonnet ✕		\$	<del>600.00</del> 360

To apply rustproofing on the repaired and replaced panels.

\$ ~~120.00~~ 50  
\$ 5,523.80

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.**

Kalin May

✓ 4/10/19 1020h

3 Apr.

4/5

After Repair photo.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental work must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by repairer  
Signature:  
Date: