

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

WDD1760422J425853

HE WENWEN

BLK 317B ANCHORVALE RD

#14-232

S 542317

TP FWD
Xiao Tony

Date

:09.10.2019

Vehicle No

:SMJ 826 C

Make/Model

:MERCEDES A180

Accident date

:03.10.2019

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Front bumper <i>torn</i>	1	\$ 1298 ✓
2	Front bumper side holder @ \$ 66.00 <i>14 new</i>	2	\$ 132 66
3	Front bumper sensor @ \$ 313.50 <i>1 piece damaged</i>	2	\$ 627 313.50
4	Front bumper LH side lower grille <i>new</i>	1	\$ 57.2 x
5	Front bumper clips (1set) <i>new</i>	1	\$ 66 30
6	Front LH headlamp <i>at</i>	1	\$ 1534 ✓
7	Front LH fender <i>Repair</i>	1	\$ 726 x
8	Front LH fender inner shield	1	\$ 165 +
9	Front LH fender inner shield clips (1 set)	1	\$ 66 +
10	Front bumper lower centre grille <i>new</i>	1	\$ 357.5 +
11	Front LH headlamp top rubber	1	\$ 26.4 +
			\$ 4483.6
			Less 10% Disc
			\$ 448.36
			Total
			\$ 4035.24

3241.5
2917.35

Labour Cost

- 1 Remove & reinstall sensor
- 2 Remove ,replace & repair consistent to the accident
- 3 Respray painting

860
\$ 150 60
\$ 1200 300
\$ 1000 500

Total

\$ 2350

Grand Total

\$ 6385.24

KKK Auto Consultants hence notify the Repaire of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repaire

Signature:

Date:

total. 3777.35
h/s: 3K

032mp

3K