

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SMD3639M/1910131

07th October 2019

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not added
not
The photo before repair
4 days
11/10/19

Date of Accident : 04th October 2019
Location : Blk 53 Sims Place Carpark
Third Party Claim Vehicle No : GBC 9197 S
Repair Cost For Vehicle No : SMD 3639 M Toyota Vellfire

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Front bumper fascia <i>DD/ae</i>	1	1,380.00	\$ 1,380.00
2	Front bumper clips <i>nae</i>	1set	85.00	\$ 85.00
3	Front bumper retainer RH	1	105.60	\$ 105.60 ?
4	Front bumper grille RH	1	980.40	\$ 980.40 ?
5	Headlamp assy RH <i>holder one</i>	1	4,198.90	\$ 4,198.90 ?
6	Front fender RH <i>n</i>	1	680.60	\$ 680.60 X
7	Headlamp garnish RH	1	129.70	\$ 129.70 ?
8	Headlamp panel RH <i>n</i>	1	313.60	\$ 313.60 X
9	Coolant (s/nett) <i>11</i>	1tin	28.00	\$ 28.00 X
				\$ 7,901.80

Labour Charges :-

	Amounts
Cut out, renew, knocking & welding headlamp panel RH, top support panel, front fender RH, front bumper support bracket, remove & install all damage parts, straighten & re-align body	\$ 850.00 <i>450</i>
Remove & refix air-con system, vacuum & top-up gas	<i>11</i> \$ 120.00 X
Spray painting on damage parts	\$ 1,200.00 <i>680</i>
Remove & refix radiator assy, engine cooling fan & motor assy all damage parts	<i>11</i> \$ 150.00 X
Check all lighting & focus headlamp after repairs	\$ 65.00 <i>20</i>
Labour Charge	\$ 2,930.00
Total Amount	\$10,530.00

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.