



Case Details

Case Reference Number : TAX/10/19/2008
Type of Repair : Accident Repair
Vehicle Registration Number : SHB5344U

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-8745-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : India International Insurance Pte Ltd
Accident Date and Time : 02/10/2019 11:15 AM
Vehicle Age(In Months) : 23

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check	X NM
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	0.00	Replace	/ DD
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Not Give	X NM
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Not Give	X NM
One Time Key In	Main			SEAL, RR BUMPER , RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	X NM
One Time Key In	Main			SEAL, RR BUMPER , LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	X NM
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	0.00	Replace	/ n/c
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.73	Replace	1	0.00	Replace	/ cut
One Time Key In	Main			FILLER, RR BUMPER , RH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Give	X NM
One Time Key In	Main			FILLER, RR BUMPER , LH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Give	X NM
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	1	0.00	Replace	/ cut
One Time Key In	Main			LENS & BODY ASSY , RR BUMPER , LH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Give	X NM
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	0.00	Replace	/ n/c

Total Spare Part Cost 2,754.24

Lump Sum Discount (%) 0.00

Final Spare Part Cost 2,754.24

Surveyor Total 0.00

Lump Sum Dis (%) 0

Final Sur Total 0.00

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	929.60	25.00	697.20	Replace	0	0	Not Give	X NM
One Time Key In	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	0	0	Not Give	X NM
Total Spare Part Cost									2,754.24	Surveyor Total 0.00				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									2,754.24	Final Sur Total 0.00				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	507.00	250	
2	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0	
3	Main	TO TRANSFER DOOR MECHANISM	120.00	0	
Total:			867.00	250.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY TAIL GATE	378.00	200	
2	Main	TO RESPRAY REAR BUMPER	378.00	200	
3	Main	TO RESPRAY BUMPER BEAM	180.00	0	
Total:			936.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
2	Main	TO REPLACE SUNDRY PARTS	100.00	20	AK
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	AK
4	Main	TO WASH AND VACUUM	60.00	0	
Total:			360.00	40.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,754.24	0.00
Total Labour Cost	867.00	250.00
Total Spray Painting	936.00	400.00
Other	360.00	40.00
Overall Total	4,917.24	690.00
Lump Sum Repair Option		
Lump Sum Total	0.00	690.00
Surveyor Approved Amount		690.00
No of Repair Days*	5	3
Remarks	-	P/P, take before spray.
Surveyor Name		STEVE CHEN
Signature		
Survey Date	04/10/2019	Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: