

Section A - Accident Details

Registration Number	SHB5344U
Case Reference Number	TAX/10/19/2008
Registration Date	30/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	CHENG ING CHUE @LIM THIAM SENG
Type of Accident	Head to Rear
Accident Date and Time	2/10/2019 7:15 PM
Accident Reported Date and Time	3/10/2019 11:57 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24103656
Special Instruction to ARC, if any	TP/III
Prepared Date and Time	3/10/2019 6:49 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$867.00	\$250.00
Total Spray Cost	\$936.00	\$400.00
Total Spare Part Cost	\$3,173.34	\$1,298.11
Total Other Cost	\$360.00	\$40.00
TOTAL COST	\$5,336.34	\$1,988.11 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	STEVE CHEN (LKK) / III
ARC / Surveyor Sign Off Date	08/10/2019 8:49 AM	08/10/2019 11:13 AM
Signature		
Remarks	Total number of repair days = 3 days. SUP = 0 day.	P/P, take before spray.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1910-0307	Invoice Number	
Quotation Date	16.10.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$507.00	\$250.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
Total Labour	\$867.00	\$250.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$936.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$360.00	\$40.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5202347030	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check X
		5215947913	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace X
		5257547040	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given X
		5257647040	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given X
		5259147050	SEAL, RR BUMPER, RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given X
		5259247040	SEAL, RR BUMPER, LH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given X
		5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace X
		5245347010	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace X
		5256547900	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given X
		5256647900	FILLER, RR BUMPER, LH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given X
		5216947020	COVER, GUARD RR BUMPER LOWER	1.00	\$14.80	25.00	\$11.10	Replace	Replace X
		8159147010	LENS & BODY ASSY, RR BUMPER, LH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given X
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace X

		67005474 40	TAIL GATE PANEL SUB- ASSY, BACK DOOR	0.00	\$929.60	0.00	\$0.00	Replace	Not Given X
			NUMBER PLATE FRAME	0.00	\$25.00	0.00	\$0.00	Replace	Not Given X
Total					\$3,453.10		\$879.01		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023470 30	REAR BUMPER REINFORCEMENT	1.00	\$318.80	25.00	\$239.10	Replace	Replace ✓
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace ✓
Total					498.80		419.10		

1298.11
+ 250.00
+ 440.00

1988.11



Case Details

Case Reference Number : TAX/10/19/2008
Type of Repair : Accident Repair
Vehicle Registration Number : SHB5344U

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-8745-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : India International Insurance Pte Ltd
Accident Date and Time : 02/10/2019 11:15 AM
Vehicle Age(In Months) : 23

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check	X N/A
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.93 0.00	Replace	/ 00
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Not Give	X N/A
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Not Give	X N/A
One Time Key In	Main			SEAL, RR BUMPER, RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	X N/A
One Time Key In	Main			SEAL, RR BUMPER, LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	X N/A
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25 0.00	Replace	/ n/c
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.73	Replace	1	418.73 0.00	Replace	/ CUT
One Time Key In	Main			FILLER, RR BUMPER, RH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Give	X N/A
One Time Key In	Main			FILLER, RR BUMPER, LH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Give	X N/A
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	1	11.10 0.00	Replace	/ CUT
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Give	X N/A
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00 0.00	Replace	/ n/c
									Total Spare Part Cost	2,754.24	Surveyor Total 0.00			
									Lump Sum Discount (%)	0.00	Lump Sum Dis (%) 0			
									Final Spare Part Cost	2,754.24	Final Sur Total 0.00			

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	929.60	25.00	697.20	Replace	0	0	Not Give	X N/A
One Time Key In	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	0	0	Not Give	X N/A
Total Spare Part Cost									2,754.24	Surveyor Total 0.00				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									2,754.24	Final Sur Total 0.00				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	507.00	250	
2	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0	
3	Main	TO TRANSFER DOOR MECHANISM	120.00	0	
Total:			867.00	250.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY TAIL GATE	378.00	200	
2	Main	TO RESPRAY REAR BUMPER	378.00	200	
3	Main	TO RESPRAY BUMPER BEAM	180.00	0	
Total:			936.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
2	Main	TO REPLACE SUNDRY PARTS	100.00	20	AK
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	AK
4	Main	TO WASH AND VACUUM	60.00	0	
Total:			360.00	40.00	

Summary

	Estimator Assessment(\$)
Total Spare Part Detail	2,754.24
Total Labour Cost	867.00
Total Spray Painting	936.00
Other	360.00
Overall Total	4,917.24
Lump Sum Repair Option	
Lump Sum Total	0.00
Surveyor Approved Amount	
No of Repair Days*	5
Remarks	
Surveyor Name	
Signature	
Survey Date	04/10/2019

Surveyor Assessment(\$)

0.00

250.00

400.00

40.00

690.00

690.00

690.00

3

P/P, take before spray.

STEVE CHEN



Save

Clear

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REQUEST FOR SUPPLYMENT PARTS

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	704 / 10 / 19 / 3008	Date of Collection	5 / 10 / 19
Vehicle No	SHB 5344 U	Date of Request	7 / 10 / 19
Vehicle Model	20107A PRIUS 4	Number of Days to Extend (if any)	1 DAY - 0


Part Number	Part Description	Quantity	Unit Price
2324, 25, 26, 28	Rear Bumper Reinforcement		41818.80 /
2324, 80, 81, 82	Reverse Sensor		4180.00 /

00 \$239.10
Start

Please submit photographs for damaged parts

By Name: CHIA Steve (LKK) Date: 7/10/19, 6:42 pm

I do solemnly and sincerely declare that: Supplementary Parts are raised for replacement for the aforesaid vehicle.


 Signature of person making this declaration
 [To be signed in front of an authorized witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / P1 / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission