

DED:

C8/MS419017635/ Av d3n2

Date/Time:

Turnover: Adnan

Merimen

ASSIGNMENT (Office)

From (Person): Revel Foo

of

MS19

Date/Time: 7/10/19 @ 4:50pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJT 8768S

Insured:

SLN 3069S

at Workshop n/s

SM Automotive

Tel:

6747 9241

of

1 kaki Bukit Ave 6 #01-43 Autobay

Policy No:

289487182MX

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

6/10/2019

CA / REV / REP. / REV 24 HRS

Date/Time:

5:07pm 7/10/19

Person Contacted:

Sukyi

H.O.D. Endorsement:

Vehicle IN (OUT)

Date/Time

Action/Instruction

Fahmud ✓

SJT 8768S - X

SLN 3069S - X

9/10/19

Informed Revel pending workshop est by merimen

25/11/19

Adrian confirmed LS \$4500 (Red 14,100-75, 7690)

26/11/19

Send preli revised via merimen

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Fievel Foo Wenyao	Date: 26 Nov 2019

Preliminary Advice

Insured Vehicle No	: SLN3069S		
TP Vehicle No	: SJT8768S	Accident Date	: 06/10/2019
Make	: TOYOTA COROLLA ALTIS	Assignment Date	: 07/10/2019
Date of Inspection	: 8/10/2019	Est. Duration of Repair	: 7
Inspection At	: SM AUTOMOTIVE		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,600.75
Revised Amount	:S\$	4,500.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,500.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

☐ The vehicle is economical/not economical for repair.

☒ The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Oct 2019 10:38		07 Oct 2019 16:50 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		Huang Lingbo, ID: S8082853E							
Main Claimant:		Lim Meng Hui							
Vehicle Reg. No.:	SJT8768S	Date of Loss:	06/10/2019 14:00 - :59 [29 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	28948718QMX (Comprehensive) Coverage: 28/04/2019 - 27/04/2020						
Vehicle Reg. No. (Insured):	SLN3069S	Policy No. (Claimant):							
		Excess:							
Repairer:	Sm Automotive - Kaki Bukit (HQ) BLOCK C - 1, KAKI BUKIT AVE 6, #01-43, 417883 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 08/10/2019]								
Adj Asg. Remarks:	on WP, Liab: NR. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Sukyl / Reena @ 6747 9241.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***SJT8768S**
[SLN3069S]
TP
Lim Meng Hui
Oct 6 2019 2:00PM
[Huang Lingbo]
Sm Automotive - Kaki Bukit

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 09/10/2019 14:09 PM.
To MSIG_FFWY1
Subject TP SURVEY SJT 8768S

Dear Fievel,

Please be informed that we have inspected the vehicle SJT 8768S on 8/10/2019.

We are pending workshop estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 978Z

Vehicle Details

Vehicle No.: SJT87685
Vehicle to be Exported: No
Intended Deregistration Date: 07 Oct 2019
Vehicle Make: TOYOTA
Vehicle Model: COROLLA ALTIS ELEGANCE
AUTO

Primary Colour: White
Manufacturing Year: 2018
Engine No.: 1ZR0B61152
Chassis No.: MR053REH604583169
Maximum Power Output: 96.0 kW (128 bhp)
Open Market Value: \$21,858.00
Original Registration Date: 30 May 2018
First Registration Date: 30 May 2018
Transfer Count: 0
Actual ARF Paid: \$22,602.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 29 May 2028
PARF Rebate Amount: \$16,951.00

Intended COE Rebate Details

COE Expiry Date: 29 May 2028
COE Category: A - Car up to 1600cc & 97kW
(130bhp)
COE Period(Years): 10
QP Paid: \$38,510.00
COE Rebate Amount: \$33,282.00
Total Rebate Amount: \$50,233.00

The information contained herein is correct as at 07 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/10/2019 11:41
Date Of Accident	06/10/2019 14:10
Exact Location Of Accident	TOA PAYOH SLIP ROAD PIE (AIRPORT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT8768S
Insured/Policyholder	
Name Of Registered Owner	LIM MENG HUI
NRIC No	S7875978Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96848078
Alternative Phone No	OFFICE-96848078

Vehicle Particulars

Manufacturer	TOYOTA
Model	ALTIS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D300132035QMY
Cover Note Number	

Driver

Name of Driver	LIM MENG HUI
NRIC No	S7875978Z
Date Of Birth	12/06/1978
Occupation	INDOOR
Date Of Driving Pass	23/10/2003
Driving Experience	15 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96848078
Fax Number	
Contact Number	OFFICE-96848078
Email Address	NOEMAIL

Address	BLK 22 ST MICHAEL'S RD #08-11
Postcode	327981
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : NGAU WAI SEE GENDER: : FEMALE
Passenger 2	NAME: : LIM DAO WEI GENDER: : MALE
Passenger 3	NAME: : LIM XIAU TONG GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM3069S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WANG YI JENG
NRIC/Passport Number	S7665516B
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (forms) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELLING ALONG THE ROAD, SLIP ROAD TO THE (AIRPORT), WHEN I STOP TO GIVE WAY TO ONCOMING TRAFFIC FROM THE, WHEN MY VEHICLE WAS STATIONARILY STOPPED, SUDDENLY ONE CAR 521 30575 CAME FROM MY REAR AND COLLIDED ONTO THE REAR PORTION OF MY VEHICLE.

DECLARATION

(We declare the foregoing particulars are true to every respect)


Policyholder's Signature
Date & Time


Driver's Signature
(If driver is not the policyholder)
Date & Time


Reporting Police Personnel's Signature
Name
ID No. / Unit No.

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: S3231488C

LIM MENG HUI

08/10/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPMS 19

MR053REH 604583169

Veron

Accident date: 06/10/2019

Estimated repair cost for vehicle no: SJT8768S TOYOTA ALTIS 1.6 A '18

CHASSIS: MR053REH604583169

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid <i>Buckled</i>		\$605.80	✓
2	2	Rear Boot Lid Hinge <i>new</i>	\$77.80	\$155.60	+
3	1	Rear Boot Lid Emblem Logo <i>2</i>		\$66.70	✓
4	1	Rear Boot Lid Corolla Logo <i>1/2</i>		\$45.70	✓
5	1	Rear Boot Lid Altis Logo		\$39.40	✓
6	1	Rear Boot Lid Number Plate <i>new</i>		\$50.00	+
7	2	Rear Boot Lid Number Plate Lamp <i>new</i>	\$62.70	\$125.40	+
8	1	Rear Boot Lid Center Moulding <i>new</i>		\$243.00	+
9	1	Rear Boot Lid Lower Chrome <i>new</i>		\$267.90	+
10	2	Rear Boot Lid Side Reflector <i>At RH cut</i>	\$401.00	\$802.00	907381
11	1	Rear Boot Lid Inner Lock <i>dent</i>		\$382.00	✓
12	1	Rear Boot Lid Inner Rubber <i>new</i>		\$166.40	+
13	1	Rear Boot Lid Inner Trim Board <i>2 new</i>		\$385.10	+
14	8	Rear Boot Lid Inner Trim Board Clip	\$6.50	\$52.00	439
15	2	Rear Tail Lamp <i>RH cut</i>	\$483.60	\$967.20	907381
16	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00	10
17	1	Rear R/H Tail Lamp Panel		\$176.90	+
18	1	Rear Bumper <i>Dented</i>		\$482.00	✓
19	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00	30
20	1	Rear R/H Bumper Side Retainer <i>new</i>		\$104.40	✓
21	1	Rear R/H Bumper Side Reflector <i>At Corolla</i>		\$35.10	✓
22	1	Rear Bumper Reinforcement <i>Dented</i>		\$381.70	✓
23	1	Rear R/H Bumper Reinforcement Bracket <i>new</i>		\$69.10	+
24	1	Rear R/H Bumper Mud Shield <i>2 new</i>		\$75.10	+
25	4	Rear R/H Bumper Mud Shield Clip	\$6.50	\$26.00	+
26	1	Rear Bumper Reverse Sensor (Special Nett) <i>Not in</i>		\$380.00	+
27	1	Rear End Panel <i>Dented</i>		\$581.10	✓

28	1	Rear End Panel Top Garnish	New		\$229.40	+
29	1	Rear R/H Fender	Regis	\$972.45	\$972.45	+
30	1	Rear R/H Fender Air Duct	per	\$174.50	\$174.50	+
31	1	Rear R/H Fender Inner Trim Board	2 per	\$415.10	\$415.10	+
32	8	Rear R/H Fender Inner Trim Board Clip		\$6.50	\$52.00	+
33	1	Rear Spare Tyre Panel	Regis		\$802.90	+
34	1	Rear Spare Tyre Panel Top Cover	2 per		\$348.20	+
35	1	Rear Spare Tyre Panel & End Panel Sealant			\$450.00	+
36	1	Rear Windscreen Seal	New		\$125.10	+
37	1	Rear Exhaust	Bent		\$781.10	✓
38	1	Rear Centre Exhaust	2 per		\$2,835.70	+
39	4	Rear Exhaust Mounting		\$33.70	\$134.80	+
40	1	Rear Exhaust Aluminium Cover			\$136.90	+

4321

3240.75

Subtotal :- \$14,220.75

Labour charges

To remove & refit cushion & trim board \$280.00 ⁶⁰

To remove & refit rear windscreen \$120.00 +

Gum off \$50.00 +

To remove & refit reverse sensor \$100.00 ⁵⁰

To remove & refit rear & centre exhaust 2380
\$380.00 ⁸⁰

To check wiring \$150.00 ³⁰

Tuff Kote \$150.00 ⁶⁰

Towing Fee \$150.00 +

Panel beating \$1,600.00 ¹⁰⁰⁰

Spray painting \$1,400.00 ¹¹⁰⁰

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Subtotal :- \$4,380.00

Total:- \$18,600.75

total: \$620.75

h/s. A.5K

(4.5K)

Adrian Lin

L/S 08/10/19. 0722

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sun@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19017635/AGVD3N2

Date: 28/11/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28948718QMX
Claimant Vehicle No :	SJT8768S	Insured Vehicle No :	SLN3069S
Date of Loss:	06/10/2019	Nature of Claim:	TP
		Claim No:	608062

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT8768S	Engine No:	1ZR0B61152
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 L (A)	Chassis No:	MR053REH604583169
Reg. Date:	30/05/2018 (Man. Year: 2018)	Odometer:	14689 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45R17	Rear Tyre Size:	215/45R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	14,270.75	3,240.75	11,030.00	77.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,330.00	2,380.00	1,950.00	45.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,600.75	5,620.75	12,980.00	69.78
Approved Total (Overridden) (S\$)		4,500.00		
Nett Amount (S\$)	18,600.75	4,500.00	14,100.75	75.81

INSPECTION

Date of Assignment:	07/10/2019	
Date Inspected:	08/10/2019 Inspected At:	Sm Automotive - Kaki Bukit (HQ) BLOCK C - 1, KAKI BUKIT AVE 6, #01-43 Singapore 417883
Estimated Period of Repair:	7.0 days	

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Nov 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJT8768S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOT LID	Buckled	605.80 F	*605.80 FL
2	2	*REAR BOOT LID HINGE	Not Necessary	155.60 F	*- FL
3	1	*REAR BOOT LID EMBLEM LOGO	Necessary	66.70 F	*66.70 FL
4	1	*REAR BOOT LID COROLLA LOGO	Necessary	45.70 F	*45.70 FL
5	1	*REAR BOOT LID ALTIS LOGO	Necessary	39.40 F	*39.40 FL
6	1	*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
7	2	*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	125.40 F	*- FL
8	1	*REAR BOOT LID CENTER MOULDING	Not Necessary	243.00 F	*- FL
9	1	*REAR BOOT LID LOWER CHROME	Not Necessary	267.90 F	*- FL
10	1	*REAR BOOT LID SIDE REFLECTOR	O/s Cut	802.00 F	*381.00 FL
11	1	*REAR BOOT LID INNER LOCK	Damaged	382.00 F	*382.00 FL
12	1	*REAR BOOT LID INNER RUBBER	Not Necessary	166.40 F	*- FL
13	1	*REAR BOOT LID INNER TRIM BOARD	Not Necessary	385.10 F	*- FL
14	8	*REAR BOOT LID INNER TRIM BOARD CLIP	Not Necessary	52.00 F	*- FL
15	1	*REAR TAIL LAMP	O/s Cut	967.20 F	*395.00 FL
16	4	*REAR TAIL LAMP CLIP	Necessary	32.00 F	*10.00 FL
17	1	*REAR R/H TAIL LAMP PANEL	Repair	176.90 F	*- FL
18	1	*REAR BUMPER	Deformed	482.00 F	*482.00 FL
19	10	*REAR BUMPER CLIP	Necessary	65.00 F	*30.00 FL
20	1	*REAR R/H BUMPER SIDE RETAINER	Necessary	104.40 F	*104.40 FL
21	1	*REAR R/H BUMPER SIDE REFLECTOR	Cracked	35.10 F	*35.10 FL
22	1	*REAR BUMPER REINFORCEMENT	Dented	381.70 F	*381.70 FL
23	1	*REAR R/H BUMPER REINFORCEMENT BRACKET	Not Necessary	69.10 F	*- FL
24	1	*REAR R/H BUMPER MUD SHIELD	Not Necessary	75.10 F	*- FL
25	4	*REAR R/H BUMPER MUD SHIELD CLIP	Not Necessary	26.00 F	*- FL
26	1	*REAR END PANEL	Dented	581.10 F	*581.10 FL
27	1	*REAR END PANEL TOP GARNISH	Not Necessary	229.40 F	*- FL
28	1	*REAR R/H FENDER	Repair	972.45 F	*- FL
29	1	*REAR R/H FENDER AIR DUCT	Not Necessary	174.50 F	*- FL
30	1	*REAR R/H FENDER INNER TRIM BOARD	Not Necessary	415.10 F	*- FL
31	8	*REAR R/H FENDER INNER TRIM BOARD CLIP	Not Necessary	52.00 F	*- FL
32	1	*REAR SPARE TYRE PANEL	Repair	802.90 F	*- FL
33	1	*REAR SPARE TYRE PANEL TOP COVER	Not Necessary	348.20 F	*- FL
34	1	*REAR SPARE TYRE PANEL & END PANEL SEALANT	Not Necessary	450.00 F	*- FL
35	1	*REAR WINDSCREEN SEAL	Not Necessary	125.10 F	*- FL
36	1	*REAR EXHAUST	Bent	781.10 F	*781.10 FL
37	1	*REAR CENTRE EXHAUST	Not Necessary	2,835.70 F	*- FL
38	4	*REAR EXHAUST MOUNTING	Not Necessary	134.80 F	*- FL
39	1	*REAR EXHAUST ALUMINIUM COVER	Not Necessary	136.90 F	*- FL
40	1	*REAR BUMPER REVERSE SENSOR	Not Necessary	380.00 FS	*- FS
41	1	*GUM	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 14,270.75 4,321.00

- List Item Discount on L Items 0.00/25.00% (\$\$) 0.00 1,080.25

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	14,270.75 3,240.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT CUSHION & TRIM BOARD	New	280.00	60.00
2	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	0.00
3	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
4	TO REMOVE & REFIT REAR & CENTRE EXHAUST	New	380.00	80.00
5	TO CHECK WIRING	New	150.00	30.00
6	TUFF KOTE	New	150.00	60.00
7	TOWING FEE	New	150.00	0.00
8	PANEL BEATING	New	1,600.00	1,000.00
9	SPRAY PAINTING	New	1,400.00	1,100.00
Gross Labour Cost (\$\$)			4,330.00	2,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >