

2501/2009

ASS. REC. BY:

REF: CS/MSH 19017637 / Dy d32k

Special Instruction:

Surveyor: Bryan

Merimen

ASSIGNMENT (Office)

From (Person): zheng hongyong

of

MSIG

Date/Time: 7/10/19 @ 4.51pm

photo O.K.

Estimated Cost:

Bill to:

OD - ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SHC 3137J

Insured:

SLK 4243P

at Workshop m/s

Chunni motor

Tel:

65425119

of

Blk 10 Amk Incl # 01-05 / 06

Policy No:

29088463MKF

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 3/10/2019

8/10/2019

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time:

5:10pm 9/10/19

Person Contacted:

Lynn

Vehicle IN / ~~OUT~~

Date/Time

Action/Instruction

Estimate 1/1

SHC 3137J - CS / FCS 19017637 / Egd3

D.O.A. 3/10/2019

SLK 4243P - X

11/10/19

Sent Preli by Merimen


ASS. REC. BY:

REF:

# ASSIGNMENT

COE 2027 April

From \_\_\_\_\_ Date \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_



(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 88 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHC 31375 Yr Regn: April 2019  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Hyundai Ioniq C.C. 1580  
 Colour: Blue A/C: Insured / Std / NI / NA  
 Sp. Reading: 44762 T/Radio: Insured / Std / NI / NA  
 Eng/No: G4LB5U193657  
 C/No: KMHC851CVKu141753  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 195/65 R15  
 R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Michelin

Front	Rear
R/Bal. <u>S</u> mm	R/Bal. <u>S</u> mm
L/Bal. <u>S</u> mm	L/Bal. <u>S</u> mm
D.O.A. <u>03/10/2019</u>	D.O.I. <u>08/10/2019</u>
Survey held at <u>Chunni AMIC</u>	

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Front 7 R

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MSIG SLK 4243P</u>

07/11/2019 From 4/5 11200/- - it 8 days 7 (Red \$7674,48, 40%)

RECEIVED 12 NOV 2019

Date/Time, File Pass to? ☐ : Preli. Report  
☐ : Final Report

Days Of Repair: 8  
 Resurvey No. of Trip: 2

Date/Time, File Return to? 8/11/19 Typist

Add Fee: ☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Tech. Invs (\$)  
☐ : Weekend (\$)

Survey Fee:	<u>700</u>
Transportation:	
Photos	
Others	<u>11</u>
TOTAL	<u>711</u>

Report Format: \_\_\_\_\_

Lump Sum / T.B.B.:

4/5 \$11200/-

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Oct 2019 10:29		07 Oct 2019 16:51 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHC3137J	Date of Loss:	03/10/2019 21:00 - :59 [6 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	29088463MKF (Comprehensive) Coverage: 02/07/2018 - 31/01/2020
Vehicle Reg. No. (Insured):	SLK4243P	Policy No. (Claimant):	
		Excess:	
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Zheng Hanyang - 6594 2547]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 08/10/2019]		
Adj Asg. Remarks:	on WP. Liab: NR. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Ms Lynn or Ms Irene at 65425119 / 6542 7162.		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Zheng Hanyang

Date: 11 Oct 2019

**Preliminary Advice**

Insured Vehicle No	: SLK4243P	Accident Date	: 03/10/2019
TP Vehicle No	: SHC3137J	Assignment Date	: 07/10/2019
Make	: HYUNDAI AE IONIQ HEV DCT	Est. Duration of Repair	: 6.00
Date of Inspection	: 08/10/2019		
Inspection At	: CHUNNI MOTOR WORK PTE LTD - AMK (HQ) BLK 10 #01-05/06, AMK AUTOPOINT SINGAPORE 568047		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages FRONT & REAR portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,874.48
Revised Amount	:S\$	14,057.52
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

MCD619131532 / ComfortDelGro Engineering Pte Ltd - Loyang  
 ENTRY DATE & TIME: 04/10/2019 14:47  
 SUBMITTED BY: Janet Lim Siang Gek

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 04/10/2019 14:47  
 Date Of Accident 03/10/2019 21:30  
 Exact Location Of Accident NICOLL HIGHWAY >> TPE  
 Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SHC3137J  
 Insured/Policyholder  
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD  
 Co Reg No 199303821R  
 Email Address FLEETSAFETY@CDGTAXI.COM.SG  
 Mobile Phone No  
 Alternative Phone No OFFICE-65508768  
 Vehicle Particulars  
 Manufacturer HYUNDAI  
 Model IONIQ HYBRID  
 Exact Purpose for which vehicle was being used at time of accident  
 Are you claiming under your own insurance policy for repair to your vehicle? NO  
 If No, Please state action to be taken THIRD PARTY  
 Vehicle Category TAXI  
 Insurance Company  
 Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD  
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT  
 Fleet Policy YES  
 Policy Number D-18088936MFSH  
 Cover Note Number  
 Driver  
 Name of Driver HOI HENG SAN  
 NRIC No S7026316E  
 Date Of Birth 10/08/1970  
 Occupation OUTDOOR  
 Date Of Driving Pass 08/12/1993  
 Driving Experience 25 YEARS AND 9 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-92328103  
 Fax Number  
 Contact Number  
 EMail Address WOODY\_HOI@YAHOO.COM

Address BLK 132 ANG MO KIO AVENUE 3  
#05-1623  
Postcode 560132  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER  
Vehicle Registration Number of Driver's Own Vehicle -  
Vehicle -  
Insurance Company of Driver's Own Vehicle -

**General Information of the Accident**

Type Of Accident CHAIN COLLISION  
Weather Conditions CLEAR  
Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
Number of vehicles (including own vehicle) involved in the accident 3  
Was any body injured in the Accident? YES  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 2  
Passenger 1

NAME: -  
GENDER: FEMALE

**Details of Police Action**

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of Intended Prosecution given? NO  
If Yes, against whom?

**Circumstances of Accident**

REFER ATTACHED

**Attachment(s)**

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? YES  
Remarks/ Reasons: -  
Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLK4243P  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver UNKNOWN  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name

Nature Of Damage FRONT

No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number SGD4592C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver UNKNOWN

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage REAR

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name HOI HENG SAN

Approximate Age

Injuries Sustain NECK

Injured person in which vehicle? SHC3137J

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

**SKETCH PLAN****IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 04.10.2019 @ 1030hrs

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.: June



## SKETCH PLAN

A- SHC 3137J  
 B- SLK 4243P  
 C- SGD 4592C

Along Nicoll Highway Twds TPE

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 03.10.2019 @ 2130hrs I was travelling along Nicoll Highway Twds TPE with one female passenger onboard.

As Veh(C) in front of me stopped and I followed suddenly veh(B) hit onto my vehicle rear portion and caused my vehicle to surge forward and hit onto veh(C)

I have company video and photos at scene to support my claims .

After the accident I felt pain on my neck and will consult a doctor.

Veh(B)- SLK 4243P- MALE DRIVER

Veh(C)- SGD 4592C - MALE DRIVER

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
 CO. REG. NO. 199303821R

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 04.10.2019 @ 1030hrs

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.: June

**CHUNNI MOTOR WORK PTE LTD****REPAIR ESTIMATE\***

VEHICLE NO : SHC 3137J

DATE : 4.10.2019

MAKE :

TEL : 6542 5119


MODEL : HYUNDAI IONIQ

FAX : 6542 6039

MPIC

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Unit Assy-SMART CRU (Radar Sensor) <i>mandy crak</i>			\$ 2,910.90	✓
	Front Bumper Cover <i>mandy crak</i>			\$ 418.30	✓
	Front Bumper Sponge <i>SVC</i>			\$ 86.90	X
	Front Bumper Reinforcement <i>SVC</i>			\$ 1,075.10	X
	Front Bumper Bracket Top (LH/RH) <i>SVC</i>		\$ 35.00	\$ 70.00	X
	Front Bumper Bracket (LH/RH) <i>SVC</i>		\$ 28.00	\$ 56.00	X
	Front Bumper Clips 10 pcs <i>Nec</i>			\$ 22.00	✓
	Headlamp (LH/RH) <i>crak</i>		\$ 1,198.80	\$ 2,397.60	✓
			<i>5748.80</i>		
	SUB TOTAL			\$ 7,036.80	
	LESS 20%			\$ 1,407.36	
	DISCOUNTED TOTAL			\$ 5,629.44	
	Labour Charge				
	Panel Beating			\$ 350.00	200/-
	Spray Painting Charge			\$ 250.00	200/-
	TOTAL LABOUR		<i>500.00</i>	\$ 600.00	
	Boot Lid <i>st</i>			\$ 2,480.40	✓
	Boot Lid Rubber <i>SVC</i>			\$ 127.40	X
	Boot Lid Lock Upper <i>NH</i>			\$ 224.00	X
	Boot Lid 'H' Emblem <i>Nec</i>			\$ 28.00	✓
	Emblem -Hybrid <i>Nec</i>			\$ 24.30	✓
	Emblem -Ioniq <i>Nec</i>			\$ 31.30	✓
	Boot Lid Glass, Lower <i>NH</i>			\$ 384.90	X
	Boot Lid Lamp (LH/RH) <i>mandy crak</i>		\$ 794.40	\$ 1,588.80	✓
	Licence Plate Trim Cover <i>st</i>			\$ 35.10	✓
	Rear Bumper <i>mandy crak</i>			\$ 459.40	✓
	Rear Bumper Reinforcement <i>crak</i>			\$ 294.80	✓
	Rear Bumper Reinforcement Bracket (LH/RH) <i>NH</i>		\$ 138.10	\$ 276.20	X
	Rear Bumper Centre Moulding Assy <i>distorted</i>			\$ 451.25	✓
	Rear Bumper Lower Centre Moulding Assy <i>NH</i>			\$ 155.00	X
	Rear Bumper Stay <i>NH</i>			\$ 138.10	X
	Rear Bumper Side Bracket (LH/RH) <i>NH</i>		\$ 33.10	\$ 66.20	X
	Rear Bumper Cover Clips <i>Nec</i>			\$ 22.00	✓
	Tail Lamp (LH/RH) <i>mandy crak</i>		\$ 870.40	\$ 1,740.80	✓
	Rear Panel <i>Distorted</i>			\$ 532.00	✓
	Rear Panel Garnish <i>NH</i>			\$ 67.70	X
	Rear Panel Lower Panel <i>NH</i>		\$ 39.40	\$ 78.80	X
	Exhaust Pipe Insulator <i>NH</i>			\$ 35.00	X
	Exhaust Silencer <i>NH</i>			\$ 943.50	X
	Exhaust Pipe Hanger <i>NH</i>			\$ 29.20	X
	Rear Windscreen Glass <i>NH</i>			\$ 607.20	X
	Rear Windscreen Moulding <i>Nec</i>			\$ 28.20	✓
			<i>7716.35</i>		
			<i>6173.08</i>		
	SUB TOTAL			\$ 10,849.55	
	LESS 20%			\$ 2,169.91	
	DISCOUNTED TOTAL			\$ 8,679.64	

SHC 3137J

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid Comfort Logo & Tel No. Sticker <i>Nec</i>			\$ 30.00	Nett ✓
	Rear No. Plate <i>Crack</i>			\$ 25.00	Nett ✓
	Rear Bumper Reverse Sensor <i>Dem</i>			\$ 135.70	Nett ✓
	Rear Bumper Reserve Light (Parking Brake Light) <i>Socket broken</i>			\$ 257.10	Nett ✓
	Rear Bumper Rubber Mat <i>Nec</i>			\$ 50.00	Nett ✓
	Rear Windscreen Sealant <i>Nec</i>			\$ 46.00	Nett ✓
			543.80	\$ 543.80	
	<b>Labour Charge</b>				
	Panel Beating			\$ 1,000.00	600/-
	Spray Painting Charge			\$ 750.00	500/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 50.00	40/-
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00	80/-
	Remove/Refix Reverse Sensor		1690.00	\$ 120.00	40/-
	Remove/Refix Exhaust Pipe			\$ 150.00	70/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	320/-
	<b>TOTAL LABOUR</b>			\$ 2,870.00	
	<b>ESTIMATE TOTAL</b>			\$ 18,322.88	
	08/10/2019 @ 0945hrs		13505.92		
	Not Antenna		551.60		
	2/5mm 68 days	Supp	14057.52		18894.48
	<i>ngan</i>	L/S	11200/-		
	2KK Auto				
					
	<div><p>KK Auto Consultants hence notify the Repairer of the following:</p><ul style="list-style-type: none"><li>• To resurvey before/after spray painting</li><li>• To display damaged part(s) during resurvey</li><li>• Parts prices are subject to confirmation</li><li>• Third party survey is on a "Without Prejudice" basis</li><li>• No illegal modification(s) is allowed</li><li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li></ul><p>Acknowledged by Repairer</p><p>Signature:</p><p>Date:</p></div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

**CHUNNI MOTOR WORK PTE LTD****REPAIR ESTIMATE\***

VEHICLE NO : SHC 3137J (Supplementary)

DATE : 8.10..2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI IONIQ

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Antenna Electrical Key <i>mainly broken</i>			\$ 689.50 ✓
	SUB TOTAL			\$ 689.50
	LESS 20%			\$ 137.90
	DISCOUNTED TOTAL			\$ 551.60
	<i>08/10/2019 @</i> <i>[Signature]</i> <i>2KK Auto</i>  <i>[Signature]</i>			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Oct 2019		07 Oct 2019 16:51 <a href="#">Edit Adj Rpt</a>	<b>S\$11,200.00</b> <a href="#">Edit Estimates</a>	<b>S\$11,200.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G	
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R	
Vehicle Reg. No.:	SHC3137J	Date of Loss: 03/10/2019 21:00 - :59 [6 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 607864	Policy/Cover Note No.: 29088463MKF (Comprehensive) Coverage: 02/07/2018 - 31/01/2020
Vehicle Reg. No. (Insured):	SLK4243P	Policy No. (Claimant):
		Excess:
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Zheng Hanyang - 6594 2547]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 06/11/2019]	
Adj Asg. Remarks:	on WP. Liab: NR. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Ms Lynn or Ms Irene at 65425119 / 6542 7162.	










































ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		
























































  

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

























































## Claim Documents

\*SHC3137J (607864)  
[SLK4243P]  
TP  
COMFORT TRANSPORTATION PTE LTD  
Oct 3 2019 9:00PM  
[GRAB RENTALS PTE LTD]  
Chunni Motor Work Pte Ltd - Amk





<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<b>View</b> <a href="#">View in Browser</a> <input type="button" value="v"/>	
<b>Assessment Reports</b>				1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/10/19 10:30	Adjuster Immediate Advice		Load HTM	
<b>Photos/Images</b>				3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/10/19 14:26	Rear View Right		Load JPG	<input checked="" type="checkbox"/>
2	26/10/19 14:26	Rear View Left		Load JPG	<input checked="" type="checkbox"/>
3	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
4	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
5	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
6	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
7	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
8	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
9	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
10	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
11	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
12	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
13	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
14	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
15	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
16	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
17	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
18	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
19	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
20	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
21	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
22	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
23	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
24	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
25	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
26	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
27	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
28	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
29	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
30	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
31	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
32	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
33	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
34	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
35	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
36	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
37	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
38	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
39	26/10/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
40	26/10/19 14:28	General View		Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
42	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
43	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
44	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
45	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
46	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
47	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
48	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
49	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
50	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
51	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
52	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
53	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
54	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
55	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
56	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
57	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
58	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
59	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
60	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
61	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
62	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
63	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
64	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
65	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
66	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
67	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
68	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
69	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
70	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
71	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
72	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
73	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
74	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
75	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
76	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
77	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
78	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
79	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
80	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
81	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
82	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
83	26/10/19 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
84	26/10/19 14:28	Front View Right	 Load JPG	<input checked="" type="checkbox"/>
85	26/10/19 14:28	Front View Left	 Load JPG	<input checked="" type="checkbox"/>
86	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
87	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
88	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
89	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
90	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
91	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
92	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
93	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
94	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
95	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
96	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
97	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
98	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
99	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
100	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
101	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
102	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
103	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
104	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
105	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
106	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
107	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
108	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
109	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
110	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
111	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
112	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
113	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
114	26/10/19 14:29	General View	 Load JPG	<input checked="" type="checkbox"/>
115	26/10/19 14:29	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
116	26/10/19 14:29	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
117	26/10/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	26/10/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	26/10/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	26/10/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	26/10/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	26/10/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	26/10/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	26/10/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
126	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
127	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
128	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
129	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
130	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
131	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
132	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
133	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
134	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
135	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
136	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
137	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
138	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
139	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
140	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
141	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
142	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
143	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
144	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
145	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
146	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
147	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
148	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
149	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
150	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
151	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
152	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
153	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
154	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
155	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
156	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
157	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
158	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
159	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
160	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
161	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
162	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
163	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
164	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
165	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
166	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
167	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
168	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
169	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
170	26/10/19 14:30	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/10/19 10:30	Estimate & SHC3137J GIA Report	 Load PDF	
2	07/10/19 11:04	Agree on SJE	 Load PDF	
3	07/10/19 11:05	PRI	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19017637/DYD3E2

Date: 12/11/2019

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

29088463MKF

#### Claimant

Vehicle No : SHC3137J

Insured Vehicle No :

SLK4243P

Date of Loss: 03/10/2019

Nature of Claim:

TP

Claim No: 607864

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHC3137J

Make &amp; Model:

HYUNDAI AE IONIQ HEV DCT, 1.6 (A)

Engine No:

G4LEJU193657

Reg. Date:

02/04/2019 (Man. Year: 2019)

Chassis No:

KMHC851CVKU141753

Colour:

Blue

Odometer:

44762 km

Engine Capacity:

1580 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$):

Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:

195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side:

Michelin 5 mm

Rear Left Side:

Michelin 5 mm

Front Right Side:

Michelin 5 mm

Rear Right Side:

Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,404.48	11,867.52	3,536.96	22.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,470.00	2,190.00	1,280.00	36.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>18,874.48</b>	<b>14,057.52</b>	<b>4,816.96</b>	<b>25.52</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>11,200.00</b>		
(S\$)	18,874.48	11,200.00	7,674.48	40.66
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,321.21</b>	<b>784.00</b>	<b>537.21</b>	<b>40.66</b>
<b>Nett Amount (S\$)</b>	<b>20,195.69</b>	<b>11,984.00</b>	<b>8,211.69</b>	<b>40.66</b>

### INSPECTION

Date of Assignment:

07/10/2019

Date Inspected:

08/10/2019 Inspected At:

Chunni Motor Work Pte Ltd - Amk (HQ)

Blk 10 #01-05/06, AMK Autopoint Singapore 568047

Estimated Period of Repair:

8.0 days

Adjuster: BRYAN TANI

Manager: YVONNE WONG YIN CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 12 Nov 2019)	
<b>Parts:</b>	N/A	HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC3137J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*UNIT ASSY-SMART CRU (RADAR SENSOR)	Mtg Cracked	2,910.90 FL	*2,910.90 FL
2	1		*FRONT BUMPER COVER	Mtg Cracked	418.30 FL	*418.30 FL
3	1		*FRONT BUMPER SPONGE	Serviceable	86.90 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Serviceable	1,075.10 FL	*- FL
5	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Serviceable	70.00 FL	*- FL
6	2		*FRONT BUMPER BRACKET (LH/RH)	Serviceable	56.00 FL	*- FL
7	10		*FRONT BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
8	2		*HEADLAMP (LH/RH)	Cracked	2,397.60 FL	*2,397.60 FL
9	1		*BOOT LID	Bent	2,480.40 FL	*2,480.40 FL
10	1		*BOOT LID RUBBER	Serviceable	127.40 FL	*- FL
11	1		*BOOT LID LOCK UPPER	Not Necessary	224.00 FL	*- FL
12	1		*BOOT LID H EMBLEM	Necessary	28.00 FL	*28.00 FL
13	1		*EMBLEM - HYBRID	Necessary	24.30 FL	*24.30 FL
14	1		*EMBLEM - IONIQ	Necessary	31.30 FL	*31.30 FL
15	1		*BOOT LID GLASS, LOWER	Not Necessary	384.90 FL	*- FL
16	2		*BOOT LID LAMP (LH/RH)	Mtg Cracked	1,588.80 FL	*1,588.80 FL
17	1		*LICENCE PLATE TRIM COVER	Bent	35.10 FL	*35.10 FL
18	1		*REAR BUMPER	Mtg Cracked	459.40 FL	*459.40 FL
19	1		*REAR BUMPER REINFORCEMENT	Cracked	294.80 FL	*294.80 FL
20	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Not Necessary	276.20 FL	*- FL
21	1		*REAR BUMPER CENTRE MOULDING ASSY	Distorted	451.25 FL	*451.25 FL
22	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Not Necessary	155.00 FL	*- FL
23	1		*REAR BUMPER STAY	Not Necessary	138.10 FL	*- FL
24	2		*REAR BUMPER SIDE BRACKET (LH/RH)	Not Necessary	66.20 FL	*- FL
25	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
26	2		*TAIL LAMP (LH/RH)	Mtg Cracked	1,740.80 FL	*1,740.80 FL
27	1		*REAR PANEL	Dented	532.00 FL	*532.00 FL
28	1		*REAR PANEL GARNISH	Not Necessary	67.70 FL	*- FL
29	2		*REAR PANEL LOWER PANEL	Not Necessary	78.80 FL	*- FL
30	1		*EXHAUST PIPE INSULATOR	Not Necessary	35.00 FL	*- FL
31	1		*EXHAUST SILENCER	Not Necessary	943.50 FL	*- FL
32	1		*EXHAUST PIPE HANGER	Not Necessary	29.20 FL	*- FL
33	1		*REAR WINDSCREEN GLASS		607.20 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Not Necessary		
34	1		*REAR WINDSCREEN MOULDING	Necessary	28.20 FL	*28.20 FL
35	1		*BOOT LID COMFORT LOGO & TEL NO. STICKER	Necessary	30.00 FS	*30.00 FS
36	1		*REAR NO. PLATE	Cracked	25.00 FS	*25.00 FS
37	1		*REAR BUMPER REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
38	1		*REAR BUMPER REVERSE LIGHT (PARKING BRAKE LIGHT)	Socket Broken	257.10 FS	*257.10 FS
39	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
40	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
41	1		*ANTENNA ELECTRICAL KEY	Mtg Broken	689.50 FL	*689.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 19,119.65 14,698.45**

- List Item Discount on L Items 20.00/20.00% (\$\$) 3,715.17 2,830.93

**Total Parts (\$\$) 15,404.48 11,867.52**

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,350.00	900.00
2	SPRAY PAINTING CHARGE	New	1,000.00	700.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	50.00	40.00
5	REMOVE / REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
6	REMOVE / REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
7	REMOVE / REFIX REVERSE SENSOR	New	120.00	40.00
8	REMOVE / REFIX EXHAUST PIPE	New	150.00	0.00
9	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	480.00	320.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,470.00</b>	<b>2,190.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >