

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 15035

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1121/2019/NS
Date : 8-Oct-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Vehicle : SFG 59 Z

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : CYF Enterprise (S) Pte Ltd
Address : 1 Sims Lane
#06-09
Singapore 387355
Telephone : HP +65 93836678
Type of Claim : Third Party Claim
Policy No. : GA280447/1
Vehicle No : **SKD 4476 H**
Model Code : Audi A5 SportBack 2.0 TFS
Model / Year : Nov-11
Engine No : CDNN 228830
Chassis No : WAUZZZ8T4BA108146
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Oct-19
Place of Accident : 3 Bukit Chermin Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKD 4476 H

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To tow back from accident scene.	S/N \$ 280.00	140 X nn
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
3	To remove and renew aircon condenser, radiator and charged air cooler. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00	✓
4	To dismantle and renew front bumper, rhs front fender, bonnet and both headlights. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 6,400.00	1750 3250 with support panel
5	To respray front bumper, bonnet, rhs front fender and hinges.	\$ 3,600.00	1650. 1750
6	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 12,032.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 4476 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,633.00	de ✓
2	FRONT BUMPER FIXING PARTS	\$ 234.00	?
3	FRONT BUMPER SIDE REINFORCEMENT BEAM	\$ 802.00	X
4	FRONT BUMPER BRACKET - RH	\$ 207.00	X
5	FRONT BUMPER SUPPORT - LH / RH	2 \$ 52.00	RH-bt, LH-X
6	FRONT BUMPER GUIDE PIECE - LH / RH	2 \$ 80.00	RH-de, LH-?
7	FRONT BUMPER COVER	\$ 116.00	de ✓
8	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 191.00	?
9	FRONT BUMPER FOAM FILLER PIECE	\$ 116.00	cu ✓
10	FOAM FILLER PIECE SUPPORT	2 \$ 18.00	?
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$ 246.00	RH-mis, LH-X
12	FRONT BUMPER COVER	\$ 89.00	de ✓
13	FRONT BUMPER PULL STRAP - LOWER	4 \$ 187.00	?
14	SIGNAL HORN - RH LOW TONE	\$ 184.00	cu ✓
15	SIGNAL HORN - LH HIGH TONE	\$ 184.00	X
16	SPRING SHACKLE - RH LOW TONE	\$ 23.00	bt ✓
17	SPRING SHACKLE - LH HIGH TONE	\$ 23.00	X
18	RADIATOR GRILLE WITH NUMBER PLATE HOLDER	\$ 713.00	cu ✓
19	QUATTRO INSCRIPTION	\$ 113.00	de ✓
20	CAUTION SIGN STICKER	NEC \$ 13.00	cu ✓
SUB TOTAL SPARE PARTS		: \$ 5,224.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 4476 H

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
94-1	FRONT BUMPER	\$ 1,633.00	de 1633.
2	FRONT BUMPER FIXING PARTS	\$ 234.00	X 777X
3	FRONT BUMPER SIDE REINFORCEMENT BEAM	\$ 802.00	X 777X
4	FRONT BUMPER BRACKET - RH	\$ 207.00	X 777X
5	FRONT BUMPER SUPPORT - LH / RH	2 \$ 52.00	RH-bt, LH-X 26
6	FRONT BUMPER GUIDE PIECE - LH / RH	2 \$ 80.00	RH-de, LH-X 40
7	FRONT BUMPER COVER	\$ 116.00	de 777
8	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 191.00	X 777
9	FRONT BUMPER FOAM FILLER PIECE	\$ 116.00	777 116.00
10	FOAM FILLER PIECE SUPPORT	2 \$ 18.00	X 777
SE 11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$ 246.00	RH-mis, LH-X 123.00
12	FRONT BUMPER COVER	\$ 89.00	de 39
13	FRONT BUMPER PULL STRAP - LOWER	4 \$ 187.00	X 777
14	SIGNAL HORN - RH LOW TONE	\$ 184.00	de 184.
15	SIGNAL HORN - LH HIGH TONE	\$ 184.00	X 777
16	SPRING SHACKLE - RH LOW TONE	\$ 23.00	bt 777
17	SPRING SHACKLE - LH HIGH TONE	\$ 23.00	X 777
SE 18	RADIATOR GRILLE WITH NUMBER PLATE HOLDER	\$ 713.00	de 713.
19	QUATTRO INSCRIPTION	\$ 113.00	de 113.
20	CAUTION SIGN STICKER	NEC \$ 13.00	de 13
SUB TOTAL SPARE PARTS		: \$ 5,224.00	

24/10/18

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 4476 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	AIRCON STICKER	NEC \$ 18.00	
22	FRONT FENDER - RH	\$ 980.00	bl X R Repair
23	FRONT FENDER ATTACHMENT PARTS	\$ 52.00	X nn
24	FRONT FENDER BRACKET - RH FRONT / REAR	2 \$ 106.00	X nn
25	FRONT FENDER BRACE	\$ 110.00	? bl (110)
26	FRONT WHEEL HOUSING LINER	\$ 169.00	X nn
27	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 41.00	X nn
28	BONNET	\$ 1,825.00	Rx
29	BONNET ATTACHMENT PARTS	\$ 152.00	?
30	BONNET LIF HINGE - LH / RH	2 \$ 152.00	?
31	BONNET ANTI - THEFT GUARD	\$ 16.00	X
32	BONNET CATCH HOOK	\$ 127.00	X
33	BONNET GAS FILLED STRUT - LH	\$ 109.00	X
34	BONNET EDGE PROTECTION - FRONT	2 \$ 50.00	X
35	BONNET LID LOCK	\$ 196.00	X
36	NICRO SWITCH	\$ 67.00	X
37	BONNET LID LOCK CABLE	\$ 44.00	X
38	BONNET LID LOCK CABLE - REAR	\$ 67.00	X
39	BONNET LOCK COVER	\$ 21.00	X
40	HEADLIGHT MOUNTING - LH / RH	2 \$ 228.00	RH - OK, LH - X 114
SUB TOTAL SPARE PARTS		\$ 4,530.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 4476 H

S/N	Parts Description	Damage Parts & Prices		REMARKS
		S/NETT		
41	HEADLIGHT BRACKET - LH / RH <i>CR</i>	2	\$ 146.00	<i>CR</i> ✓, LH-X nn 73.00
42	HEADLIGHT - LH / RH	2	\$ 4,340.00	<i>CR</i> ✓, LH-X nn
43	GAS DISCHARGE LAMP		\$ 398.00	X nn
44	GAS DISCHARGE LAMP CONTROL UNIT		\$ 1,051.00	X nn
45	LIFT CYLINDER - LH / RH	2	\$ 502.00	<i>CR</i> ✓, LH-X nn 251
46	LIFT CYLINDER SECURING BRACKET - RH		\$ 26.00	X nn
47	HEADLIGHT HOSE <i>ms</i>	5	\$ 179.00	<i>ms</i> ✓
48	HEADLIGHT T-PIECE		\$ 14.00	X nn
49	HALOGEN FOG LAMP - LH / RH <i>ms</i>	2	\$ 470.00	<i>ms</i> ✓, LH-X nn
50	LOCK CARRIER		\$ 928.00	?
51	LOCK CARRIER BRACE - RH		\$ 41.00	?
52	COOLANT REGULATOR SUPPORT	2	\$ 69.00	X nn
53	A/C CONDENSER		\$ 677.00	?
54	CHARGE AIR COOLER		\$ 513.00	?
55	CHARGE AIR COOLER PRESSURE HOSE - RH		\$ 261.00	?
56	COOLANT RADIATOR		\$ 1,246.00	?
57	READY MIX COOLANT	4	\$ 84.00	?
58	RADIATOR AIR GUIDE - LH / RH		\$ 56.00	<i>CR</i> ✓, LH-X nn 28
59	RADIATOR SEALING STRIP - UPPER		\$ 21.00	X nn
60	STRAINER		\$ 21.00	X nn
SUB TOTAL SPARE PARTS		:	\$ 11,043.00	

4340

4154