

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKD 4476 H

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To tow back from accident scene.	S/N	\$ 280.00	Xnn
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$ 360.00 ✓
3	To remove and renew aircon condenser, radiator and charged air cooler. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	\$ 1,200.00	\$ 1,200.00 ✓
4	To dismantle and renew front bumper, rhs front fender, bonnet and both headlights. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.		\$ 6,400.00	\$ 1,750.00 ✓
5	To respray front bumper, bonnet, rhs front fender and hinges.		\$ 3,600.00	\$ 1,650.00 ✓
6	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00 ✓
TOTAL LABOUR CHARGES		:	\$ 12,032.00	\$ 5,152.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 4476 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,633.00	\$ 1,306.40 ✓de
2	FRONT BUMPER FIXING PARTS	\$ 234.00	} xnn
3	FRONT BUMPER SIDE REINFORCEMENT BEAM	\$ 802.00	
4	FRONT BUMPER BRACKET - RH	\$ 207.00	
5	FRONT BUMPER SUPPORT - LH / RH	2 \$ 52.00	\$ 20.32 RH-bt ✓
6	FRONT BUMPER GUIDE PIECE - LH / RH	2 \$ 80.00	\$ 31.52 RH-de ✓
7	FRONT BUMPER COVER	\$ 116.00	\$ 92.40 ✓de
8	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 191.00	xnn
9	FRONT BUMPER FOAM FILLER PIECE	\$ 116.00	\$ 92.40 ✓cut
10	FOAM FILLER PIECE SUPPORT	2 \$ 18.00	xnn
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$ 246.00	\$ 98.00 RH-mis ✓
12	FRONT BUMPER COVER	\$ 89.00	\$ 70.88 ✓de
13	FRONT BUMPER PULL STRAP - LOWER	4 \$ 187.00	xnn
14	SIGNAL HORN - RH LOW TONE	\$ 184.00	\$ 146.80 ✓cta
15	SIGNAL HORN - LH HIGH TONE	\$ 184.00	xnn
16	SPRING SHACKLE - RH LOW TONE	\$ 23.00	\$ 23.00 bt ✓
17	SPRING SHACKLE - LH HIGH TONE	\$ 23.00	xnn
18	RADIATOR GRILLE WITH NUMBER PLATE HOLDER	\$ 713.00	\$ 570.00 ✓cta
19	QUATTRO INSCRIPTION	\$ 113.00	\$ 113.00 ✓hec
20	CAUTION SIGN STICKER	NEC \$ 13.00	\$ 9.76 ✓hec
SUB TOTAL SPARE PARTS		\$ 5,224.00	\$ 2,574.48

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 4476 H

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
				\$ 2,574.48
21	AIRCON STICKER	NEC	\$ 18.00	✓ hec
22	FRONT FENDER - RH		\$ 980.00	x repair
23	FRONT FENDER ATTACHMENT PARTS		\$ 52.00	x nh
24	FRONT FENDER BRACKET - RH FRONT / REAR	2	\$ 106.00	x nh
25	FRONT FENDER BRACE		\$ 110.00	\$ 88.00 ✓ bt
26	FRONT WHEEL HOUSING LINER		\$ 169.00	x nh
27	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 41.00	
28	BONNET		\$ 1,825.00	
29	BONNET ATTACHMENT PARTS		\$ 152.00	
30	BONNET LIF HINGE - LH / RH	2	\$ 152.00	
31	BONNET ANTI - THEFT GUARD		\$ 16.00	
32	BONNET CATCH HOOK		\$ 127.00	
33	BONNET GAS FILLED STRUT - LH		\$ 109.00	
34	BONNET EDGE PROTECTION - FRONT	2	\$ 50.00	
35	BONNET LID LOCK		\$ 196.00	
36	NICRO SWITCH		\$ 67.00	
37	BONNET LID LOCK CABLE		\$ 44.00	
38	BONNET LID LOCK CABLE - REAR		\$ 67.00	
39	BONNET LOCK COVER		\$ 21.00	
40	HEADLIGHT MOUNTING - LH / RH	2	\$ 228.00	\$ 90.80 RH-cra ✓
SUB TOTAL SPARE PARTS			\$ 4,530.00	\$ 2,753.28

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 4476 H

S/N	Parts Description	c/f	Damage Parts & Prices		REMARKS
			S/NETT		
				\$	2,753.28
41	HEADLIGHT BRACKET - LH / RH	2	\$ 146.00	\$ 57.92	2xnn RH-check ✓
42	HEADLIGHT - LH / RH	2	\$ 4,340.00	\$ 1,736.00	2xnn RH-check ✓
43	GAS DISCHARGE LAMP		\$ 398.00		3xnn
44	GAS DISCHARGE LAMP CONTROL UNIT		\$ 1,051.00		
45	LIFT CYLINDER - LH / RH	2	\$ 502.00	\$ 200.40	2xnn RH-check ✓
46	LIFT CYLINDER SECURING BRACKET - RH		\$ 26.00		xnn
47	HEADLIGHT HOSE	5	\$ 179.00	\$ 143.20	dis ✓
48	HEADLIGHT T-PIECE		\$ 14.00		xnn
49	HALOGEN FOG LAMP - LH / RH	2	\$ 470.00	\$ 188.00	2xnn RH-check ✓
50	LOCK CARRIER		\$ 928.00		
51	LOCK CARRIER BRACE - RH		\$ 41.00		
52	COOLANT REGULATOR SUPPORT	2	\$ 69.00		xnn
53	A/C CONDENSER		\$ 677.00		
54	CHARGE AIR COOLER		\$ 513.00		
55	CHARGE AIR COOLER PRESSURE HOSE - RH		\$ 261.00		
56	COOLANT RADIATOR		\$ 1,246.00		
57	READY MIX COOLANT	4	\$ 84.00		2xnn
58	RADIATOR AIR GUIDE - LH / RH		\$ 56.00	\$ 21.76	RH-check ✓
59	RADIATOR SEALING STRIP - UPPER		\$ 21.00		2xnn
60	STRAINER		\$ 21.00		
SUB TOTAL SPARE PARTS			\$ 11,043.00	\$ 5,100.56	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 4476 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
			\$ 5,100.56
61	INTAKE MANIFOLD	\$ 88.00	
62	BELLOWS	\$ 98.00	3x nn
63	AIR FILTER	\$ 279.00	\$ 223.20 - Check ✓
64	AIR MASS METER	\$ 533.00	3x nn
65	INTAKE MANIFOLD	\$ 133.00	
66	FRONT NO PLATE	S/N \$ 40.00	\$ 40.00 - nec ✓
67	SUNDRIES	\$ 500.00	\$ 30.80 - nec ✓
TOTAL SPARE PARTS		\$ 22,468.00	\$ 5,394.56
TOTAL LABOUR CHARGES		\$ 12,032.00	\$ 5,152.00
GRAND TOTAL		\$ 34,500.00	\$ 10,546.56

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant