

Khanchna (LKK Auto)

From: Taufikh (LKKAuto)
Sent: 4 September 2020 11:55 AM
To: Khanchna (LKK Auto)
Subject: RE: AMENDED FINAL REVISION - SKD4476H - TP AIG - SURVEYED 09 OCT 2019 RE-SURVEYED 21 OCT 2019

Hi Khanchna,

AIR FILTER - CRACK
FRONT NO PLATE - NECESSARY
SUNDRIES - NECESSARY

Regards
Taufikh

From: Khanchna (LKK Auto) [mailto:khanchna@lkkauto.com]
Sent: Friday, 4 September 2020 10:52 AM
To: Taufikh (LKKAuto)
Subject: FW: AMENDED FINAL REVISION - SKD4476H - TP AIG - SURVEYED 09 OCT 2019 RE-SURVEYED 21 OCT 2019

Hi Taufikh,

Please let me know the conditions for the item 63, 66 and 67.

Material List for Accident Vehicle Regn No. SKD 4476 H				
S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		6/7	\$	5,100.56
61	INTAKE MANIFOLD		\$ 88.00	
62	BELLOWS		\$ 98.00	
63	AIR FILTER		\$ 279.00	\$ 223.20
64	AIR MASS METER		\$ 533.00	
65	INTAKE MANIFOLD		\$ 133.00	
66	FRONT NO PLATE	S/N	\$ 40.00	\$ 40.00
67	SUNDRIES		\$ 500.00	\$ 38.80
TOTAL SPARE PARTS			\$ 22,468.00	\$ 5,394.56
TOTAL LABOUR CHARGES			\$ 12,032.00	\$ 5,152.00
GRAND TOTAL			\$ 34,500.00	\$ 10,546.56
All charges are not inclusive of GST.				
Legend: Remarks (OK) = Approved, Remarks (N) = Not approved				
Spares parts are Special Net.				

Thank you.

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)