

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 59655**AAD1910-018***Not Notified**Resumy B4 point*

4107.43

~~8467.43~~

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

07 OCT 2019

SHD 59655

JTDKB3FU703075517

TOYOTA

PRIUS

2.10.19

AIG

1/11/2018

		PART
1	1	FRONT BUMPER
2	1	FRONT BUMPER SIDE RETAINER LH
3	1	ABSORBER, FRONT BUMPER, LOWER
4	1	ABSORBER, FRONT BUMPER ENERGY
5	1	FRONT LED LAMP (LOWER) LH
6	1	FRONT HEADLAMP LH
7	1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1
8	1	MOTOR, HEADLAMP LEVELING, LH
9	1	FRONT FENDER LH
10	1	LINER, FRONT FENDER, LH
11	1	FRONT FENDER EMBLEM LH
12	1	GRILLE SUB-ASSY, RADIATOR
13	1	GRILLE, RADIATOR, LOWER NO.1
14	1	FRONT BONNET
15	1	HINGE ASSY, HOOD, LH

		LIST
\$	Bu	516.00 ✓
\$	DIV	82.30 ✓
\$	Sn	132.70 X
\$	Sn	79.60 X
\$	Sn	951.40 ✓
\$	Sn	2,637.60 ✓
\$	Sn	960.50 X
\$	Sn	487.50 ✓
\$	Sn	977.80 X
\$	Sn	202.50 X
\$	Sn	54.60 ✓
\$	Sn	346.00 X
\$	Sn	170.10 X
\$	Sn	983.10 X
\$	Sn	58.90 X

TOTAL \$ 8,640.60**25% \$ 2,160.15****\$ 6,480.45****Special Nett**

1	1	FRONT WHEEL RIM
2	1	FRONT WHEEL RIM COVER
3	1	FRONT TYRE 195/65/15
4	1	CLIP, FRONT FENDER LINER
5	1	FRONT NUMBER PLATE WITH MOULDING
6	1	BUMPER CLIP FRT

\$	Sn	1,570.55 X
\$	Sn	175.80 X
\$	Sn	350.00 X
\$	Sn	22.00 X
\$	Sn	200.00 X
\$	Sn	66.00 ✓

TOTAL \$ 2,384.35**TOTAL PARTS \$ 8,864.80**

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 59655**AAD1910-018****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00	4001
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of Front Bonnet fittings, attachments and perform water seepage test.	\$	nn 170.00	X

TOTAL \$ 11,000.00**Over All Total \$ 19,864.80**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(PART-BY-PART) Repair Days

15 days

2 days