

(Release)

INS. CASE OWNER:

CC 6 / AIG1901 7707, Aetna

LKK:
IDAC:

Surveyor:

Admin

DOI:

ASSIGNMENT

7/10/19

Date / Time:

7/10/19

Registered in Merimen:

8/10/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJW 1777

Name of Insured:

LEO SUNNY MOON

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A:

4/10/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

WONG FOONG MEI WONG MEI

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

5124574344

Policy No.:

1800001411

Make / Model:

MERCEDES

Place of Accident:

PIE

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKL 5112J

SJW 1777

SUD 3A39J

SKL 8213P



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

Sin

Hwee

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time	STAGE	DATE/ PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
07/11/19	Call OI:	10.10.19
	After call ltr to OI:	
	Documentation Check List: Handler	Typist
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE Date/Time:		Sent By:	
FINALIZATION Date/Time:		Confirm with:	
Repair Cost:	S\$ 10,000	(14 days) Reduction:	63 %
FINAL SETTLEMENT Date/Time: 10-01-20		Confirm with: KME	
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	28
Repair Cost:	S\$ 10,000	5VEN CC 010 300	
Loss of Rental (LOR):	S\$ 1,600	(14 days) = 1400	
Loss of Use (LOU):	S\$ -	(5 x days)	
Loss of Income (LOI):	S\$ -	(5 x days)	
LOR only ☒	LOU only ☐	LOR + LOU ☐	LOR + LOU ☐ (Tick only one)
GIA/LTA Search	S\$ 45		
Medical:	S\$ -		
Disbursement:	S\$ -	(e.g. Tow/ Independent)	
Legal Cost	S\$ -		
Total:	S\$ 11,607.45	Global Sum S\$:	
FINAL PAYMENT Date/Time: 10-01-20		Confirm with: KME	
Payee 1:	S\$ 11,607.45	Name 1:	SIN HYVAH MOON Pte Ltd
Payee 2: (Strike if N.A.)	S\$ -	Name 2:	
Payee 3: (Strike if N.A.)	S\$ -	Name 3:	

COPY SENT
16/1/2020

ASSIGNMENT

Postcode _____
 Insurance Company Name _____
 From Nature Of Damage _____ Date: _____
 Est. No. Of Passenger (Including Driver) _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV _____
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Fport: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 14 days Res.: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SW3939J Vr Regn: 2010 August
 Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Lexus 15250 cc 2500
 Colour: slues A/C: Insured / Std / NI / NA
 Sp Reading: 96303 T/Radio: Insured / Std / NI / NA

Eng/No _____
 C/No: JTHBK26270 5121522

Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17
 R: 225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal: 06 mm R/Bal: 06 mm
 L/Bal: 06 mm L/Bal: 06 mm
 D.O.A. D.O.I: 07/10/19

Survey held at: Sin Hwee

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP ALG.
	1/2: +10,000 (USD) = 16,929.92 63%
	MV: 325K
	PV: 22.1K
	Nett: 10.4K

Date/Time, File Path to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File System to?

2)

Days Of Repair:

Resurvey No. of Trip:

 Addl Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Insp. (\$)

☐ (M&I) and (\$)

Survey Fee:

Transportation:

1) \$ + PS. \$

2) Poles

3) Other

TOTAL

SIN HWEE MOTOR PTE LTD

ESTIMATE

*** Main Workshop ***

Blk 3023A Ubi Road 1 #01-59 S(408717)

*** Spray Paint Workshop @ Autobay ***

1 Kaki Bukit Avenue 6, #01-25 S(417883)

REG NO: 201327079M

TAN MILTON

DATE	5/10/2019
VEHICLE NO:	SLD 3939 J
MAKE:	LEXUS
MODEL:	IS250

TP Chassis
Asks.

QUANTITY	DESCRIPTION	UNIT	AMOUNT
1 PC	FRONT BUMPER <i>Del'd</i>	883.08	883.08 ✓
10 PCS	FRONT BUMPER CLIP <i>see</i>	3.50	35.00 ✓
2 PCS	BUMPER SIDE RETAINER <i>see</i>	69.69	139.38 ✓
1 PC	REINFORCEMENT <i>see</i>	481.65	481.65 ✓
1 PC	FRONT BUMPER SPONGE <i>see</i>	147.35	147.35 ✓
2 PCS	FRONT HEADLAMP BEAM <i>see</i>	162.03	324.06 ✓
2 PCS	FRONT HEADLAMP <i>see</i>	3,269.64	6,539.28 ✓
1 PC	FRONT BONNET <i>see</i>	1,759.11	1,759.11 ✓
8 PCS	BONNET INSULATOR CLIP <i>see</i>	3.50	28.00 ✓
1 PC	SUPPORT PANEL <i>see</i>	1,236.39	1,236.39 ✓
1 PC	SUPPORT PANEL TOP GARNISH <i>see</i>	388.77	388.77 ✓
1 PC	RADIATOR ASSY <i>see</i>	2,068.90	2,068.90 ✓
1 PC	CONDENSER <i>see</i>	1,180.46	1,180.46 ✓
1 PC	BUMPER CENTER GRILLE <i>see</i>	298.07	298.07 ✓
1 PC	CENTER GRILLE <i>see</i>	650.87	650.87 ✓
1 PC	NUMBER PLATE GARNISH <i>see</i>	160.55	160.55 ✓
1 PC	REAR BOOTLID <i>see</i>	1,260.40	1,260.40 ✓
1 PC	REAR BOOTLID GARNISH <i>see</i>	513.30	513.30 ✓
1 PC	BOOTLID CENTER LOGO <i>see</i>	69.70	69.70 ✓
1 PC	LEXUS LOGO <i>see</i>	48.90	48.90 ✓
1 PC	IS250 LOGO <i>see</i>	47.58	47.58 ✓
1 PC	BOOTLID INNER LOCK <i>see</i>	423.40	423.40 ✓
1 PC	WEATHERSTRIP <i>see</i>	192.85	192.85 ✓
1 PC	BOOTLID LAMP L/H <i>see</i>	325.63	325.63 ✓
1 PC	TAILLAMP L/H <i>see</i>	467.15	467.15 ✓
1 PC	REAR BUMPER <i>see</i>	848.55	848.55 ✓
2 PCS	RETAINER (INNER) <i>see</i>	38.90	77.80 ✓
2 PCS	RETAINER (OUTER) <i>see</i>	41.60	41.60 ✓
1 PC	TOW HOOK COVER <i>see</i>	20.11	20.11 ✓
1 PC	REAR BUMPER SPONGE <i>see</i>	107.50	107.50 ✓
1 PC	REAR BUMPER REINFORCEMENT <i>see</i>	585.63	585.63 ✓
10 PCS	REAR BUMPER CLIP <i>see</i>	3.50	35.00 ✓
1 PC	REAR BUMPER LOWER SPOILER <i>see</i>	1,580.22	1,580.22 ✓
1 PC	END PANEL <i>see</i>	585.21	585.21 ✓
1 PC	PANEL TOP GARNISH <i>see</i>	325.40	325.40 ✓
2 PCS	REVERSE SENSOR <i>see</i>	368.20	736.40 ✓

19480.27

17532.24

	SUBTOTAL		24,613.25
LESS 10%	LESS 10%	-10.00%	-2,461.33
1 SET	NUMBER PLATE AND HOLDER <i>see</i>	120.00	120.00 ✓

Tel: 6745 5783 Fax: 6744 9582

Email: sinhweemotor@gmail.com

Website: www.sinhweemotor.com

TOTAL

SIN HWEE MOTOR PTE LTD

ESTIMATE

*** Main Workshop ***

Blk 3023A Ubi Road 1 #01-59 S(408717)

*** Spray Paint Workshop @ Autobay ***

1 Kaki Bukit Avenue 6, #01-25 S(417883)

REG NO: 201327079M

TAN MILTON

DATE	5/10/2019
VEHICLE NO:	SLD 3939 J
MAKE:	LEXUS
MODEL:	IS250

QUANTITY	DESCRIPTION	UNIT	AMOUNT
-	TO INSTALL AND CALIBRATE REAR REVERSE SENSOR	60.00	60.00 ✓
-	TO DISMOUNT AND MOUNT INNER TRIMS, BOARD AND FITTINGS TO FACILITATE REPAIR WORK.	100.00	100.00 60
-	TO TRANSFER BOOTLID TRIMS, MECHANISMS AND FITTINGS TO NEW BOOTLID	100.00	100.00 60
-	TO REPLACE REAR END PANEL AND RESTORE FLOORBOARD INCLUDE KNOCKING, CUTTING AND WELDING TO REPLACE, INSTALL AND ALIGN AFFECTED PARTS TO SYMMETRICAL SPEC.	950.00	950.00 800
-	TO SUPPLY AND KOTE REAR AFFECTED PARTS	250.00	250.00 60
-	TO CARRY OUT WIRE CHECKING ON REAR AFFECTED PARTS	120.00	120.00 30
-	TO SPRAY PAINT REAR BOOTLID, BUMPER, END PANEL, FLOORBOARD AND REAR FENDER	700.00	700.00 600
-	TO DISMOUNT AND MOUNT RADIATOR AND CONDENSER TO FACILITATE REPAIR WORK TO SUPPLY AND TOP UP AIR CON GAS	300.00	300.00 120
-	4 LTS ENGINE COOLANT	3220 58.00	58.00 40
-	TO REPLACE FRONT SUPPORT PANEL INCLUDE KNOCKING, CUTTING AND WELDING TO INSTALL AND ALIGN AFFECTED PARTS TO SYMMETRICAL SPEC.	900.00	900.00 700
-	TO SPRAY PAINT FRONT BOONET, BUMPER, SUPPORT PANEL AND FENDERS	850.00	850.00 600
-	TO SUPPLY AND TUFF KOTE	150.00	150.00 60
-	TO CHECK AND CARRY OUT WIRE CHECKING	120.00	120.00 30

KK Auto Consultants

the Repairer of the following:

- To return survey before/after spray
- To display damaged parts
- Parts prices are subject to confirmation
- Third party survey is on a
- No illegal modification(s) is allowed
- Supplementary item(s) must be
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 2075.24
H/S: 10K
Adrian Lim
4/5 07/10/19
12 days

Tel: 6745 5783 Fax: 6744 9582

Email: sinhweemotor@gmail.com

Website: www.sinhweemotor.com

TOTAL \$26,929.92

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	085H
Vehicle Details	
Vehicle No.:	SLD3939J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS IS250 AUTO STD FL
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	4GR0650808
Chassis No.:	JTHBK262705121522
Maximum Power Output:	153.0 kW (205 bhp)
Open Market Value:	\$38,495.00
Original Registration Date:	03 Aug 2010
First Registration Date:	03 Aug 2010
Transfer Count:	1
Actual ARF Paid:	\$38,495.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Aug 2020
PARF Rebate Amount:	\$19,247.00
Intended COE Rebate Details	
COE Expiry Date:	02 Aug 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$34,600.00
COE Rebate Amount:	\$2,836.00
Total Rebate Amount:	\$22,083.00

The information contained herein is correct as at 07 Oct 2019

OK



New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Google Home.

Hands-free help around the house.

SEARCH

IS250

Price Range

Depreciation

Year Reg

Vehicle Type

Search

View All

Advanced Search

Used Car Comparison

Comparing 3 vehicles

Lexus IS250

Lexus IS250

Lexus IS250



Close All

Add all to Shortlist

Add to Shortlist

Add to Shortlist

Add to Shortlist

Back to search result

Use search bar above to compare.

CAR DETAILS

Price	\$33,800	\$34,800	\$35,500	-
Instalment	\$2,210	\$1,934	\$1,973	-
Registration Date	24-Sep-2010	10-Nov-2010	11-Nov-2010	-
Manufactured	2010	2010	2010	-
Mileage	92,000 km	172,000 km	136,000 km	-
Transmission	Auto	Auto	Auto	-
Engine Cap	2,500 cc	2,500 cc	2,500 cc	-
Road Tax	\$1,800 /yr	\$1,800 /yr	\$1,800 /yr	-
Power	153.0 kW (205 bhp)	153.0 kW (205 bhp)	153.0 kW (205 bhp)	-
Curb Weight	1,625 kg	1,625 kg	1,625 kg	-
Features	Powerful And Responsive 2.5L 24 Valve, V6 Dual VVT-i Engine, 6 Speed Auto Transmission, 205Bhp. Keyless Entry/Push Start, Cruise Control.	Powerful And Responsive 2.5L 24 Valve, V6 Dual VVT-i Engine, 6 Speed Auto Transmission, 205Bhp. Keyless Entry/Push Start, Cruise Control.	Powerful And Responsive 2.5L 24 Valve, V6 Dual VVT-i Engine, 6 Speed Auto Transmission, 205Bhp. Keyless Entry/Push Start, Cruise Control.	-
Accessories	Keyless Entry/Start, Cruise Control/Electric Folding Mirrors, Lexus Factory Fitted Audio System, Parking Sensors. Dual Electric Seats. Sport Rims.	Lexus Factory Fitted Audio System, Parking Sensors. Dual Electric Seats. Sport Rims, Leather Seats. Solar Film. Rear Aircon.	Lexus Factory Fitted Audio System, Parking Sensors. Dual Electric Seats. Sport Rims, Leather Seats. Solar Film. Rear Aircon.	-
Description	Excellent Condition. With Original Paintwork. Cheap And Elegant Short Term Drive. Serviced Timely And Regularly. 100% Accident Free. 100% Loan Approval With Low Interest Rate! Please Call For Test Drive Now.	Price Comes With A New Leather Work Just Done On 26/09/2109 And Also A New Paintwork! Such A Good Deal! Renew 10 Years COE At \$76388, 5 Years At \$56388. Great Condition With Original Paintwork. Trade Ins Welcome! Free Workshop Check For Your Peace Of Mind! One Of The Most Popular Entry Level Luxury Sedans All Across Asia! Durable! Free Paint Work And Leather Work. Wait No More For This Details.	Well Maintained By Careful Owner! Immaculate Condition Inside Out! Welcome Trade In/ STA Evaluation. Kindly Call/SMS For Viewing Appointment.	-
COE	\$43,334	\$44,001	\$44,001	-
OMV	\$38,845	\$38,280	\$38,495	-
ARF	\$38,845	\$38,280	\$38,495	-
Depreciation	\$14,910 /yr	\$14,330 /yr	\$14,830 /yr	-
No. of Owners	2	3	2	-
Type of Vehicle	Luxury	Luxury	Luxury	-
Category	PARF Car	PARF Car, Consignment Car	PARF Car, Premium Ad Car	-
Availability	Available	Available	Available	-

SELLER INFORMATION

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Friday, 11 October 2019 10:50 AM
To: Khim Goh
Subject: ACCIDENT INVOLVING SLD 3939J & SJW 177J ON 04/10/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir/Madam,

ACCIDENT INVOLVING SLD 3939J & SJW 177J ON 04/10/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher@sng.lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

K.M

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	08 Oct 2019 14:38	Cim Dtl Modified	Claimant's Name: -> TAN MILTON. Claimant's ID: -> S1607085H.	[A] Lau Shu Pei
2	08 Oct 2019 14:38	Cim Veh Model Changed	(202456) LEXUS IS250 2.5 STD FL (A).	[A] Lau Shu Pei
3	08 Oct 2019 14:38	Cim Created	Reg No: SLD3939J. Acct Date: 2019/10/04. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). TP Insurer: Tokio Marine Insurance Singapore Ltd (HQ). Workshop: Sin Hwee Motor Pte Ltd (HQ)	[A] Lau Shu Pei
4	08 Oct 2019 14:38	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
5	08 Oct 2019 14:38	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/10/17	[A] Lau Shu Pei
6	08 Oct 2019 14:38	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
7	08 Oct 2019 14:38	Cim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
8	08 Oct 2019 14:39	Label Added	(19):Fastlane.	[A] Lau Shu Pei
9	08 Oct 2019 14:39	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] Lau Shu Pei
10	10 Oct 2019 09:18	Cim Registration Modified	Acct Time:14:00:00->14:55:00.	[I] AIG OneClaim Integration User
11	21 Nov 2019 17:07	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
12	21 Nov 2019 17:07	Cim Dtl Modified	3PJ Reg. Date: -> 2010/08/03.	[A] JOANNE LEE KHANG MIN
13	21 Nov 2019 17:07	Cim Details Notified		[A] JOANNE LEE KHANG MIN
14	22 Nov 2019 16:56	Adj Mandate Request	CutReq:11607.45:LIABILITY: 100% B:28 5VEH CC OID 3RD	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2307088	09 Oct 2019 11:50:18	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	AIG Asia Pacific Insurance Pte. Ltd. (Express)	SLD3939J	SJW177J	11.77
2353011	21 Nov 2019 17:07:46	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLD3939J	SJW177J	11.77

Print Received Message

This mail is associated with :

*SLD3939J (5129512432SG)
[SJW177J]
TP
TAN MILTON
Oct 4 2019 2:55PM
[LEO SUNG HOON]
Sin Hwee Motor Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 09/01/2020 14:45 PM
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$11607.45) - SLD3939J - Claim Handler: Chan, Kian-Meng

Approved:11607.45.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Oct 2019 Edit Reg		07 Oct 2019 00:00 Edit Adj Rpt	\$510,000.00 Edit Estimates	\$510,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LEO SUNG HOON, ID: S0076974F		
Main Claimant:	TAN MILTON, ID: S1607085H		
Vehicle Reg. No.:	SLD3939J	Date of Loss:	04/10/2019 14:00 - :59 [110 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 51295124325G	Policy/Cover Note No.:	1800001411 (Comprehensive)
Vehicle Reg. No. (Insured):	SJW177J	Policy No. (Claimant):	19-MT105324-R01
		Excess:	
Repairer:	Sin Hwee Motor Pte Ltd (HQ) Blk 3023A, Ubi Road 1, #01-59, 408717 Ubi - Tel: 67455783		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 17/10/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (09/01/2020): Alert - Adj Mandate Approved (\$511607.45) - SLD3939J - Claim Handler: Chan, Kian...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLD3939J (5129512432SG)
[SJW177J]
TP
TAN MILTON
Oct 4 2019 2:55PM
[LEO SUNG HOON]
Sin Hwee Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser					
Letters/Correspondences															1 per page			☒					
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print					
1	{Draft}		Third Party Express Settlement – Payment Breakdown												1			Edit					
Photos/Images															3 per page			☒					
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print					
1	04/11/19 14:23		General View												1			Load JPG			☒		
2	04/11/19 14:23		General View												1			Load JPG			☒		
3	04/11/19 14:23		General View												1			Load JPG			☒		
4	04/11/19 14:23		General View												1			Load JPG			☒		
5	04/11/19 14:23		General View												1			Load JPG			☒		
6	04/11/19 14:23		General View												1			Load JPG			☒		
7	04/11/19 14:23		General View												1			Load JPG			☒		
8	04/11/19 14:23		General View												1			Load JPG			☒		
9	04/11/19 14:23		General View												1			Load JPG			☒		
10	04/11/19 14:23		General View												1			Load JPG			☒		
11	04/11/19 14:23		General View												1			Load JPG			☒		
12	04/11/19 14:23		General View												1			Load JPG			☒		
13	04/11/19 14:23		General View												1			Load JPG			☒		
14	04/11/19 14:23		General View												1			Load JPG			☒		
15	04/11/19 14:23		General View												1			Load JPG			☒		
16	04/11/19 14:23		General View												1			Load JPG			☒		
17	04/11/19 14:23		General View												1			Load JPG			☒		
18	04/11/19 14:23		General View												1			Load JPG			☒		
19	04/11/19 14:23		General View												1			Load JPG			☒		
20	04/11/19 14:23		General View												1			Load JPG			☒		
21	04/11/19 14:23		General View												1			Load JPG			☒		
22	04/11/19 14:23		General View												1			Load JPG			☒		
23	04/11/19 14:23		General View												1			Load JPG			☒		
24	04/11/19 14:23		General View												1			Load JPG			☒		
25	04/11/19 14:23		General View												1			Load JPG			☒		
26	04/11/19 14:23		General View												1			Load JPG			☒		
27	04/11/19 14:23		General View												1			Load JPG			☒		
28	04/11/19 14:23		General View												1			Load JPG			☒		
29	04/11/19 14:23		General View												1			Load JPG			☒		
30	04/11/19 14:23		General View												1			Load JPG			☒		
31	04/11/19 14:23		General View												1			Load JPG			☒		
32	04/11/19 14:23		General View												1			Load JPG			☒		
33	04/11/19 14:23		General View												1			Load JPG			☒		
34	04/11/19 14:23		General View												1			Load JPG			☒		
35	04/11/19 14:23		General View												1			Load JPG			☒		
36	04/11/19 14:23		General View												1			Load JPG			☒		
37	04/11/19 14:23		General View												1			Load JPG			☒		
38	04/11/19 14:23		General View												1			Load JPG			☒		
39	04/11/19 14:23		General View												1			Load JPG			☒		
40	04/11/19 14:23		General View												1			Load JPG			☒		

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	04/11/19 14:23	General View	 Load JPG	☒
42	04/11/19 14:23	General View	 Load JPG	☒
43	04/11/19 14:23	General View	 Load JPG	☒
44	04/11/19 14:23	General View	 Load JPG	☒
45	04/11/19 14:23	General View	 Load JPG	☒
46	04/11/19 14:23	General View	 Load JPG	☒
47	04/11/19 14:23	General View	 Load JPG	☒
48	04/11/19 14:23	General View	 Load JPG	☒
49	04/11/19 14:23	General View	 Load JPG	☒
50	04/11/19 14:23	General View	 Load JPG	☒
51	04/11/19 14:23	General View	 Load JPG	☒
52	04/11/19 14:23	General View	 Load JPG	☒
53	04/11/19 14:23	General View	 Load JPG	☒
54	04/11/19 14:23	General View	 Load JPG	☒
55	04/11/19 14:23	General View	 Load JPG	☒
56	04/11/19 14:23	General View	 Load JPG	☒
57	04/11/19 14:23	General View	 Load JPG	☒
58	04/11/19 14:23	General View	 Load JPG	☒
59	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
60	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
61	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
62	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
63	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
64	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
65	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
66	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
67	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
68	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
69	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
70	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
71	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
72	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
73	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
74	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
75	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
76	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
77	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
78	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
79	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
80	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
81	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
82	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
83	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
84	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
85	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
86	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
87	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
88	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
89	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
90	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
91	04/11/19 14:23	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/10/19 17:06	TP GIA REPORT	 Load PDF	
2	22/11/19 10:12	RENTAL RECEIPT	 Load PDF	

Letters/Correspondences				1 per page	☒
No	Finalized On			Thumbnail	Print
3	22/11/19 10:12	LKK Auto Consultants Pte Ltd (HQ)			
		LTA SEARCH		Load PDF	
4	22/11/19 10:12	LOD		Load PDF	
5	22/11/19 10:12	LETTER TO OI		Load PDF	
6	17/01/20 11:28	WORKSHOP INVOICE		Load PDF	
7	17/01/20 11:28	AUTHORISATION TO ACT FORM		Load PDF	
8	17/01/20 11:28	Release Voucher		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	09/10/19 11:45	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJW177J (Insd veh)	Model:	LEXUS IS250 2.5 STD FL (A)
	SLD3939J (TP veh)		
Date of Accident:	04/10/2019		

Global Sum Settlement :	☐ Yes	☒ No
Repair Estimate	: \$	26,929.92
Final Repair Cost	: \$	10,000.00
Loss of Use	: \$	days at \$0.00 per day
Rental (if any)	: \$	1,600.00 16 days
LTA / GIA Search Fee	: \$	7.45
Others:	: \$	0.00
	: \$	
Final Settlement Sum	: \$	11,607.45

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ 0 ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Sin Hwee Motor Pte Ltd	: \$	11,607.45
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

17 Jan
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19017707/AEA3Q2

Date: 17/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800001411

Claimant Vehicle No : SLD3939J Insured Vehicle No : SJW177J

Date of Loss: 04/10/2019 Nature of Claim: TP Claim No: 5129512432SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLD3939J

Make & Model: LEXUS IS250, 2.5 STD FL (A)

Reg. Date: 03/08/2010 (Man. Year: 2010)

Colour: Silver

Engine Capacity: 2500 cc

Market Value/New Car Price: N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

Engine No: 4GR0650808

Chassis No: JTHBK262705121522

Odometer: 96303 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,271.92	17,532.24	4,739.68	21.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,658.00	3,220.00	1,438.00	30.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,929.92	20,752.24	6,177.68	22.94
Approved Total (Overridden) (S\$)		10,000.00		
Nett Amount (S\$)	26,929.92	10,000.00	16,929.92	62.87
+ Car Rental (16.0 x S\$100.00/day) (S\$)		1,600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		11,607.45		

INSPECTION

Date of Assignment: 07/10/2019

Date Inspected: 07/10/2019 Inspected At:

Sin Hwee Motor Pte Ltd (HQ)
Blk 3023A, Ubi Road 1, #01-59
Singapore 408717

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	883.08 FL	*883.08 FL
2	10		*FRONT BUMPER CLIP	Necessary	35.00 FL	*35.00 FL
3	2		*BUMPER SIDE RETAINER	Necessary	139.38 FL	*139.38 FL
4	1		*REINFORCEMENT	Bent	481.65 FL	*481.65 FL
5	1		*FRONT BUMPER SPONGE	Cracked	147.35 FL	*147.35 FL
6	2		*FRONT HEADLAMP BEAM	Not Necessary	324.06 FL	*- FL
7	2		*FRONT HEADLAMP	Cracked	6,539.28 FL	*6,539.28 FL
8	1		*FRONT BONNET	Buckled	1,759.11 FL	*1,759.11 FL
9	8		*BONNET INSULATOR CLIP	Necessary	28.00 FL	*28.00 FL
10	1		*SUPPORT PANEL	Buckled	1,236.39 FL	*1,236.39 FL
11	1		*SUPPORT PANEL TOP GARNISH	Not Necessary	388.77 FL	*- FL
12	1		*RADIATOR ASSY	Not Necessary	2,068.90 FL	*- FL
13	1		*CONDENSER	Dented	1,180.46 FL	*1,180.46 FL
14	1		*BUMPER CENTER GRILLE	Not Necessary	298.07 FL	*- FL
15	1		*CENTER GRILLE	Cracked	650.87 FL	*650.87 FL
16	1		*NUMBER PLATE GARNISH	Deformed	160.55 FL	*160.55 FL
17	1		*REAR BOOTLID	Repair	1,260.40 FL	*- FL
18	1		*REAR BOOTLID GARNISH	Cracked	513.30 FL	*513.30 FL
19	1		*BOOTLID CENTER LOGO	Necessary	69.70 FL	*69.70 FL
20	1		*LEXUS LOGO	Necessary	48.90 FL	*48.90 FL
21	1		*IS250 LOGO	Necessary	47.58 FL	*47.58 FL
22	1		*BOOTLID INNER LOCK	Damaged	423.40 FL	*423.40 FL
23	1		*WEATHERSTRIP	Cut	192.85 FL	*192.85 FL
24	1		*BOOTLID LAMP L/H	Not Necessary	325.63 FL	*- FL
25	1		*TAILLAMP L/H	Not Necessary	467.15 FL	*- FL
26	1		*REAR BUMPER	Deformed	848.55 FL	*848.55 FL
27	2		*RETAINER (INNER)	Necessary	77.80 FL	*77.80 FL
28	2		*RETAINER (OUTER)	Necessary	41.60 FL	*41.60 FL
29	1		*TOW HOOK COVER	Deformed	20.11 FL	*20.11 FL
30	1		*REAR BUMPER SPONGE	Cracked	107.50 FL	*107.50 FL
31	1		*REAR BUMPER REINFORCEMENT	Bent	585.63 FL	*585.63 FL
32	10		*REAR BUMPER CLIP	Necessary	35.00 FL	*35.00 FL
33	1		*REAR BUMPER LOWER SPOILER	Deformed	1,580.22 FL	*1,580.22 FL
34	1		*END PANEL	Dented	585.21 FL	*585.21 FL
35	1		*PANEL TOP GARNISH	Deformed	325.40 FL	*325.40 FL
36	2		*REVERSE SENSOR	Damaged	736.40 FL	*736.40 FL
37	1		*SET NUMBER PLATE AND HOLDER	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,733.25	19,480.27
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,461.33	1,948.03
Total Parts (\$\$)	22,271.92	17,532.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO INSTALL AND CALIBRATE REAR REVERSE SENSOR	New	60.00	60.00
2	TO DISMOUNT AND MOUNT INNER TRIMS ,BOARD AND FITTINGS TO FACILITATE REPAIR WORK	New	100.00	60.00
3	TO TRANSFER BOOTLID TRIMS ,MECHANISM AND FITTINGS TO NEW BOOTLID	New	100.00	60.00
4	TO REPLACE ,REAR END PANEL AND RESTORE FLOORBOARD INCLUDE KNOCKING ,CUTTING AND WELDING TO REPLACE ,INSTALL AND ALIGN AFFECTED PARTS TO SYMMETRICAL SPEC	New	950.00	800.00
5	TO SUPPLY AND KOTE REAR AFFECTED PARTS	New	250.00	60.00
6	TO CARRY OUT WIRE CHECKING ON REAR AFFECTED PARTS	New	120.00	30.00
7	TO SPRAY PAINT REAR BOOTLID ,BUMPER ,END PANEL,FLOORBOARD AND REAR FENDER	New	700.00	600.00
8	TO DISMOUNT AND MOUNT RADIATOR AND CONDENSER TO FACILITATE REPAIR WORK TO SUPPLY AND TOP UP AIR CON GAS	New	300.00	120.00
9	4 LTS ENGINE COOLANT	New	58.00	40.00
10	TO REPLACE FRONT SUPPORT PANEL INCLUDE KNOCKING ,CUTTING AND WELDING TO INSTALL AND ALIGN AFFECTED PARTS TO SYMMETRICAL SPEC	New	900.00	700.00
11	TO SPRAY PAINT FRONT BONNET ,BUMPER ,SUPPORT PANEL AND FENDERS	New	850.00	600.00
12	TO SUPPLY AND TUFF KOTE	New	150.00	60.00
13	TO CHECK AND CARRY OUT WIRE CHECKING	New	120.00	30.00
Gross Labour Cost (S\$)			4,658.00	3,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >