



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

✉ zoomautowerks@gmail.com

Car Number: SLP8803X

Model: PEUGEOT 2008 *ALL*

Date: 09/10/2019

Not Anthony Hall

Damaged Area: (Rear Portion Damaged)

*1/5 @ 3900
Hday.
9/10/19*

Supplementary may be included during the cost of repair :

Parts / Material :

	Quantity		
1 Rear Bumper	<i>10/12</i>	\$	780.00 ✓
2 Rear Bumper End Side	<i>1 1</i>	\$	198.00 X
3 Rear Bumper Side Reflector	<i>\$265.00 X 2pcs 1 1</i>	\$	530.00 X
4 Rear Bumper Inner Top Support	<i>one</i>	\$	350.00 ✓
5 Rear Bumper Reinforcement	<i>set</i>	\$	480.00 ✓
6 Rear Bumper Clips	<i>\$6.00 X 10pcs 11</i>	\$	60.00 ✓
7 Rear Tailgate Panel	<i>10</i>	\$	1,500.00 ✓
8 MKT Rear Tailgate Fixing	<i>11</i>	\$	90.00 X
9 Rear Tailgate Badge (2008)	<i>11</i>	\$	84.00 ✓
10 Rear Tailgate Badge (HDI)	<i>11</i>	\$	45.00 ✓
11 Rear Tailgate Badge (PEUGEOT)	<i>11</i>	\$	98.00 ✓
12 Rear Tailgate LOGO	<i>11</i>	\$	174.00 ✓
13 Rear Tailgate Windscreen InnerSeal	<i>11</i>	\$	195.00 ✓
14 Rear Tailgate Lock Assy	<i>1 1</i>	\$	385.00 X
15 Rear Tailgate Outer Garnish	<i>1 1</i>	\$	495.00 X
16 Rear Tailgate Inner Rubber	<i>1 1</i>	\$	356.00 X
17 Rear Tailgate Lamp	<i>\$375.00 X 2pcs 1 1</i>	\$	750.00 X
18 Rear Taillamp	<i>\$480.00 X 2pcs 1 1</i>	\$	960.00 X
19 Rear Taillamp Lower Bracket	<i>\$80.00 X 2pcs 1 1</i>	\$	160.00 X
20 Rear End Panel	<i>1 1</i>	\$	570.00 X
21 Rear End Panel Top Garnish	<i>1 1</i>	\$	395.00 X
22 Rear Exhaust End Pipe	<i>1 1</i>	\$	1,426.00 X
23 Rear Exhaust Chrome Muffler	<i>1 1</i>	\$	228.00 X
24 Rear Bumper Reverse Sensor	<i>\$300.00 X 2pcs 1 1</i>	\$	600.00 <i>2005.2</i>
25 Reverse Sensor Bracket	<i>\$85.00 X 2pcs 1 1</i>	\$	170.00 X
26 Reverse Sensor Holder Seal Rubber	<i>\$35.00 X 2pcs 1 1</i>	\$	70.00 X

Parts : \$ 11,149.00

Less Parts 10% : \$ 1,114.90

Total Parts : \$ 10,034.10

Special Net Items :

Rear Number Plate With Garnish

\$ 11 80.00 X

Reverse Camera

\$ 11 580.00 X

Rear End Panel Sealant

\$ 11 100.00 7

Rear Tailgate Glass Sealant

\$ 100 100.00 40 S.N

Total S/N Parts : \$ 860.00**Labour :**

To Remove & Renew Rear Affected Accident Areas

\$ 1,400.00 450

To Putty, Spray Paint on Rear Affected Accident Areas

\$ 1,200.00 600

To Remove & Install Rear Tailgate Glass

\$ 250.00 120

To Check & Re-Connect all electrical wiring

\$ 150.00 30

To Re-position & Install Reverse Sensor

\$ 250.00 50

To Re-Programme & Reset Diagnostic

\$ 11 450.00 X

To Rust Proof Affected Areas

\$ 250.00 40

Total Labour : \$ 3,950.00**TOTAL PARTS : \$ 10,034.10****TOTAL SPECIAL NET ITEM : \$ 860.00****TOTAL LABOUR : \$ 3,950.00****TOTAL REPAIR COST : \$ 14,844.10**

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM :

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :

FINALISED AMOUNT :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-3766
102
P-3389.40
S.N-240.00
L-1290.00
4919.40
202
3935.52