

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19017713/T1GB3N2

Date: 20/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLC1779Y	Insured Vehicle No :	SHA1871X
Date of Loss: 06/10/2019	Nature of Claim: TP	Claim No: MCT19100142

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC1779Y		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Engine No:	1ZR562717
Reg. Date:	04/05/2016 (Man. Year: 2016)	Chassis No:	MR053REH104548860
Colour:	Blue	Odometer:	204888 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,082.10	1,322.25	2,759.85	67.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,900.00	1,740.00	2,160.00	55.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,982.10	3,062.25	4,919.85	61.64
Approved Total (Overridden) (\$\$)		2,900.00		
(\$\$)	7,982.10	2,900.00	5,082.10	63.67
+ GST 7.00/7.00% (\$\$)	558.75	203.00	355.75	63.67
Nett Amount (\$\$)	8,540.85	3,103.00	5,437.85	63.67
+ Car Rental (5.0 x S\$85.00/day + 7.00% GST) (\$\$)		454.75		
Nett Liability (\$\$)		3,557.75		

INSPECTION

Date of Assignment:	11/10/2019	
Date Inspected:	11/10/2019 Inspected At:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road Singapore 629705
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Nov 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC1779Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	755.00 FL	*- FL
2	2		*BOOTLID HINGE LH/RH	Not Necessary	136.00 FL	*- FL
3	1		*BOOTLID CHROME	Not Necessary	232.00 FL	*- FL
4	1		*BOOTLID LOGO	Necessary	60.00 FL	*60.00 FL
5	1		*BOOTLID ALTIS LOGO	Necessary	42.00 FL	*42.00 FL
6	1		*BOOTLID COROLLA LOGO	Necessary	42.00 FL	*42.00 FL
7	2		*BOOTLID LAMP LH/RH	Not Necessary	710.00 FL	*- FL
8	10		*BOOTLID INSULATOR CLIPS	Not Necessary	55.00 FL	*- FL
9	1		*REAR BUMPER	Deformed	485.00 FL	*485.00 FL
10	10		*REAR BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
11	2		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	240.00 FL	*- FL
12	1		*REAR BUMPER REINFORCEMENT	Bent	395.00 FL	*395.00 FL
13	1		*REAR END PANEL	Repair	590.00 FL	*- FL
14	1		*REAR END PANEL TOP GARNISH	Deformed	240.00 FL	*240.00 FL
15	10		*REAR END PANEL TOP GARNISH CLIPS	Necessary	59.00 FL	*59.00 FL
16	1		*BOOTLID LOCK	Bent	385.00 FL	*385.00 FL
17	2		*TAILLAMP LH/RH	Not Necessary	790.00 FL	*- FL
18	2		*TAILLAMP WHITE CLIPS	Not Necessary	11.80 FL	*- FL
19	2		*TAILLAMP LOWER BRKT LH/RH	Repair	160.00 FL	*- FL
20	1		*FRONT FENDER RH (NPA)	Repair	0.00 FS	*- FS
21	1		*FRONT FENDER LH (NPA)	Repair	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,442.80	1,763.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,360.70	440.75
Total Parts (\$\$)	4,082.10	1,322.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEAT ,CUT,WELD ,RE-ALIGN & REPLACE DAMAGED PARTS OF FRONT AFFECTED AREA	New	1,500.00	750.00
2	PANEL BLEND AND SPRAY PAINT ON FRONT BUMPER ,FRONT FENDER RH & LH	New	1,500.00	750.00
3	REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR	New	200.00	60.00
4	DISMANTLE & TRANSFER BOOTLID FITTING & MECHANISM TO NEW BOOTLID	New	200.00	60.00
5	REMOVE & REINSTALL 2 PIECES OF BUMPER SENSORS	New	150.00	30.00
6	REMOVE & REINSTALL REAR REVERSE CAMERA	New	150.00	30.00
7	CONDUCT WATER SEEPAGE TEST	New	120.00	30.00
8	CHECK WIRING ,RE-ALIGN HEADLAMPS & TAILLAMPS ,ENSURE PROPER FUNCTIONING	New	80.00	30.00
Gross Labour Cost (\$\$)			3,900.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >