

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE dated 29/08/2019

III	ACCIDENT DATE	: 06/10/2019@0345
	VRN	: SLC1779Y
ATTN: MOTOR CLAIMS DEPT	MODEL	: TOYOTA ALTIS 1.6
	TP VRN	: SHA1871X

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 BOOTLID	1	\$ 755.00	\$ 755.00	RY
2 BOOTLID HINGE LH/RH	2	\$ 68.00	\$ 136.00	X
3 BOOTLID CHROME	1	\$ 232.00	\$ 232.00	X
4 BOOTLID LOGO	1	\$ 60.00	\$ 60.00	new
5 BOOTLID ALTIS LOGO	1	\$ 42.00	\$ 42.00	new
6 BOOTLID COROLLA LOGO	1	\$ 42.00	\$ 42.00	new
7 BOOTLID LAMP LH/RH	2	\$ 355.00	\$ 710.00	X
8 BOOTLID INSULATOR CLIPS	10	\$ 5.50	\$ 55.00	X
9 REAR BUMPER	1	\$ 485.00	\$ 485.00	de -
10 REAR BUMPER CLIPS	10	\$ 5.50	\$ 55.00	new
11 REAR BUMPER SIDE RETAINER LH/RH	2	\$ 120.00	\$ 240.00	?
12 REAR BUMPER REINFORCEMENT	1	\$ 395.00	\$ 395.00	bt -
13 REAR END PANEL	1	\$ 590.00	\$ 590.00	bt ✓
14 REAR END PANEL TOP GARNISH	1	\$ 240.00	\$ 240.00	de -
15 REAR END PANEL TOP GARNISH CLIPS	10	\$ 5.90	\$ 59.00	new
16 BOOTLID LOCK	1	\$ 385.00	\$ 385.00	bt -
17 TAILLAMP LH/RH	2	\$ 395.00	\$ 790.00	?
18 TAILLAMP WHITE CLIPS	2	\$ 5.90	\$ 11.80	?
19 TAILLAMP LOWER BRKT LH/RH	2	\$ 80.00	\$ 160.00	?
			\$ 5,442.80	
Discount -25%			\$ 1,360.70	
			\$ 4,082.10	
5 FRONT FENDER RH	Repair			
6 FRONT FENDER LH	Repair			
	PARTS TOTAL		\$ 4,082.10	

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of Rear Affected Area	\$ 1,500.00	1000
Putty, Blend And Spray Paint on Rear Bumper, Rear Fender RH & LH, boot lid & Rear end panel	\$ 1,500.00	1000
Remove & refit rear end panel lining & garnish to facilitate repair	\$ 200.00	60
Dismantle & transfer bootlid fitting & mechanism to new bootlid	\$ 200.00	60
Remove & reinstall 2 pieces of bumper sensors	\$ 150.00	30
Remove & reinstall rear reverse camera	\$ 150.00	30

Conduct water seepage test
Check Wiring, Re-align Headlamps & Taillamps, Ensure Proper Functioning

\$ 120.00
\$ 80.00

30
30

LABOURS TOTAL

\$ 3,900.00

Grand Total : \$ 7,982.10

Add 7% GST : \$ 558.75

Nett Total : \$ 8,540.85

No. of repair days: 7



CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

Tanflm 97445749
WP'
11/10/19 @ 3pm
Resurvey before paint
05 days
Tanflm 11/10/19

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: