

JOEN (1/13) Wef
ASS. REC. BY: MORIS

REF:


101/

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SGE 31130
at Workshop m/s: pruice
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

6847
Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SGE 31130 Yr Regn: 1/3, 12
Type: ☒ M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA
Make: BMW 328i c.c. 1997
Colour: white A/C: Insured / Std / NI / NA
Sp. Reading: 140823 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WBA3A52020F253478
Gen. Cond: ☒ Good / Fair / Poor / Burnt
Steering: ☒ Good / Jammed / Leaked / Burnt or
Brake: ☒ Good / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: _____ R: 225/45 R18
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ SUMI /
TOYO / YOKO or
Front: 6 mm Rear: 6 mm
R/Bal. 6 mm L/Bal. 6 mm
D.O.A. 5/10/19 D.O.I. 8/10/19
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
N/S Rear
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17A 42981

45 \$8000/- (Red- \$7,694.13 / 491)

MV: \$59,800
Rebate: \$43,981
NV: \$16,819

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$ _____) \$ + RS \$ _____
☐ : Interview (\$ _____) Photo
☐ : Tech. Invs (\$ _____) Others
☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ _____)

TOTAL

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-33/34/36 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

08-11-19

Date Of Accident : 05-10-19

Our Ref : SGE 3113D/T/19

Tan Cheng Nam

Blk 106 Spottiswoode Park Road

#19-138

Singapore 080106

LKK Auto Consultants hence notify the Repairer of the following:
 - To survey & estimate after spray painting
 - To check & estimate after spray painting
 - Parts & labour subject to confirmation
 - This estimate is on a "without prejudice" basis
 - No work is to be done until the repairer has received the necessary approval from the insurance company
 Date: 10/10/19
 Approved by Repairer

ESTIMATE BILL ON VEH. NO. : SGE 3113D

MODEL : B.M.W 318i

CHASSIS NO. : A3220115N20B20A

LIST ITEM

Rear Bumper Fascia	1225.32	Deepcut/re	1,320.00
Rear Bumper Side Retainer LH		17	80.00 X
Rear Bumper Chrome Moulding		re	131.40
Rear Bumper Clips		10pcs @ 5.00	50.00
Rear Door Assy LH		body	1,180.00
Rear Door Hinge		2pcs @ 120.00	240.00
Rear Door Checker		17	80.00 X
Rear Door Weatherstripe		re	150.00
Rear Door Stopper		re	48.00
Rear Door Inner Lock		slotted/tur	260.00
Rear Door Inner Trim Board		re/tur	630.00
Rear Door Quarter Glass Moulding		re/seat	220.00
Rear Door Window Regulator		seat	220.00
Rear Door Window Regulator Motor		re	325.00
Rear Door Window Glass Channel Rubber		re	230.00
Rear Door Outer Handle		re	120.00
Rear Door Outer Handle Knob		17	80.00 X
Rear Door Speaker		17	180.00 X

Rockel Panel Spoiler

cut/a 680.00

Rockel Panel Spoiler Bracket

11 58.00 X

Rear Knuckle Arm LH

Ref/cur 1,010.00

Rear Absorber LH

11 480.00 X

Rear Lower Arm

11 321.00 X

Rear Control Arm (Short)

cur 180.00

Rear Control Arm (Long)

11 292.00 X

Rear Trailing Arm

11 580.00 X

Rear Wheel Bearing Hup

7ye 510.00

Sport Rim Assy

cur 1,570.00 1000S-N

11,225.40

Less Discount 5%:

561.27

10,664.13

SPECIAL NETT ITEM

Rear Door Quarter Glass Sealant

11 60.00 X

Tyre Assy

see 480.00 X

LABOUR CHARGE

Towing

11 120.00 X

To check wiring system

100.00 30

To tuff coat affected areas

200.00 50

To reset electrical module system

380.00 50

To remove & refix rear LH door mechanism

280.00

To remove & refix rear LH door guater glass

150.00 } 80

To check & adjust computer wheel alignment (Before & After)

240.00 120

To remove & refix rear LH undercarriage components

400.00 150

To remove & refix rear LH sport rim & contact wheel balancing

11 120.00 X

To respray affected areas

1,250.00 1000

To renew damaged parts, straighten & repair rear LH fender, door pillar and aligned all parts

1,250.00 650

15,694.13

GST 7% :

1,098.59

TOTAL AMOUNT:

16,792.72

COMPUTERISED 4 WHEEL ALIGNMENT HUNTER DSP700

Company: PRECISE AUTO SERVICE
: SGE 3113 D
e 8.10.19 11:12



SGE 3113 D

BMW : 3 Series - F31 (2012 -) : All Rear Wheel Drive Models : Series : 18" Wheel

Front : Left

Actual	Before	Specified Range
-0°34'	-0°34'	-0°50' 0°10'
6°27'	6°27'	
0°05'	0°05'	0°05' 0°09'
22°04'	22°04'	
21°30'	21°30'	
		-1°56' -0°56'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°01'	0°01'	-0°50' 0°10'
6°51'	6°51'	
0°08'	0°08'	0°05' 0°09'
12°54'	12°54'	
12°56'	12°56'	
		-1°56' -0°56'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°35'	-0°35'	-0°30' 0°30'
-0°23'	-0°23'	-0°30' 0°30'
9°10'	9°10'	
0°13'	0°13'	0°02' 0°26'

Rear : Left

Actual	Before	Specified Range
-2°00'	-2°00'	-1°55' -1°05'
-0°07'	-0°06'	0°07' 0°11'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°34'	-1°34'	-1°55' -1°05'
0°07'	0°07'	0°07' 0°11'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°26'	-0°26'	-0°30' 0°30'
0°00'	0°01'	0°06' 0°30'
-0°07'	-0°07'	-0°12' 0°12'

COMPUTERISED 4 WHEEL ALIGNMENT HUNTER DSP700

PRECISE AUTO SERVICE
SGE 3113 D
11.10.19 18:23



SGE 3113 D

BMW : 3 Series - F31 (2012 -) : All Rear Wheel Drive Models : Series : 18" Wheel

Front : Left

Actual	Before	Specified Range
-0°28'	-0°28'	-0°50' 0°10'
5°59'	5°59'	
0°08'	0°08'	0°05' 0°09'
15°43'	15°42'	
15°14'	15°14'	
		-1°56' -0°56'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°01'	0°01'	-0°50' 0°10'
6°52'	6°52'	
0°06'	0°06'	0°05' 0°09'
12°43'	12°43'	
12°43'	12°43'	
		-1°56' -0°56'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°29'	-0°29'	-0°30' 0°30'
-0°53'	-0°53'	-0°30' 0°30'
3°00'	3°00'	
0°14'	0°14'	0°02' 0°26'

Rear : Left

Actual	Before	Specified Range
-1°26'	-1°26'	-1°55' -1°05'
0°08'	0°08'	0°07' 0°11'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°11'	-1°11'	-1°55' -1°05'
0°10'	0°10'	0°07' 0°11'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°16'	-0°16'	-0°30' 0°30'
0°19'	0°19'	0°06' 0°30'
-0°01'	-0°01'	-0°12' 0°12'

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	684F
Vehicle Details	
Vehicle No.:	SGE3113D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	08 Oct 2019
Vehicle Make:	B.M.W.
Vehicle Model:	328I 2.0 AT D/AB 4DR ABS HID NAV
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	A3220115N20B20A
Chassis No.:	WBA3A52020F253478
Maximum Power Output:	180.0 kW (241 bhp)
Open Market Value:	\$42,783.00
Original Registration Date:	01 Mar 2012
First Registration Date:	01 Mar 2012
Transfer Count:	1
Actual ARF Paid:	\$42,783.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Feb 2022
PARF Rebate Amount:	\$25,669.00
Intended COE Rebate Details	
COE Expiry Date:	28 Feb 2022
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$74,340.00
COE Rebate Amount:	\$17,312.00
Total Rebate Amount:	\$42,981.00

The information contained herein is correct as at 08 Oct 2019

OK



[New Cars](#) [Used Cars](#) [Sell My Car](#) [Directory](#) [Products](#) [Insurance](#) [Articles](#) [Forum](#) [Resources](#)

[Advanced Search](#)

Home » Used Cars » Car Empire Automobiles Pte Ltd » BMW 3 Series 328i Luxury

BMW 3 Series 328i Luxury

[Overview](#) [Financial](#) [Insurance](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#)



Price	\$59,800		
Depreciation	\$15,740 /yr View models with similar depre	Reg Date	02-Mar-2012 (2yrs 4mths 21days COE left)
Mileage	78,000 km (10.3k /yr)	Manufactured	2012
Road Tax	\$1,210 /yr	Transmission	Auto
Dereg Value	\$44,304 as of today (change)	OMV	\$44,138
COE	\$74,340	ARF	\$44,138
Engine Cap	1,997 cc	Power	180.0 kW (241 bhp)
Curb Weight	1,455 kg	No. of Owners	1
Type of Vehicle	Luxury Sedan		

Features

BMW 2.0L Twin Turbo Engine Producing 241bhp, 8 Speed Transmission, Keyless Entry/Start Function, Paddle Shifters. View specs of the BMW 3 Series Sedan (2012-2019)

Accessories

Original Factory Fitted Audio System, Leather Seats, Sports Rims, Multi Function Steering, Cruise Control, Memory Seat.

Description

1 Owner. Fully Maintained By Agent. Excellent And Original Condition. Well Maintained Interior And Exterior, Low Mileage Done, Lowest Interest Rate. Lowest Monthly Installment. Highest Trade In Value For Used Car. Fast And Hassle Free Transaction. Call Now For Viewing.

Category

MPV Car

Status

Available

Resources



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)



Car Valuation - Free
Find out the market value of your existing car for free. [Get started](#)

Printed on: 05-Oct-2019 | Last Updated on: 06-Oct-2019

Upfront Payment

[» more Financial Info](#)

Transfer Fee	\$25
Down Payment	\$17,940 (change) Maximum 70% loan



[Shortlist](#) [Compare](#) [Add note](#)
[Report Error](#) [More Actions](#)

Seller Information

Company	Car Empire Automobiles Pte Ltd • dealer's profile • 61 vms sold 48 vms available	
Address	210 Turf Club Road Lot B11 Search cars nearby this location	
Location	Car Mall @ The Golfstand	
Office No	69097310	
Contact Person (x)	Ben	88668682
	Sean	90120468
	Soon	97379527

[View Our : Used Car List / Company Profile](#)

Summer Lee (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 8 October, 2019 10:46 AM
To: Precise Auto Service; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: C Meenachi - III
Subject: RE: Pre-repair Inspection for SGE 3113D. Your Insured Vehicle no : SJA 3193H.
Attachments: 07102019163416.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SGE3113D and let us have your report urgently.

This claim will be handled by Ms Meena.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee

 **INDIA
INTERNATIONAL
INSURANCE
SINGAPORE**
Serving the region since 1987
64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

P: Arine

T: 11.08.2019

V: 1h

E. ✓

From: Precise Auto Service [mailto:Support@preciseauto.sg]
Sent: 08 October, 2019 10:12 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: Pre-repair Inspection for SGE 3113D. Your Insured Vehicle no : SJA 3193H.

Dear Sir,

We refer to your email on dated 08-10-2019. Please be informed that we would like to select **Mr. Marcus Chua** from **LKK Auto Consultants Pte Ltd** as our SJE.

Car in workshop ready for PRI.

Thank You.

Best Regards
Arine

On Tue, 8 Oct 2019 at 09:40, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- Automobile Inspection Services Pte Ltd
- VP Appraisal
- Form Team Adjusters Pte Ltd
- Infiniti Appraisal Service
- JP Knights Adjusters
- LBS Auto Consultants Pte Ltd
- Priority Services
- RT Appraisal
- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext - 248

From: Precise Auto Service [mailto:Support@preciseauto.sg]

Sent: 07 October, 2019 5:29 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Pre-repair Inspection for SGE 3113D. Your Insured Vehicle no : SJA 3193H.

Dear Sir,

We refer to the above mentioned matter, herewith enclosed 2 days notice for your attention.

Kindly arrange a date and time to do a PRI for our client vehicle (*SGE 3113D*) in our workshop ASAP.

Thank You

Best Regards

Arine

--

T : 6745 7367 | **F :** 6841 3390


E : support@preciseauto.sg

W : www.preciseauto.sg


A : No.1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883




Follow us on social media:



<https://www.instagram.com/preciseautosvs/>



<https://twitter.com/preciseautosvs>



<https://www.facebook.com/PreciseAutoService/>

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

--

T : 6745 7367 | **F :** 6841 3390

E : support@preciseauto.sg

W: www.preciseauto.sg

A : No.1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883

Follow us on social media:



<https://www.instagram.com/preciseautosvs/>



<https://twitter.com/preciseautosvs>



<https://www.facebook.com/PreciseAutoService/>

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Print Received Message

This mail is associated with :

***SGE3113P (MPC2019D0001213)**

[SJA3193H]

TP

TAN CHENG NAM

Oct 5 2019 12:00AM

[MOHAMED ALIFF BIN ZAINUDIN]

Precise Auto Service

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 05/02/2020 14:28 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (\$9910.00) - SGE3113P - Claim Handler: C. Meenachi

Approved:9910.00:OUR RECOMMENDATION IS AS FOLLOWS : COR \$8,560.00 LOR (\$150 x 9 DAYS) 1,350.00
TOTAL 9,910.00 OFFER GLOBAL \$9,500.00

PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-33/34/36 AUTOBAY SINGAPORE 417883

TEL : 6745 7367 FAX : 6841 3390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

Accident Date : 05-10-19

OUR REF : SGE 3113D/T/19(SJE)

Tan Cheng Nam

Blk 106 Spottiswoode Park Road

#19-138

Singapore 080106

TAX INVOICE

Invoice No. : TP1911-003

DATE : 15-11-19

FINAL BILL ON VEH. NO. : SGE 3113D

VEHICLE MODEL : B.M.W 318i

LUMP SUM REPAIR

INCLUDING SUPPLY OF PARTS & LABOUR

PANEL BEATING & SPRAY PAINTING

8,000.00

SUB-TOTAL : 8,000.00

ADD GST 7% : 560.00

TOTAL AMOUNT SGD : 8,560.00

This is a computer generated document and requires no signature.

Print Received Message

This mail is associated with :

***SGE3113P (MPC2019D0001213)**

[SJA3193H]

TP

TAN CHENG NAM

Oct 5 2019 12:00AM

[MOHAMED ALIFF BIN ZAINUDIN]

Precise Auto Service

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 02/03/2020 10:23 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10180.00) - SGE3113P - Claim Handler: C. Meenachi

Approved:10180.00.

...CLAIM SUBFOLDER...(Pending for Survey Report)
Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Oct 2019 Edit Reg		08 Oct 2019 00:00 Edit Adj Rpt	\$58,000.00 Edit Estimates	\$58,000.00 View Rpt		Pending for Survey Report Cancel Case

MainReferenceClaim DetailsDocumentsShow All

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	MOHAMED ALIFF BIN ZAINUDIN, ID: S87403268		
Main Claimant:	TAN CHENG NAM, ID: S0003684F		
Vehicle Reg. No.:	SGE3113D	Date of Loss:	05/10/2019 00:00 - :59 [91 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MPC2019D0001213	Policy/Cover Note No.:	D18MPC0003096
Vehicle Reg. No. (Insured):	SJA3193H	Policy No. (Claimant):	M0008816
		Excess:	
Repairer:	Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36, 417883 Kaki Bukit - Tel: 67457367		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by C. Meenachi - 6347 6073]		
Claimant's Insurer:	Etiga Insurance Pte Ltd (HQ) - Tel: 63360477		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 17/10/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- III_SG (02/03/2020): Alert - Adj Mandate Approved (\$10180.00) - SGE3113P - Claim Handler: C. Meenach...
- III_SG (05/02/2020): Alert - Adj Mandate Approved (\$9910.00) - SGE3113P - Claim Handler: C. Meenachi
- III_SG (17/01/2020): Alert - Adj Mandate Approved (\$9500.00) - SGE3113P - Claim Handler: C. Meenachi
- III_SG (26/11/2019): Alert - Adj Mandate Approved (\$0.00) - SGE3113P - Claim Handler: C. Meenachi

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGE3113D (MPC2019D0001213)
[SJA3193H]
TP
TAN CHENG NAM
Oct 5 2019 12:00AM
[MOHAMED ALIFF BIN ZAINUDIN]
Precise Auto Service

Upload DocumentsUpload PhotosCompose New LetterViewView in Browser

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/12/19 09:22	Chassis Number	 Load JPG	☒
2	30/12/19 09:22	Odometer Reading	 Load JPG	☒
3	30/12/19 09:22	General View	 Load JPG	☒
4	30/12/19 09:22	General View	 Load JPG	☒
5	30/12/19 09:22	General View	 Load JPG	☒
6	30/12/19 09:22	General View	 Load JPG	☒
7	30/12/19 09:22	General View	 Load JPG	☒
8	30/12/19 09:22	General View	 Load JPG	☒
9	30/12/19 09:22	General View	 Load JPG	☒
10	30/12/19 09:22	General View	 Load JPG	☒
11	30/12/19 09:22	General View	 Load JPG	☒
12	30/12/19 09:22	General View	 Load JPG	☒
13	30/12/19 09:22	General View	 Load JPG	☒
14	30/12/19 09:22	General View	 Load JPG	☒
15	30/12/19 09:22	General View	 Load JPG	☒
16	30/12/19 09:22	General View	 Load JPG	☒
17	30/12/19 09:22	General View	 Load JPG	☒
18	30/12/19 09:22	General View	 Load JPG	☒
19	30/12/19 09:22	General View	 Load JPG	☒
20	30/12/19 09:22	General View	 Load JPG	☒
21	30/12/19 09:23	General View	 Load JPG	☒
22	30/12/19 09:23	General View	 Load JPG	☒
23	30/12/19 09:23	General View	 Load JPG	☒
24	30/12/19 09:23	General View	 Load JPG	☒
25	30/12/19 09:23	General View	 Load JPG	☒
26	30/12/19 09:23	General View	 Load JPG	☒
27	30/12/19 09:23	General View	 Load JPG	☒
28	30/12/19 09:23	General View	 Load JPG	☒
29	30/12/19 09:23	General View	 Load JPG	☒
30	30/12/19 09:23	General View	 Load JPG	☒
31	30/12/19 09:23	General View	 Load JPG	☒
32	30/12/19 09:23	General View	 Load JPG	☒
33	30/12/19 09:23	General View	 Load JPG	☒
34	30/12/19 09:23	General View	 Load JPG	☒
35	30/12/19 09:23	General View	 Load JPG	☒
36	30/12/19 09:23	General View	 Load JPG	☒
37	30/12/19 09:23	General View	 Load JPG	☒
38	30/12/19 09:23	General View	 Load JPG	☒
39	30/12/19 09:23	General View	 Load JPG	☒
40	30/12/19 09:23	General View	 Load JPG	☒
41	30/12/19 09:23	General View	 Load JPG	☒
42	30/12/19 09:23	General View	 Load JPG	☒
43	30/12/19 09:23	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	30/12/19 09:23	General View	 Load JPG	☒
45	30/12/19 09:23	General View	 Load JPG	☒
46	30/12/19 09:23	General View	 Load JPG	☒
47	30/12/19 09:23	General View	 Load JPG	☒
48	30/12/19 09:23	General View	 Load JPG	☒
49	30/12/19 09:23	General View	 Load JPG	☒
50	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
51	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
52	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
53	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
54	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
55	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
56	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
57	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
58	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
59	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
60	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
61	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
62	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
63	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
64	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
65	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
66	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
67	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
68	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
69	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
70	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
71	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
72	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
73	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
74	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
75	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
76	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
77	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
78	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
79	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
80	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
81	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
82	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
83	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
84	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
85	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
86	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
87	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
88	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
89	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
90	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
91	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
92	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
93	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
94	30/12/19 09:25	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/10/19 15:12	EMAIL FROM III DD 08102019	 Load PDF	
2	08/10/19 15:12	WKSP NOTICE	 Load PDF	
3	09/10/19 17:31	TP GIA REPORT	 Load PDF	

Photos/Images				3 per page	☐
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
4	30/12/19 09:19	LOA AND OTHER DOCUMENTS		Load PDF	
5	30/12/19 09:19	LOD		Load PDF	
6	10/01/20 16:53	RENTAL RECEIPT		Load PDF	
7	10/01/20 16:53	LOD		Load PDF	
8	27/03/20 10:08	WORKSHOP INVOICE		Load PDF	
9	27/03/20 10:09	AUTHORISATION TO ACT FORM		Load PDF	
10	27/03/20 10:09	DISCHARGE VOUCHER		Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	09/10/19 09:00	Singapore Accident Statement		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19017716/UGS3Q2

Date: 27/03/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MPC0003098
 Claimant Vehicle No: SGE3113D Insured Vehicle No: SJA3193H
 Date of Loss: 05/10/2019 Nature of Claim: TP Claim No: MPC2019D0001213

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGE3113D
 Make & Model: BMW 328i, 2.0 (A) Engine No: A3220115N20B20A
 Reg. Date: 01/03/2012 (Man. Year: 2011) Chassis No: WBA3A52020F253478
 Colour: White Odometer: 140823 km
 Engine Capacity: 1997 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,204.13	7,792.23	3,411.90	30.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,490.00	2,210.00	2,280.00	50.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,694.13	10,002.23	5,691.90	36.27
Approved Total (Overridden) (S\$)		8,000.00		
(S\$)	15,694.13	8,000.00	7,694.13	49.03
+ GST 7.00/7.00% (S\$)	1,098.59	560.00	538.59	49.03
Nett Amount (S\$)	16,792.72	8,560.00	8,232.72	49.03
+ Car Rental (9.0 x S\$180.00/day) (S\$)		1,620.00		
Nett Liability (S\$)		10,180.00		

INSPECTION

Date of Assignment: 08/10/2019
 Date Inspected: 08/10/2019 Inspected At: Precise Auto Service (HQ)
 No 1 Kaki Bukit Ave 6, #02-34/36
 Singapore 417883
 Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jan 2020)
Parts:	143	BMW 328i 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGE3113D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Deep Cut / Deformed	1,320.00 FL	*1,205.32 FL
2	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	80.00 FL	*- FL
3	1		*REAR BUMPER CHROME MOULDING	Necessary	131.40 FL	*131.40 FL
4	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
5	1		*REAR DOOR ASSY LH	Badly Dented	1,180.00 FL	*1,180.00 FL
6	2		*REAR DOOR HINGE	Not Necessary	240.00 FL	*- FL
7	1		*REAR DOOR CHECKER	Not Necessary	80.00 FL	*- FL
8	1		*REAR DOOR WEATHERSTRIP	Necessary	150.00 FL	*150.00 FL
9	1		*REAR DOOR STOPPER	Necessary	48.00 FL	*48.00 FL
10	1		*REAR DOOR INNER LOCK	Shorted / Twisted	260.00 FL	*260.00 FL
11	1		*REAR DOOR INNER TRIM BOARD	Deformed / Twisted	630.00 FL	*630.00 FL
12	1		*REAR DOOR QUARTER GLASS MOULDING	Necessary / Bent	220.00 FL	*220.00 FL
13	1		*REAR DOOR WINDOW REGULATOR	Bent	220.00 FL	*220.00 FL
14	1		*REAR DOOR WINDOW REGULATOR MOTOR	Jammed	325.00 FL	*325.00 FL
15	1		*REAR DOOR WINDOW GLASS CHANNEL RUBBER	Necessary	230.00 FL	*230.00 FL
16	1		*REAR DOOR OUTER HANDLE	Damaged	120.00 FL	*120.00 FL
17	1		*REAR DOOR OUTER HANDLE KNOB	Not Necessary	80.00 FL	*- FL
18	1		*REAR DOOR SPEAKER	Not Necessary	180.00 FL	*- FL
19	1		*ROCKER PANEL SPOILER	Cut / Deformed	680.00 FL	*680.00 FL
20	1		*ROCKER PANEL SPOILER BRACKET	Not Necessary	58.00 FL	*- FL
21	1		*REAR KNUCKLE ARM LH	Bent / Twisted	1,010.00 FL	*1,010.00 FL
22	1		*REAR ABSORBER LH	Not Necessary	480.00 FL	*- FL
23	1		*REAR LOWER ARM	Not Necessary	321.00 FL	*- FL
24	1		*REAR CONTROL ARM (SHORT)	Twisted	180.00 FL	*180.00 FL
25	1		*REAR CONTROL ARM (LONG)	Not Necessary	292.00 FL	*- FL
26	1		*REAR TRAILING ARM	Not Necessary	580.00 FL	*- FL
27	1		*REAR WHEEL BEARING HUP	Damaged	510.00 FL	*510.00 FL
28	1		*SPORT RIM ASSY	Cut	1,491.50 FS	*1,000.00 FS
29	1		*REAR DOOR QUARTER GLASS SEALANT	Not Necessary	60.00 FS	*- FS
30	1		*TYRE ASSY	Serviceable	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,686.90	8,149.72
- List Item Discount on L Items 5.00/5.00% (S\$)	482.77	357.49
Total Parts (S\$)	11,204.13	7,792.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	120.00	0.00
2	TO CHECK WIRING SYSTEM	New	100.00	30.00
3	TO TUFF COAT AFFECTED AREAS	New	200.00	50.00
4	TO RESET ELECTRICAL MODULE SYSTEM	New	380.00	50.00
5	TO REMOVE & REFIX REAR LH DOOR MECHANISM }	New	280.00	80.00
6	TO REMOVE & REFIX REAR LH DOOR GLASS }	New	150.00	0.00
7	TO CHECK & ADJUST COMPUTER WHEEL ALIGNMENT (BEFORE & AFTER)	New	240.00	120.00
8	TO REMOVE & REFIX REAR LH UNDERCARRIAGE COMPONENTS	New	400.00	150.00
9	TO REMOVE & REFIX REAR LH SPORT RIM & CONTACT WHEEL BALANCING	New	120.00	0.00
10	TO RESPRAY AFFECTED AREAS	New	1,250.00	1,080.00
11	TO RENEW DAMAGED PARTS ,STRAIGHTEN & REPAIR REAR LH FENDER ,DOOR PILLAR AND ALIGNED ALL PARTS	New	1,250.00	650.00
Gross Labour Cost (\$\$)			4,490.00	2,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >