



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

AKA

9 October 2019

n.f. Approval
2/s = 7600
12 day.

REG NO.: SLZ 6235 X
MAKE/MODEL: HONDA FREED

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Rear tailgate <i>147.30</i>	<i>Salg 100</i> \$ 1,460.70
2	Rear tailgate dampers	<i>17</i> \$ 181.40 X
1	Rear tailgate inner board	<i>Defene</i> \$ 391.70
2	Rear tailgate lamps <i>368</i>	<i>N/S</i> \$ 736.00 <i>IPC</i>
1	Rear tailgate lock	<i>1W1</i> \$ 186.20
1	Rear tailgate logo	<i>1W1</i> \$ 90.70
1	Rear tailgate inner handle	<i>1W1</i> \$ 200.70 X
1	Rear tailgate rubber	<i>1W1</i> \$ 188.70
1	Rear tailgate "FREED" emblem	<i>1W1</i> \$ 100.30
1	Rear tailgate "HYBRID" emblem	<i>1W1</i> \$ 85.00
1	Rear number plate chrome garnish	<i>1W1</i> \$ 270.90
2	Rear taillamps	<i>1W1</i> \$ 917.40
1	Rear end panel	<i>1W1</i> \$ 520.30
1	Rear end panel inner garnish	<i>1W1</i> \$ 199.70
1	Rear end panel inner member	<i>1W1</i> \$ 300.70
1	Rear bumper <i>655.40</i>	<i>1W1</i> \$ 967.30
1	Rear bumper beam	<i>1W1</i> \$ 288.70
2	Rear bumper brackets	<i>1W1</i> \$ 95.80 X
1	Rear bumper <i>lower tray</i>	<i>1W1</i> \$ 170.00
2	Rear bumper side retainers <i>4090</i>	<i>1W1</i> \$ 81.80 <i>IPC</i>
1	Rear number plate lamp	<i>1W1</i> \$ 70.70 X
1	Rear floor panel <i>1120.00</i>	<i>cramped/</i> \$ <i>1120.00</i>
1	Rear exhaust silencer	<i>1W1</i> \$ 820.70 X
2	Rear exhaust mountings	<i>1W1</i> \$ 141.00 X
1	Rear fender <i>1W1</i>	<i>1W1</i> \$ 1,294.60 X
1	Rear fender inner trim <i>1W1</i>	<i>1W1</i> \$ 550.00
1	Rear fender quarter glass moulding	<i>1W1</i> \$ 15.00 X
		\$ 11,745.70
	Less 20%	\$ 2,349.14
		\$ 9,396.56

150%

1-786190
202
628952

SPECIAL NETT ITEMS

- 1 Rear windscreen inner seal
 1 Rear windscreen sealant
 1 Rear "PRIVATE HIRE" sticker
 1 Rear bumper clip (1 set)
 1 Rear reverse sensor (1 set)
 1 Rear reverse camera
 1 Rear fender quarter glass sealant

\$	net	85.00	30
\$	net	80.00	40
\$	11	48.00	X
\$	net	50.00	40
\$	shld	350.00	200
\$	shld	450.00	350
\$	11	50.00	X
\$		1,113.00	

660

S/N

LABOUR CHARGES

- 1 To remove, replaced damaged lamps and check up rear wiring.
 2 To remove and refit inner garnishes.
 3 To remove and refit rear reverse sensor and camera.
 4 To transfer rear tailgate mechanism and wiring assembly.
 5 To remove and refit rear windscreen glass.
 6 To remove and refit quarter glass to assist repair.
 7 To remove, refit and replace exhaust silencer and mountings.
 8 To apply undercoating.
 9 Panel beating.
 10 To re-spray painting on the affected areas.

\$		80.00	30
\$		150.00	80
\$		150.00	50
\$		120.00	60
\$		180.00	120
\$	11	120.00	X
\$	11	120.00	X
\$		180.00	100
\$		1,800.00	1400
\$		1,600.00	1200
\$		4,500.00	

3040

GRAND TOTAL :

\$ 15,009.56

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

P-7861.90
 507

P-3930.96

S.N-660.00

L-3040.00

763096