

Cecilia

利汽车喷漆私人有限公司
RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

FINALIZATION FORM

ATTN TO: STEVE-LKK
Surveyor Name and Company

Date of Accident : 7-Oct-2019

BILL TO: AXA
TP Insurer

VEHICLE REG. NO.

TYPE OF CLAIM: TP

SMA3163J

Make / Model : MAZDA 2

COST OF REPAIR

Parts Cost / List : \$ 2,666.00

Supp. Parts : \$ -

Special Nett : \$ 280.00

Total Parts : \$ 2,412.80

Total Labour : \$ 1,440.00

TOTAL REPAIR COST : \$ 3,852.80

Total Parts Cost/List :	\$	2,666.00
Plus / Less : 20%	\$	533.20
Total :	\$	2,132.80

Lump Sum Discount : 20%	\$	770.56
Lump Sum Amount:	\$	3,082.24

Final Lump Sum Amount : \$ 3,050.00

Submitted by / Date : ERIC

No. of Repair Days: 6

Confirmed by / Date : _____

利 汽 車 噴 漆 有 限 公 司 RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

Vehicle Reg. No.: **SMA3163J**
 Vehicle Reg. Date: **5/31/2018**
 Make / Model: **MAZDA 2**
 Engine No.: **P520514004**
 Chassis No.: **MM6DL2SAAJW380742**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	REAR BOOT / DO		\$ 862.00		\$ 862.00 /
2	1	REAR BOOT HINGE LH X NAI		\$ 150.00		
3	1	REAR BOOT HINGE RH X NAI		\$ 150.00		
4	1	REAR BOOT LOCK / BT		\$ 191.00		\$ 191.00 /
5	1	REAR BOOT INNER SWITCH X NAI		\$ 110.00		
6	1	REAR BOOT WEATHER STRIP / TN		\$ 113.00		\$ 113.00 /
7	1	REAR BOOT LOGO / NPC		\$ 59.00		\$ 59.00 /
8	1	REAR BOOT EMBLEM "MAZDA2" / NPC		\$ 58.00		\$ 58.00 /
9	1	REAR BOOT EMBLEM "SKYACTIV" / NPC		\$ 68.00		\$ 68.00 /
10	1	REAR BOOT LAMP LH X NAI		\$ 209.00		
11	1	REAR BOOT LAMP RH X NAI		\$ 209.00		
12	1	REAR BOOT INNER TRIM X NAI		\$ 303.00		
13	10	REAR BOOT INNER TRIM CLIPS X NAI		\$ 50.00		
14	1	REAR BUMPER / DO		\$ 455.00		\$ 455.00 /
15	1	REAR BUMPER RETAINER LH / BR		\$ 23.00		\$ 23.00 /
16	1	REAR BUMPER RETAINER RH / BR		\$ 23.00		\$ 23.00 /
17	10	REAR BUMPER CLIPS / NPC		\$ 50.00		\$ 50.00 30/
18	1	REAR BUMPER REINFORCEMENT X NAI				
19	1	REAR BUMPER SPONGE X NAI				
20	1	REAR BUMPER REFLECTOR LH X NAI		\$ 53.00		
21	1	REAR BUMPER REFLECTOR RH X NAI		\$ 53.00		
22	1	REAR LOWER BUMPER X NAI				
23	1	REAR BUMPER BRACKET LH X NAI		\$ 13.00		
24	1	REAR BUMPER BRACKET RH X NAI		\$ 13.00		
25	1	REAR BUMPER PROTECTOR NA / NPC			\$ 80.00 /	
26	1	REAR END PANEL / DO		\$ 656.00		\$ 656.00 /
27	1	REAR END PANEL TOP GARNISH / CRU		\$ 58.00		\$ 58.00 /
28	10	REAR END PANEL TOP GARNISH CLIPS / NPC		\$ 50.00		\$ 50.00 15/
29	1	TAIL LAMP LH X NAI		\$ 396.00		
30	1	TAIL LAMP RH X NAI		\$ 396.00		
31	1	REVERSE SENSOR / Short		\$ 204.00	\$ 200.00 /	
32	0	0				
33	0	0				
34	0	0				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

Steve (LKK) w/ Mr. Nade 8/10/19, 12.00pm
 5 days
 L/S, Rg Af Spg

280 / 2611
 -20%
 2088.80

Tel: 6694 3197 Fax: 6694 3191

Vehicle Reg. No. :	SMA3163J
Vehicle Reg. Date:	5/31/2018
Make / Model :	MAZDA 2
Engine No. :	P520514004
Chassis No. :	MM6DL2SAAJW380742

Estimates on Labour

[illegible]

P-2088.80
 11-280
 L-1440
 3898.80
 L/S-3047.94
 = 3050