

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: AXA INSURANCE

DATE: 7/10/2019
VEHICLE NO: SLR4545G
MODEL: MERCEDES CLA45S
YEAR: 2014
ACCIDENT DATE: 5/10/2019
TYPE OF CLAIM: TP CLAIM
CLAIM ADVISOR: LOUIS ONG (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
BOOTLID	1	REPAIR
REAR LOGO - CLA 45	1	\$ 78.50 x
REAR LOGO - AMG	1	\$ 76.40 x
REAR BUMPER	1	\$ 2,195.30 de ✓
REAR BUMPER CLIPS	10	\$ 50.00 3 ones ✓
REAR BUMPER RETAINER	2	\$ 88.60 ?
REAR BUMPER RETAINER BLADE	2	\$ 68.40 x
REAR BUMPER SIDE RETAINER - BIG	2	\$ 188.60 x
REAR BUMPER DIFFUSER	1	\$ 668.90 de ✓
REAR BUMPER GRILLE	1	\$ 257.50 at ✓
REAR REINFORCEMENT	1	\$ 768.40 ?
REAR BUMPER SPONGE	1	\$ 236.40 ?

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tan Jiah 97495749
WP
11/10/19 1145
Resurvey after repair
tanjiah@lkkauto.com
02 days

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

END PANEL	1	\$	648.30 X
SPARE TYRE PANEL - FIBER	1	\$	415.50 X
REVERSE SENSOR	2	\$	884.80 ?
REVERSE SENSOR HOLDER	4	\$	100.40 net

TOTAL:	\$	6,726.00
DISCOUNT 10%:	\$	672.60
	\$	6,053.40

S/NET		PRICE
END PANEL SEALANT	1	\$ 80.00 X
REAR BUMPER SIDE STICKER - SET	1	\$ 150.00 / 100 net
REAR EXHAUST PIPE FINISHER	2	\$ 567.40 X
		\$ 797.40

LABOUR	PRICE
LABOUR FOR FACILITATE REPAIR - REAR	\$ 1,600.00 250.
TO RESRAY REAR BUMPER	\$ 300.00 250.
TO REPSRAY BOOTLID	\$ 300.00 X
TO RESPRAY END PANEL	\$ 300.00 X
RUST PROOFING	\$ 80.00 X
SUNDARIES	\$ 50.00 X
TO DIAGNOSE AND RESET BACK TO ORIGINAL	\$ 250.00 150.
TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR	\$ 250.00 40.
TO REMOVE AND REFIT REVERSE SENSOR	\$ 100.00 30
TO CHECK AND RECONNECT ALL NECESSARY WIRING	\$ 50.00 30.
TOTAL:	\$ 3,280.00

TOTAL:	\$	10,130.80
7% GST:	\$	709.16
	\$	10,839.96