

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

KK

NOT WITHIN
6/1/82 82000k
Bumay After Paing

3 days

REPAIR ESTIMATE FOR SKW5336Y

No.	Qty	List Items			
1	1	Front bumper	CM	\$ 447.25	✓
2	1	Front bumper "TOYOTA" logo	na	\$ 47.67	✓
3	2	Front bumper fog lamp cover	sn	\$ 130.00	X
4	1	Front bumper air grille	Di	\$ 138.50	✓
5	1	Front bumper inner top garnish	na	\$ 169.70	✓
6	2	Front bumper side retainer	old	\$ 107.80	✓
7	1	Front bumper inner reinforcement	na	\$ 361.00	✓
8	1 set	Front bumper clips	na	\$ 30.00	✓
9	1	Front grille	CM	\$ 220.70	✓
10	1	Front bonnet	na	\$ 488.20	X
11	2	Headlamp	my	\$ 767.00	✓
12	1	Front support panel	na	\$ 883.40	X
				\$ 3,791.22	
			Less 25%	\$ 947.81	
			Total :	\$ 2,843.42	

Special Nett Items

13	1	Front number plate	na	\$ 50.00	✓
----	---	--------------------	----	----------	---

Labour

1		Labour Charges for remove/refit, cutting/welding and replacement of damages.		\$ 900.00	4001
2		To putty and spray Spray Paintings charges.		\$ 1,000.00	3601
3		To remove, refix A/c condenser, radiator and etc, including refill of A/c gas.	na	\$ 140.00	X
4		To check wirings and lightings.		\$ 40.00	201
5		To supply and apply anti rust treatment	na	\$ 80.00	X
			Total :	\$ 2,160.00	

Total Parts and Labour : \$ 5,053.42

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary work must be resurveyed and is subject to approval from insurance Company

Acknowledged by: _____
Signature: _____
Date: _____