

15/5/2010

INS. CASE OWNER:

Jaime

CC3 /EQ1901

7728, Fpb1.52

LKK:

IDAC:

Surveyor:

Ram

DOI:

7/10/19

Date / Time:

7/10/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBB 5262T

Name of Insured:

W77 WP

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

7/10/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

DON MARK RUTO FERNANDEZ

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHB 9774



INSRS:

WSP:

Tel:

Liability:

RMKS:

SMRT



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SHB 9774-X

GBB 5262T-X

STAGE

DATE / PIC

11/11/19

Sent TP video to EG(Jaime).

11/11/19

Rec'd email from Jaime: AS
submit up

11/11/19

File -> Shuper to check up.

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

LOR + LO

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

#230-W

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

ASS. REC. BY: Ram

REF: EQ

ASSIGNMENT

From: _____ Date: 7/10/2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHB 935Y

at Workshop n/s: SMPT
of woodlands Depot

Insured: _____

Policy No: _____


Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: \$4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS Imp

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHB 935Y Yr Regn: Dec / 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius C.C. 1798

Colour: maroon A/C: Insured / Std / NI / NA

Sp. Reading: 248206 T/Radio: Insured / Std / NI / NA

Eng/No: -

C/No: JTDKB3FU208576105*

Gen. Cond: Good (Fair) Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NW / S/Rim / STD A/Rim or

Tyre Size: F: 195 / 50 R15

R: 195 / 50 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WESTLAKE

Front

Rear

R/Bal. S mm R/Bal. S mm

L/Bal. S mm L/Bal. S mm

D.O.A. 3/10/2019

D.O.I. 7/10/19

Survey held at SMART

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & O/S rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3rd TP VEH NO.: GBB 5262T

PIP \$ 4931.13 (Reel \$ 7431.07 / 6th 10/19/2013)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : Weekend (\$)

Other: _____

TOTAL

Report Format: _____

Lump Sum / M.B.E. ()



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/EQI19017728/Fpb3

Date: 08.10.2019

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHB935Y


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 07.10.2019 at the premises of M/s SMRT Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	12,362.20
Revised Estimate Amount	: S\$	4,550.71
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

RAM
Licensed Appraiser



Case Details

Case Reference Number : TAX/10/19/2013
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB935Y

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-8761-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : EQ Insurance Company Ltd
 Accident Date and Time : 03/10/2019 10:40 AM
 Vehicle Age(In Months) : 22

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation												Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace ▾	Br ✓
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check ▾	XAN
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	1	84.53	Replace ▾	Br ✓
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Not Givr ▾	XAN
One Time Key In	Main			SEAL, RR BUMPER , RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Givr ▾	XAN
One Time Key In	Main			SEAL, RR BUMPER , LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Givr ▾	XAN
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace ▾	NRC ✓
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace ▾	CUT ✓
One Time Key In	Main			FILLER, RR BUMPER , RH	1	119.90	119.90	25.00	89.93	Replace	1	0	Repair ▾	XAN R
Total Spare Part Cost									8,735.20	Surveyor Total			3,151.11	
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)			0	
Final Spare Part Cost									8,735.20	Final Sur Total			3,151.11	

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Givr	xnn
One Time Key In	Main			ANTENNA, ELECTRICAL KEY	1	60.30	60.30	10.00	54.27	Replace	0	0	Not Givr	xnn
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	✓ nec
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	0	0	Not Givr	xnn
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, RH	1	486.80	486.80	10.00	438.12	Replace	1	438.12	Replace	Br✓
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, RH	1	438.10	438.10	10.00	394.29	Replace	1	394.29	Replace	Br✓
One Time Key In	Main			COVER, REAR COMBINATION LAMP, RH	1	54.00	54.00	10.00	48.60	Replace	1	48.60	Replace	cut
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	824.80	25.00	618.60	Replace	1	0	Repair	x R
One Time Key In	Main			PATCH, SIDE PANEL REAR END, RH & LH	1	33.70	33.70	25.00	25.28	Replace	0	0	Not Givr	xnn
One Time Key In	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	929.60	25.00	697.20	Replace	0	0	Not Givr	xnn
One Time Key In	Main			TAILGATE TRIM, RH	1	92.10	92.10	25.00	69.07	Replace	0	0	Not Givr	xnn
One Time Key In	Main			COVER, REAR FLOOR UNDER, RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Not Givr	xnn
One Time Key In	Main			COVER, REAR FLOOR UNDER, LH	1	234.30	234.30	25.00	175.73	Replace	0	0	Not Givr	xnn
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Not Givr	xnn

Total Spare Part Cost 8,735.20

Surveyor Total 3,151.11

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 8,735.20

Final Sur Total 3,151.11

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			WIRE, REAR DOOR, RH	1	206.70	206.70	10.00	186.03	Replace	0	0	Not Giv	xnn
One Time Key In	Main			SPOILER SUB-ASSY, REAR	1	1,322.10	1,322.10	25.00	991.57	Replace	1	0	Repair	x R
One Time Key In	Main			TAIL GATE GLASS SUB-ASSY, BACK DOOR	1	1,569.70	1,569.70	25.00	1,177.28	Replace	1	1,177.28	Replace	Br ✓
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	891.20	25.00	668.40	Replace	1	0	Repair	x R
One Time Key In	Main			TAIL GATE BACK DOOR HINGE ASSY, RH	1	59.10	59.10	25.00	44.33	Replace	0	0	Not Giv	xnn
One Time Key In	Main			TAIL GATE BACK DOOR HINGE ASSY, LH	1	59.10	59.10	25.00	44.33	Replace	0	0	Not Giv	xnn
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	111.00	Replace	x R nec
One Time Key In	Main			GLASS, REAR DOOR QUARTER WINDOW, RH	1	104.60	104.60	25.00	78.45	Replace	0	0	Not Giv	xnn
One Time Key In	Main			WEATHERSTRIP, REAR DOOR QUARTER WINDOW, RH	1	47.70	47.70	25.00	35.78	Replace	0	0	Not Giv	xnn
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Giv	xnn
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, LH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Giv	xnn
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	x R nec
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	x R nec
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Giv	xnn
Total Spare Part Cost									8,735.20	Surveyor Total 3,151.11				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									8,735.20	Final Sur Total 3,151.11				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	845.00	300	
Total:			845.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
3	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	80	
4	Main	TO RESPRAY REAR SPOILER	180.00	120	
5	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	150	
6	Main	TO RESPRAY REAR PANEL	180.00	0	
7	Main	TO RESPRAY REAR FENDER RH	378.00	200	
Total:			1,656.00	750.00	


Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	100	/rec
2	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	0	X
3	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	X
4	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET) SN	350.00	350.00	/rec
5	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	/rec
6	Main	TO WASH AND VACUUM	60.00	0	X
7	Main	TOWING CHARGE	56.00	0	✓ 40 ✓
8	Main	TO REPLACE SUNDRY PARTS	100.00	20	/rec
Total:			1,126.00	490.00	

14680.60

15080.60x

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	8,735.20	3,151.11
Total Labour Cost	845.00	300.00
Total Spray Painting	1,656.00	750.00
Other	1,126.00	490.00
Overall Total	12,362.20	4,691.11
Lump Sum Repair Option		
Lump Sum Total	0.00	4,691.11
Surveyor Approved Amount		4,691.11
No of Repair Days*	7	3
Remarks	-	PART BY PART REPAIR, TAKE BEFORE SPRAY
Surveyor Name		STEVE CHEN
Signature		
Survey Date	07/10/2019	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REQUEST FOR SUPPLYMENT PARTS

Contractor:			
Accident Case Number	TAK 10/19/2013	Date of Collection	1 1
Vehicle No	SUB 935	Date of Request	08/10/2019
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	2 1

S/N	Part Number	Part Description	Quantity	Unit Price
		LABOR TO REPAIR REAR END PANEL		\$ 200
		LABOR TO SPRAY REAR END PANEL		\$ 200


(M)
100 ✓
100 ✓

<<<Please submit photographs for damaged parts>>>

I, (Name) Steve (LKK)

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

 8/10/19, 5:50pm
Signature of person making this declaration
(to be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledges By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
66 Woodlands Industrial Park E4, Singapore 757755
FAX Number: 63655532
Estimator Telephone Number: 68952622
Accident Reporting Number: 6862672

Date Generated: 18/10/2019

User ID: PehBuan

Section A - Accident Details

Registration Number	SHB935Y
Case Reference Number	TAX/10/19/2013
Registration Date	12/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TAN SOH KEONG
Type of Accident	Head to Rear
Accident Date and Time	3/10/2019 6:40 PM
Accident Reported Date and Time	4/10/2019 8:21 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	3/10/2019 6:47 PM
Replacement Vehicle Issued?	No
Job Card Number	24103670
Special Instruction to ARC, if any	TOWED \$40 / REAR PORTION
Prepared Date and Time	4/10/2019 6:07 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,045.00	\$400.00
Total Spray Cost	\$1,836.00	\$850.00
Total Spare Part Cost	\$8,735.20	\$3,151.13
Total Other Cost	\$1,126.00	\$530.00
TOTAL COST	\$12,742.20	\$4,931.13 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	STEVE CHEN (LKK) / EQ
ARC / Surveyor Sign Off Date	09/10/2019 9:50 AM	09/10/2019 1:10 PM
Signature		
Remarks	Total number of repair days = 4 days. SUP = + 1 day.	PART BY PART REPAIR, TAKE BEFORE SPRAY

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1910-0351	Invoice Number	
Quotation Date	17.10.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR END PANEL	\$200.00	\$100.00
TO REPAIR REAR PORTION	\$645.00	\$300.00
Total Labour	\$1,045.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$80.00
TO RESPRAY REAR SPOILER	\$180.00	\$120.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$150.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,836.00	\$850.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$100.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$350.00	\$350.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TOWING CHARGE	\$56.00	\$40.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
Total Other Costs	\$1,126.00	\$530.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace
		52023470 30	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check X
		52575470 40	RETAINER, RR BUMPER, RH	1.00	\$112.70	25.00	\$84.53	Replace	Replace
		52576470 40	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given X
		52591470 50	SEAL, RR BUMPER, RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given X



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
51 Woodlands Industrial Park E4, Singapore 757705
Fax Number: 63685592
Estimator Telephone Number: 68562823
Accident Reporting Number: 68562872

Date Generated: 18/10/2015

User ID: PohSuen

52592470 40	SEAL, RR BUMPER, LH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	X
52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace	✓
52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace	✓
52565479 00	FILLER, RR BUMPER, RH	1.00	\$119.90	100.00	\$0.00	Replace	Repair	R
	SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X
89997301 00	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Not Given	X
	PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	✓
52169470 20	COVER, GUARD RR BUMPER LOWER	0.00	\$14.80	0.00	\$0.00	Replace	Not Given	X
61581470 10	LENS & BODY ASSY, RR BUMPER, RH	1.00	\$486.80	10.00	\$438.12	Replace	Replace	✓
61551472 81	LENS & BODY, REAR COMBINATION LAMP, RH	1.00	\$438.10	10.00	\$394.29	Replace	Replace	✓
61497470 20	COVER, REAR COMBINATION LAMP, RH	1.00	\$54.00	10.00	\$48.60	Replace	Replace	✓
61601471 50	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$824.80	100.00	\$0.00	Replace	Repair	R
65565470 10	PATCH, SIDE PANEL REAR END, RH & LH	0.00	\$33.70	0.00	\$0.00	Replace	Not Given	X
67005474 40	TAIL GATE PANEL SUB-ASSY, BACK DOOR	0.00	\$929.60	0.00	\$0.00	Replace	Not Given	X
67937470 60C0	TAILGATE TRIM, RH	0.00	\$92.10	0.00	\$0.00	Replace	Not Given	X
58398470 50	COVER, REAR FLOOR UNDER, RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given	X
58399470 30	COVER, REAR FLOOR UNDER, LH	0.00	\$234.30	0.00	\$0.00	Replace	Not Given	X
66259470 10	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given	X
82153472 50	WIRE, REAR DOOR, RH	0.00	\$206.70	0.00	\$0.00	Replace	Not Given	X
76085479 16	SPOILER SUB-ASSY, REAR	1.00	\$1,322.10	100.00	\$0.00	Replace	Repair	R
68105472 91	TAIL GATE GLASS SUB-ASSY, BACK DOOR	1.00	\$1,569.70	25.00	\$1,177.28	Replace	Replace	✓
76801471 10A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$891.20	100.00	\$0.00	Replace	Repair	R
68810470 61	TAIL GATE BACK DOOR HINGE ASSY, RH	0.00	\$59.10	0.00	\$0.00	Replace	Not Given	X
68810470 61	TAIL GATE BACK DOOR HINGE ASSY, LH	0.00	\$59.10	0.00	\$0.00	Replace	Not Given	X
	SEALANT W/SCREEN	3.00	\$37.00	0.00	\$111.00	Replace	Replace	✓
68123470 30	GLASS, REAR DOOR QUARTER WINDOW, RH	0.00	\$104.60	0.00	\$0.00	Replace	Not Given	X
68188470 30	WEATHERSTRIP, REAR DOOR QUARTER WINDOW	0.00	\$47.70	0.00	\$0.00	Replace	Not Given	X
61591470 10	LENS & BODY ASSY, RR BUMPER, LH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	X
61561471 51	LENS & BODY, REAR COMBINATION LAMP, LH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given	X
	SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	✓
	STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	✓
	SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
Total			\$10,906.10		\$3,151.13			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

3151.13
+ 400.00
+ 1380.00

4931.13

Case Details

Case Reference Number : TAX-10-190013
 Type of Repair : Accident Repair
 Vehicle Registration Number : 3H556557

Company Type : SMT Taxi Pte Ltd
 Estimation ID : EST-R761-10
 Assigned By : Tax-Casualty Manager Team

Insurance Company Name : EQ Insurance Company Ltd
 Accident Date and Time : 02/05/2019 10:43 AM
 Vehicle Age(In Months) : 22

Documents / Photographs

View Documents / Photographs

Total Documents : 1

Estimation Details

Spare Part's Cost Detail

SMT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace	✓
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check	✓
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	1	84.53	Replace	✓
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Not Give	✓
One Time Key In	Main			SEAL, RR BUMPER, RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	✓
One Time Key In	Main			SEAL, RR BUMPER, LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	✓
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	✓
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace	✓
One Time Key In	Main			FILLER, RR BUMPER, RH	1	119.90	119.90	25.00	89.93	Replace	1	0	Repair	✓
Total Spare Part Cost									6,735.20	Surveyor Total				3,151.11
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)				0
Final Spare Part Cost									6,735.20	Final Sur Total				3,151.11

SMRT Recommendation										Surveyor Approval				
ECM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	
One Time Key In	Main			ANTENNA ELECTRICAL KEY	1	60.30	60.30	10.00	54.27	Replace	0	0	Not Give	
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	0	120.00	Replace	
One Time Key In	Main			COVER GUARD RR BUMPER LOWER	1	11.80	11.80	25.00	8.85	Replace	0	0	Not Give	
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, RH	1	466.80	466.80	10.00	438.12	Replace	1	438.12	Replace	
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, RH	1	438.10	438.10	10.00	394.29	Replace	1	394.29	Replace	
One Time Key In	Main			COVER, REAR COMBINATION LAMP, RH	1	54.60	54.60	10.00	49.14	Replace	1	49.14	Replace	
One Time Key In	Main			PANEL SUB ASSY, FLYDER REAR RH	1	624.80	624.80	25.00	468.60	Replace	1	0	Repair	
One Time Key In	Main			PATCH, SIDE PANEL REAR END, RH & LH	1	33.70	33.70	25.00	25.28	Replace	0	0	Not Give	
One Time Key In	Main			TAIL GATE PANEL SUB ASSY, BACK DOOR	1	929.60	929.60	25.00	697.20	Replace	0	0	Not Give	
One Time Key In	Main			TAILGATE TRIM, RH	1	92.10	92.10	25.00	69.08	Replace	0	0	Not Give	
One Time Key In	Main			COVER, REAR FLOOR UNDER, RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Not Give	
One Time Key In	Main			COVER, REAR FLOOR UNDER, LH	1	234.30	234.30	25.00	175.73	Replace	0	0	Not Give	
One Time Key In	Main			COVER, REAR FLOOR UNDER, CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Not Give	
Total Spare Part Cost									5,735.20	Surveyor Total				3,151.11
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)				0
Final Spare Part Cost									5,735.20	Final Sur Total				3,151.11

SMRT Recommendation										Surveyor Approval				
RCM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis (%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			WIRE, REAR DOOR, RH	1	206.70	206.70	10.00	186.03	Replace	0	0	Not Give	X/R
One Time Key In	Main			SPOILER SUB-ASSY, REAR	1	1,322.10	1,322.10	25.00	991.57	Replace	1	0	Repair	X/R
One Time Key In	Main			TAIL GATE GLASS SUB-ASSY, BACK DOOR	1	1,569.70	1,569.70	25.00	1,177.28	Replace	1	1,177.28	Replace	X/R
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	891.20	25.00	668.40	Replace	1	0	Repair	X/R
One Time Key In	Main			TAIL GATE BACK DOOR HINGE ASSY, RH	1	59.10	59.10	25.00	44.33	Replace	0	0	Not Give	X/R
One Time Key In	Main			TAIL GATE BACK DOOR HINGE ASSY, LH	1	59.10	59.10	25.00	44.33	Replace	0	0	Not Give	X/R
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	111.00	Replace	X/R
One Time Key In	Main			GLASS, REAR DOOR QUARTER WINDOW, RH	1	104.60	104.60	25.00	78.45	Replace	0	0	Not Give	X/R
One Time Key In	Main			WEATHERSTRIP, REAR DOOR QUARTER WINDOW, RH	1	47.70	47.70	25.00	35.78	Replace	0	0	Not Give	X/R
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Give	X/R
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, LH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Give	X/R
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	X/R
One Time Key In	Main			STICKER DECAL 6555 8838	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	X/R
One Time Key In	Main			SEALANT BIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	X/R
Total Spare Part Cost									8,735.20	Surveyor Total		3,151.11		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									8,735.20	Final Sur Total		3,151.11		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Man	TO REPAIR HEAD POSITION	845.00	200	
Total:			845.00	200.00	+ 129 (Syn) = 490

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Man	TO RESPRAY HEAD BUMPER	320.00	200	
2	Man	TO RESPRAY FRONT BEAM	150.00	0	
3	Man	TO RESPRAY COLLOR BUMPER BR	190.00	0	
4	Man	TO RESPRAY REAR SHOCKER	180.00	200	
5	Man	TO RESPRAY DELIGATE OUTSIDE BARRIER	180.00	100	
6	Man	TO RESPRAY REAR PANEL	150.00	0	
7	Man	TO RESPRAY REAR FENDER BR	478.00	200	
Total:			1,656.00	700.00	+ 129 (Syn) = 850

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Man	TO REMOVE AND REFLUX REAR WINDSCREEN	340.00	150	✓
2	Man	TO TRANSFER REAR TAIL LIGHT MECHANISM	20.00	0	X
3	Man	TO TEST AND FIX REVERSE SENSOR SYSTEM	120.00	0	
4	Man	TO PROVIDE LARVER A MATERIAL FOR BOW AN FLY NET	300.00	350.00	✓
5	Man	TO CHECK WIND AHC SYSTEM FUNCTION	80.00	0	✓
6	Man	TO WASH AND VACUUM	40.00	0	
7	Man	TO WAX CHARGE	80.00	0	40 / n/c
8	Man	TO REPLACE SURROFF PARTS	100.00	20	✓
Total:			1,120.00	490.00	+ 40 = 530

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Low Speed Part Detail	6,785.20	3,193.71
Low Speed Part Cost	605.00	300.00
Total Injury Funding	5,306.00	792.00
Other	1,126.00	480.00
Grand Total	12,360.00	4,865.71
Lump Sum Repair Option		
Lump Sum Total	0.00	4,865.71
Subtotal Approved Amount		4,865.71
Total Repair Cost	0	0
Remarks		PART BY PART REPAIR. TAKE 85% OFE SPAY.
Surveyor Name		STEVE CHEN
Signature		
Drawing Date	07/10/2019	Save Clear

LKK Auto Consultants hereby notify the Receiver of the following:

- To receive information upon pricing
- To receive damaged on the existing structure
- Parts which are subject to confirmation
- Total body work to be done without "original" parts
- The above conditions to be shown
- All components should be replaced and be subject to their approval from Insurance Company

As witnessed by Receiver:

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	369K

Vehicle Details

Vehicle No.:	SHB935Y
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS111453
Chassis No.:	JTDKB3FU203576105
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	12 Dec 2017
First Registration Date:	12 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Dec 2025
PARF Rebate Amount:	\$3,750.00

Intended COE Rebate Details

COE Expiry Date:	11 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$26,376.00
Total Rebate Amount:	\$30,126.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 07 Oct 2019

OK

Shu Pei (LKKAUTO)

From: Jaime Tay <jaime.tay@eqinsurance.com.sg>
Sent: Thursday, 10 October 2019 10:16 AM
To: Shu Pei (LKKAUTO)
Cc: Hsiao Tong (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving GBB5262T (OI : EQI - DM19HO02746-JT) and SHB935Y (TP : LKK REF - CC3/EQI19017728/Fpb3) on 03.10.2019
Attachments: OI-GBB5262T.PDF

WITHOUT PREJUDICE

Dear Shu Pei,

Please find enclosed OI GIA report as requested.

Thank you.

Regards,

Jaime Tay
Executive | Claims




EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9882 | tel 65 6223 9433 ext 882 | fax 65 6223 4190
www.eqinsurance.com.sg



A Member of Citystate



you've got a friend

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: 08 October 2019 16:59
To: EQI PRS <EQIPRS@eqinsurance.com.sg>; Joel Goh <joel.goh@eqinsurance.com.sg>; Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Direct Settlement - Accident Involving GBB5262T (OI : EQI - TBA) and SHB935Y (TP : LKK REF - CC3/EQI19017728/Fpb3) on 03.10.2019

WITHOUT PREJUDICE

Dear Sir/ Madam,

We refer to the above matter.

We have inspected TP vehicle SHB 935Y at M/s SMRT Automotive Services Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank You.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Total Control Panel

[Login](#)

To: eqiprs@eqinsurance.com.sg

[Remove](#) lkkauto.com from my allow list

From: shupeil@lkkauto.com

You received this message because the domain lkkauto.com is on your allow list.

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Tuesday, 22 October 2019 2:40 PM
To: Tan Lee Gek (Auto Svcs/Claims) (LeeGek@smrt.com.sg)
Subject: Your Ref: TAX/10/19/2013 (SHB935Y) *Our Ref: CC3/EQI19017728/Fpb3 [ACCIDENT INVOLVING GBB 5262T(EQ) AND SHB 935Y ON 03/10/2019]
Attachments: Statement of GBB5262T.pdf

Your Ref: **TAX/10/19/2013 (SHB935Y)**
Our Ref: CC3/EQI19017728/Fpb3

Without Prejudice

Dear Sirs/Mdm,

ACCIDENT INVOLVING GBB 5262T(EQ) AND SHB 935Y ON 03/10/2019

We refer to the above matter.

Please be informed that liability is unclear. Our insured driver reported that your client had encroached into his lane and resulted the accident. Attached is a copy of our insured accident report for your easy reference.

As per EQ instruction, we would like to request for evidences (ie: video footage/ scene photos / PIR) for our necessary action.

Appreciate an early reply.

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>
Sent: Friday, 1 November 2019 4:06 PM
To: Hsiao Tong (LKKAuto)
Cc: Admin A; Su Li (LKK Auto)
Subject: Re: Accident on 3/10/2019 involving SHB 935Y & GBB 5262T (EQ's insured) Our Ref: TAX/10/19/2013/lg
Attachments: VIDEO-2019-11-01-15-54-33.mp4

Dear Hsiao Tong,

We attach the video footage from rear camera for your perusal. It clearly showed that our taxi did not cut into your insured's lane as alleged. Our driver slowed down and stopped as he was waiting for the traffic on the left to be clear before filtering left when your insured came at a fast speed from behind on the same lane and rammed onto the rear portion of our stationary taxi.

Please let us have your offer soon. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)
Claims Department
SMRT Automotive Services Pte Ltd



From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]
Sent: 31/10/2019 17:35
To: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis)
Cc: Admin A; Su Li (LKK Auto)
Subject: RE: LOD Re: Accident on 3/10/2019 involving SHB 935Y & GBB 5262T (EQ's insured) Our Ref: TAX/10/19/2013/lg

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

Please be informed that liability is unclear. Our insured driver reported that your client had encroached into his lane and resulted the accident. Attached is a copy of our insured accident report for your easy reference.

As per EQ instruction, we would like to request for evidences (ie: video footage/ scene photos / PIR) for our necessary action.

Appreciate an early reply.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>

Sent: Tuesday, 29 October 2019 9:19 AM

To: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: LOD Re: Accident on 3/10/2019 involving SHB 935Y & GBB 5262T (EQ's insured) Our Ref: TAX/10/19/2013/lg

Dear All,

We quantify our claim as follows:-

Cost of Repair	\$4931.13
Loss of Rental	\$1151.59 (10.25 days x \$112.35)
Loss of Income	\$615.00 (10.25 day x \$60.00)
LTA Search Fee	\$7.00
Total	\$6704.72

We enclose the following documents:

- 1) Repair invoice
- 2) Proof of rental rate
- 3) GIA report
- 4) Accident vehicle laid-up report
- 5) LTA search
- 6) Hirer's letter of authorisation

Please be informed that our relief driver Mr Tan Soh Keong (NRIC No. Sxxxx898H) is claiming his injury and loss of income (based on his medical leave) through his own lawyer. We are claiming the loss of income (based on downtime) on behalf of our hirer Mr Yeong Chye Lai (NRIC No. Sxxxx177D).

Please let us have your offer soon. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)

Claims Department

SMRT Automotive Services Pte Ltd



Hsiao Tong (LKKAuto)

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>
Sent: Tuesday, 29 October 2019 9:19 AM
To: CS A Team; Admin A
Subject: LOD Re: Accident on 3/10/2019 involving SHB 935Y & GBB 5262T (EQ's insured)
Our Ref: TAX/10/19/2013/lg
Attachments: img-X29090022-0001.pdf

Dear All,

We quantify our claim as follows:-

Cost of Repair	\$4931.13
Loss of Rental	\$1151.59 (10.25 days x \$112.35)
Loss of Income	\$615.00 (10.25 day x \$60.00)
LTA Search Fee	\$7.00
Total	\$6704.72

We enclose the following documents:

- 1) Repair invoice
- 2) Proof of rental rate
- 3) GIA report
- 4) Accident vehicle laid-up report
- 5) LTA search
- 6) Hirer's letter of authorisation

Please be informed that our relief driver Mr Tan Soh Keong (NRIC No. Sxxxx898H) is claiming his injury and loss of income (based on his medical leave) through his own lawyer. We are claiming the loss of income (based on downtime) on behalf of our hirer Mr Yeong Chye Lai (NRIC No. Sxxxx177D).

Please let us have your offer soon. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)

Claims Department

SMRT Automotive Services Pte Ltd





Date: 4/10/2019

Our Ref. No.:

Letter of Authorisation

I, Tan Soh Keong (NRIC No.: [REDACTED])
registered hirer / (relief driver) / taxi share driver of SMRT taxi registration number
SHB 9354 hereby authorise **SMRT Automotive Services Pte Ltd**
("AutoSvs") to deal with all matters arising out of the accident between my taxi
and GBB 5262T happened on 03/10/19 1840hrs
along Raffles Boulevard

(the "Accident") on my behalf, including but not limited to instituting and any claims or
proceedings against such party or parties (as AutoSvs deems fit in its absolute
discretion) in respect of any claim, demand, loss, cost, expense, liability, damages or
action made against us or incurred or suffered by us.

Without prejudice to the foregoing, I further authorise AutoSvs to negotiate, resolve
and settle any proceeding or claim arising out of the accidents, including but not limited
to doing any act or executing any document or signing the Discharge Voucher on my
behalf as may be required.

Name: Tan Soh Keong Signature: Ken Tan

NRIC No.

Tel No.

Address:
.....
.....



SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 1990042802
Invoice No. : IV191000371
Date : 21.10.2019
Vehicle No. : SHB935Y
Your Ref No. : TAX/10/19/2013
Our Ref No. : 24103670
Terms : 30 Days



Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

Description	Qty	Unit Cost	Add \$	(Discount) Amount	Amount
Parts					
COVER, RR BUMPER ASSY	1.00	\$ 423.90	(25.00)	\$ 105.97	\$ 317.93
REAR BUMPER REINFORCEMENT	0.00	\$ 318.80	0.00	\$ 0.00	\$ 0.00
RETAINER, RR BUMPER, RH	1.00	\$ 112.70	(25.00)	\$ 28.17	\$ 84.53
RETAINER, RR BUMPER, LH	0.00	\$ 111.50	0.00	\$ 0.00	\$ 0.00
SEAL, RR BUMPER , RH	0.00	\$ 85.20	0.00	\$ 0.00	\$ 0.00
SEAL, RR BUMPER , LH	0.00	\$ 85.20	0.00	\$ 0.00	\$ 0.00
CLIPS PIECE, FRT & RR BUMPER	10.00	\$ 1.50	(25.00)	\$ 3.75	\$ 11.25
GUARD, RR BUMPER, LOWER	1.00	\$ 558.30	(25.00)	\$ 139.57	\$ 418.73
FILLER, RR BUMPER , RH	1.00	\$ 119.90	(100.00)	\$ 119.90	\$ 0.00
SENSOR REVERSE	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
ANTENNA, ELECTRICAL KEY	0.00	\$ 60.30	0.00	\$ 0.00	\$ 0.00
PIXEL STICKER	2.00	\$ 60.00	0.00	\$ 0.00	\$ 120.00
COVER, GUARD RR BUMPER LOWER	0.00	\$ 14.80	0.00	\$ 0.00	\$ 0.00
LENS & BODY ASSY , RR BUMPER , RH	1.00	\$ 486.80	(10.00)	\$ 48.68	\$ 438.12
LENS & BODY, REAR COMBINATION LAMP , RH	1.00	\$ 438.10	(10.00)	\$ 43.81	\$ 394.29
COVER, REAR COMBINATION LAMP, RH	1.00	\$ 54.00	(10.00)	\$ 5.40	\$ 48.60
PANEL SUB-ASSY, FENDER REAR RH	1.00	\$ 824.80	(100.00)	\$ 824.80	\$ 0.00
PATCH, SIDE PANEL REAR END , RH & LH	0.00	\$ 33.70	0.00	\$ 0.00	\$ 0.00
TAIL GATE PANEL SUB-ASSY, BACK DOOR	0.00	\$ 929.60	0.00	\$ 0.00	\$ 0.00
TAILGATE TRIM , RH	0.00	\$ 92.10	0.00	\$ 0.00	\$ 0.00
COVER, REAR FLOOR UNDER , RH	0.00	\$ 169.50	0.00	\$ 0.00	\$ 0.00
COVER, REAR FLOOR UNDER , LH	0.00	\$ 234.30	0.00	\$ 0.00	\$ 0.00
COVER, REAR FLOOR UNDER CENTER	0.00	\$ 222.60	0.00	\$ 0.00	\$ 0.00
WIRE, REAR DOOR, RH	0.00	\$ 206.70	0.00	\$ 0.00	\$ 0.00


Authorized Signature
for SMRT Automotive Services Pte Ltd



SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 1990042802
Invoice No. : IV191000371
Date : 21.10.2019
Vehicle No. : SHB935Y
Your Ref No. : TAX/10/19/2013
Our Ref No. : 24103670
Terms : 30 Days

Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

Description	Qty	Unit Cost	Add %	(Discount) Amount	Amount
SPOILER SUB-ASSY, REAR	1.00	\$1322.10	(100.00)	\$1322.10	\$ 0.00
TAIL GATE GLASS SUB-ASSY, BACK DOOR	1.00	\$1569.70	(25.00)	\$ 392.42	\$ 1177.28
TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1.00	\$ 891.20	(100.00)	\$ 891.20	\$ 0.00
TAIL GATE BACK DOOR HINGE ASSY, RH	0.00	\$ 59.10	0.00	\$ 0.00	\$ 0.00
TAIL GATE BACK DOOR HINGE ASSY, LH	0.00	\$ 59.10	0.00	\$ 0.00	\$ 0.00
SEALANT W/SCREEN	3.00	\$ 37.00	0.00	\$ 0.00	\$ 111.00
GLASS , REAR DOOR QUARTER WINDOW , RH	0.00	\$ 104.60	0.00	\$ 0.00	\$ 0.00
WEATHERSTRIP, REAR DOOR QUARTER WINDOW , RH	0.00	\$ 47.70	0.00	\$ 0.00	\$ 0.00
LENS & BODY ASSY , RR BUMPER , LH	0.00	\$ 486.80	0.00	\$ 0.00	\$ 0.00
LENS & BODY, REAR COMBINATION LAMP , LH	0.00	\$ 438.10	0.00	\$ 0.00	\$ 0.00
SMRT LOGO	1.00	\$ 7.80	0.00	\$ 0.00	\$ 7.80
STICKER DECAL 6555 8888	1.00	\$ 21.60	0.00	\$ 0.00	\$ 21.60
SEALANT SIKAFLEX	0.00	\$ 37.00	0.00	\$ 0.00	\$ 0.00
Sub-Total					\$ 3151.13

Labour

TO REPAIR REAR END PANEL	1.00	\$ 100.00	0.00	\$ 0.00	\$ 100.00
TO REPAIR REAR PORTION	1.00	\$ 300.00	0.00	\$ 0.00	\$ 300.00

Others

TO RESPRAY REAR PANEL	1.00	\$ 100.00	0.00	\$ 0.00	\$ 100.00
TO RESPRAY REAR BUMPER	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO RESPRAY BUMPER BEAM	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
TO RESPRAY FILLER RR BUMPER RH	1.00	\$ 80.00	0.00	\$ 0.00	\$ 80.00

Authorised Signature
for SMRT Automotive Services Pte Ltd



SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

GST Reg No. : MR-8500001-7
CRN : 199004280Z
Invoice No. : IV191000371
Date : 21.10.2019
Vehicle No. : SHB935Y
Your Ref No. : TAX/10/19/2013
Our Ref No. : 24103670
Terms : 30 Days

Description	Qty	Unit Cost	Add %	/ (Discount) Amount		Amount
TO RESPRAY REAR SPOILER	1.00	\$ 120.00	0.00	\$	0.00	\$ 120.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	1.00	\$ 150.00	0.00	\$	0.00	\$ 150.00
TO RESPRAY REAR PANEL	0.00	\$ 180.00	0.00	\$	0.00	\$ 0.00
TO RESPRAY REAR FENDER RH	1.00	\$ 200.00	0.00	\$	0.00	\$ 200.00
TO REMOVE AND REFIX REAR WINDSCREEN	1.00	\$ 100.00	0.00	\$	0.00	\$ 100.00
TO TRANSFER REAR TAILGATE MECHANISM	0.00	\$ 120.00	0.00	\$	0.00	\$ 0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	0.00	\$ 120.00	0.00	\$	0.00	\$ 0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	1.00	\$ 350.00	0.00	\$	0.00	\$ 350.00
TO CHECK WIRING AND SYSTEM FUNCTION	1.00	\$ 20.00	0.00	\$	0.00	\$ 20.00
TO WASH AND VACUUM	0.00	\$ 60.00	0.00	\$	0.00	\$ 0.00
TOWING CHARGE	1.00	\$ 40.00	0.00	\$	0.00	\$ 40.00
TO REPLACE SUNDRY PARTS	1.00	\$ 20.00	0.00	\$	0.00	\$ 20.00

GRAND TOTAL \$ 4,931.13

Remark :

Make/Model : PRIUS4
Accident Date : 03.10.2019

N.B. Payment by cheque should be crossed and
made payable to 'SMRT Automotive Services Pte Ltd'.
No receipt will be issued unless requested.

Authorised Signature
for SMRT Automotive Services Pte Ltd



SMRT Taxis Pte Ltd

MEMORANDUM

To: Claims Dept

Our Ref: TAX/10/19/2013

From: SMRT Taxis Pte Ltd

Date: 10/10/2019

**ACCIDENT INVOLVING SHB935Y AND GBB5262T ON 3/10/2019
6:40 PM ALONG RAFFLES BOULEVARD.**

This is to confirm that the daily rental rate for SHB935Y is \$112.35 per day.

Please proceed to recover any rental loss from the third party as a result of the above accident.

Thank you.

Yours sincerely
SMRT TAXIS PTE LTD



for Manager



Laid Up Report

Accident Start Date : 01/10/2019

Accident End Date : 18/10/2019

Date Generated : 11/10/2019

User Name : LeeGek

Case Reference Number	Vehicle Registration Number	Company Type	Vehicle Make	Vehicle Model	Job Card Number	Date and Time (Accident Repair)	Date and Time (Repair Completed)
TAX/10/19/2013	SHB935Y	SMRT Taxis Pte Ltd	TOYOTA	PRIUS4	24103670	03/10/2019 6:47 PM	14/10/2019 10:28 AM

Enquire Transaction History

Enquire Transaction History

Log Date/Time:	04 Oct 2019 / 16:32:32	Transaction Amount:	\$7.49
Asset Type:	Vehicle	Channel:	External Agency
Asset ID:	GBB5262T	Business Transaction Reference No.:	2019100416323232222
Transaction Type:	18.32 Insurance Enquiry (GIRO Payment)		
User ID:	ESASBAHD - BALQISH BINTE ABDUL HALIL		

Search Date / Time: 03 Oct 2019 18:40:00
Insurance Company: EQ INSURANCE COMPANY LTD
Information displayed is correct as at the log date and time.

[Enquire Related Logs](#)

[Back to List](#)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC3/EQ19017728/Fpb3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 02-12-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 5262T	Veh. Inspected	SHB 935Y
Policy No.	DMCPHQ19-003248	Coverage (\$)	0.00
Claim No.	DM19O02746-JT	Excess (\$)	0.00
Assign From		Assign Date	07/10/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU203576105	Colour	MAROON
Odometer	248206	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/50 R15	WEST LAKE	5 mm
L/H Front Tyre	195/50 R15	WEST LAKE	5 mm
R/H Rear Tyre	195/50 R15	WEST LAKE	5 mm
L/H Rear Tyre	195/50 R15	WEST LAKE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/10/2019	Inspection Date	07/10/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 935Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER, RR BUMPER ASSY (DISC 25%)	BROKEN	423.90	317.93
1	RETAINER, RR BUMPER, RH (DISC 25%)	BROKEN	112.70	84.53
10	CLIPS PIECE, FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	GUARD, RR BUMPER, LOWER (DISC 25%)	CUT	558.30	418.73
1	TAIL GATE GLASS SUB-ASSY, BACK DOOR (DISC 25%)	BROKEN	1,569.70	1,177.28
1	LENS & BODY ASSY, RR BUMPER, RH (DISC 10%)	BROKEN	486.80	438.12
1	LENS & BODY REAR COMBINATION LAMP, RH (DISC 10%)	BROKEN	438.10	394.29
1	COVER, REAR COMBINATION LAMP, RH (DISC 10%)	CUT	54.00	48.60
2	PIXEL STICKER @ \$60.00 (SN)	NECESSARY	120.00	120.00
3	SEALANT W/SCREEN @ \$37.00 (SN)	NECESSARY	111.00	111.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	318.80	-
1	RETAINER, RR BUMPER, LH	NOT NECESSARY	111.50	-
1	SEAL, RR BUMPER, RH	NOT NECESSARY	85.20	-
1	SEAL, RR BUMPER, LH	NOT NECESSARY	85.20	-
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
1	ANTENNA, ELECTRICAL KEY	NOT NECESSARY	60.30	-
1	COVER, GUARD RR BUMPER LOWER	NOT NECESSARY	14.80	-
1	PATCH, SIDE PANEL REAR END, RH & LH	NOT NECESSARY	33.70	-
1	TAIL GATE PANEL SUB-ASSY, BACK DOOR	NOT NECESSARY	929.60	-
1	TAILGATE TRIM, RH	NOT NECESSARY	92.10	-
1	COVER, REAR FLOOR UNDER, RH	NOT NECESSARY	169.50	-
1	COVER, REAR FLOOR UNDER, LH	NOT NECESSARY	234.30	-
1	COVER, REAR FLOOR UNDER CENTER	NOT NECESSARY	222.60	-
1	WIRE, REAR DOOR, RH	NOT NECESSARY	206.70	-
1	TAIL GATE BACK DOOR HINGE ASSY, RH	NOT NECESSARY	59.10	-
1	TAIL GATE BACK DOOR HINGE ASSY, LH	NOT NECESSARY	59.10	-
1	GLASS, REAR DOOR QUARTER WINDOW, RH	NOT NECESSARY	104.60	-
1	WEATHERSTRIP, REAR DOOR QUARTER WINDOW, RH	NOT NECESSARY	47.70	-

Report Ref No. CC3/EQ19017728/Fpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LENS & BODY ASSY, RR BUMPER, LH	NOT NECESSARY	486.80	-
1	LENS & BODY REAR COMBINATION LAMP, LH	NOT NECESSARY	438.10	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	FILLER, RR BUMPER, RH	TO REPAIR SEE LABOUR	119.90	-
1	PANEL SUB-ASSY, FENDER REAR RH	TO REPAIR SEE LABOUR	824.80	-
1	SPOILER SUB-ASSY, REAR	TO REPAIR SEE LABOUR	1,322.10	-
1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	TO REPAIR SEE LABOUR	891.20	-
1	SOLAR FILM (SN)	NECESSARY	350.00	350.00
			11,403.60	3,501.13
	LABOUR			
	PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF FILLER, RR BUMPER, RH; PANEL SUB-ASSY, FENDER REAR RH; SPOILER SUB-ASSY, REAR AND TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY.		845.00	300.00
	SPRAY PAINT.		1,656.00	750.00
	TO REMOVE AND REFIX REAR WINDSCREEN.		240.00	100.00
	TO TRANSFER REAR TAILGATE MECHANISM.	NOT NECESSARY	120.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	NOT NECESSARY	120.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TOWING CHARGE.		56.00	40.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	LABOUR TO REPAIR REAR END PANEL. (ADDITIONAL)		200.00	100.00
	LABOUR TO SPRAY REAR END PANEL. (ADDITIONAL)		200.00	100.00
			3,677.00	1,430.00
	GRAND TOTAL		15,080.60	4,931.13
RECOMMENDED COST OF REPAIRS				4,931.13

Report Ref No. CC3/EQ19017728/Fpb3s2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.