SMM Dealer

# **Performance Motors Limited**

A Sime Darby Motors Company Co. Reg. No. 197401559W GET Reg. No M2-0020061-x Toll(Free Number (1800-2255249)

303. Alexandra Road Sime Darby Performance Centre Singapore 189941 Fax. 64747770

280, Kampong Arang Road East Chast Centre Singapore 438180 Fax. 63449773

313, Alexandra Road Sime Darby Business Centre Eingapore 189964 Fax. 64796601 (AfterBales) 64796524 (Motorrad)



GST REG. NO : M2 - 0020081 - X

08 OCT 2019

33

1,679.35

Total Parts

#### ESTIMATE

Estimate No Date Estima Prepared By	ated : 07/10/2019	Page No. : 1 of 5	
Seth Tanu;	phony Gardens	- ACCOUNT - 121 AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Chartis Building Singapore 079120	
REGN. NO.	CHASSIS NO. REGN. D	ATE MODEL MILEAGE	
SKJ549B	WBA1A120X0VV23840 21/12/2	012 116iA/5 0	
	DESCRIPTION	VA	LUE
	Replacing rear bumper panel and attachments, bootlid	rework   170 2,12   173 U 1,92   23 0 27   23 U 1,92   23 U 1,92	5.00
	Spray rear bumper and bootlid	1730 1,92	3.00
	To remove and install boot compartment carpet a to facilitate repairs.	and gamish 23 0, 27	1.00
	To check electrical wiring systems and lightings rear section for proper function.		
	Sundries NA	80-00 7 15	0.00
-	To supply rear emboss number plate.	54 / 8	3.00
		Total Labour 1: 4,72	9.00
	DESCRIPTION 2	QTY PRIC VA	LUE
	REAR BUMPER CARRIER 4 2		6.45
	RR BUMPER CENTER GUIDE 2 SHH		5.75
	RR BUMPER LH SIDE GUIDE		2.95
	DECORATIVE STRIP (LINE URBAN)		2.95
	REAR BUMPER PRIMED (LINES)		4.40
	DECOUPLING RING PDC TORQUE CONVERT		6.65 20.20

# BMM Dealer

#### **Performance Motors Limited**

A Sime Darby Motors Company Co. Reg. No. 197401559W GET Mag. No M2-0020081-x Toll-Free Number (1800-3255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 155941 Fax 44747770 280. Kampong Arang Road East Coast Centre Singapore 438180 Fax: 63469773

315. Alexandra Road Sime Darby Business Centre Singapore 19994 Fax 64796604 (AfterSales) 64796604 (Motorrad)



GST REG. NO : M2 - 0020081 - X

#### ESTIMATE

Estimate No.

Date Estimated

: b1 52987

: 07/10/2019

Prepared By

: Joseph Yaguel

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SKJ549B

WBA1A120X0VV23840

21/12/2012

116iA/5

0

Page No. : 2 of 5

LICC fulls Consultants hence notify the Regulator of the following:

- . To resurvey beforefuller spray painting
- . To display domaged part(s) during resurvey
- . Furth proces are subject to confirmation.
- \* Third pany survey is on a "Without Prejudice" :
- + 'marriage' modification(s) is allowed
- Test of the line approval from triaurance C.

stemed by Repairer

10-6

135
need Yes / No
LINO PML Yes / N



Labour 1 : 4,729.00 Parts : 1,679.35 Labour 2 : 0.00 Excess : 0.00

Excess : 0.00
Total GST @ 7% : 448.58

Grand Total : 6,856.93

<sup>\*\*</sup> THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

<sup>\*\*</sup> PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# **Performance Motors Limited**

A member of the Sime Darby Group Co. Reg. No. 197401558W, OST Reg. No. M2-0020081-X



## Supplementary

Estimate No. :

b1 52987

Date Estimated :

07/10/2019

Prepared By :

Joseph Yaguel

- ESTIMATE REPAIR FOR -

Seth Tanuja Devi Mrs Surajananthan

11 Jalan Mata Ayer

#04-64 Euphony Gardens

- ACCOUNT -

121

AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way

#08-16 Chartis Building

Singapore 079120

Singapore 759154

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SKJ549B

WBA1A120X0VV23840

21/12/2012

116iA/5

0

DESCRIPTION

ORIGINAL PRICE

DISC. %

NETT

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# SET MOUNTS PDC SENSOR REAR	58.90	1.00		58.90 - MES-
# (DG/SL) ADHESIVE SET K6	53.05	1.00		53.05 - MES-

# SUPPLEMENTARY ITEMS

Total Labour:

Total Parts:

111.95

Total Labour & Parts:

111.95

# **Performance Motors Limited**

A member of the Sime Derby Group.
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## **Final Report**

Estimate No. :

b1 52987

Date Estimated :

07/10/2019

Prepared By :

Joseph Yaguel

- ESTIMATE REPAIR FOR -

Seth Tanuja Devi Mrs Surajananthan

11 Jalan Mata Ayer

#04-64 Euphony Gardens

- ACCOUNT -

121

AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way

#08-16 Chartis Building

Singapore 079120

Singapore 759154

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SKJ549B

WBA1A120X0VV23840

21/12/2012

116iA/5

0

DESCRIPTION	ORIGIN	IAL PRICE	DISC. %	NETT
To replace rear bumper and attachments including make good the bootlid, remove attachments to facilitate repairs and knock out dented area caused by the accident.		1,700.00		1,700.00
To respray rear bumper and bootlid.		1,730.00		1,730.00
To remove and install boot compartment carpet and garnish to facilitate repairs.		230.00		230.00
To check electrical wiring systems and lightings at the rear section for proper function.		150,00		150.00
To supply rear emboss number plate.		83.00		83.00
Sundries		80.00		80.00
DESCRIPTION UNI	T PRICE	QTY	DISC. %	NETT
DECORATIVE STRIP (LINE URBAN) REAR BUMPER PRIMED (LINES)	114.95 966.65	1.00		114.95 966.65
SET MOUNTS PDC SENSOR REAR	58.90	1.00		58.90
DECOUPLING RING PDC TORQUE CONVERTE (DG/SL) ADHESIVE SET K6	5.10 53.05	1.00		20.40 53.05

# SUPPLEMENTARY ITEMS

Total Labour:	3,973.00
Total Parts :	1,213.95
Total Labour & Parts:	5,186.95
GST @7%:	363.09
Grand Total:	5,550.04

LOSS OF USE = \$60 X 5 DAYS GIA SEARCH FEE - \$2.00

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	1341
Vehinle Dehalls	
Vehicle No.:	SKJ549B
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Nov 2019
Vehicle Make:	B.M.W.
Vehicle Model:	116I AT ABS D/AIRBAG 2WD HID 5DR
Primary Colour:	Grey
Manufacturing Year:	2012
Engine No.:	B097J335N13B16A
Chassis No.:	WBA1A120X0VV23840
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$26,475.00
Original Registration Date:	21 Dec 2012
First Registration Date:	21 Dec 2012
Transfer Count:	0
Actual ARF Paid:	\$26,475.00
intended PARE Reparte Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Dec 2022
PARF Rebate Amount:	\$17,208.00
Interneted COF Reparts Distalls	
COE Expiry Date:	20 Dec 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$81,889.00
COE Rebate Amount:	\$25,557.00
Total Rebate Amount:	\$42,765.00

The information contained herein is correct as at 06 Nov 2019

OK

48,000 42765 5235 Sk

#### Asher Sng (LKKAuto)

From:

Asher Sng (LKKAuto)

Sent:

Thursday, 10 October 2019 11:55 AM

To:

PRSE

Subject:

RE: REQUEST FOR DIRECT SETTLEMENT - SKJ549B & SLB2927K ON 05/10/2019 \*\*\*LKK

REF:CC3/AIG19017737/eb3

# 'WITHOUT PREJUDICE' SAVE AS TO COSTS

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards.

Asher Sng | Case Handler LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: <u>ashenna@ikkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | \$(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Thursday, 10 October 2019 11:48 AM
Thursday, 10 October 2019 11:48 AM

To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Subject: Re: REQUEST FOR DIRECT SETTLEMENT - SKJ549B & SLB2927K ON 05/10/2019 \*\*\*LKK

REF:CC3/AIG19017737/eb3

Dear Asher,

Kindly reply on liability.

Thank you.

Regards, Caroline C/o Performance Motors Limited - Body and Paint 303 Alexandra Road Singapore 159941 DID: 6319 0174 Fax: 6479 4601

From: Shu Pei (LKKAuto) <shupei@lkkauto.com>

Sent: Tuesday, 8 October 2019 4:42 PM
To: PBSP <pml-pbsp@simedarby.com.sg>

Cc: 雷理 @ <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>

Subject: FW: REQUEST FOR DIRECT SETTLEMENT - SKJ549B & SLB2927K ON 05/10/2019 \*\*\*LKK

REF:CC3/AIG19017737/eb3

Dear Sir /Madam,

We refer to the below email.

Please be informed that we are currently pending for our insured's report.

Kindly note that for liability, claim negotiation and settlement, please contact Asher at 6841 6051.

Our respective case handler will look into the matter and revert to you in due course.

Thank you

To check availability of the case handler, you may contact the undersigned

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: <a href="mailto:ahupei@likkauto.com">ahupei@likkauto.com</a> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | 5(408933)

From: PBSP <pml-pbsp@simedarby.com.sg> Sent: Tuesday, 8 October 2019 2:49 PM

To: CS A Team < cs-a@lkkauto.com>; Admin A < admin-a@lkkauto.com>

Cc: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Subject: REQUEST FOR DIRECT SETTLEMENT - SKJ549B & SLB2927K ON 05/10/2019

Dear Sirs

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards, Caroline C/o Performance Motors Limited - Body and Paint 303 Alexandra Road Singapore 159941 DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

#### LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To

: AIG Asia Pacific Insurance Pte. Ltd.

Attn

: Ler, Bernard-JQ

Your Ref

: 4151247370SG

Our Ref

: CC3/AIG19017737/R1EB3

Date

: 04 Dec 2019

"WITHOUT PREJUDICE"

#### ACCIDENT INVOLVING SLB2927K & SKJ549B ON 05/10/2019

Refer to the above accident.

The accident occurred when insured rear ended third party vehicle. We have clarified with the OI on the nature of the accident and he/she is aware that his/her NCD would be affected.

On behalf of AIG Asia Pacific Insurance Pte. Ltd., we have successfully I not successfully carried out TP Express Settlement between your insured (vehicle no. SLB2927K) and third party claimant (vehicle no. SKJ549B).

Summary of offer made to workshop Performance Motors Limited is as follows:

Revised Claimed \$ 6,976.72 \$ Cost of Repairs (w/GST) 5,350.00

Loss of Use (4days x \$60) 240.00 (4days x \$60) S 240.00 \$ 2.00

LTA Search Fee

\$ 2.00 \$

Amount of claim at Liability 100%

S 5.592.00

Our surveyor recommended 5days repair.

Market Value: \$48,000 LTA Rebate: \$42,765 Nett Value: \$5,235

Enclose herewith the relevant supporting documents for your perusal.

For your approval please.

Regards,

Asher Sng Rong Yi

LKK Auto Consultants Pte Ltd

Merimen e-Claims

# **Print Received Message**

This mail is associated with:

\*SKJ549B (4151247370SG) [SLB2927K]

TP

SETH TANUJA DEVI MRS SURAJANANTHAN Oct 5 2019 1:00PM [MS BOO CHOR HWEE]

Performance Motors Limited

From

AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 02/01/2020 12:06 PM.

To

LKK\_HQ

Subject

Alert - Adj Mandate Approved (S\$5592.00) - SKJ549B - Claim Handler: Ler, Bernard-JQ

Approved:5592.00:Cost of Repair \$5,350.00 As per surveyor finalization Loss of Use \$240.00 4 days @ S\$ 60/day LTA/ GIA Search Fee \$2.00 Total \$5,592.00

# ...CLAIM SUBFOLDER...(Pending for Survey Report) Express

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Ad	Submitted	Ins Auth'ed	Status		
Main	09 Oct 2019 Edit Reg		04 Nov 2019 00:00 Edit Adj Rpt	S\$5,000.00 Edit Estimates	4 1 2 2 2 2	5,000.00 ew Rpt		Report	Pending for Survey Report Cancel Case	
	Main		teference	Claim I	Details		Documents		Show All	
CLAIM SI	JBFOLDER DE	TAILS				Created	by adjuster]			
Insured:	MS 800 (	CHOR HWEE, ID	: S7321319C							
Main Claimant:	SETH TAN	UJA DEVI MRS	SURAJANANTHAN,	ID: S7938134	No.					
Vehicle Re No.:	SKJ549	В		Date	of Loss:	05/10/2019 13:00 - :59 [81 Months and 14 Days From LTA Reg Date (Man Yr)				
Claim Type	TP / 415	/ 4151247370SG			//Cover No.:	2100458890 (Comprehensive)				
Vehicle Re No. (Insured):	SLB2927	к		Polic (Clair	y No. mant):	VPA/1688696				
Attorna				Exce	SST:					
Repairer:		nce Motors Limi /63190174	ited (Alexandra) 303	Alexandra Roa	d, Sime I	Darby Perform	mance Centre, 159	941 Alexandra	- Tel:	
Handling Insurer:		Pacific Insuranc Dian.Ler@aig.com	ce Pte. Ltd. (Express	) - Tel: 65-641	-3000	. [Handled b	y Ler, Bernard-J	Q]		
Claimant's Insurer:	AXA Insu		<b>IQ)</b> - Tel: 6880 4888						cash tubaha	
Adjuster:	LKK Auto	Consultants Ptr	e Ltd (HQ) - Tel: 625	6-3561 [Hand	fled by P	OHD RASU	L] [Final Rpt	due 17/10/	2019]	
ASSOCIA	TED MAIL RE	CEIVED					Vie	w All Comp	ose Case Ma	
<ul> <li>AIG_SG</li> </ul>	EXPRESS (02	/01/2020): Alert	- Adj Mandate Appr	roved (S\$5592	00) - 51	KJ5498 - Cl	aim Handler: Ler	, Bernard		
ALL ASS	OCIATED TAS	KSE			10	View All	Search Tasks C	reate New Task	Comple	
Due Da		Type Tasi	k Group Subject	Handler	Assign	ned By	Completed On	Created	On Don	

#### Claim Documents

# \*SKJ549B (4151247370SG) [SLB2927K] TP SETH TANUJA DEVI MRS SURAJANANTHAN Oct 5 2019 1:00PM [MS BOO CHOR HWEE] Performance Motors Limited

Let	ters/Corresponder	ces	1 per	page V	100
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
Į.	(Draft)	Third Party Express Settlement - Payment Breakdown	0	Edit	
Ass	essment Reports		1 per	page 🔽	V
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	-
1	04/12/19 11:50	Adjuster Immediate Advice	0	Load HTM	
Pho	otos/Images		3 per	page V	2
No:	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	biebook	Thumbnail	-
1	04/12/19 11:45	General View	0	Load JPG	V
2	04/12/19 11:45	General View	0	Load JPG	2
3	04/12/19 11:45	General View	0	Load JPG	P
4	04/12/19 11:45	General View	0	Load JPG	P
5	04/12/19 11:45	General View	0	Load JPG	V
5	04/12/19 11:45	General View	0	Load JPG	2
7	04/12/19 11:45	General View	0	Load JPG	E
В	04/12/19 11:45	General View	0	Load JPG	2
9	04/12/19 11:45	General View	0	Load JPG	V
10	04/12/19 11:45	General View	0	Load JPG	8
11	04/12/19 11:45	General View	0	Load JPG	2
12	04/12/19 11:45	General View	0	Load JPG	8
-	ECONOMINATION DE LA CONTRACTOR DE LA CON	General View	0	Load JPG	5
13	04/12/19 11:45	General View	0	Load JPG	2
14	04/12/19 11:45	General View	0	Load JPG	2
15	04/12/19 11:45	Washington and the second and the se	0	Load JPG	2
16	04/12/19 11:45	General View			1
17	04/12/19 11:45	General View	0	Load JPG	2
18	04/12/19 11:45	General View	0	Load JPG	8
19	04/12/19 11:45	General View	0	Load JPG	2
20	04/12/19 11:45	General View	0	Load JPG	2
21	04/12/19 11:45	Odometer Reading	0	Load JPG	V
22	04/12/19 11:45	Chassis Number	0	Load JPG	2
23	04/12/19 11:45	General View	0	Load JPG	N
24	04/12/19 11:45	General View	0	Load JPG	R
25	04/12/19 11:45	General View	0	Load JPG	D
26	04/12/19 11:45	General View	0	Load JPG	2
27	04/12/19 11:45	Reinspection Photo	0	Load JPG	2
28	04/12/19 11:45	Reinspection Photo	0	Load JPG	2
29	04/12/19 11:45	Reinspection Photo	0	Load JPG	N
30	04/12/19 11:45	Reinspection Photo	0	Load JPG	P
31	04/12/19 11:45	Reinspection Photo	0	Load JPG	Z
Doc	cumentation		1 per	page V	E
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	1.50	Thumbnall	-
1	08/10/19 16:31	TP ESTIMATE	0	Load PDF	
2	08/10/19 16:31	TP GIA REPORT	0	Load PDF	
3	11/10/19 11:21	LETTER TO 01	0	Load PDF	

Lett	ters/Corresponde	nces	1 per	page V	2 Z	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
4	04/12/19 11:43	TP ESTIMATE - MARKED	0	Load PDF		
5	04/12/19 11:43	TP LOD	0	Load PDF		
6	04/12/19 11:50	LTA PARF COE Rebate Details	0	Load PDF		
7	09/01/20 08:45	WORKSHOP INVOICE	0	Load PDF		
8	09/01/20 08:45	AUTHORISATION TO ACT FORM	0	Load PDF		
9	09/01/20 08:45	Release Voucher	6	Load PDF		
10	09/01/20 DB:45	LOD	0	Load POF		
11	09/01/20 08:45	GIA SEARCH	6	Load PDF		
No.	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print	
1	09/10/19 15:06	OI GIA REPORT	0	Load PDF		

#### **Documents Checklist**

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			,
Show Remarks To: Handling Insurer Note: Remarks are private unless you whom it to other parties.			

NOTE:	TO BE	COMP	ETED	RY	SURV	/EYOR
PACE I E.	I O DE	COMP		01	2011	

$I \leftarrow A M$		

## THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	o: SLB2927K (Insd veh) Model: SKJ549B (TP veh)		Model:	BMW 116I 1.6 ABS D/AIRBAG 2WD 5DR			
Date of Accident:	05/10/2019				DSC		
				_			
Global Sum Settlen	nent : [ ] Yes		[X] No				
Repair Estimate		: \$	6,977.3	1			
Final Repair Cost		: \$	5,350.00				
Loss of Use		: \$	240.00		4.00	days a	at \$60.00 per day
Rental (if any)		: \$	0.00			days	
LTA / GIA Search F	ee	: \$	2.00				
Others:		: S	0.00	0			
		: \$					
Final Settlement St	ım	: \$	5,592.00	0			
Is Third Party Wor below)	kshop GIA Registere	d?	[X] YES	1	1	NO	(Kindly indicate
A) For Non GIA F	Registered Workshop:		Agreed Liabilit	y		(9	6)
B) For GIA Regis	tered Workshop:		BOLA Applica 27	ble: Y	es/ A	lo- BC	LA Scenario No:
BOLA Liability:	(%)		Assessed Liab	oility (	*):		(%)
* Assessed Lia	bility to be filled only fo	r chai	n collisions and fo	or cas	05 W	here B	OLA does not apply
Remarks							
Payment Instructi	on: Payee's Breakdov	vn					
Performance I	Motors Limited		: \$				5,592.00
2)			- 8				

1)	Performance Motors Limited	: \$	5,592.00
2)		: S	
3)		: \$	

JOANNE LEE KHANG MIN	09 Jan 2020
LKK Auto Consultants Pte Ltd	Date

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

#### LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG19017737/R1EA3Q2

Date:

09/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100458890

Claimant Vehicle No:

SKJ549B

Insured Vehicle No: SLB2927K

Date of Loss:

05/10/2019

Nature of Claim:

TP

Claim No: 4151247370SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKJ549B

Make & Model:

BMW 116I, 1.6 ABS D/AIRBAG 2WD 5DR HID

Engine No:

B097J335N13B16A

55671 km

Reg. Date:

DSC (A) 21/12/2012 (Man. Year: 2012)

Chassis No: Odometer:

WBA1A120X0VV23840

Colour. Engine Capacity: Grey

1598 cc

Market Value/New Car

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable): No Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Yes Engine Modification:

Front Tyre Size: Front Left Side:

205/50 R17 Continental 6 mm Rear Tyre Size: Rear Left Side:

205/50 R17 Continental 6 mm

Front Right Side:

Continental 6 mm

Rear Right Side:

Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,024.85	1,376.95	647.90	32.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,496.00	3,810.00	686.00	15.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,520.85	5,186.95	1,333.90	20.46
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	6,520.85	5,000.00	1,520.85	23.32
+ GST 7.00/7.00% (S\$)	456.46	350.00	106.46	23.32
Nett Amount (S\$)	6,977.31	5,350.00	1,627.31	23.32
+ Loss of Use (4.0 x S\$6	60.00/day) (S\$)	240.00		
+ Doc/S	earch Fee (S\$)	2.00		
Ne	tt Liability (S\$)	5,592.00		

INSPECTION

Date of Assignment:

04/11/2019

Date Inspected: 04/11/2019 Inspected At: Performance Motors Limited

(Alexandra)

303 Alexandra Road, Sime Darby

Performance Centre Singapore 159941

Estimated Period of Repair: 5.0 days

Manager: Asher Sng Rong Yi

Adjuster Report

Adjuster: MOHD RASUL

Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# REPAIR DETAILS

# Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00FS	*80.00FS
2	1		*REAR EMBOSS NUMBER PLATE	Bent	83.00 FS	*83.00 FS
3	1		*REAR BUMPER CARRIER	Not Necessary	416.45FS	*-FS
4	1		*RR BUMPER CENTER GUIDE	Not Necessary	55.75 FS	*-FS
5	1		*RR BUMPER LH SIDE GUIDE	Not Necessary	52.95 FS	*-FS
6	1		*RR BUMPER RH SIDE GUIDE	Not Necessary	52.95 FS	*-FS
7	1		*DECORATIVE STRIP (LINE URBAN)	Scratched	114.95 FS	*114.95 FS
8	1		*REAR BUMPER PRIMED (LINES)	Deformed	966.65 FS	*966.65 FS
9	4		*DECOUPLING RING PDC TORQUE CONVERTE	Necessary	20.20FS	*20.40 FS
10	1		*SET MOUNTS PDC SENSOR REAR	Necessary	58.90 FS	*58.90 FS
11	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS
F=Fn	=Franchise part. S=SpcNett.		Total Parts (S\$)	2,024.85	1,376.95	

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items There are no new miscellaneous Items selected.

#### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REPLACING REAR BUMPER PANEL AND ATTACHMENTS , REWORK BOOTLID	New	2,125.00	1,700.00
2	SPRAY REAR BUMPER AND BOOTLID	New	1,923.00	1,730.00
3	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	230.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
	Gross Lab	oour Cost (S\$)	4,496.00	3,810.00
	Report was unsubmitted d	uring this print-out.		

< END OF ESTIMATES >