

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

08 OCT 2019

E S T I M A T E

Estimate No. : b1 52987
Date Estimated : 07/10/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Seth Tanuja Devi Mrs Surajanathan
11 Jalan Mata Ayer
#04-64 Euphony Gardens
Singapore 759154

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKJ549B	WBA1A120X0VV23840	21/12/2012	1161A/5	0

DESCRIPTION**VALUE**

Replacing rear bumper panel and attachments, rework bootlid

1700 2,125.00

Spray rear bumper and bootlid

1730 1,923.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

230 271.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 171.00

Sundries

80 150.00

To supply rear emboss number plate.

54 83.00

Total Labour 1: 4,729.00

DESCRIPTION**QTY****PRIC****VALUE**

REAR BUMPER CARRIER

1

416.45

416.45

RR BUMPER CENTER GUIDE

1

55.75

55.75

RR BUMPER LH SIDE GUIDE

1

52.95

52.95

RR BUMPER RH SIDE GUIDE

1

52.95

52.95

DECORATIVE STRIP (LINE URBAN)

1

114.40

114.40

REAR BUMPER PRIMED (LINES)

1

986.65

986.65

DECOUPLING RING PDC TORQUE CONVERTE

4

5.05

20.20

Total Parts : 1,679.35

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 52987**
Date Estimated : **07/10/2019**
Prepared By : **Joseph Yaguel**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKJ549B	WBA1A120X0VV23840	21/12/2012	1161A/5	0

LES Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice"
- No repair modification(s) is allowed
- Any supplementary item(s) must be resurveyed
- Subject to final approval from Insurance C

Witnessed by Repairer

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 04/11/19 @ 1030 Excess S\$ _____

Surveyor's Name PMR Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

REPAIR PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's Signature _____

Days Recommended 4-5 days

5 days



Labour 1	:	4,729.00
Parts	:	1,679.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	448.58
Grand Total	:	6,856.93

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 52987**
Date Estimated : **07/10/2019**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -
Seth Tanuja Devi Mrs Surajanathan
11 Jalan Mata Ayer
#04-64 Euphony Gardens

Singapore 759154

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKJ549B	WBA1A120X0VV23840	21/12/2012	116iA/5	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments including make good the bootlid, remove attachments to facilitate repairs and knock out dented area caused by the accident.	1,700.00		1,700.00 ✓
To respray rear bumper and bootlid.	1,730.00		1,730.00 ✓
To remove and install boot compartment carpet and garnish to facilitate repairs.	230.00		230.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00 ✓
To supply rear emboss number plate.	83.00		83.00 ✓
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
DECORATIVE STRIP (LINE URBAN)	114.95	1.00		114.95 ✓
REAR BUMPER PRIMED (LINES)	966.65	1.00		966.65 ✓
# SET MOUNTS PDC SENSOR REAR	58.90	1.00		58.90 ✓
DECOUPLING RING PDC TORQUE CONVERTE	5.10	4.00		20.40
# (DG/SL) ADHESIVE SET K6	53.05	1.00		53.05 (s)

SUPPLEMENTARY ITEMS

Total Labour :	3,973.00
Total Parts :	1,213.95
Total Labour & Parts :	5,186.95
GST @7%:	363.09
Grand Total :	5,550.04

LOSS OF USE = \$60 X 5 DAYS
GIA SEARCH FEE - \$2.00

Repair find
(sk)

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020061-X



Supplementary

Estimate No. : **b1 52987**
Date Estimated : **07/10/2019**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -

Seth Tanuja Devi Mrs Surajanathan
11 Jalan Mata Ayer
#04-64 Euphony Gardens

Singapore 759154

- ACCOUNT -

121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKJ549B	WBA1A120X0VV23840	21/12/2012	116iA/5	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# SET MOUNTS PDC SENSOR REAR <i>see</i>	58.90	1.00		58.90
# (DG/SL) ADHESIVE SET K6 <i>see</i>	53.05	1.00		53.05

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	111.95
Total Labour & Parts :	111.95