

INSURER

INS. CASE OWNER

CC 6 / CTI1901 7738, Aeb3nz

LKK:
IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

8/10/19

Date / Time:

8/10/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGZ 1123C

Claim No.:

SWM1902WURW

Name of Insured:

FOO SN LEE (PA SHUN)

Policy No.:

EMP15N315471900

Insured Tel No.:

HP:

Make / Model:

BMW

Excess Sec II :S\$

D.O.A:

5/10/19

Place of Accident:

Ennos Unit Impsuri WY

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO. Driver Name / Age:

WY SE NG

SUNG CHANG

NI GIA REPORT: YES / NO :

TP GIA REPORT: YES / NO

Driver Tel No.:

(VL: YES / NO)

Insured Liability:

Final ? Yes / No

SGE 677R



INSRS:

WSP:

Tel:

Liability:

RMKS:

modern



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time	STAGE	DATE/ PIC
	Non-Reporting 1st (1st):	
	Non-Reporting 1st (2nd):	
	Non-Reporting 1st (Final):	
	Notification 1st (if non-pickup):	
25.11.19	Call OI:	Agree 25.11.19
	After call 1st to OI:	
	Documentation Check List:	Handler Typist
	Notification 1st (if non-pickup):	
	After call 1st to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	45 S\$ 4,000	(8 days) Reduction: 55 %
FINAL SETTLEMENT	Date/Time: 10.12.19	Confirm with: GRACE
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.: 31
Repair Cost:	2/19 S\$ 4,380.00	000 REPAIR SHOWN TO
Loss of Rental (LOR):	S\$ -	(9 days)
Loss of Use (LOU):	S\$ 450.00	(S 50) x 9 days
Loss of Income (LOI):	S\$ -	(S x days)
LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐	(Tick only one)	
GIA/LTA Search	S\$ 2.00	
Medical:	S\$ -	
Disbursement:	S\$ -	(e.g. Tow/ Independent)
Legal Cost:	S\$ -	
Total:	S\$ 4,732.00	Global Sum S\$:
FINAL PAYMENT	Date/Time: 10.12.19	Confirm with: GRACE
Payee 1:	S\$ 4,732.00	Name 1: MODERN AUTOMOTIVE PRE LTD
Payee 2: (Strike if N.A.)	S\$	Name 2:
Payee 3: (Strike if N.A.)	S\$	Name 3:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 8 days Res: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: 8GE6333R Tr Regd: 2006 April
 Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Vios cc 1497
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 152074 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MR053H74204179136
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ Inorder / Jammed / Leaked / Burnt or _____
 Brake: ☒ Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / ☒ S/Rim / STD A/Rim or _____
 Tyre Size: F: 185/60R14
 R: 185/60R14
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Viking
 Front Rear
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 08/10/19
 Survey held at Modern
 Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Claim <u>COE Expiry: 15/04/21</u>
	<u>45:4,000 (REQ: 4,914.65 55%)</u>
	MV: <u>121K</u>
	PV: <u>TK 7.036</u>
	Nett: <u>4.964</u>

Date/Time, File Pass to/ ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to/

3

Report Format: _____

Long Form / LR: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Insp (\$

☐ Other (\$

Survey Fee:

Transportation:

E + PS _____

F1000

C4000

20/10

Adrian

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Tel : 6389 - 6111
Fax : 6224 - 7478 / 7175

Acher.

Quotation
DATE : 08.10.2019
VEH NO : SGE6333R
MODEL : Toyota Vios
D O A : 05.10.2019
YR REF : SGZ1123C

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SGE6333R (TOYOTA VIOS)

Item	Description	Qty	Amt
NO	LIST ITEMS		
1	Rear Bumper <i>Distorted</i>	1	298.00 ✓
2	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>new</i>	2	64.00 ✓
4	Rear End Panel <i>Distorted</i>	1	666.00 ✓
5	Rear End Panel Top Garnish <i>distorted</i>	1	86.00 ✓
6	Rear End Panel Top Garnish Clips <i>new</i>	1	10.00 ✓
7	Taillamp - LH & RH <i>cracked</i>	2	501.40 ✓
8	Taillamp Panel - LH & RH <i>Buckled</i>	2	270.00 ✓
9	Bootlid <i>Distorted</i>	1	543.00 ✓
10	Bootlid Lock <i>distorted</i>	1	45.00 ✓
11	Bootlid Weatherstripe <i>int. dist.</i>	1	61.30 ✓
12	Bootlid Outer Moulding <i>distorted</i>	1	149.60 ✓
13	Bootlid Hinges - LH & RH <i>Dist</i>	2	113.40 ✓
14	Toyota Logo	1	41.80 ✓
15	Vios Wording	1	52.50 ✓
16	1.5 Wording	1	31.50 ✓
17	E Wording	1	38.50 ✓
18	vvti Emblem	1	33.20 ✓
19	Rear Fender - LH <i>Repair</i>	1	544.00 +
20	Rear Windscreen Moulding <i>new</i>	1	71.90 +
21	Spare Tyre Panel <i>Repair</i>	1	668.50 +
22	Spare Tyre Panel Top Cover <i>torn</i>	1	151.50 ✓
23	Rear Exhaust Pipe	1	389.00 +
24	Rear Exhaust Moulding <i>new</i>	1	26.10 +
Less 25%			\$ 4,886.20
			(1,221.55)
			\$ 3,664.65

RE: ESTIMATE FOR ACCIDENT REPAIR SGE6333R (TOYOTA VIOS)

S/NETT ITEMS

1	Reverse Sensor	1	280.00	280
2	Rear End Panel Sealant	1	60.00	✓
3	Rear Windscreen Sealant	1	60.00	✗

260

\$ 400.00

Total parts

\$ 4,064.65

LABOUR CHARGE

1	To knocking out rear portion & renew above parts	\$ 2,000.00	1200
2	To putty & spray up paint works	\$ 1,800.00	1200
3	To check wiring system	\$ 60.00	30
4	To underseal	\$ 150.00	60
5	To remove reverse sensor	\$ 100.00	50
6	To remove upholstery and rear seat	\$ 300.00	100
7	To remove rear windscreen	\$ 150.00	✗
8	To remove exhaust pipe	\$ 150.00	✗
9	To remove fuel tank	\$ 150.00	✗

2640

Total Labour

\$ 4,850.00

Grand Total

\$ 8,914.65

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 5290.10
1/2 4K.
08 Days.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Details	
Owner ID Type:	Business
Owner ID:	200D
Vehicle Details	
Vehicle No.:	SGE6333R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	09 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E A
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	1NZX397277
Chassis No.:	MR053HY4204179136
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$13,040.00
Original Registration Date:	20 Apr 2006
First Registration Date:	20 Apr 2006
Transfer Count:	4
Actual ARF Paid:	\$14,344.00
PARF Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Details	
COE Expiry Date:	19 Apr 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$23,039.00
COE Rebate Amount:	\$7,039.00
Total Rebate Amount:	\$7,039.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 09 Oct 2019

OK

[SEARCH](#) [Price Range](#) [Depreciation](#) [> 10 year\(s\)](#) [Vehicle Type](#) [Search](#) [View All](#) [Advanced Search](#)

Used Car Comparison

— Comparing 4 Vehicles —

Toyota Vios 1.5A E (COE till 06/2021)



[Clear All](#)

[Add all to Shortlist](#)

[Back to search result](#)

[Add to Shortlist](#)

Toyota Vios 1.5A E (COE till 06/2021)



[Add to Shortlist](#)

Toyota Vios 1.5A E (COE till 08/2021)



[Add to Shortlist](#)

Toyota Vios 1.5A E (COE till 12/2021)



[Add to Shortlist](#)

CAR DETAILS

Price	\$12,800	\$13,999	\$13,800	\$15,500
Instalment	N.A.	N.A.	N.A.	N.A.
Registration Date	09-Jun-2006	06-Jul-2006	22-Aug-2006	13-Dec-2006
Manufactured	2006	2006	2006	2006
Mileage	-	140,855 km	104,638 km	170,000 km
Transmission	Auto	Auto	Auto	Auto
Engine Cap	1,497 cc	1,497 cc	1,497 cc	1,497 cc
Road Tax	\$889 /yr	\$889 /yr	\$889 /yr	\$889 /yr
Power	80.0 kW (107 bhp)	80.0 kW (107 bhp)	80.0 kW (107 bhp)	80.0 kW (107 bhp)
Curb Weight	1,020 kg	1,020 kg	1,020 kg	1,020 kg
Features	-	1.5L VVT-i 16 Valves Inline DOHC Engine, 5 Speed Auto Transmission, ABS, EBD, Dual SRS Airbags, 4 Disc Brake, Fuel Efficiency Of 15km/L	-	-
Accessories	Duo-Tone Leather Interior, Original Sports Rims, Factory Fitted Audio System.	Black Interior, Leather Seats, 15" Sports Rims, Factory Audio/CD Player, Front/Rear Recording Camera, Tinted Films, Remote Alarm.	Original Factory Fitted Audio System, Leather Seats, Solar Film, Side Indicator, Fog Light, Reverse Sensor.	-
Description	Car Well Maintained. Serviced Regularly. Idea For Short Term Drive. Call Now To Arrange A Test Drive Today!	Reliable Toyota Vios, For Short Term. Low Mileage. Regularly Serviced. COE Rebate Above \$11k Now. Nice '2900' Plate. Leather Replaced. Sell As It Is Condition. Probably Most Practical, Reliable 1.5L Engine, With Good Fuel Efficiency! Call Us For A Viewing Appointment Today!	Monthly Only \$575, Cheaper Than Rental. Low Mileage, Super Affordable, Immaculate Unit, No Repair Needed, Can Be Use For Private Hire Services. High Loan Available. Various In House Loan With Competitive Interest Rate. Call Now For Further Enquiries And Appointment.	-
COE	\$23,227	\$23,227	\$25,759	\$25,636
OMV	\$12,707	\$12,707	\$12,347	\$12,237
ARF	\$13,978	\$8,577	\$11,104	\$11,461
Depreciation	\$7,680 /yr	\$8,110 /yr	\$7,390 /yr	\$7,120 /yr
No. of Owners	4	3	6	2
Type of Vehicle	Sedan	Sedan	Sedan	Sedan
Category	COE Car	COE Car	COE Car, Low Mileage Car	COE Car
Availability	Available	Available	Available	Available
Remarks	COE expiry date 2021-12-12	COE expiry date 2021-12-12	COE expiry date 2021-12-12	COE expiry date 2021-12-12

Shu Pei (LKKAUTO)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Thursday, 10 October 2019 8:53 AM
To: Shu Pei (LKKAUTO); Asher Sng (LKKAUTO)
Subject: RE: OUR REF: SNM19D204728-SGZ1123C-TKL- Direct Settlement - Accident Involving SGZ1123C (OI : CTI - TBA) AND SGE6333R (TP : LKK REF - CC6/CTI19017738/eb3) on 05.10.2019
Attachments: SGZ1123C.PDF

Without Prejudice

Dear Shu Pei,

We refer to your email below.

Attached is our insured's GIA report for your necessary action.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Wednesday, October 9, 2019 3:56 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Shu Pei (LKKAUTO) <shupeil@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Subject: OUR REF: SNM19D204728-SGZ1123C-TKL- Direct Settlement - Accident Involving SGZ1123C (OI : CTI - TBA) AND SGE6333R (TP : LKK REF - CC6/CTI19017738/eb3) on 05.10.2019

Dear Kah Leong,

Please revert LKK.

Note : officer in charge – Kah Leong

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Shu Pei (LKKAuto) [<mailto:shupe@lkkauto.com>]

Sent: Tuesday, 8 October, 2019 4:42 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Alfred Toh <alfred.toh@sg.cntaiping.com>; Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Subject: Direct Settlement - Accident Involving SGZ1123C (OI : CTI - TBA) AND SGE6333R (TP : LKK REF - CC6/CTI19017738/eb3) on 05.10.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have received a new assignment from M/s Modern Automotive Pte Ltd and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP's GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19017738/Aeb3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 16-12-2019



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGZ 1123C	Veh. Inspected	SGE 6333R
Policy No.	DMPCSN3035431900	Coverage (\$)	0.00
Claim No.	SNM19D204728	Excess (\$)	0.00
Assign From		Assign Date	08/10/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	MR053HY4204179136	Colour	SILVER
Odometer	152074	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R14	VIKING	6 mm
L/H Front Tyre	185/60 R14	VIKING	6 mm
R/H Rear Tyre	185/60 R14	VIKING	6 mm
L/H Rear Tyre	185/60 R14	VIKING	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	05/10/2019	Inspection Date	08/10/2019
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGE 6333R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DISTORTED	298.00	298.00
1	SET REAR BUMPER CLIPS	NECESSARY	30.00	30.00
2	REAR BUMPER SIDE HOLDER-LH & RH	NECESSARY	64.00	64.00
1	REAR END PANEL	DISTORTED	666.00	666.00
1	REAR END PANEL TOP GARNISH	DEFORMED	86.00	86.00
1	REAR END PANEL TOP GARNISH CLIPS	NECESSARY	10.00	10.00
2	TAILLAMP-LH & RH	CRACKED	501.40	501.40
2	TAILLAMP PANEL-LH & RH	BUCKLED	270.00	270.00
1	BOOTLID	DISTORTED	543.00	543.00
1	BOOTLID LOCK	DAMAGED	45.00	45.00
1	BOOTLID WEATHERSTRIPE	CUT	61.30	61.30
1	BOOTLID OUTER MOULDING	DEFORMED	149.60	149.60
2	BOOTLID HINGES-LH & RH	BENT	113.40	113.40
1	TOYOTA LOGO	NECESSARY	41.80	41.80
1	VIOS WORDING	NECESSARY	52.50	52.50
1	1.5 WORDING	NECESSARY	31.50	31.50
1	E WORDING	NECESSARY	38.50	38.50
1	VVTI EMBLEM	NECESSARY	33.20	33.20
1	REAR FENDER-LH	TO REPAIR SEE LABOUR	544.00	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	71.90	-
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	668.50	-
1	SPARE TYRE PANEL TOP COVER	TORN	151.50	151.50
1	REAR EXHAUST PIPE	NOT NECESSARY	389.00	-
1	REAR EXHAUST MOULDING	NOT NECESSARY	26.10	-
	LESS 25% DISCOUNT		-1,221.55	-796.68
			3,664.65	2,390.02
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	60.00	60.00

Report Ref No. CC6/CTI19017738/Aeb3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	60.00	-
			400.00	260.00
	LABOUR			
	TO KNOCKING OUT REAR PORTION & RENEW ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER-LH AND SPARE TYRE PANEL.		2,000.00	1,200.00
	TO PUTTY & SPRAY UP PAINT WORKS.		1,800.00	1,200.00
	TO CHECK WIRING SYSTEM.		50.00	30.00
	TO UNDERSEAL.		150.00	60.00
	TO REMOVE REVERSE SENSOR.		100.00	50.00
	TO REMOVE UPHOLSTERY AND REAR SEAT.		300.00	100.00
	TO REMOVE REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO REMOVE EXHAUST PIPE.	NOT NECESSARY	150.00	-
	TO REMOVE FUEL TANK.	NOT NECESSARY	150.00	-
			4,850.00	2,640.00
GRAND TOTAL			8,914.65	5,290.02
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,000.00

Report Ref No. CC6/CTI19017738/Aeb3q2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.