

Adrian

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road #16-00
 Springleaf Tower
 Singapore 079909
 Tel : 6389 - 6111
 Fax : 6224 - 7478 / 7175

Aches.

Quotation
 DATE : 08.10.2019
 VEH NO : SGE6333R
 MODEL : Toyota Vios
 D O A : 05.10.2019
 YR REF : SGZ1123C

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SGE6333R (TOYOTA VIOS)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Distorted</i>	1	298.00 ✓
2	Rear Bumper Clips <i>NR</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>NR</i>	2	64.00 ✓
4	Rear End Panel <i>Dislodged</i>	1	666.00 ✓
5	Rear End Panel Top Garnish <i>sehd</i>	1	86.00 ✓
6	Rear End Panel Top Garnish Clips <i>NR</i>	1	10.00 ✓
7	Taillamp - LH & RH <i>cracked</i>	2	501.40 ✓
8	Taillamp Panel - LH & RH <i>Buckled</i>	2	270.00 ✓
9	Bootlid <i>Dislodged</i>	1	543.00 ✓
10	Bootlid Lock <i>DRG</i>	1	45.00 ✓
11	Bootlid Weatherstripe <i>cut</i>	1	61.30 ✓
12	Bootlid Outer Moulding <i>sehd</i>	1	149.60 ✓
13	Bootlid Hinges - LH & RH <i>Bent</i>	2	113.40 ✓
14	Toyota Logo	1	41.80 ✓
15	Vios Wording	1	52.50 ✓
16	1.5 Wording <i>NR</i>	1	31.50 ✓
17	E Wording	1	38.50 ✓
18	vvti Emblem	1	33.20 ✓
19	Rear Fender - LH <i>Repair</i>	1	544.00 ✗
20	Rear Windscreen Moulding <i>NR</i>	1	71.90 ✗
21	Spare Tyre Panel <i>Repair</i>	1	668.50 ✗
22	Spare Tyre Panel Top Cover <i>torn</i>	1	151.50 ✓
23	Rear Exhaust Pipe	1	389.00 ✗
24	Rear Exhaust Moulding <i>NR</i>	1	26.10 ✗
Less 25%			
			\$ 4,886.20
			(1,221.55)
			\$ 3,664.65

386.80

2380.10

RE: ESTIMATE FOR ACCIDENT REPAIR SGE6333R (TOYOTA VIOS)

S/NETT ITEMS

1	Reverse Sensor	1	280.00	200
2	Rear End Panel Sealant	1	60.00	✓
3	Rear Windscreen Sealant	1	60.00	x

260

\$ 400.00

Total parts

\$ 4,064.65

LABOUR CHARGE

1	To knocking out rear portion & renew above parts	\$ 2,000.00	1400
2	To putty & spray up paint works	\$ 1,800.00	1400
3	To check wiring system	\$ 50.00	30
4	To underseal	\$ 150.00	60
5	To remove reverse sensor	\$ 100.00	50
6	To remove upholstery and rear seat	\$ 300.00	100
7	To remove rear windscreen	\$ 150.00	x
8	To remove exhaust pipe	\$ 150.00	x
9	To remove fuel tank	\$ 150.00	x

2640

Total Labour

\$ 4,850.00

Grand Total

\$ 8,914.65

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 5250.10

h/s: 4K.

08 Days.