

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

ERIC ANG WEIMING

08/10/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 06/10/2019

Supplementary repair cost for vehicle no: SFT26A BMW 740Li 3.0 A '11

CHASSIS: WBAKB22020CN74932

S/n	Qty	Items	U/price	Amount
1	2	Rear Bumper Side Bracket <i>He ne</i>	\$215.00	\$430.00 <i>X</i>
2	1	Rear Bumper Inner Cover <i>could</i>		\$95.00 <i>✓</i>
3	1	Rear Bumper Reinforcement Outer Cover <i>could</i>		\$84.00 <i>✓</i>
4	1	Rear Antenna <i>Dong</i>		\$226.00 <i>✓</i>
5	1	Rear Absorber Pump <i>Noe ne</i>		\$1,965.00 <i>X</i>

Total:- \$2,800.00

405

384.75