

ASS. REC. BY:

REF:

INC19017741/Kod362

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Theresa Viramala

of

INC

Date/Time:

8/10/19 @ 10:04am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCQ 95B

Insured:

8GV80182

at Workshop m/s:

Leong Auto

Tel:

9692 4113

of

160 Sin Ming Drive #02-13

Policy No:

Claim No:

MT/1065564-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

5/10/2019

CA / REV / REP. / REV 24 HRS

9287 0733 (Dane)

H.O.D. Endorsement:

Date/Time:

10:40am @ 8/10/19

Person Contacted:

Daniel

Vehicle

IN / OUT

Date/Time

Action/Instruction

Johny /

SCQ 95B - X

8GV80182 - X

8/11 1/19 8850d email

C\$ 8,009.65

Red - 49 %

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Tuesday, 8 October 2019 11:55 AM
To: Admin-D (LKKAuto); assignments
Cc: SUR; Theresa Vimala D/O Balagangadharan
Subject: RE: TP CASES FARMED OUT TO LKK ON 08/10/2019

Hi LKK, here is the list of the OIC details etc....

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg

income
more different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at income.com.sg/careers

in with you

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 8 October 2019 11:02 AM
To: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>; assignments <assignments@lkkauto.com>
Cc: Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 08/10/2019

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Theresa Vimala D/O Balagangadharan [mailto:thrsvim.bala@income.com.sg]

Sent: Tuesday, 8 October 2019 10:04 AM

To: assignments <assignments@lkkauto.com>; Catherine Chong (LKK Auto) <admin-d@lkkauto.com>

Cc: Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>; Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>

Subject: RE: TP CASES FARMED OUT TO LKK ON 08/10/2019

Dear LKK,

Please assist to survey the following vehicles as per Tse Kiat's instruction :-

SN	DIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	CHRYLLIS	MT/1065646-002	8/10/2019	SMH465X	CAR TIMES AUTOLUTION PTE LTD	160 SIN MING DRIVE #02-04 AUTOCITY	Yuki Peck / 64715111		SJQ0148R	1/10	
2	CYNDIE YONG	MT/1065698-001	8/10/2019	SMK2182H	COMPLETE VMS PTE LTD	176 SIN MING DRIVE #03-14 SIN MING AUTOCARE SINGAPORE 575721	Chiu S. L / 6455 0012		YP8220Z	6/10	
3	JEFF LIN	MT/1065519-002	8/10/2019	SLL8018S	EM-1 AUTO PTE. LTD.	BLK 8 #01-68 SIN MING INDUSTRIAL EST SECTOR C SINGAPORE 575643	Chia Sin Muk / 9666 6556		SJV7242M	5/10	

4	JARED	MT/1065564-002	8/10/2019	SCQ95B	LEONG AUTO PTE LTD	160 SIN MING DRIVE #02-13 SIN MING AUTO CITY	Daniel Tan/Cady Lee / 9692 4113	SGV8018Z	5/10	
5	HELENA TAN	MT/1065715-001	8/10/2019	51Z1046G	TEAM AUTOPRO PTE LTD	BLK 160 SIN MING DRIVE #01-14 SINGAPORE	Eric Lee / 8269 9999	SGV9761D	5/10	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg




At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.

www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	384C
Vehicle Details	
Vehicle No.:	SCQ958
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Oct 2019
Vehicle Make:	KIA
Vehicle Model:	FORTE K3 1.6A
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	G4FGGH657316
Chassis No.:	KNAFX411MH5665307
Maximum Power Output:	95.3 kW (127 bhp)
Open Market Value:	\$14,319.00
Original Registration Date:	29 Sep 2016
First Registration Date:	29 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$14,319.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Sep 2026
PARF Rebate Amount:	\$10,739.00
Intended COE Rebate Details	
COE Expiry Date:	28 Sep 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,506.00
COE Rebate Amount:	\$35,896.00
Total Rebate Amount:	\$46,635.00

The information contained herein is correct as at 09 Oct 2019

OK

20GB for \$18 / month

Stop worrying about your contracts, switch to Circle

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Q30 1.5 Diesel, 4-cylinder Turbocharged Engine.



Powerful 1.5L Turbocharged Engine Claiming 100kg Torque OF 250NM.
Wearnes Automotive [Show Ad](#)



Browse by Category ▾

Sort by Date Posted ▾ 20 results/page ▾

1 vehicles

kia cerato

Advanced Search 🔍

Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection kia cerato	Any	Any	2016	Any	Any	Any	Available
 Kia Cerato Forte K3 1.6A	\$66,800	\$8,150 /yr	23-Nov-2016	1,591 cc	42,767 km	Sedan	Available
Agent Maintained! 1 Owner Only! SX Model With High OMV. 5 Years Engine Warranty. Original Factory Unit From C&C. Enjoy Exclusive Bank Loan And In House Loan Available. Call/SMS Now For Viewing Appointment.							
Benefit Auto Enterprise Pte Ltd							
Posted: 08-Oct-2019 Tags: 2016 Kia Cerato, 2016 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia							

Save this search criteria, to get email alerts whenever a match is found.

Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view [Expired ads](#)

20 ▾ results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to CDE cars & QPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used kia cerato, kia cerato Singapore, used kia cerato Singapore, used kia cerato, used vehicles Singapore or even buy used kia cerato Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CDE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Shirley Hiew (LKK Auto)

From: Leong Auto Admin <tjh@leongauto.com.sg>
Sent: Wednesday, 15 January 2020 10:44 am
To: Shirley Hiew (LKK Auto); Kenneth Kong (LKKAuto)
Cc: Leong Auto Trading; Ops Leong Auto
Subject: Estimate Finalisation: SCQ 95B DOA - 05/10/2019

Dear Sir/Madam,

We confirm acceptance of COR at \$8500.00 (before GST) in 7 working days for repairs.

Best Regards,
Daniel Tan/Cady Lee
Leong Auto Pte Ltd
Office : 6266-6448 Fax : 6266-6358

Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Please like our Facebook page at: <https://www.facebook.com/leongautogroup>

On Mon, 13 Jan 2020 at 10:35, Ops Leong Auto <ops1@leongauto.com.sg> wrote:

Dear all,

Please help to finalise with surveyor and send cc to Shirley from lkk.

----- Forwarded message -----

From: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>
Date: Wednesday, January 8, 2020
Subject: SCQ 95B DOA - 05/10/2019
To: Ops Leong Auto <ops1@leongauto.com.sg>

Attach finalised for SCQ 95B. Kenneth

From: Ops Leong Auto [mailto:ops1@leongauto.com.sg]
Sent: Saturday, 4 January, 2020 7:43 PM
To: Shirley Hiew (LKK Auto); Kenneth Kong (LKKAuto)
Cc: EMELLENE TENG
Subject: Re: SCQ 95B DOA - 05/10/2019

Dear Mr Kong,

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/10/2019 17:50
Date Of Accident	05/10/2019 13:45
Exact Location Of Accident	JURONG WEST CENTRAL 1 SLIP TOWARDS JALAN BOON LAY.
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCQ95B
Insured/Policyholder	
Name Of Registered Owner	WONG YEW KONG
NRIC No	S1514384C
Email Address	YEWKONGRICHARD@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96932739
Alternative Phone No	OFFICE-96932739

Vehicle Particulars

Manufacturer	KIA
Model	FORTE K3 1.6A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	UNITED OVERSEAS INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DHOM120036571801
Cover Note Number	N.A.

Driver

Name of Driver	WONG YEW KONG
NRIC No	S1514384C
Date Of Birth	06/06/1961
Occupation	INDOOR
Date Of Driving Pass	22/02/1993
Driving Experience	26 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96932739
Fax Number	
Contact Number	OFFICE-96932739
Email Address	YEWKONGRICHARD@GMAIL.COM

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG JURONG WEST CENTRAL 1 SLIP ROAD TOWARDS JALAN BOON LAY, I WAS STATIONARY AND CHECKED MY BLIND SPOT TO GIVE WAY TO ON-COMING VEHICLE, SUDDENLY I FELT AN IMPACT FROM MY VEHICLE REAR AND NOTE THAT VEHICLE 'B' HAD HIT ONTO MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGV8018Z
Vehicle Make/Model/Colour	HONDA/VEZEL HYBRID
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LI KWOK HUNG
NRIC/Passport Number	S2589738B
Contact Number	92231128
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforsaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (Form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to HW, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



- (A) SCQ95B
- (B) SGV801PZ

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELLING ALONG JURING WEST CENTRAL 1 SLIP ROAD TOWARDS JALAN BOON LAY. I WAS STATIONARY AND CHECKED MY BLIND SPOT TO GIVE WAY TO ON-COMING VEHICLE. SUDDENLY I FELT AN IMPACT FROM MY VEHICLE REAR AND NOTE THAT VEHICLE 'B' HAD HIT INTO MY VEHICLE.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
(Date & Time)


Driver's Signature
(If driver is not the policyholder)
(Date & Time)


Reporting Centre Personnel's Signature
Name: *Raymond*
NIC/VIN No.:

LEONG AUTO PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #02-13, Singapore 575722
Tel: 62666448 Fax: 62666358 Email: Sales@leongauto.com.sg
Business Registration No. 201312846W
GST Registration No. 201312846W

ESTIMATE

Date: 7/10/2019
DOA: 5/10/2019

Vehicle No: SCQ95B
Make & Model: Kia Cerato K3

S/N	Qty	Item Description	Parts Price	Surveyor
1	1	Rear Boot Lid	\$ -	
2	1	Rear Boot Lid Centre Logo	\$ -	
3	1	Rear Boot Lid "Cerato" Emblem	\$ -	
4	1	Rear Boot Lid "Forte" Emblem	\$ -	
5	1	Rear Boot Lid "K" Emblem	\$ -	
6	1	Rear Boot Lid "3" Emblem	\$ -	
7	1	Rear Boot Lid "Cycle & Carriage" Emblem	\$ -	
8	1	Rear Boot Lid Weatherstrip	\$ -	
9	2	Rear Boot Lid Reflector Lamp	\$ -	
10	2	Rear Boot Lid Reflector Lamp Gasket	\$ -	
11	2	Rear Boot Lid No Plate Lamp	\$ -	
12	1	Rear Boot Lid Lock Mechanism	\$ -	
13	1	Rear Boot Lid Lock Catch	\$ -	
14	2	Rear Boot Lid Hinges	\$ -	
15	2	Rear Boot Lid Rubber Stopper	\$ -	
16	1	Rear Boot Lid Inner Trim	\$ -	
17	1	Rear Left Tail Lamp	\$ -	
18	1	Rear Right Tail Lamp	\$ -	
19	2	Rear Tail Lamp Gasket	\$ -	
20	2	Rear Tail Lamp Base Panel	\$ -	
21	1	Rear End Panel	\$ -	
22	1	Rear End Panel Top Garnish	\$ -	
23	1	Rear End Panel Sensor	\$ -	
24	1	Rear End Panel Sensor Bracket	\$ -	
25	1	Rear Spare Tyre Top Board	\$ -	
26	2	Rear Fender Inner Trim	\$ -	
27	2	Rear Fender Inner Shield	\$ -	
28	1	Rear Bumper	\$ -	
29	2	Rear Bumper Retainer	\$ -	
30	1	Rear Bumper Bracket	\$ -	
31	1	Rear Bumper Lower Lip	\$ -	
32	2	Rear Bumper Lower Lip Reflector	\$ -	
33	1	Rear Bumper Reinforcement	\$ -	
34	1	Rear Exhaust Assy	\$ -	
35	2	Rear Exhaust Mounting	\$ -	
36	1	Rear Exhaust Heat Shield	\$ -	
Less 25%			\$ -	

Special Nett Items

1	Sundries	\$ 50.00	7
2	1 set Rear Boot Lid Inner Trim Clips	\$ 50.00	✓
3	2 set Rear Boot Lid Reflector Lamp Clips	\$ 50.00	7
4	2 Rear Boot Lid Reflector Lamp Sealant	\$ 80.00	x
5	1 Rear Left Tail Lamp Sealant	\$ 50.00	✓
6	1 Rear Right Tail Lamp Sealant	\$ 50.00	7
7	2 set Rear Tail Lamp Clips	\$ 80.00	✓
8	2 Rear Tail Lamp Base Panel Sealant	\$ 150.00	7
9	1 Rear End Panel Sealant	\$ 150.00	7
10	1 set Rear End Panel Top Garnish Clips	\$ 80.00	✓
11	2 set Rear Fender Inner Trim Clips	\$ 50.00	7
12	2 set Rear Fender Inner Shield Clips	\$ 50.00	7
13	1 set Rear Bumper Clips	\$ 50.00	✓

LEONG AUTO PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #02-13, Singapore 575722
Tel: 62666448 Fax: 62666358 Email: Sales@leongauto.com.sg
Business Registration No. 201312846W
GST Registration No. 201312846W

Not Notified
1 Day & ?
Recovery After Pains 5-7 days

ESTIMATE

Date: 7/10/2019
DOA: 5/10/2019

Vehicle No: SCQ95B
Make & Model: Kia Cerato K3

S/N	Qty	Item Description	Parts Price	Surveyor
1	1	Rear Boot Lid	\$ -	
2	1	Rear Boot Lid Centre Logo	\$ -	
3	1	Rear Boot Lid "Cerato" Emblem	\$ -	
4	1	Rear Boot Lid "Forte" Emblem	\$ -	
5	1	Rear Boot Lid "K" Emblem	\$ -	
6	1	Rear Boot Lid "3" Emblem	\$ -	
7	1	Rear Boot Lid "Cycle & Carraige" Emblem	\$ -	
8	1	Rear Boot Lid Weatherstrip	\$ -	
9	2	Rear Boot Lid Reflector Lamp	\$ -	
10	2	Rear Boot Lid Reflector Lamp Gasket	\$ -	
11	2	Rear Boot Lid No Plate Lamp	\$ -	
12	1	Rear Boot Lid Lock Mechanism	\$ -	
13	1	Rear Boot Lid Lock Catch	\$ -	
14	2	Rear Boot Lid Hinges	\$ -	
15	2	Rear Boot Lid Rubber Stopper	\$ -	
16	1	Rear Boot Lid Inner Trim	\$ -	
17	1	Rear Left Tail Lamp	\$ -	
18	1	Rear Right Tail Lamp	\$ -	
19	2	Rear Tail Lamp Gasket	\$ -	
20	2	Rear Tail Lamp Base Panel	\$ -	
21	1	Rear End Panel	\$ -	
22	1	Rear End Panel Top Garnish	\$ -	
23	1	Rear End Panel Sensor	\$ -	
24	1	Rear End Panel Sensor Bracket	\$ -	
25	1	Rear Spare Tyre Top Board	\$ -	
26	2	Rear Fender Inner Trim	\$ -	
27	2	Rear Fender Inner Shield	\$ -	
28	1	Rear Bumper	\$ -	
29	2	Rear Bumper Retainer	\$ -	
30	5	Rear Bumper Bracket	\$ -	
31	1	Rear Bumper Lower Lip	\$ -	
32	2	Rear Bumper Lower Lip Reflector	\$ -	
33	1	Rear Bumper Reinforcement	\$ -	
34	1	Rear Exhaust Assy	\$ -	
35	2	Rear Exhaust Mounting	\$ -	
36	1	Rear Exhaust Heat Shield	\$ -	
Less 25%			\$ -	

Special Nett Items

1		Sundries	\$ 50.00	?
2	1 set	Rear Boot Lid Inner Trim Clips	\$ 50.00	✓
3	2 set	Rear Boot Lid Reflector Lamp Clips	\$ 50.00	✓
4	2	Rear Boot Lid Reflector Lamp Sealant	\$ 80.00	x
5	1	Rear Left Tail Lamp Sealant	\$ 50.00	✓
6	1	Rear Right Tail Lamp Sealant	\$ 50.00	✓
7	2 set	Rear Tail Lamp Clips	\$ 80.00	✓
8	2	Rear Tail Lamp Base Panel Sealant	\$ 150.00	✓
9	1	Rear End Panel Sealant	\$ 150.00	✓
10	1 set	Rear End Panel Top Garnish Clips	\$ 80.00	✓
11	2 set	Rear Fender Inner Trim Clips	\$ 50.00	✓
12	2 set	Rear Fender Inner Shield Clips	\$ 50.00	✓
13	1 set	Rear Bumper Clips	\$ 50.00	✓

14	1	Rear No Plate With Garnish	<i>Rs</i> \$ 80.00	<i>455m</i>
15	2	Rear Bumper Reverse Sensor	<i>Rs</i> \$ 250.00	<i>2001m</i>
16	1 set	Rear Reverse Camera	\$ 380.00	<i>7</i>
			\$ 1,650.00	
Total parts				
S/N	Labour Description		Amount	Amount
	Labour for panel beating, cut, weld, straighten rear fenders and replace rear			
1	damaged parts.		\$ 1,600.00	<i>7</i>
2	To putty and spray painting rear portion.		\$ 1,400.00	<i>9001</i>
3	To check rear lighting and wiring.		\$ 80.00	<i>201</i>
4	To remove and install rear boot lid lock mechanism.		\$ 120.00	<i>501</i>
5	To remove and install rear seat, inner garnish and trim to facilitate the repair.		\$ 380.00	<i>7</i>
6	To apply anti rust proofing to rear affected area.		\$ 250.00	<i>7</i>
7	To remove and install rear reverse sensor.		\$ 60.00	<i>501</i>
8	To remove and install exhaust muffler and rear exhaust centre pipe		<i>nn</i> \$ 150.00	<i>X</i>
9	To remove & refit boot lid component to replace boot lid, check & re-adjust the close gap and alignment and water seepage		\$ 120.00	<i>501</i>
Total labour :			\$ 4,160.00	
Total parts :			\$ -	
Total labour :			\$ 4,160.00	
Total repair cost :(Before GST)				

UKK Auto Consultants (hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- This parts survey is on a "Without Prejudice" basis
- No Price modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer:

Signature:

Date:

LEONG AUTO PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #02-13, Singapore 575722
Tel: 62666448 Fax: 62666358 Email: Sales@leongauto.com.sg
Business Registration No. 201312846W
GST Registration No. 201312846W

*Not Withstand
L1 Eng 88500/-
Reserve After Paint*

ESTIMATE

Date: 7/10/2019
DOA: 5/10/2019

Vehicle No: SCQ95B

Make & Model: Kia Cerato K3

S/N	Qty	Item Description	Parts Price	Surveyor
1	1	Rear Boot Lid 1073	\$ 1,148.20	✓
2	1	Rear Boot Lid Centre Logo	\$ 65.00	✓
3	1	Rear Boot Lid "Cerato" Emblem	\$ 55.00	✓
4	1	Rear Boot Lid "Forte" Emblem	\$ 55.00	✓
5	1	Rear Boot Lid "K" Emblem	\$ 53.00	✓
6	1	Rear Boot Lid "3" Emblem	\$ 53.00	✓
7	1	Rear Boot Lid "Cycle & Carraige" Emblem	\$ 58.00	✓
8	1	Rear Boot Lid Weatherstrip	\$ 157.00	501in
9	2	Rear Boot Lid Reflector Lamp @355.00	\$ 1,519.40	✓
10	2	Rear Boot Lid Reflector Lamp Gasket	\$ 128.20	✓
11	2	Rear Boot Lid No Plate Lamp	\$ 188.40	X
12	1	Rear Boot Lid Lock Mechanism 185.00	\$ 220.00	✓
13	1	Rear Boot Lid Lock Catch	\$ 59.00	X
14	2	Rear Boot Lid Hinges	\$ 145.60	✓
15	2	Rear Boot Lid Rubber Stopper	\$ 12.90	X
16	1	Rear Boot Lid Inner Trim	\$ 187.80	✓
17	1	Rear Left Tail Lamp 772	\$ 843.20	✓
18	1	Rear Right Tail Lamp 772	\$ 843.20	✓
19	2	Rear Tail Lamp Gasket	\$ 164.20	✓
20	2	Rear Tail Lamp Base Panel	\$ 355.30	✓
21	1	Rear End Panel 428.00	\$ 698.80	✓
22	1	Rear End Panel Top Garnish	\$ 162.10	✓
23	1	Rear End Panel Sensor	\$ -	✓
24	1	Rear End Panel Sensor Bracket	\$ -	✓
25	1	Rear Spare Tyre Top Board	\$ 265.90	✓
26	2	Rear Fender Inner Trim	\$ 644.60	2+
27	2	Rear Fender Inner Shield	\$ 160.50	X
28	1	Rear Bumper 768.00	\$ 862.20	✓
29	2	Rear Bumper Retainer	\$ 164.20	✓
30	2	Rear Bumper Bracket	\$ 642.00	24H
31	1	Rear Bumper Lower Lip 421.00	\$ 571.30	✓
32	2	Rear Bumper Lower Lip Reflector	\$ 384.20	X
33	1	Rear Bumper Reinforcement 395.00	\$ 450.00	✓
34	1	Rear Exhaust Assy		
35	2	Rear Exhaust Mounting		
36	1	Rear Exhaust Heat Shield		
			\$ 11,317.20	
Less 10%			\$ 1,131.72	
			\$ 10,185.48	
<u>Special Nett Items</u>				
1		Sundries	\$ 50.00	X
2	1 set	Rear Boot Lid Inner Trim Clips	\$ 50.00	✓
3	2 set	Rear Boot Lid Reflector Lamp Clips	\$ 50.00	X
4	2	Rear Boot Lid Reflector Lamp Sealant	\$ 80.00	X
5	1	Rear Left Tail Lamp Sealant	\$ 50.00	✓
6	1	Rear Right Tail Lamp Sealant	\$ 50.00	X
7	2 set	Rear Tail Lamp Clips	\$ 80.00	✓
8	2	Rear Tail Lamp Base Panel Sealant	\$ 150.00	605in
9	1	Rear End Panel Sealant	\$ 150.00	301in
10	1 set	Rear End Panel Top Garnish Clips	\$ 80.00	✓
11	2 set	Rear Fender Inner Trim Clips	\$ 50.00	2+
12	2 set	Rear Fender Inner Shield Clips	\$ 50.00	X
13	1 set	Rear Bumper Clips	\$ 50.00	✓

14	1	Rear No Plate With Garnish	At	\$	80.00	455m
15	2	Rear Bumper Reverse Sensor	nd	\$	250.00	2005m
16	1 set	Rear Reverse Camera	Short	\$	380.00	2
				\$	1,650.00	
		Total parts		\$	11,835.48	
S/N	Labour Description		Amount		Amount	
1	Labour for panel beating, cut, weld, straighten rear fenders and replace rear damaged parts.		\$	1,600.00	800l	
2	To putty and spray painting rear portion.		\$	1,400.00	900l	
3	To check rear lighting and wiring.		\$	80.00	20l	
4	To remove and install rear boot lid lock mechanism.		\$	120.00	50l	
5	To remove and install rear seat, inner garnish and trim to facilitate the repair.		\$	380.00	100l	
6	To apply anti rust proofing to rear affected area.		\$	250.00	90l	
7	To remove and install rear reverse sensor.		\$	60.00	50l	
8	To remove and install exhaust muffler and rear exhaust centre pipe		~	\$	150.00	X
9	To remove & refit boot lid component to replace boot lid, check & re-adjust the close gap and alignment and water seepage		\$	120.00	50l	
	Total labour :		\$	4,160.00		
	Total parts :		\$	11,835.48		
	Total labour :		\$	4,160.00		
	Total repair cost : (Before GST)		\$	15,995.48		

16,509.65

LKK Auto Consultants hereby notify
the Repairer of the following:

- To resurvey before/after any painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be conveyed and is subject to final approval from Insurance Company

Acknowledged by Receiver:

Signature:

Date:

LEONG AUTO PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #02-13, Singapore 575722
Tel: 62666448 Fax: 62666358 Email: Sales@leongauto.com.sg
Business Registration No. 201312846W
GST Registration No. 201312846W

ESTIMATE

Date: 7/10/2019

DOA: 5/10/2019

Vehicle No: SCQ95B

Make & Model: Kia Cerato K3

S/N	Qty	Item Description	Parts Price	Surveyor
		Supplementary Items		
1	2	Rear Bumper Reinforcement Bracket <i>Q82-w</i>	\$ 571.30	
			\$ 571.30	
		Less 10%	\$ 57.13	
			\$ 514.17	

LKK Auto Consultants hence notify
the Repairer of the following:

- To rectify before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Stamp:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19017741/Ksd3e2

73 BRAS BASAH ROAD

Date: 16-01-2020

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN : JARED

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGV 8018Z	Veh. Inspected	SCQ 95B
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1065564-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	08/10/2019

2. Vehicle Particulars & Condition

Make & Model	KIA FORTE K3 1.6A	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KNAFX411MH5665307	Colour	METALLIC DARK BLUE
Odometer	36274 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	YOKOHAMA	9 mm
L/H Front Tyre	205/55 R16	YOKOHAMA	9 mm
R/H Rear Tyre	205/55 R16	YOKOHAMA	9 mm
L/H Rear Tyre	205/55 R16	YOKOHAMA	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/10/2019	Inspect Date / Time	08/10/2019 (11:12 AM)
Survey held at	LEONG AUTO PTE LTD 160 SIN MING DRIVE #02-13 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCQ 95B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	BENT	1,148.20	1,073.00
1	REAR BOOT LID CENTRE LOGO	NECESSARY	65.00	65.00
1	REAR BOOT LID "CERATO" EMBLEM	NECESSARY	55.00	55.00
1	REAR BOOT LID "FORTE" EMBLEM	NECESSARY	55.00	55.00
1	REAR BOOT LID "K" EMBLEM	NECESSARY	53.00	53.00
1	REAR BOOT LID "3" EMBLEM	NECESSARY	53.00	53.00
1	REAR BOOT LID "CYCLE & CARRIAGE" EMBLEM	NECESSARY	58.00	58.00
2	REAR BOOT LID REFLECTOR LAMP	CRACKED	1,519.40	710.00
2	REAR BOOT LID REFLECTOR LAMP GASKET	NECESSARY	128.20	128.20
2	REAR BOOT LID NO PLATE LAMP	SERVICEABLE	188.40	-
1	REAR BOOT LID LOCK MECHANISM	JAMMED	220.00	185.00
1	REAR BOOT LID LOCK CATCH	TO REPAIR SEE LABOUR	59.00	-
2	REAR BOOT LID HINGES	DISTORTED	145.60	145.60
2	REAR BOOT LID RUBBER STOPPER	SERVICEABLE	12.90	-
1	REAR BOOT LID INNER TRIM	MTG CRACKED	187.80	187.80
1	REAR LEFT TAIL LAMP	CRACKED	843.20	772.00
1	REAR RIGHT TAIL LAMP	CRACKED	843.20	772.00
2	REAR TAIL LAMP GASKET	NECESSARY	164.20	164.20
2	REAR TAIL LAMP BASE PANEL	BENT	355.30	355.30
1	REAR END PANEL	BENT	698.80	428.00
1	REAR END PANEL TOP GARNISH	DISTORTED	162.10	162.10
1	REAR END PANEL SENSOR (NPA)	NOT NECESSARY	-	-
1	REAR END PANEL SENSOR BRACKET (NPA)	NOT NECESSARY	-	-
1	REAR SPARE TYRE TOP BOARD	CRACKED	265.90	265.90
2	REAR FENDER INNER TRIM	N/S CRACKED	644.60	322.30
2	REAR FENDER INNER SHIELD	SERVICEABLE	160.50	-
1	REAR BUMPER	BENT	862.20	768.00
2	REAR BUMPER RETAINER	DISTORTED	164.20	164.20
5	REAR BUMPER BRACKET	CRACKED (3PCS ONLY)	642.00	385.20

Report Ref No. CS/INC19017741/Ksd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER LOWER LIP	BUCKLED	571.30	421.00
2	REAR BUMPER LOWER LIP REFLECTOR	SERVICEABLE	384.20	-
1	REAR BUMPER REINFORCEMENT	BUCKLED / CRACKED	450.00	395.00
2	REAR BUMPER REINFORCEMENT BRACKET (ADDITIONAL)	BENT	571.30	164.00
	LESS 10% DISCOUNT		-1,173.15	-830.78
			10,558.35	7,477.02
1	REAR BOOT LID WEATHERSTRIP (SN) (50%)	CUT	157.00	78.50
	LESS 10% DISCOUNT		-15.70	-
			141.30	78.50
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
1	SET REAR BOOT LID INNER TRIM CLIPS (SN)	NECESSARY	50.00	50.00
2	SET REAR BOOT LID REFLECTOR LAMP CLIPS (SN)	NOT NECESSARY	50.00	-
2	REAR BOOT LID REFLECTOR LAMP SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR LEFT TAIL LAMP SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR RIGHT TAIL LAMP SEALANT (SN)	NOT NECESSARY	50.00	-
2	SET REAR TAIL LAMP CLIPS (SN)	NECESSARY	80.00	80.00
2	REAR TAIL LAMP BASE PANEL SEALANT (SN)	NECESSARY	150.00	60.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	150.00	30.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	80.00	80.00
2	SET REAR FENDER INNER TRIM CLIPS (SN)	NECESSARY (1SET ONLY)	50.00	25.00
2	SET REAR FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	REAR NO PLATE WITH GARNISH (SN)	BENT	80.00	45.00
2	REAR BUMPER REVERSE SENSOR (SN)	DENTED	250.00	200.00
1	SET REAR REVERSE CAMERA (SN)	SHORTED	380.00	380.00
			1,650.00	1,050.00

Report Ref No. CS/INC19017741/Ksd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR FENDERS AND REPLACE REAR DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR BOOT LID LOCK CATCH.		1,600.00	800.00
	TO PUTTY AND SPRAY PAINTING REAR PORTION.		1,400.00	900.00
	TO CHECK REAR LIGHTING AND WIRING.		80.00	20.00
	TO REMOVE AND INSTALL REAR BOOT LID LOCK MECHANISM,		120.00	50.00
	TO REMOVE AND INSTALL REAR SEAT, INNER GARNISH AND TRIM TO FACILITATE THE REPAIR.		380.00	100.00
	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA.		250.00	90.00
	TO REMOVE AND INSTALL REAR REVERSE SENSOR.		60.00	50.00
	TO REMOVE AND INSTALL EXHAUST MUFFLER AND REAR EXHAUST CENTRE PIPE.	NOT NECESSARY	150.00	-
	TO REMOVE & REFIT BOOT LID COMPONENT TO REPLACE BOOT LID, CHECK & RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND WATER SEEPAGE.		120.00	50.00
			4,160.00	2,060.00
	GRAND TOTAL		16,509.65	10,665.52
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			8,500.00

Report Ref No. CS/INC19017741/Ksd3e2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.