

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD8628X

DATE: 5. Oct. 2019

MAKE : HYUNDAI

MODEL : IONIQ

DOA: 4. Oct. 2019

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Bumper Cover xxxxxx			\$418.30
1	Front Bumper Bracket - LH x			\$28.00
	Front Bumper Top Bracket - LH x			\$12.00
10	Front Bumper Clips x		\$2.20	\$22.00
1	Front Bumper Upper Molding x			\$108.50
1	Front Fender - LH ---			\$490.70
1	Front Fender Shield - LH x			\$114.70
1	Headlamp - LH ---			\$1,198.80
1	BLUEDRIVE Emblem - LH ---			\$26.60
1	Front Wheel Cover - LH x			\$346.40
1	Steering Tie Rod End - LH x			\$94.70
SUB TOTAL				\$2,860.70
LESS 20%				\$572.14
DISCOUNTED TOTAL				\$2,288.56
1	Advertisement - LHF Fender ---			\$100.00
Labour Charge				
1	Panel Beating			\$1,280.00
1	Spray Painting Charge			\$500.00
1	Wiring Charge			\$80.00
1	Tuff Kote			\$80.00
1	Front Wheel Alignment			\$120.00
TOTAL LABOUR				\$2,060.00
ESTIMATE TOTAL				\$4,448.56
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Nett

TOTAL LABOUR

ESTIMATE TOTAL

Larry Ng

Kah 16/10/19


7/10/19

1035km

2 Days

P.P.P

Before Paint photo



400

320

\$1,280.00

\$500.00

20 \$80.00

20 \$80.00

x \$120.00

\$2,060.00

\$4,448.56