

ASS. REC. BY:

REF: csmc19017751/Tly d3

Special Instruction:

Surveyor: laufk

ASSIGNMENT (Office)

Menmen

From (Person): Christina Wong

of

M81GDate/Time: 8/10/19 @ 4.41pm

photo ok

Estimated Cost:

Bill to:

OI / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMD 6167M

Insured:

SLP 3467R

at Workshop m/s

Quicks

Tel:

6631 0683

of

12 Sungai Kadut AvenuePolicy No: 29079608Claim No: 607269

Sum Insured:

Excess:

Make of Veh:

D.O.A.

30/9/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 5/3pm 28/10/19

Person Contacted:

GVA

Vehicle IN/OUT

Date/Time

Action/Instruction

EstimateInsp: 27A Tanjong Pagar14/0ct @ 08:52. Revised via preli advise

Surround

Taufm

REF:

MS16

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s \_\_\_\_\_  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SMD16167M Yr Regn: 20/8 Aug  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: Mini Cooper S Cabrio cc 1998  
Colour: Green A/C: Insured / Std / NI / NA  
Sp. Reading: 1447M T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: WMWJ520X03D44368  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Leaked / Burnt or  
Brake: Inorder / Jammed / Leaked / Burnt or  
Modl: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 205/45R17  
R: 205/45R17  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Hankook  
Front \_\_\_\_\_ Rear \_\_\_\_\_  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. \_\_\_\_\_ D.O.I. 9/10/14 @ 2400psi  
Survey held at Eurokars  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear o/s  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
7/11/19	Confirm PIP \$354789 3 days (Red \$2059-00, 36%)

RECEIVED 5 NOV 2019

Date/Time, File Pass to? ☐ : Preli. Report  
1) ☐ : Final Report

Date/Time, File Return to? 2) 8/11/19 Typist

Report Format :  
Lump Sum / I.B.I.: (\$ PIP \$3547-89)

Days Of Repair: 3  
Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Tech. Invs (\$)  
☐ : Weekend (\$)

Survey Fee:	150 11 161
Transportation: \$ + RS \$	
Photos	
Others	
TOTAL	

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Christina Wong

Date: 14 Oct 2019

**Preliminary Advice**

Insured Vehicle No	: SLP3467R	Accident Date	: 30/09/2019
TP Vehicle No	: SMD6167M	Assignment Date	: 08/10/2019
Make	: MINI COOPER S	Est. Duration of Repair	: 3.00
Date of Inspection	: 09/10/2019		
Inspection At	: EUROKARS HABITAT PTE LTD (SUNGEI KADUT) 12 SUNGEI KADUT AVENUE SINGAPORE 729648		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,606.89
Revised Amount	:S\$	3,439.92
Check Items (Estimated)	:S\$	107.97
Total	:S\$	3,547.89
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( x ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Oct 2019		08 Oct 2019 16:41 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS

Insured: <b>LOW WEE JIA</b> , ID: S8540490C, Tel: +6581121607		[Created by insurer]
Main Claimant: <b>SARABJEET KAUR D/O S DALIP SINGH</b> , ID: S1670211J		
Vehicle Reg. No.: <b>SMD6167M</b>	Date of Loss: 30/09/2019 08:00 - :59	[13 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type: <b>TP / 607269</b>	Policy/Cover Note No.: 29079608 (Comprehensive)	Coverage: 01/06/2019 - 31/05/2020
Vehicle Reg. No. (Insured): <b>SLP3467R</b>	Policy No. (Claimant):	
	Excess:	S\$700.00
Repairer: <b>Eurokars Habitat Pte Ltd (Sungei Kadut)</b> 12 Sungei Kadut Avenue, 729648 Sungei Kadut - Tel:		
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Christina Wong</b> - 6643 1311]		
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Imm.Advice due 09/10/2019]		
Driver/Custodian (Insured): <b>ONG XUN NING</b> (34 / Female), NRIC: S8520125E, Tel: +6598636055 Email:		
Adj Asg. Remarks: Survey appt 09/10/19, 2.30pm. Owner waiting. on WP. Please contact us ASAP if you cannot attend this assignment. Liab: clear. Contact: Eva @ 6331 0680 / 6331 0683.		

#### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Yvonne Wong (LKK Auto)

---

**From:** Yvonne Wong (LKK Auto)  
**Sent:** Thursday, November 07, 2019 6:29 PM  
**To:** jessicahs@eurokars.com.sg; Taufikh (LKKAuto)  
**Cc:** zul.fadzli@eurokars.com.sg; sarah.candida@eurokars.com.sg;  
jobithomas@eurokars.com.sg; rickteo@eurokars.com.sg  
**Subject:** FINALIZATION SMD6167M TP MSIG (MINI)

Hi Jessica Shastri

WITHOUT PREJUDICE

Confirm total \$3,547.89 before GST @ 3 working days.

**Kindly send Final invoice and all supporting documents directly to MSIG Insurance.**

Thank you.

Best Regards,

**Yvonne Wong (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [yvonnnewong@lkkauto.com](mailto:yvonnnewong@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** jessicahs@eurokars.com.sg [mailto:jessicahs@eurokars.com.sg]  
**Sent:** Wednesday, November 06, 2019 3:01 PM  
**To:** Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Admin A <admin-a@lkkauto.com>  
**Cc:** zul.fadzli@eurokars.com.sg; sarah.candida@eurokars.com.sg; jobithomas@eurokars.com.sg;  
rickteo@eurokars.com.sg  
**Subject:** FINALIZATION SMD6167M TP MSIG (MINI)

Dear Taufikh,

Our COR computation is attached for your agreement.

COR: \$3,547.89 before GST

3 repair days (not including preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Kindly confirm the above as soon as possible.

Thank you very much.

Regards,

**Jessica Shastri**

**Admin Executive – Insurance Claims**

27A, Tanjong Penjuru

Singapore 609042

Dir: +65 6331 0691 | Fax: +65 6331 0690 | Email: [jessicahs@eurokars.com.sg](mailto:jessicahs@eurokars.com.sg)  
Website: [www.eurokarsgroup.com](http://www.eurokarsgroup.com)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 30/09/2019 15:55  
Date Of Accident 30/09/2019 08:30  
Exact Location Of Accident BISHAN ST 21  
Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SMD6167M  
**Insured/Policyholder**  
Name Of Registered Owner SARABJEET KAUR D/O S DALIP SINGH  
NRIC No S1670211J  
Email Address SARA@ECK.COM.SG  
Mobile Phone No (LOCAL) +65-91872042  
Alternative Phone No OTHERS-91872042

### Vehicle Particulars

Manufacturer MINI  
Model COOPER  
Exact Purpose for which vehicle was being used at time of accident  
Are you claiming under your own insurance policy for repair to your vehicle? NO  
If No, Please state action to be taken THIRD PARTY  
Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD  
Type Of Coverage COMPREHENSIVE  
Fleet Policy NO  
Policy Number GA393580  
Cover Note Number

### Driver

Name of Driver SARABJEET KAUR D/O S DALIP SINGH  
NRIC No S1670211J  
Date Of Birth 20/07/1964  
Occupation INDOOR  
Date Of Driving Pass 22/06/1993  
Driving Experience 26 YEARS AND 3 MONTHS  
Gender FEMALE  
Mobile Number (LOCAL) +65-91872042  
Fax Number  
Contact Number OTHERS-91872042  
Email Address SARA@ECK.COM.SG

Address	BLK 192 PASIR RIS ST 12 #05-06
Postcode	510192
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PAX 1 GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORD BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	UNABLE TO UPLOAD - REQ FROM OWNER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP3467R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ONG XUN HING
NRIC/Passport Number	S8520125E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	



No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name	SARABJEET KAUR D/O S DALIP SINGH
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SMD6167M
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

## Sketch Plan


### SKETCH PLAN

#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

30/9/19.

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2

## SKETCH PLAN

	<b>Vehicle</b> A-SMD 6167 M B-SLP 3467 R
	<b>Legend</b> 

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

was driving to work & stop at the ~~stop~~ Slip Rd as there were on coming veh. I was hit at back by hit SLP 3467 R. I was hurt by the steering wheel. ~~hit~~ *mayex*

## DECLARATION

I/We declare the foregoing particulars are true in every respect.  
 Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against own policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

*[Signature]*  
 Policyholder's Signature  
 Date & Time:

*[Signature]*  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

*[Signature]*  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

30/9/19



**EUROKARS HABITAT PTE LTD**  
**27A TANJONG PENJURU, SINGAPORE 609042**  
**ESTIMATE COST OF REPAIRS**



<b>MSIG INSURANCE (SINGAPORE) PTE LTD</b>		<b>NAME :</b> Ms SK D/O S Dalip Singh		<b>WIP :</b> 31025	
4 SHENTON WAY #21-01		<b>ADDRESS :</b> Blk 192 Pasir Ris Street 12		<b>EXCESS :</b>	
SGX CENTRE 2 S 068807		#05-06		<b>DATE :</b> 03.10.2019	
<b>ATTN. :</b> MOTOR CLAIMS		<b>TEL :</b> 91872042			
<b>FAX :</b>					
<b>VEH NO :</b>	<b>SMD6167M</b>	<b>DATE IN :</b>		<b>CONTACT PERSON :</b>	EVA 63310683
<b>CHASSIS NO :</b>	WMWWJ520X03D44368	<b>MILEAGE :</b>		<b>TYPE OF CLAIM :</b>	TP
<b>MODEL :</b>	F57	<b>DATE REG.:</b>	28.08.2018	<b>POLICY NO. :</b>	
<b>NATURE OF WORKS</b>					
<b>S/NO</b>	<b>Parts Description</b>			<b>REVISED</b>	<b>PRICES</b>
		<b>QTY</b>			
1	REAR BUMPER	1	M51.12.7.380.020	del ✓	\$ 1,041.82
2	REAR BUMPER GUIDE RH	1	M51.12.7.432.942	? can	\$ 107.97
3	BLIND RIVET	4	M07.14.7.411.141	del ✓	\$ 15.60
4	CLIP	4	M07.14.2.754.954	del ✓	\$ 7.20
5	REAR BUMPER LOWER GRILLE FRAME	1	M51.12.7.365.071	X un	\$ 151.26
6	REAR BUMPER LOWER GRILLE	1	M51.12.7.365.075	X un	\$ 146.71
7	REAR FENDER WHEEL ARCH	1	M51.77.7.300.822	X un	\$ 177.39
8	CLIP, BOTTOM	8	M51.71.7.154.239	del ✓	\$ 17.68
9	REAR BUMPER SIDE LOWER TRIM COVER PDC	1	M51.12.7.380.538	del ✓	\$ 87.62
10	TAIL LAMP RING BLACK	1	M63.21.7.464.172	X un	\$ 161.66
11	SPLASH SHIELD	1	M51.71.7.290.794	X un	\$ 152.10
12	SENSOR	1	B66.20.9.274.428	X un	\$ 323.31
13	SENSOR GASKET	1	B66.20.9.283.203	del X un	\$ 6.57
<b>TOTAL PARTS</b>					\$ 2,396.89
					\$ -
<b>TOTAL PARTS COST</b>					\$ 2,396.89
<b>Labour Description</b>					
1	TO REPLACE REAR BUMPER & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			840	\$ 1,260.00
2	TO RESPRAY REAR BUMPER.			800	\$ 1,000.00
3	TO TRANSFER THE REVERSE SENSORS.			200	\$ 500.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			NETT ✓	\$ 150.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			NETT ✓	\$ 250.00
6	SUNDRIES.			net 30	\$ 50.00
<b>TOTAL LABOUR</b>					\$ - \$ 3,210.00

TOTAL PARTS	\$ -	\$ 2,396.89
TOTAL	\$ -	\$ 5,606.89
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

**\*DISCLAIMER**

- 1 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.
- 2 TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.
- 3 THIS IS ONLY AN ESTIMATE BASED ON PARTS AVAILABILITIES AT CURRENT LOCAL SINGAPORE WAREHOUSE. IF THERE IS A NEED TO INCLUDE AIRFREIGHT PARTS, WE WILL INFORM DULY.

*[Signature]*  
14/10/19

Tan Jia 97495749  
'wp'  
9/10/19 @ 240pm  
3 days  
Resurvey before paint  
sur @ lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



**EUROKARS HABITAT PTE LTD**  
**27A TANJONG PENJURU, SINGAPORE 609042**  
**FINALIZATION COST OF REPAIRS**



<b>MSIG INSURANCE (SINGAPORE) PTE LTD</b>		<b>NAME :</b> Ms SK D/O S Dalip Singh		<b>WIP :</b> 31025	
4 SHENTON WAY #21-01		<b>ADDRESS :</b> Blk 192 Pasir Ris Street 12		<b>EXCESS :</b>	
SGX CENTRE 2 S 068807		#05-06		<b>DATE:</b> 03.10.2019	
<b>ATTN. :</b> MOTOR CLAIMS		<b>TEL :</b> 91872042			
<b>FAX :</b>					
<b>VEH NO :</b>	<b>SMD6167M</b>	<b>DATE IN :</b>		<b>CONTACT PERSON :</b>	EVA 63310683
<b>CHASSIS NO :</b>	WMWWJ520X03D44368	<b>MILEAGE :</b>		<b>TYPE OF CLAIM :</b>	TP
<b>MODEL :</b>	F57	<b>DATE REG.:</b>	28.08.2018	<b>POLICY NO. :</b>	
<b>NATURE OF WORKS</b>					
<b>S/NO</b>	<b>Parts Description</b>			<b>REVISED</b>	<b>PRICES</b>
	<b>QTY</b>				
1	REAR BUMPER	1	M51.12.7.380.020	\$ 1,041.82	\$ 1,041.82
2	REAR BUMPER GUIDE RH	1	M51.12.7.432.942	\$ 107.97	\$ 107.97
3	BLIND RIVET	4	M07.14.7.411.141	\$ 15.60	\$ 15.60
4	CLIP	4	M07.14.2.754.954	\$ 7.20	\$ 7.20
5	REAR BUMPER LOWER GRILLE FRAME	1	M51.12.7.365.071		\$ 151.26
6	REAR BUMPER LOWER GRILLE	1	M51.12.7.365.075		\$ 146.71
7	REAR FENDER WHEEL ARCH	1	M51.77.7.300.822		\$ 177.39
8	CLIP, BOTTOM	8	M51.71.7.154.239	\$ 17.68	\$ 17.68
9	REAR BUMPER SIDE LOWER TRIM COVER PDC	1	M51.12.7.380.538	\$ 87.62	\$ 87.62
10	TAIL LAMP RING BLACK	1	M63.21.7.464.172		\$ 161.66
11	SPLASH SHIELD	1	M51.71.7.290.794		\$ 152.10
12	SENSOR	1	B66.20.9.274.428		\$ 323.31
13	SENSOR GASKET	1	B66.20.9.283.203		\$ 6.57
<b>TOTAL PARTS</b>				\$ 1,277.89	\$ 2,396.89
					\$ -
<b>TOTAL PARTS COST</b>				\$ 1,277.89	\$ 2,396.89
<b>Labour Description</b>					
1	TO REPLACE REAR BUMPER & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 840.00	\$ 1,260.00
2	TO RESPRAY REAR BUMPER.			\$ 800.00	\$ 1,000.00
3	TO TRANSFER THE REVERSE SENSORS.			\$ 200.00	\$ 500.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$ 150.00	\$ 150.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			\$ 250.00	\$ 250.00
6	SUNDRIES.			\$ 30.00	\$ 50.00
<b>TOTAL LABOUR</b>				\$ 2,270.00	\$ 3,210.00

TOTAL PARTS	\$ 1,277.89	\$ 2,396.89
TOTAL	\$ 3,547.89	\$ 5,606.89
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ 3,547.89	
GST 7%	\$ 248.35	\$ -
GRAND TOTAL	\$ 3,796.24	\$ -

NUMBER OF DAYS: 3 WORKING DAYS(EXCLUDE WAITING FOR SURVEY,AUTHORIZATION,PARTS,SAT,SUN & PH)

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19017751/T1YD3N2

Date: 11/11/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29079608
Claimant Vehicle No :	SMD6167M	Insured Vehicle No :	SLP3467R
Date of Loss:	30/09/2019	Nature of Claim:	TP
		Claim No:	607269

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD6167M	Engine No:	G018H744B48A20F
Make & Model:	MINI COOPER S, 2.0 F56 (A)	Chassis No:	WMWWJ520X03D44368
Reg. Date:	28/08/2018 (Man. Year: 2018)	Odometer:	14474 km
Colour:	Green		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45R17	Rear Tyre Size:	205/45R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,446.89	1,307.89	1,139.00	46.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,160.00	2,240.00	920.00	29.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,606.89</b>	<b>3,547.89</b>	<b>2,059.00</b>	<b>36.72</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>392.48</b>	<b>248.35</b>	<b>144.13</b>	<b>36.72</b>
<b>Nett Amount (S\$)</b>	<b>5,999.37</b>	<b>3,796.24</b>	<b>2,203.13</b>	<b>36.72</b>

INSPECTION

Date of Assignment:	08/10/2019	
Date Inspected:	09/10/2019	Inspected At: Eurokars Habitat Pte Ltd (Sungei Kadut) 12 Sungei Kadut Avenue Singapore 729648
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 11 Nov 2019)
<b>Parts:</b>	144	MINI COOPER S 2.0 F56 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMD6167M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed	1,041.82 FS	*1,041.82 FS
2	1	*REAR BUMPER GUIDE RH	Cracked	107.97 FS	*107.97 FS
3	4	*BLIND RIVET	Necessary	15.60 FS	*15.60 FS
4	4	*CLIP	Necessary	7.20 FS	*7.20 FS
5	1	*REAR BUMPER LOWER GRILLE FRAME	Not Necessary	151.26 FS	*- FS
6	1	*REAR BUMPER LOWER GRILLE	Not Necessary	146.71 FS	*- FS
7	1	*REAR FENDER WHEEL ARCH	Not Necessary	177.39 FS	*- FS
8	8	*CLIP,BOTTOM	Necessary	17.68 FS	*17.68 FS
9	1	*REAR BUMPER SIDE LOWER TRIM COVER PDC	Deformed	87.62 FS	*87.62 FS
10	1	*TAIL LAMP RING BLACK	Not Necessary	161.66 FS	*- FS
11	1	*SPLASH SHIELD	Not Necessary	152.10 FS	*- FS
12	1	*SENSOR	Not Necessary	323.31 FS	*- FS
13	1	*SENSOR GASKET	Not Necessary	6.57 FS	*- FS
14	1	*SUNDRIES	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>2,446.89</b>	<b>1,307.89</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	1,260.00	840.00
2	TO RESPRAY REAR BUMPER	New	1,000.00	800.00
3	TO TRANSFER THE REVERSE SENSORS	New	500.00	200.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	150.00	150.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	250.00	250.00
<b>Gross Labour Cost (S\$)</b>			<b>3,160.00</b>	<b>2,240.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >