

India

75.00

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
				SHD 3462P	
	Rear Bumper Cnd			\$ 553.00	✓
	Rear Bumper Clip 10 pcs h/c			\$ 22.00	✓
	Rear Bumper Bracket, LH h/c			\$ 35.60	X
	Rear Fender With Housing (LH) Dented		2020.00	\$ 4,736.80	✓
	Rear Fender Inner Lining (LH) h/c			\$ 169.30	X
	Rear Windscreen Moulding h/c			\$ 28.30	✓
	Rear Door (LH) Dented			\$ 2,201.10	✓
	Door Centre Pillar Outer (LH) Dented			\$ 2,527.80	✓
	Rear Tyre Rim (LH) 2 disintegrated			\$ 325.30	2 ✓
	Rear Wheel Hup-Cap (LH) cnd			\$ 107.10	✓
	Rear Wheelbearing ING & Hub 2 Down			\$ 362.00	2 ✓
	Rear Trailing Arm (LH) 2 disintegrated			\$ 192.00	2 ✓
	Rear Assist (LH) 2 disintegrated			\$ 145.70	2 ✓
	Rear Shock Absorber (LH) 2 disintegrated			\$ 276.30	2 ✓
	Rear Shock Absorber Mounting (LH) h/c			\$ 81.30	X
	Rear Crossmember h/c			\$ 1,021.50	X
	Stabilizer Bar h/c			\$ 199.60	X
	Stabilizer Link h/c			\$ 85.90	X
	Rear Upper Arm (LH) 2 disintegrated			\$ 335.75	2 ✓
	Rear Lower Arm (LH) 2 disintegrated			\$ 353.80	2 ✓
	Rear Knuckle Arm (LH) 2 disintegrated			\$ 545.60	2 ✓
			9995.75		
			7996.60		
	SUB TOTAL			\$ 14,305.75	
	LESS 20%			\$ 2,861.15	
	DISCOUNTED TOTAL			\$ 11,444.60	
	Rear Bumper Rubber Mat h/c			\$ 50.00	Nett ✓
	Rear Windscreen Sealant h/c			\$ 46.00	Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (LH) h/c			\$ 80.00	Nett ✓
	Rear Tyre (LH) h/c		176.00	\$ 216.00	Nett X
				\$ 392.00	

Qty	Parts Description/ Labour	Type	Unit Price	SHD 3462P Amount
	Labour Charge			
	Panel Beating			\$ 2,400.00 1000/-
	Spray Painting Charge			\$ 1,800.00 1000/-
	Wiring Charge			\$ 100.00 22
	Tuff Kote			\$ 150.00 40/-
	Towing Charge			\$ 50.00 14
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Reverse Sensor			\$ 120.00 40/-
	Remove/Refix Undercarriage (FRT)			\$ 200.00 150/-
	Remove/Refix Fuel Tank			\$ 150.00 22
	Transfer of Door		\$ 120.00	\$ 240.00 120/-
	Remove/Refix Undercarriage (RR)			\$ 200.00 150/-
	Four Wheel Alignment			\$ 120.00 60/-
	Remove/Refix Dashboard			\$ 350.00 22
	Remove/Refix Front Windscreen Glass			\$ 120.00 22
	Remove/Refix Cushion & Upholstery Front			\$ 90.00 22
	Re-set Frt & Rear ABS System		\$ 200.00	\$ 400.00
	Re-set Frt & Rear Power Window System		\$ 200.00	\$ 400.00
	Diagnostic & Rsetting To Erase Fault Code			\$ 480.00 } 150/-
	TOTAL LABOUR			\$ 7,640.00
	ESTIMATE TOTAL			\$ 34,111.20
	08/10/2019 @ 1045hr			16567.52
	N/A Antinul			L/S 13250/-
	2/Smu 10 days.			
	<u>Ryan</u>			
	LKK Auto			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company