

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

HO SOO LIEW

BLK 609 BEDOK RESERVOIR ROAD

#08-676

S 470609

TP Chian
Vic

Date

:21.10.2019

Vehicle No

:SMA 8052

Make/Model

:TOYOTA VIOS

Accident date

:04.10.2019

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Rear bumper <i>Repaired</i>	1	\$ 408.6 ✓
2	Rear bumper side holder @ \$ 191.90 <i>RH Danged</i>	2	\$ 383.8 <i>34</i>
3	Rear bumper clips (1 set) <i>Nec</i>	1	\$ 66 <i>30</i>
4	Rear end panel <i>Repair</i>	1	\$ 859.6 <i>x</i>
5	Rear RH lamp <i>cracked</i>	1	\$ 409 <i>323</i>
6	Rear RH lamp housing <i>Buckled</i>	1	\$ 411.8 <i>155</i>
7	Rear RH mud flap <i>Neu</i>	1	\$ 208.2 <i>x</i>
8	Rear windscreen rubber <i>Neu</i>	1	\$ 191.8 ✓
9	Rear fender <i>Distorted</i>	1	\$ 1068.4 ✓
10	Rear RH door <i>Distorted</i>	1	\$ 1079.6 ✓
11	Rear RH door glass outer <i>moulding Replaced</i>	1	\$ 408.9 <i>125</i>
12	Rear RH door quater glass rubber <i>at</i>	1	\$ 420.1 <i>85</i>
13	Rear RH door outer handle <i>Danged</i>	1	\$ 193.3 ✓
14	Rear RH door protector <i>Distorted</i>	1	\$ 188.6 ✓
15	Rear RH door frame black sticker (1 set) <i>Neu</i>	1	\$ 133.2 <i>80(SN)</i>
16	Rear RH door glass channel <i>But</i>	1	\$ 408.4 <i>79</i>
17	Rear RH door top hinge <i>Neu</i>	1	\$ 188.6 <i>x</i>
18	Rear RH door lower hinge <i>Neu</i>	1	\$ 188.6 <i>x</i>
19	Rear RH door stopper <i>Neu</i>	1	\$ 200.5 <i>x</i>
20	Rear RH door weather strip <i>at</i>	1	\$ 210.8 ✓
21	Rear RH door inner board <i>cracked</i>	1	\$ 860.1 <i>465</i>
22	Rear RH door inner lock <i>Jammed</i>	1	\$ 41.3 ✓
23	Rear RH door eye <i>Neu</i>	1	\$ 200.3 <i>x</i>
24	Rear RH door power window regulator <i>Danged</i>	1	\$ 210.6 ✓
25	Rear RH door power window motor <i>Danged</i>	1	\$ 617.8 <i>387.70</i>
26	Front RH door <i>Buckled</i>	1	\$ 1339.2 <i>985</i>
27	Front RH door glass outer moulding <i>Neu</i>	1	\$ 200.3 <i>x</i>
28	Front RH door inner lock <i>Neu</i>	1	\$ 617.8 <i>x</i>
29	Front RH door protector <i>Neu</i>	1	\$ 189.5 <i>x</i>
30	Front RH door inner board <i>Neu</i>	1	\$ 804.4 <i>x</i>
31	Front RH door weather strip <i>Neu</i>	1	\$ 200.1 <i>x</i>

is subject to final approval from Insurance Company

Supplementary (terms) must be reviewed and

No illegal modification is allowed

Third party survey is on a Without Prejudice basis

Prices are subject to market fluctuation

Any damaged part to be replaced

• Temporary repairs are not allowed

• The Repairer of the following:

LK Auto Consultancy

Acknowledged by Repairer

Signature:

Date:

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

HO SOO LIEW

BLK 609 BEDOK RESERVOIR ROAD

#08-676

S 470609

Date

:21.10.2019

Vehicle No

:SMA 8052

Make/Model

:TOYOTA VIOS

Accident date

:04.10.2019

No	DESCRIPTION	Qty	Amount (S\$)
32	Front RH door black sticker (1 set) <i>new</i>	1	\$ 188.6 80(SN)
33	RH door pillar <i>Regis</i>	1	\$ 694.5 <i>x</i>
34	Rear RH shock absorber <i>3 new</i>	1	\$ 200.5 <i>x</i>
35	Rear RH knuckle arm	1	\$ 617.8 <i>x</i>
36	Rear RH knuckle arm bearing <i>Dogd.</i>	1	\$ 640.1 <i>✓</i>
37	Rear axle <i>new</i>	1	\$ 2993.2 <i>x</i>
			\$ 18243.9
		Less 25% Disc	\$ 4560.97
		Total	\$ 13682.93

Special Nett Items

1	Rear bumper reverse sensor <i>new</i>	480	\$ 380 <i>x</i>
2	Rear sport rim <i>ut</i>		\$ 800 <i>480</i>
3	Rear tyre <i>new</i>		\$ 300 <i>x</i>
		Total	\$ 1480

Labour Cost

1	To check wheel alignment	\$ 100 <i>80</i>
2	To supply rear windscreen sealant	\$ 50 <i>✓</i>
3	To supply rear end panel inner sealant	\$ 200 <i>x</i>
4	Remove & reinstall rear windscreen	\$ 150 120
5	Remove & reinstall rear suspension	\$ 300 80
6	Remove & reinstall roof lining + cushion	\$ 300 150
7	Remove & reinstall door glass <i>hitting</i>	\$ 200 160
8	Remove, replace & repair consistent to the accident	\$ 2200 1500
9	Respray painting	\$ 1600 1300
10	Tuff kote	\$ 150 120
	Total	\$ 5250

Grand Total

\$ 20412.93

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 9376.35

4/5 : 7.5K

09 Days

7.5K