

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 15:11

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014756 Date: 17/01/2020 Order: SML7015U Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SML7015U (V 42048) Regn Date: 30/05/2019 Mileage: 3621 WIP No.: 11658
Model: A4 SEDAN 2.0 TFSI 8W2ADG Chassis: WAUZZZF49KA059196 Engine: CVK 079729 Dept: U
You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-1100.00	1.00	-1,100.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW LHS WING MIRROR ASSY	300.00	1.00	300.00
S	BODYWORK	M: TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW LHS FRONT FENDER AND LHS HEADLIGHT. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND LHS WING MIRROR COVER	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT. TO INSPECT LHS FRONT WHEEL SUSPENSION FOR FURTHER DAMAGES	280.00	1.00	280.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8W0821105A	FENDER (LAST) Less 020%	1.00	699.50	559.60
X	A8W0821467	BRACKET (SHARE) Less 020%	1.00	31.50	25.20
X	AN 0161857	POP-RIVET Less 020%	6.00	3.00	14.40
X	A8W0821433B	BRACKET (LAST) Less 020%	1.00	30.20	24.16
X	A8W0821171A	WHEEL HOUS (SHARE) AP Less 020%	1.00	223.00	178.40
X	A8W0853823B 9B9	STONEGUARD (LAST) Less 020%	1.00	45.80	36.64
X	A8W0601025EF	007482/(V) (GER) WHEEL Less 020%	1.00	651.00	520.80

Parts 1,359.20
Labour 0.00
Sublet 3,502.00
Menus 0.00
Lubricant 0.00

Sub-Total 3,761.20

7% GST 263.28

Grand Total 4,024.48



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SML7015U

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1100/2019/EH
18 October 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE: CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 SEDAN 2.0 TFSI
Vehicle Chassis No. : WAUZZZF49KA059196
Vehicle Regn No. : SML 7015 U
Vehicle Mileage : 3632 KM
Vehicle Owner : Mr. Poon Chew Hay
Certificate No : 1900103049
Own Damage Excess : \$ 1,177.00 (Inclusive GST)
Accident Date : 8 September 2019
Place : 355 Tanglin Road
Repair Cost : \$ 4024.48
WIP No. : 11658
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 6 pm
Date : 18/10/2019