

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 14986

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1200/2019/NS
Date	:	7-Oct-19

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Neo Yeow Yang
Address	:	46 Pavilion View #01-46 Singapore 658460
Telephone	:	HP +65 92288852
Type of Claim	:	Own Damage Claims
Policy No.	:	1900109455
Vehicle No	:	SMN 3000 C
Model Code	:	Audi A3 Sedan 1.0 TFSI 8V
Model / Year	:	Jun-19
Engine No	:	CHZ B23469
Chassis No	:	WAUZZZ8V7KA079193
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	5-Oct-19
Place of Accident	:	PIE Near CTE Exit Towards Toa Payoh

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMN 3000 C

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To remove and renew aircon condenser, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00	?
3	To dismantle and renew front bumper, lhs front fender, bonnet and both headlights. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 5,600.00	1750 without lock carrier 3000 with lock carrier.
4	To respray front bumper, bonnet, lhs front fender and hinges.	\$ 3,200.00	1650.
5	To carry out diagnostic check.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 10,552.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 3000 C

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>old</i>	\$ 1,830.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 170.00	X
3	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	\$ 35.00	X
4	FRONT BUMPER GRILLE - CENTRE <i>old</i>	\$ 146.00	✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 488.00	X
6	FRONT BUMPER CLOSING ELEMENT - LH / RH ? 2	\$ 540.00	?
7	FRONT BUMPER COVER TRIM - LH / RH <i>new</i> 2	\$ 296.00	X
8	FRONT BUMPER WHEEL HOUSING LINER ADAPTER - LH / RH <i>new</i> 2	\$ 68.00	X
9	RADIATOR GRILLE <i>old</i>	\$ 1,301.00	✓
10	RADIATOR GRILLE CLOSING ELEMENT ?	\$ 174.00	?
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i> 2	\$ 342.00	X
12	FRONT BUMPER SIDE REINFORCEMENT BEAM ?	\$ 660.00	?
13	FRONT BUMPER FOAM FILLER PIECE ?	\$ 172.00	?
14	FOAM FILLER PIECE COVER ?	\$ 111.00	?
15	AIRCON STICKER <i>2 new</i>	NEC \$ 7.00	✓
16	CAUTION SIGN STICKER	NEC \$ 13.00	✓
17	SIGNAL HORN - RH LOW TONE ?	\$ 182.00	?
18	SIGNAL HORN - LH HIGH TONE ?	\$ 182.00	?
19	FRONT FENDER - LH <i>Repaired</i>	\$ 778.00	✓
20	FRONT FENDER ATTACHMENT PARTS ?	\$ 65.00	?
SUB TOTAL SPARE PARTS		: \$ 7,560.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 3000 C

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	FRONT FENDER BRACKET - LH ?	\$ 25.00	?
22	FRONT FENDER BRACKET - LH ?	\$ 35.00	?
23	FRONT FENDER BRACE ?	\$ 88.00	?
24	FRONT WHEEL HOUSING LINER - LH	\$ 158.00	X
25	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS ^{2 up}	\$ 81.00	X
26	BONNET <i>Distorted</i>	\$ 2,898.00	✓
27	BONNET ATTACHMENT PARTS ?	\$ 149.00	?
28	BONNET LID HINGE - LH / RH <i>new</i>	2 \$ 112.00	X
29	BONNET GAS FILLED STRUT <i>new</i>	\$ 109.00	X
30	BONNET CATCH HOOK ?	\$ 81.00	?
31	BONNET STRIKER - LH / RH ?	2 \$ 200.00	?
32	BONNET EDGE PROTECTION <i>new</i>	\$ 25.00	✓
33	BONNET LID LOCK <i>Turned</i>	2 \$ 367.00	✓
34	BONNET BOWDEN CABLE - CENTRE ?	\$ 53.00	?
35	BONNET LID LOCK CABLE	\$ 67.00	?
36	PLENUM CHAMBER COVER <i>ht</i>	\$ 164.00	✓
37	PLENUM CHAMBER TOP COVER ?	\$ 15.00	✓
38	LED HEADLIGHT - LH / RH <i>LH covered, RH</i>	2 \$ 10,058.00	<i>5029</i>
39	HEADLIGHT WASHER SYSTEM LIFT CYLINDER - LH / RH <i>new</i>	2 \$ 256.00	X
40	HEADLIGHT HOSE <i>new</i>	\$ 61.00	X
SUB TOTAL SPARE PARTS		\$ 15,002.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 3000 C

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
41	WASH WATER RESERVOIR	\$ 186.00	?
42	LOCK CARRIER	\$ 663.00	?
43	A/C CONDENSER	\$ 503.00	?
44	RADIATOR	\$ 878.00	?
45	ADDITONAL RADIATOR	\$ 837.00	?
46	READY MIX COOLANT	4 \$ 165.00	?
47	RADIATOR FAN	\$ 1,046.00	?
48	RADIATOR AIR GUIDE - LH / RH	2 \$ 44.00	?
49	RADIATOR AIR GUIDE - UPPER CENTRE	\$ 11.00	?
50	EXTERNAL TEMPERATURE SENSOR	\$ 54.00	?
51	TEMPERATURE SENSOR BRACKET	\$ 17.00	?
52	AIR INLET	\$ 53.00	?
53	INTAKE AIR GUIDE	\$ 62.00	?
54	INTER COOLER GASKET	\$ 13.00	?
55	AIR FILTER	\$ 252.00	?
56	WATER DRAINAGE HOSE	\$ 31.00	?
57	INTAKE MANIFOLD	\$ 129.00	?
58	FRONT NO PLATE <i>Beit</i>	S/N \$ 40.00	✓
59	SUNDRIES	\$ 500.00	?
TOTAL SPARE PARTS		: \$ 28,046.00	
TOTAL LABOUR CHARGES		: \$ 10,552.00	
GRAND TOTAL		: \$ 38,598.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian King

Surveyed Date

: 08/10/15

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: NE & changed, 06 Days Without Lode Carrier
09 Days With Lode Carrier

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant