

V.A.S.S. REC. BY:

REF: CS/FWD 1904797/KF3⁸²

Special Instruction:

Survivor: Kenneth

ASSIGNMENT (Office)

From (Person): Vanessa Chan

of

FWD

Date/Time: 9.10.19 12.55p

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJ C 2190L

Insured:

SLP 7522M

at Workshop m/s

Yee Auto

Tel:

645 72625

of 160 Sn ming Drive #02-17

Policy No:

PNPV2019-00010433

Claim No:

1201900030294

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 7.10.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9.10.19

1.19pm

Person Contacted:

Ah Chan

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJ C 2190L - x
	SLP 7522M - x
17/1	LI Ling @ 2900h email & confirm (Red. 6709; 69010)

ASS. REC. BY:

REF:

FWD/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 10/12 Person Contacted: _____

Vehicle: IN / OUT

Veh No: STC 21902Yr Regn: 02, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy EstinaColour: M. BlackSp. Reading: 163668

Eng/No: _____

C/No: ACR 50Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD A/Rim orTyre Size: F: 225/45 R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Green max

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 7/10/19Survey held at ✓Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

RECEIVED 17 JAN 2020

Date/Time, File Pass to?

1) AM Typist

Date/Time, File Return to?



: Prell. Report



: Final Report

Days Of Repair: 4Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

TP

2900/-

200
50
50+50

Nivitha (LKK Auto)

From: venessa.chan@fwd.com
Sent: Wednesday, 9 October 2019 12:55 PM
To: admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: lionel.tan@fwd.com; motorclaims.sg@fwd.com
Subject: Urgent: Pre-Repair Inspection: Your Vehicle: SLP 7522 M; Our Ref: YeeAuto-SJC 2190 L; Accident Involving SJC 2190 L & SLP 7522 M on 7 October 2019

Dear Nivitha,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen & I will upload the documents accordingly.

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Venessa Chan - SGUser
Sent: Wednesday, October 9, 2019 12:53 PM
To: bonnie kwok
Cc: Lionel Tan Tian Pei - SGUser; Motor Claims SG - SG Common; yeeauto pteltd
Subject: Urgent: Pre-Repair Inspection: Your Vehicle: SLP 7522 M; Our Ref: YeeAuto-SJC 2190 L; Accident Involving SJC 2190 L & SLP 7522 M on 7 October 2019

Hi ST,

Thank you for your selection of LKK Auto Consultants Pte Ltd.
We will proceed to assign survey.

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: bonnie kwok [<mailto:litigation@bonniekwok.com>]

Sent: Wednesday, October 9, 2019 12:48 PM

To: Venessa Chan - SGUser

Cc: Lionel Tan Tian Pei - SGUser; Motor Claims SG - SG Common; yeeauto pteltd

Subject: Re: Urgent: Pre-Repair Inspection: Your Vehicle: SLP 7522 M; Our Ref: YeeAuto-SJC 2190 L; Accident Involving SJC 2190 L & SLP 7522 M on 7 October 2019

Dear Sirs,

Our client confirms that the date of the accident is on 7 October 2019.

Our client agrees to LKK Auto Consultants Pte Ltd as the Single Joint Expert (SJE).

Please let us have their report in due course.

Kindly request for the SJE to contact the repairers, M/s Yee Auto Pte Ltd at 6457 5768 to make the necessary arrangements.

Regards,

ST

--

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Wed, 9 Oct 2019 at 10:38, <venessa.chan@fwd.com> wrote:

WITHOUT PREJUDICE

Dear ST ,

Please assist to confirm the accident date as our insured reported accident date is 06.10.2019.

Meanwhile, we refer to your email dated on 09.10.2019 of the PRI Notice of your client's vehicle SJC2190L.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. RT APPRAISAL PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.

***Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com.**

Thank you.

Best Regards,


Venessa Chan
Administrative Assistant, Claims



FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com



From: bonnie kwok [mailto:litigation@bonniekwok.com]

Sent: Wednesday, October 9, 2019 10:11 AM

To: Motor Claims SG - SG Common

Subject: Urgent: Pre-Repair Inspection: Your Vehicle: SLP 7522 M; Our Ref: YeeAuto-SJC 2190 L; Accident Involving SJC 2190 L & SLP 7522 M on 7 October 2019

Urgent

Dear Sirs,

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle no. SJC 2190 L at M/s Yee Auto Pte Ltd, Block 160 Sin Ming Drive #02-17 Sin Ming Autocity Singapore 575722.

Regards,

ST

--

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/10/2019 13:32
Date Of Accident	07/10/2019 07:30
Exact Location Of Accident	CHANGKAT CHANGI PRIMARY SCHOOL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJC2190L
Insured/Policyholder	
Name Of Registered Owner	NG SHEI-LI (HUANG XUELI)
NRIC No	S7711352E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96876028
Alternative Phone No	OTHERS-96876028

Vehicle Particulars

Manufacturer	TOYOTA
Model	ESTIMA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5112361168
Cover Note Number	

Driver


Name of Driver	TAY KIE TONG FABIAN
NRIC No	S7105435G
Date Of Birth	03/02/1971
Occupation	OUTDOOR
Date Of Driving Pass	05/08/1993
Driving Experience	26 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96876028
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

No. Of Passenger (Including Driver)

SKETCH PLAN

(A) SJC2190L

(B) SLP7522M



Changkat Changi Primary School


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 7/10/2019 at 7:30am. I was travelling my Vehicle (A) SJC2190L at Changkat Changi Primary School. As I go straight to exit. Suddenly, the Vehicle (B) SLP7522M which stationary at left side move forward turning out and hit my Vehicle rear left portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : FWD Singapore Pte Ltd
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 408868

Estimate No: ES1900094

Date: 09 Oct 2019

Policy No:

Veh Reg No: SJC2190L

Make/Model: TOYOTA ESTIMA
AERAS 2.4 A

Chassis No: ACR500059401

Engine No: 2AZF116298

Reg. Date: 01/02/2008

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 07/10/2019

TP Veh Reg No: SLP7522M

*Not Authorised
61 Day @ 2900h
Repair After Paint
- 4 days*

Estimate Repair Cost to Vehicle No :SJC2190L

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
Net Price				
1 REAR TYRE - LH	280.00	1 PC	<i>Ln</i> 280.00 <i>X</i>	
2 REAR WHEEL RIM - LH	800.00	1 PC	<i>Ln</i> 800.00 <i>450.00</i>	
			1,080.00	1,080.00
Spare Parts				
3 REAR AXLE BEAM	1,680.40	1 PC	<i>Ln</i> 1,680.40 <i>2</i>	
4 REAR BUMPER	782.20	1 PC	<i>Ln</i> 782.20 <i>1</i>	
5 REAR BUMPER CLIPS	40.00	1 SET	<i>Ln</i> 40.00 <i>1</i>	
6 REAR BUMPER SIDE RETAINER - LH	65.20	1 PC	<i>Ln</i> 65.20 <i>1</i>	
7 REAR BUMPER SIDE RETAINER - RH	65.20	1 PC	<i>Ln</i> 65.20 <i>X</i>	
8 REAR FENDER - LH	1,350.00	1 PC	<i>Ln</i> 1,350.00 <i>X</i>	
9 REAR FENDER INNER SHIELD - LH	125.90	1 PC	<i>Ln</i> 125.90 <i>X</i>	
10 REAR FENDER PROTECTOR - LH	228.90	1 PC	<i>Ln</i> 228.90 <i>1</i>	
11 REAR KNUCKLE ARM - LH	480.60	1 PC	<i>Ln</i> 480.60 <i>2</i>	
12 REAR SHOCK ABSORBER - LH	425.10	1 PC	<i>Ln</i> 425.10 <i>X</i>	
13 REAR WHEEL BEARING - LH	285.50	1 PC	<i>Ln</i> 285.50 <i>2</i>	
			5,529.00	5,529.00
Labour				
14 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,200.00	1 JOB	1,200.00 <i>200</i>	
15 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,500.00	1 JOB	1,500.00 <i>250</i>	
16 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	150.00	1 JOB	<i>Ln</i> 150.00 <i>X</i>	
17 WHEEL ALIGNMENT	150.00	1 T	150.00 <i>60</i>	
			3,000.00	3,000.00

251

LKK Auto Consultants hereby notify the Repairer of the following:

- To recovery information only painting
- To delay damages until during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Complimentary (100%) 1 year 100,000km warranty and is subject to final approval from LKK Auto Consultants Company

Acknowledged by Repairer
Signature:
Date:



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : FWD Singapore Pte Ltd
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 408868

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 07/10/2019
TP Veh Reg No: SLP7522M

Estimate No: ES1900094
Date: 09 Oct 2019
Policy No:
Veh Reg No: SJC2190L
Make/Model: TOYOTA ESTIMA
AERAS 2.4 A
Chassis No: ACR500059401
Engine No: 2AZF116298
Reg. Date: 01/02/2008

Estimate Repair Cost to Vehicle No :SJC2190L

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
			Total	SS 9,609.00
			Add GST @ 7%	672.63
			Total Amount Payable	SS 10,281.63

TOTAL: SINGAPORE DOLLAR TEN THOUSAND TWO HUNDRED EIGHTY ONE AND CENTS SIXTY THREE ONLY

For Yee Auto Pte Ltd


AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Oct 2019 Edit Reg		09 Oct 2019 00:00 Edit Adj Rpt	S\$2,900.00 Edit Estimates	S\$2,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	Handy Wijaya, ID: S8274178Z		
Main Claimant:	NG SHEI-LI, ID: S7711352E		
Vehicle Reg. No.:	SJC2190L	Date of Loss:	07/10/2019 00:00 - :59 [140 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1201900030294	Policy/Cover Note No.:	PNPV2019-00010433
Vehicle Reg. No. (Insured):	SLP7522M	Policy No. (Claimant):	
		Excess:	
Repairer:	Yee Auto Pte Ltd (HQ) 160 SIN MING DRIVE, #02-17 SIN MING AUTOCITY, 575722 Sin Ming - Tel: 6457 2625		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 18/10/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJC2190L (1201900030294)**
[SLP7522M]
TP
NG SHEI-LI
Oct 7 2019 12:00AM
[Handy Wijaya]
Yee Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports				1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/01/20 13:32	Adjuster Immediate Advice	i	Load HTM	
Photos/Images				3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/01/20 13:33	General View	i	Load JPG	✓
2	17/01/20 13:33	General View	i	Load JPG	✓
3	17/01/20 13:33	General View	i	Load JPG	✓
4	17/01/20 13:33	General View	i	Load JPG	✓
5	17/01/20 13:33	General View	i	Load JPG	✓
6	17/01/20 13:33	General View	i	Load JPG	✓
7	17/01/20 13:33	General View	i	Load JPG	✓
8	17/01/20 13:33	General View	i	Load JPG	✓
9	17/01/20 13:33	General View	i	Load JPG	✓
10	17/01/20 13:33	General View	i	Load JPG	✓
11	17/01/20 13:33	General View	i	Load JPG	✓
12	17/01/20 13:33	General View	i	Load JPG	✓
13	17/01/20 13:33	General View	i	Load JPG	✓
14	17/01/20 13:33	General View	i	Load JPG	✓
15	17/01/20 13:38	Reinspection Photo	i	Load JPG	✓
16	17/01/20 13:38	Reinspection Photo	i	Load JPG	✓
17	17/01/20 13:38	Reinspection Photo	i	Load JPG	✓
18	17/01/20 13:38	Reinspection Photo	i	Load JPG	✓
Documentation				1 per page ▼	✓
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	11/10/19 11:53	E-filed GIA report	i	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/FWD19017797/KTF3S2
Date: 20/01/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00010433
 Claimant Vehicle No: SJC2190L Insured Vehicle No: SLP7522M
 Date of Loss: 07/10/2019 Nature of Claim: TP Claim No: 1201900030294

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJC2190L
 Make & Model: TOYOTA ESTIMA, 2.4 AERAS (A) Engine No: 2AZF116298
 Reg. Date: 01/02/2008 (Man. Year: 2007) Chassis No: ACR500059401
 Colour: Metallic Black Odometer: 163668 km
 Engine Capacity: 2362 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
 Front Left Side: GREEN-MAX 9 mm Rear Left Side: GREEN-MAX 7 mm
 Front Right Side: GREEN-MAX 9 mm Rear Right Side: GREEN-MAX 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,609.00	3,122.10	3,486.90	52.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	510.00	2,490.00	83.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,609.00	3,632.10	5,976.90	62.20
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	9,609.00	2,900.00	6,709.00	69.82
+ GST 7.00/7.00% (S\$)	672.63	203.00	469.63	69.82
Nett Amount (S\$)	10,281.63	3,103.00	7,178.63	69.82

INSPECTION

Date of Assignment: 09/10/2019
 Date Inspected: 09/10/2019 Inspected At: 160 SIN MING DRIVE, #02-17 SIN MING AUTOCITY
 Estimated Period of Repair: 4.0 days Singapore 575722
 Repairer: Yee Auto Pte Ltd

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Jan 2020)

Parts: M1-MPV TOYOTA ESTIMA 2.4 AERAS (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJC2190L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR AXLE BEAM	Bent	1,680.40 F	*1,680.40 FL
2	1		*REAR BUMPER	Buckled	782.20 F	*782.20 FL
3	1		*SET REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
4	1		*REAR BUMPER SIDE RETAINER - LH	Distorted	65.20 F	*65.20 FL
5	1		*REAR BUMPER SIDE RETAINER - RH	Serviceable	65.20 F	*- FL
6	1		*REAR FENDER - LH	Repair	1,350.00 F	*- FL
7	1		*REAR FENDER INNER SHIELD - LH	Serviceable	125.90 F	*- FL
8	1		*REAR FENDER PROTECTOR - LH	Cracked	228.90 F	*228.90 FL
9	1		*REAR KNUCKLE ARM - LH	Bent	480.60 F	*480.60 FL
10	1		*REAR SHOCK ABSORBER - LH	Serviceable	425.10 F	*- FL
11	1		*REAR WHEEL BEARING - LH	Necessary	285.50 F	*285.50 FL
12	1		*REAR TYRE - LH	Serviceable	280.00 FS	*- FS
13	1		*REAR WHEEL RIM - LH	Dented	800.00 FS	*450.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	6,609.00	4,012.80
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	890.70
Total Parts (\$\$)	6,609.00	3,122.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	New	1,200.00	200.00
2	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	New	1,500.00	250.00
3	TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL.	New	150.00	0.00
4	WHEEL ALIGNMENT.	New	150.00	60.00
Gross Labour Cost (\$\$)			3,000.00	510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >