



Section A - Accident Details

Registration Number	SHB5829M
Case Reference Number	TAX/10/19/2020
Registration Date	9/7/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	TAN KIM HUA
Type of Accident	Side Swipe
Accident Date and Time	5/10/2019 3:40 PM
Accident Reported Date and Time	7/10/2019 9:48 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	5/10/2019 8:51 PM
Replacement Vehicle issued?	No
Job Card Number	24103699
Special Instruction to ARC, if any	TP / TOWED \$40/ RIGHT FRONT PORTION
Prepared Date and Time	7/10/2019 4:17 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$400.00
Total Spray Cost	\$1,116.00	\$550.00
Total Spare Part Cost	\$5,387.80	\$2,010.86
Total Other Cost	\$544.44	\$248.44
TOTAL COST	\$7,893.24	\$3,209.30
Lump Sum Total	\$7,900.00	\$3,200.00 (L/S)
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	STEVE CHEN (LKK) / AIG
ARC / Surveyor Sign Off Date	11/10/2019 1:39 PM	11/10/2019 10:33 AM
Signature		
Remarks	Total number of repair days = 3 days. SUP = 0 day.	L/S repair, take after spray.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1910-0382	Invoice Number	
Quotation Date	19.10.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$845.00	\$400.00
Total Labour	\$845.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	\$180.00	\$150.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,116.00	\$550.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$40.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$148.44	\$148.44
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$544.44	\$248.44

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace ✓
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace ✓
		52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Check X
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Check X
		57013-47030	ARM SUB-ASSY, FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given X
		52114-47140	BRACKET, FR BUMPER	0.00	\$110.40	0.00	\$0.00	Replace	Not Given X
			NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given X
			NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Not Given X
		53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	1.00	\$311.10	25.00	\$233.33	Replace	Replace ✓
		81210-12230	FOG LAMP RH	0.00	\$295.20	0.00	\$0.00	Replace	Check X
		81220-12230	FOG LAMP LH	0.00	\$280.10	0.00	\$0.00	Replace	Not Given X
		81519-47050	BRACKET, FR TURN LOWER RH	0.00	\$26.00	0.00	\$0.00	Replace	Not Given ✓

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63665582
Estimator Telephone Number : 68662823
Accident Reporting Number : 68662572

Date Generated : 22/10/2019

User ID : PohSuan

81519-47060	BRACKET, FR TURN UPPER RH	0.00	\$24.40	0.00	\$0.00	Replace	Not Given	X
81511-47050	LENS & BODY, FR TURN RH	1.00	\$511.80	10.00	\$460.62	Replace	Replace	✓
81529-47060	BRACKET, FR TURN CENTER LH	0.00	\$58.20	0.00	\$0.00	Replace	Not Given	X
81529-47050	BRACKET, FR TURN LOWER LH	0.00	\$26.00	0.00	\$0.00	Replace	Not Given	X
81529-47040	BRACKET, FR TURN UPPER LH	0.00	\$24.40	0.00	\$0.00	Replace	Not Given	X
81521-47050	LENS & BODY, FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given	X
53113-47040	GRILLE RADIATOR LOWER NO.2	0.00	\$94.60	0.00	\$0.00	Replace	Not Given	X
53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Not Given	X
52128-47903	COVER, FR BUMPER HOLE LH	0.00	\$18.50	0.00	\$0.00	Replace	Not Given	X
52128-47903	COVER, FR BUMPER HOLE LH	0.00	\$18.50	0.00	\$0.00	Replace	Not Given	X
76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	X
52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Not Given	X
52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given	X
52115-47040	BUMPER SUPPORT F/RH	1.00	\$76.40	25.00	\$57.30	Replace	Replace	✓
53201-47902	SUPPORT SUB-ASSY	0.00	\$1,460.40	0.00	\$0.00	Replace	Not Given	X
81130-47500	HEAD LAMP RH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	✓
53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given	X
53801-47050	FENDER FRT/RH	1.00	\$723.40	100.00	\$0.00	Replace	Repair	R
75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	✓
53875-47030	FENDER LINER FRT/RH	1.00	\$171.70	25.00	\$128.78	Replace	Replace	✓
53851-47040	FENDER LINER PAD, FR WHEEL. RH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given	X
Total			\$7,953.51		\$2,143.22			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		81210-12230	FOG LAMP RH	1.00	\$295.20	10.00	\$265.68	Replace	Replace
		76851-47020	BUMPER LIP FRT	1.00	\$139.60	25.00	\$104.70	Replace	Replace
Total					434.80		370.38		

2513.60

- 202

2016.88

+ 400.00

+ 798.44

3208.32

4/5 \$3200/-



Case Details

Case Reference Number : TAX/10/19/2020
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB5829M

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-8777-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 05/10/2019 07:40 AM
 Vehicle Age(In Months) : 63

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace	✓ CR4
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	✓ NR
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Check	✓ X NR
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Check	✓ X NR
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give	✓ X NR
One Time Key In	Main			BRACKET, FR BUMPER	1	110.40	110.40	25.00	82.80	Replace	0	0	Not Give	✓ X NR
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	0	0	Not Give	✓ X NR
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	0	0	Not Give	✓ X NR
One Time Key In	Main			BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	311.10	25.00	233.33	Replace	1	233.33	Replace	✓ NR

Total Spare Part Cost 6,364.37

Surveyor Total 2,143.20

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 5,091.50

Final Sur Total 1,714.56

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			FOG LAMP RH	1	295.20	295.20	10.00	265.68	Replace	0	0	Check	X N/A
One Time Key In	Main			FOG LAMP LH	1	280.10	280.10	10.00	252.09	Replace	0	0	Not Given	X N/A
One Time Key In	Main			BRACKET, FR TURN LOWER RH	1	26.00	26.00	25.00	19.50	Replace	0	0	Not Given	X N/A
One Time Key In	Main			BRACKET, FR TURN UPPER RH	1	24.40	24.40	25.00	18.30	Replace	0	0	Not Given	X N/A
One Time Key In	Main			LENS & BODY, FR TURN RH	1	511.80	511.80	10.00	460.62	Replace	1	460.62	Replace	/ CUT
One Time Key In	Main			BRACKET, FR TURN CENTER LH	1	58.20	58.20	25.00	43.65	Replace	0	0	Not Given	X N/A
One Time Key In	Main			BRACKET, FR TURN LOWER LH	1	26.00	26.00	25.00	19.50	Replace	0	0	Not Given	X N/A
One Time Key In	Main			BRACKET, FR TURN UPPER LH	1	24.40	24.40	25.00	18.30	Replace	0	0	Not Given	X N/A
One Time Key In	Main			LENS & BODY, FR TURN LH	1	511.80	511.80	10.00	460.62	Replace	0	0	Not Given	X N/A
One Time Key In	Main			GRILLE RADIATOR LOWER NO.2	1	94.60	94.60	25.00	70.95	Replace	0	0	Not Given	X N/A
One Time Key In	Main			GRILLE, RADIATOR	1	310.60	310.60	25.00	232.95	Replace	0	0	Not Given	X N/A
One Time Key In	Main			COVER, FR BUMPER HOLE LH	1	18.50	18.50	25.00	13.88	Replace	0	0	Not Given	X N/A
One Time Key In	Main			COVER, FR BUMPER HOLE LH	1	18.50	18.50	25.00	13.88	Replace	0	0	Not Given	X N/A
One Time Key In	Main			BUMPER LIP FRT	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Given	X N/A
Total Spare Part Cost									6,364.37	Surveyor Total 2,143.20				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									5,091.50	Final Sur Total 1,714.56				

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Not Givr ▾	X N/A
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Givr ▾	X N/A
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	1	57.30	Replace ▾	X N/A
One Time Key In	Main			SUPPORT SUB-ASSY	1	1,460.40	1,460.40	25.00	1,095.30	Replace	0	0	Not Givr ▾	X N/A
One Time Key In	Main			HEAD LAMP RH	1	945.20	945.20	10.00	850.68	Replace	1	850.68	Replace ▾	✓ CWT
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Givr ▾	X N/A
One Time Key In	Main			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	1	0	Repair ▾	X R
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace ▾	✓ MC
One Time Key In	Main			FENDER LINER FRT/RH	1	171.70	171.70	25.00	128.77	Replace	1	128.77	Replace ▾	✓ TN
One Time Key In	Main			FENDER LINER PAD, FR WHEEL RH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Givr ▾	X N/A
Total Spare Part Cost									6,364.37	Surveyor Total			2,143.20	
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)			20	
Final Spare Part Cost									5,091.50	Final Sur Total			1,714.56	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT RH PORTION	845.00	400	
Total:			845.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			1,116.00	550.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	150	
3	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
4	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
Total:			1,116.00	550.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	40	nk
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	nk
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	nk
4	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	148.44	148.44	nk
5	Main	TO REPLACE SUNDRY PARTS	100.00	20	nk
6	Main	TO WASH AND VACUUM	80.00	0	
Total:			544.44	208.44	248.44

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	5,091.50	1,714.56
Total Labour Cost	845.00	400.00
Total Spray Painting	1,116.00	550.00
Other	544.44	208.44
Overall Total	7,596.94	2,873.00
Lump Sum Repair Option		
Lump Sum Total	7,600.00	2,850.00
Surveyor Approved Amount		2,850.00
No of Repair Days*	6	3

Estimator Assessment(\$)

Remarks

Surveyor Name

Signature




Survey Date

08/10/2019

Surveyor Assessment(\$)

L/S repair, take after spray.

STEVE CHEN



Save

Clear

L&K Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REQUEST FOR SUPPLYMENT PARTS

Contractor			
Accident Case Number	TAX 10/19/2020	Date of Collection	1 / 1
Vehicle No	SHB 5829 M	Date of Request	10/10/2019
Vehicle Model	84c TOYOTA PRIUS	Number of Days to Extend (If any)	90

S/N	Part Number	Part Description	Quantity	Unit Price
		Fog Lamp RH	1pc	\$265.68
		FRONT BUMPER LIP	1pc	MISSING


OR
MIS
\$104.70

<<Please submit photographs for damaged parts>>

I, (Name) Steve Clark

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.



10/19/19, 6:48pm

Signature of person making this declaration
(to be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the charges of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission