

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XB 6424B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT GRILLE (CONSISTENT)	NOT NECESSARY	680.00	-
18	FRONT GRILLE CLIP @\$8.00 (CONSISTENT)	NOT NECESSARY	144.00	-
1	FRONT GRILLE EMBLEM LOGO (CONSISTENT)	NOT NECESSARY	130.00	-
1	FRONT GRILLE FL10 LOGO (CONSISTENT)	NOT NECESSARY	150.00	-
1	FRONT GRILLE INTERCOOLER LOGO (CONSISTENT)	NOT NECESSARY	120.00	-
1	FRONT BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	2,800.00	-
1	FRONT L/H HEAD LAMP (CONSISTENT)	NOT NECESSARY	530.00	-
1	FRONT L/H CORNER PANEL (CONSISTENT)	NOT NECESSARY	850.00	-
1	FRONT L/H CORNER PANEL LAMP (CONSISTENT)	NOT NECESSARY	390.00	-
1	FRONT L/H STEP PANEL (CONSISTENT)	BENT	450.00	450.00
1	FRONT L/H DOOR (CONSISTENT)	TO REPAIR SEE LABOUR	4,300.00	-
2	FRONT L/H DOOR HINGE @\$200.00 (CONSISTENT)	NOT NECESSARY	400.00	-
1	FRONT L/H DOOR VOLVO LOGO (CONSISTENT)	NECESSARY	120.00	120.00
	LESS 10% DISCOUNT		-	-57.00
			11,064.00	513.00
	SPECIAL NETT ITEMS			
1	FRONT L/H DOOR COMPANY STICKER (SN) (CONSISTENT)	NECESSARY	250.00	100.00
			250.00	100.00
	<u>LABOUR</u>			
	TO REMOVE & REFIT FRONT L/H DOOR ,GLASS ,LOCK ,RUBBER ,GEAR MOTOR & TRIM BOARD .	NOT NECESSARY	480.00	-
	TO CHECK WIRING.	NOT NECESSARY	100.00	-
	TUFF KOTE.	NOT NECESSARY	150.00	-
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT L/H DOOR .		1,200.00	400.00
	SPRAY PAINTING.		1,400.00	500.00
			3,330.00	900.00
	GRAND TOTAL		14,644.00	1,513.00

Report Ref No. CC4/ASM19017800/Apa3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,200.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM19017800/Apa3q2



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.