



新福德車廠私人有限公司

AXA
LKK, ADRIAN

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

YISHUN TOWING PTE LTD

05-10-2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP AXA

Xiao Tony

Accident date: 01/10/2019

Estimated repair cost for vehicle no: XB6424B VOLVO FL10 9.6 M' 99

CHASSIS: YV2F4B9D5XA289788

S/n	Qty	Items	U/price	Amount
1	1	Front Grille Assy		\$680.00 x
2	18	Front Grille Clip	\$8.00	\$144.00 x
3	1	Front Grille Emblem Logo		\$130.00 x
4	1	Front Grille FL10 Logo		\$150.00 x
5	1	Front Grille Intercooler Logo		\$120.00 x
6	1	Front Bumper		\$2,800.00 x
7	1	Front L/H Head Lamp		\$530.00 x
8	1	Front L/H Corner Panel		\$850.00 x
9	1	Front L/H Corner Panel Lamp		\$390.00 x
10	1	Front L/H Step Panel		\$450.00 ✓
11	1	Front L/H Door		\$4,300.00 x
12	2	Front L/H Door Hinge	\$200.00	\$400.00 x
13	1	Front L/H Door Volvo Logo		\$120.00 ✓
14	1	Front L/H Door Company Sticker		\$250.00 100/50

Subtotal:- \$11,314.00

S70

S.N: 100

S13

Labour charges

To remove & refit front L/H door, glass, lock, rubber, gear motor & trim board	\$480.00 *
To check wiring	\$100.00 *
Tuff kote	\$150.00 *
Panel beating	\$1,200.00 400
Spray painting	\$1,400.00 500
Subtotal:-	<u>\$3,330.00</u>
Total:-	<u>\$14,644.00</u>

total: 1813.

4/5: 1.2K.

03 Days.

1.2K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: