

FASTECH AUTO PTE LTD  
 BLK1 KAKI BUKIT AVE 6  
 #01-46,48,50 AUTOBAY  
 SINGAPORE 417883

not allocated  
 date  
 9/10/19  
 4/29 \$700  
 through after repair  
 today

VEHICLE NO: SFG 682Z

QTY	PARTICULAR
1 PCS	BOOTLID
1 PCS	BOOTLID REAR LOGO
1 PCS	BOOTLID WEATHERSTRIP 313-20
1 PCS	BOOTLID INNER LOCK
1 PCS	BOOTLID LOCK STICKER
1 PCS	REAR BUMPER SPORT (1600)
1 PCS	REAR BUMPER LOWER SKIRTING 850
2 PCS	REAR BUMPER PDC SENSOR @\$313.00 266
1 SET	REAR BUMPER CLIPS
1 PCS	REAR BUMPER REINFORCEMENT 425.00
1 PCS	REAR BUMPER TOP RETAINER 185.00
2 PCS	REAR BUMPER REFLECTORS @\$85.00
2 PCS	TAILLAMPS @\$885.00 695.00
1 PCS	REAR END PANEL 1018-20
1 PCS	REAR END PANEL TOP GARNISH
1 PCS	REAR EXHAUST
1 PCS	REAR EXHAUST HEATSHIELD
1 PCS	REAR END PANEL SEALANT
1 PCS	REAR EXHAUST END CUTTER

R	\$1,575.20	X
M	\$85.00	✓
TW	\$399.20	✓
SU	\$366.50	X
SU	\$85.80	X
M/O	\$1,800.00	✓
D/O	\$1,200.00	✓
Shards	\$626.00	IPC
M	\$50.00	✓
SO	\$711.20	✓
Seat/cr	\$305.60	✓
A	\$170.00	X
M/S	\$1,770.00	IPC
M	\$1,255.20	✓
A	\$322.30	X
R	\$1,680.00	X
Seat	\$299.20	✓
M	\$50.00	✓
SU	\$380.00	X
	\$13,131.20	

(102)

LABOUR CHARGES

TO CHECK WIRING	\$80.00	-30
TO DISMANTLE & REPLACING PDC SENSOR	\$80.00	-80
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY	\$150.00	-80
TO DISMANTLE & REFIX REAR EXHAUST	\$120.00	-60
TO REPROGRAMME & RESET SYSTEM	\$200.00	-80
TO SPRAY RUST PROOFING	\$80.00	-30
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,200.00	650
TO PUTTY & SPRAY PAINTING	\$1,500.00	900
<b>TOTAL</b>	<b>\$16,541.20</b>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

P-583660  
 102  
 528794  
 713284  
 570635