

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Steve (LKK) nil prindl 8/10/19, 3.30pm
4dy
L/S
Ry AL 5m

Ms AIG Asia Pacific Insurance Pte Ltd

Date: 08/10/2019

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLM3709J

CHASSIS NO : NHP1707061473

MAKE / MODEL : Toyota Sienta Hybrid 1.5X Auto

DATE OF ACCIDENT : 18/09/2019

YOUR INSURED VEHICLE NUMBER : SFW1207Y

MILEAGE : 277427 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
11	Rear tailgate / <i>00</i>	1PC	\$1,879.00	\$1,879.00
14	Rear tailgate weatherstrip <i>x</i>	1PC	\$432.00	\$432.00
15	Rear tailgate lock / <i>AT</i>	1PC	\$504.00	\$504.00
16	Rear tailgate lock catch <i>x</i>	1PC	\$64.80	\$64.80
20	Rear tailgate Toyota logo <i>AK</i>	1PC	\$60.00	\$60.00
21	Rear end panel <i>2 x R</i>	1PC	\$828.00	\$828.00
24	Rear end panel top garnish <i>x</i>	1PC	\$250.00	\$250.00
25	Rear bumper reinforcement <i>x</i>	1PC	\$338.10	\$338.10
26	Rear bumper sponge <i>q</i>	1PC	\$157.50	\$157.50
27	Rear bumper / <i>BR</i>	1PC	\$1,257.83	\$1,257.83
34	Rear bumper pad / <i>CRU</i>	1PC	\$64.80	\$64.80
LIST TOTAL S\$:				\$5,836.03
25.00% DISCOUNT S\$:				\$1,459.01
				\$4,377.02

SPECIAL NETT

1	Bumper clips <i>AK</i>	1 SET	\$80.00 <i>30</i>
2	Reverse sensor <i>SHM</i>	1 SET	\$260.00 <i>200</i>
3	Windscreen sealant <i>AK</i>	1PC	\$100.00 <i>40</i>
Special Nett Total S\$:			\$440.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LABOUR CHARGES

3	To remove and install rear tailgate glass	\$120.00	/
3	Transfer tailgate mechanism	\$100.00	50
	To labour charge for removing rear tailgate, rear bumper, end		
4	panel and spare tyre ^x panel out to facilitate repairs and replacement of damaged parts	\$1,000.00	550
5	To respray rear tailgate, rear end panel, spare tyre ^x panel and rear bumper	\$1,200.00	600
8	To deactivate and active high voltage battery as a safety precautions	\$300.00	X 50
9	To conduct a standard of operating procedures post repairs diagnostic scan test as a requirements for hybrid cars upon	\$300.00	X
LABOUR TOTAL S\$:		\$3,020.00	
TOTAL S\$:		\$7,837.02	
7% GST		\$548.59	
GRAND TOTAL S\$:		\$8,385.61	