

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Steve (LKK) nil Primid 8/10/19, 3 3/4
 4 dy
 L/S
 RJ AL SM

Ms AIG Asia Pacific Insurance Pte Ltd
 Date: 08/10/2019
 Attn: MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLM3709J
 CHASSIS NO: NHP1707061473
 MAKE / MODEL: Toyota Sienta Hybrid 1.5X Auto
 DATE OF ACCIDENT: 18/09/2019
 YOUR INSURED VEHICLE NUMBER: SFW1207Y
 MILEAGE: 277427 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>	
11	Rear tailgate / <i>DD</i>	1PC	\$1,879.00	\$1,879.00	1086 /
14	Rear tailgate weatherstrip X <i>NAI</i>	1PC	\$432.00	\$432.00	
15	Rear tailgate lock / <i>NT</i>	1PC	\$504.00	\$504.00	430 /
16	Rear tailgate lock catch X <i>NAI</i>	1PC	\$64.80	\$64.80	
20	Rear tailgate Toyota logo / <i>NAI</i>	1PC	\$60.00	\$60.00	/
21	Rear end panel <i>2 X R</i>	1PC	\$828.00	\$828.00	
24	Rear end panel top garnish X <i>NAI</i>	1PC	\$250.00	\$250.00	
25	Rear bumper reinforcement X <i>NAI</i>	1PC	\$338.10	\$338.10	
26	Rear bumper sponge X <i>NAI</i>	1PC	\$157.50	\$157.50	
27	Rear bumper / <i>BR</i>	1PC	\$1,257.83	\$1,257.83	377 /
34	Rear bumper pad / <i>CRU</i>	1PC	\$64.80	\$64.80	/
				LIST TOTAL S\$:	\$5,836.03
				25.00% DISCOUNT S\$:	\$1,459.01
					\$4,377.02

2917.80
 - 70%
 1614.24

SPECIAL NETT

1	Bumper clips / <i>NAI</i>	1 SET	\$80.00	30
2	Reverse sensor / <i>SM</i>	1 SET	\$260.00	200
3	Windscreen sealant / <i>NAI</i>	1PC	\$100.00	40
			Special Nett Total S\$:	\$440.00

270

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LABOUR CHARGES

- | | | | |
|---|---|------------|-----|
| 3 | To remove and install rear tailgate glass | \$120.00 | / |
| 3 | Transfer tailgate mechanism | \$100.00 | 50 |
| 4 | To labour charge for removing rear tailgate, rear bumper, end panel and spare tyre panel out to facilitate repairs and replacement of damaged parts | \$1,000.00 | 550 |
| 5 | To respray rear tailgate, rear end panel, spare tyre panel and rear bumper | \$1,200.00 | 600 |
| 8 | To deactivate and active high voltage battery as a safety precautions | \$300.00 | 50 |
| 9 | To conduct a standard of operating procedures post repairs diagnostic scan test as a requirements for hybrid cars upon | \$300.00 | X |

LABOUR TOTAL S\$:	\$3,020.00
TOTAL S\$:	\$7,837.02
7% GST	\$548.59
GRAND TOTAL S\$:	<u>\$8,385.61</u>

1370

P - 1614.24

NI - 270

L - 1370

3254.24

L/S - 2603.39

= 2600