

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

ROC:53360061L

GST:53360061L

QT19/PC4710C/TPC-578

Steve (LKK)

wrl R/L 10/10/19, 10.11 am

L/S

R/L AL SH

6 dy

Lonpac Insurance Bhd
100 Beach Road
#19-00 Shaw Tower
Singapore 189702

QUOTATION

Dear Sir,

Cost of Repair to Vehicle PC4710C

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (\$\$)	AMOUNT (\$\$)
1.	Front windscreen / CRA	1	3,800.00	3,800.00
2.	Front windscreen inner moulding / MC	1	680.00	680.00
3.	Front RH rear view mirror assy / BR	1	1,350.00	1,350.00
4.	Front RH panel / DD	1	4,200.00	4,200.00
5.	Sealant / MC	8	40.00	320.00
6.	Labour to remove & refit front windscreen	1	1,000.00	1,000.00 800
7.	Check wiring	1	20.00	20.00 /
8.	Labour charges	1	1,200.00	1,200.00 1000
9.	Spray painting	1	800.00	800.00 700
SUB-TOTAL				SS13,370.00

- Price before 7% gst

Thank you.

Yours faithfully,



Winnie Chai

HP: 9850-9666

