CONNECTS

QT19/PC4710C/TPC-578

Lonpac Insurance Bhd 100 Beach Road #19-00 Shaw Tower Singapore 189702

QUOTATION

Dear Sir,

Cost of Repair to Vehicle PC4710C

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Front windscreen	1	3,800.00	3,800.00
2.	Front windscreen inner moulding	1	680.00	680.00
3.	Front RH rear view mirror assy	1	1,350.00	1,350.00
4.	Front RH panel	1	4,200.00	4,200.00
5.	Sealant	8	40.00	320.00
6.	Labour to remove & refit front windscreen	1	1,000.00	1,000.00
7.	Check wiring	1	20.00	20.00
8.	Labour charges	1	1,200.00	1,200.00
9.	Spray painting	1	800.00	800.00
	D: 10 Th		SUB-TOTAL	S\$13,370.00

Price before 7% gst

Thank you.

Yours faithfully,

Winnie Chai HP: 9850-9666