

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 15234

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1215/2019/NS
Date : 8-Oct-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Tan Kean Hui
Address : 235 Tembeling Road
#02-03
Singapore 423720
Telephone : HP +65 83828745
Type of Claim : Own Damage Claims
Policy No. :
Vehicle No : **SGX 580 H**
Model Code : Audi A3 Cabriolet 1.4 TFS
Model / Year : May-18
Engine No : CZC 774164
Chassis No : WAUZZZ8V7J1054082
Mileage :
Date In : 9-Apr-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 8-Oct-19
Place of Accident : MCE Tunnel

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGX 580 H

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear wire harness, relay, fuse boxes, audio equipment, rhs rear window and lifting mechanism. Rhs trims, luggage compartment trims.	S/N \$ 1,600.00 ✓	✓
2	To remove and reinstall rear parking aid.	S/N \$ 280.00 ✓	✓
3	To remove and reinstall convertible top, complete with frame, hydraulic system assy, storage box etc.	S/N \$ 1,800.00 ✓	photo. ✓
4	To dismantle rear bumper, rear lid assy and fixtures. Cut out and reweld rhs 1/4 panel, sill panel, inner B pillar. To renew rear bumper. Reorganise crash management components. Reinstall all parts removed.	\$ 6,300.00 3500	3000. 4200
5	To respray rhs rear fender, rhs sill panel, door entrance and rear bumper. To carry out joint sealer works and stone chip treatment. End Panel	\$ 4,000.00	2800 1650 2200
6	To renew rhs rear rim and carry out wheel alignment.	S/N \$ 280.00 ✓	✓
7	To carry out diagnostic checks.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 14,452.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGX 580 H

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
1	REAR FENDER - RH <i>distorted</i>	\$ 2,110.00 ✓	1688
2	NOISE INSULATION PLATE - RH <i>new</i>	\$ 64.00 ✕	X
3	REAR BUMPER <i>tom</i>	\$ 1,793.00 ✓	1434.40
4	REAR BUMPER STICKY PAD ? nn 4	\$ 21.00 ? ✕	X
5	REAR BUMPER FIXING PARTS <i>new</i>	\$ 175.00 ✕	X
6	REAR BUMPER WHEEL HOUSING LINER ADAPTER - RH <i>new</i>	\$ 34.00 ✕	X
7	REAR BUMPER GUIDE SECTION - RH <i>dyd</i>	\$ 15.00 ✓	11.44
8	REAR BUMPER LOCKING MECHANISM <i>the</i>	\$ 27.00 ✓	21.20
9	REAR BUMPER SPOILER - LH <i>new</i>	\$ 216.00 ✕	
10	REAR LIGHT REFLECTOR - RH <i>new</i>	\$ 38.00 ✕	
11	LED TAIL LIGHT - RH <i>3 new</i>	\$ 800.00 ✕	
12	TAIL LIGHT TRIM - RH	\$ 27.00 ✕	
13	REAR WHEEL HOUSING LINER - RH ? X NN	\$ 223.00 ?	
14	WHEEL HOUSING LINER ATTACHMENT PARTS ? nec	\$ 52.00 ?	41.60
15	REAR BUMPER GUIDE SECTION - RH <i>7 damage</i>	\$ 60.00 ?	47.84
16	REAR ALUMINIUM RIM - RH <i>cut</i>	\$ 666.00 ✓	532.40
17	ACRYLIC SEALANT	S/N \$ 180.00 ✓	180
18	CAVITY WAX	S/N \$ 140.00 ✓	140
19	STONE CHIP	S/N \$ 180.00 ✓	180
20	METAL FILLER POWDER	S/N \$ 280.00 ✓	280
21	SUNDRIES nec	\$ 500.00 ?	1.92
TOTAL SPARE PARTS		\$ 7,601.00	
TOTAL LABOUR CHARGES		\$ 14,452.00	
GRAND TOTAL		\$ 22,053.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 09/10/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 16 Days.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 15234

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1215/2019/NS
Date	:	8-Oct-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Tan Kean Hui
Address	:	235 Tembeling Road #02-03 Singapore 423720
Telephone	:	HP +65 83828745
Type of Claim	:	Own Damage Claims
Policy No.	:	
Vehicle No	:	SGX 580 H
Model Code	:	Audi A3 Cabriolet 1.4 TFS
Model / Year	:	May-18
Engine No	:	CZC 774164
Chassis No	:	WAUZZZ8V7J1054082
Mileage	:	
Date In	:	9-Apr-19
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	8-Oct-19
Place of Accident	:	MCE Tunnel

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGX 580 H

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear wire harness, relay, fuse boxes, audio equipment, rhs rear window and lifting mechanism. Rhs trims, luggage compartment trims.	S/N \$ 1,600.00 ✓	
2	To remove and reinstall rear parking aid.	S/N \$ 280.00 ✓	
3	To remove and reinstall convertible top, complete with frame, hydraulic system assy, storage box etc.	S/N \$ 1,800.00 ✓	photo.
4	To dismantle rear bumper, rear lid assy and fixtures. Cut out and reweld rhs 1/4 panel, sill panel, inner B pillar. To renew rear bumper. Reorganise crash management components. Reinstall all parts removed.	\$ 6,300.00	3000.
5	To respray rhs rear fender, rhs sill panel, door entrance and rear bumper. To carry out joint sealer works and stone chip treatment. <i>End Panel</i>	\$ 4,000.00	1650 2200.
6	To renew rhs rear rim and carry out wheel alignment.	S/N \$ 280.00 ✓	
7	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 14,452.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGX 580 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR FENDER - RH <i>Distorted</i>	\$	2,110.00 ✓
2	NOISE INSULATION PLATE - RH <i>new</i>	\$	64.00 ✓
3	REAR BUMPER <i>tom</i>	\$	1,793.00 ✓
4	REAR BUMPER STICKY PAD ?	4 \$	21.00 ?
5	REAR BUMPER FIXING PARTS <i>new</i>	\$	175.00 ✓
6	REAR BUMPER WHEEL HOUSING LINER ADAPTER - RH <i>new</i>	\$	34.00 ✓
7	REAR BUMPER GUIDE SECTION - RH <i>Dist</i>	\$	15.00 ✓
8	REAR BUMPER LOCKING MECHANISM <i>Rhr</i>	\$	27.00 ✓
9	REAR BUMPER SPOILER - LH <i>new</i>	\$	216.00 ✓
10	REAR LIGHT REFLECTOR - RH <i>new</i>	\$	38.00 ✓
11	LED TAIL LIGHT - RH <i>3 new</i>	\$	800.00 ✓
12	TAIL LIGHT TRIM - RH	\$	27.00 ✓
13	REAR WHEEL HOUSING LINER - RH ?	\$	223.00 ?
14	WHEEL HOUSING LINER ATTACHMENT PARTS ?	\$	52.00 ?
15	REAR BUMPER GUIDE SECTION - RH <i>CRAT</i>	\$	60.00 ?
16	REAR ALUMINIUM RIM - RH <i>ut</i>	\$	666.00 ✓
17	ACRYLIC SEALANT <i>2</i>	S/N \$	180.00 ✓
18	CAVITY WAX <i>new</i>	S/N \$	140.00 ✓
19	STONE CHIP	S/N \$	180.00 ✓
20	METAL FILLER POWDER	S/N \$	280.00 ✓
21	SUNDRIES	\$	500.00 ?
TOTAL SPARE PARTS		: \$	7,601.00
TOTAL LABOUR CHARGES		\$	14,452.00
GRAND TOTAL		\$	<u>22,053.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Admin Lj
Surveyed Date : 09/10/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 16 Days.

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant