

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd

Date: 4/9/2019

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. : SLH4305K

CHASSIS NO : GP71044191

MAKE / MODEL : Honda Shuttle Hybrid 1.5 Auto

DATE OF ACCIDENT : 04/10/2019

YOUR INSURED VEHICLE NUMBER : SKA9986K

MILEAGE : 205347 Km

PARTS DESCRIPTION

	QTY	UNIT PRICE	LIST PRICE
1 Rear bumper X R	1PC	\$1,850.00	\$1,850.00
2 R/R fender / 00	1PC	\$2,000.00	\$2,000.00
LIST TOTAL S\$:			\$3,850.00
20.00% DISCOUNT S\$:			\$770.00
			\$3,080.00

SPECIAL NETT

1 Bumper and end panel clips X	1 SET	\$200.00
Special Nett Total S\$:		\$200.00

LABOUR CHARGES

1 To labour charge for remove rear bumper out to facilitate repairs and replacement of damaged parts. Also include straightenning R/R fender	\$900.00	600 700
2 To respray rear bumper and R/R fender	\$900.00	450
3 To remove and install R/R 1/4 glass	\$120.00	100

LABOUR TOTAL S\$:	\$1,920.00
TOTAL S\$:	\$5,200.00
7% GST	\$364.00
GRAND TOTAL S\$:	\$5,564.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve (LKK) W/L Mr. J. L. 8/10/19, 4.39pm
4 dy
RJ AL sy
L/S