



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER:
UNKNOWN

India International Insurance Pte Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	06/10/2019
Vehicle Reg. No.:	SFB100M	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	MERCEDES-BENZ S350, 3.5 (A)	Vehicle Reg. Date:	01/07/2007
Vehicle Colour:	GREY	Chassis No:	WDD2211562A139252
Engine No:	27296530628611		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	10,259.23
Miscellaneous Items	11.00
Labour	2,020.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	12,290.23
+ GST 7.00% (S\$)	860.32
Nett Amount (S\$)	13,150.55

This claim is handled by: WEI JIAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Tanf'km 97495749 /
'WP' 67410434
17/10/19 @ 350pm
24 days
Resurvey after repair
Lumpsum
Sur @ kuantu.wm.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Oct 2019)
Parts:	143	MERCEDES-BENZ S350 3.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFB100M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	10.00	0.00	conq — *1,925.20 FL
2	10		*BUMPER CLIPS	10.00	0.00	nei — *90.00 FL
3	10		*RIVET	10.00	0.00	nei — *90.00 FL
4	1		*AIR VENT LH	10.00	0.00	? *92.50 FL
5	1		*REAR FENDER COWLING LH	10.00	0.00	de? *130.50 FL
6	1		*REAR RIM LH	10.00	0.00	cut — *804.75 FL
7	1		*REAR TRHUST ARM LH	10.00	0.00	? *510.20 FL
8	1		*REAR LOWER ARM LH	10.00	0.00	? *536.50 FL
9	1		*REAR KNUCKLE ARM LH	10.00	0.00	? *1,915.10 FL
10	1		*REAR ABSORBER LH	10.00	0.00	? *4,388.20 FL
11	1		*REAR CAMBER STRUT LH	10.00	0.00	? *540.40 FL
12	1		*REAR WHEEL HUB LH	10.00	0.00	? *285.80 FL
13	10		*REAR COWLING CLIPS	10.00	0.00	nei — *90.00 FL 30
14	1		*REAR FENDER LH - REPAIR	10.00	0.00	-

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	11,399.15
- List Item Discount on L Items (\$\$)	1,139.92
Total Parts (\$\$)	10,259.23

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS	New	400 500.00
2	TO SPRAY PAINT ALL AFFECTED ACCIDENT AREAS	New	400 600.00
3	TO REMOVE & REFIX REAR SENSOR & CHECK WIRING	New	30 80.00
4	TO REMOVE & REFIX WHEEL RIM AND BALANCING	New	30 60.00
5	WHEEL ALIGNMENT	New	✓ 80.00
6	TO RUST PROOF AFFECTED AREAS	New	30 50.00
7	PROGRAM SETTING	New	150 300.00
8	TO REMOVE & REFIX REAR UNDERCARRIAGE	New	photo. 150? 350.00
Gross Labour Cost (\$\$)			2,020.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >